

REPORT OF

THE STATISTICAL SURVEY OF INFRASTRUCTURAL FACILITIES IN STATE  
GOVERNMENT OWNED PRIMARY AND SECONDARY SCHOOLS IN  
ONDO STATE, 2010

CONDUCTED BY:

**MINISTRY OF ECONOMIC PLANNING AND BUDGET**

(RESEARCH AND STATISTICS DEPARTMENT)

AKURE, ONDO STATE

# FOREWORD

School infrastructure constitutes a major component of conducive/enabling environment for teaching and learning. The creation of child/learning friendly environment in our schools will go a long way at achieving all round development of the child and the attainment of development targets in education.

This survey appraised the status of infrastructural facilities in state government owned primary and secondary schools in terms of availability, quantity, functionality, and adequacy. The shortfall/gap in the supply of these facilities and the ones requiring immediate rehabilitation are presented as part of this report.

The report is in two parts:

- Part 1 Summary of infrastructural facilities in primary and secondary schools on local government basis. [Tables 1-36]
- Part 2 Status of infrastructural facilities in each school [Tables 37-72]

The document is commended to policy makers, planners and other stakeholders in the education sector.

We appreciate the efforts of officers in the Ministry of Education, Universal Basic Education Board, Area Education Offices, Primary and Secondary Schools in the State for their cooperation during the field work.

Comments and suggestions for improvement of future exercise are welcome from readers and users of this report.

Director,  
Research and Statistics  
Ministry of Economic Planning & Budget  
Akure  
December, 2010

# TABLE OF CONTENTS

	<b>PAGE</b>
<b>TITLE PAGE</b>	
<b>FOREWORD</b>	<b>2</b>
<b>TABLE OF CONTENTS</b>	<b>3 -6</b>
<b>CHAPTER ONE: INTRODUCTION AND SURVEY METHODOLOGY</b>	<b>7 - 11</b>
<b>1.1 INTRODUCTION</b>	
<b>1.2 OBJECTIVES OF THE SURVEY</b>	
<b>1.3 COVERAGE OF THE SURVEY</b>	
<b>1.4 SCOPE OF THE SURVEY</b>	
<b>1.5 METHOD OF DATA COLLECTION</b>	
<b>1.6 TABULATION/ANALYSIS PROCEDURE</b>	
<b>1.7 REFERENCE PERIOD</b>	
<b>CHAPTER TWO: FINDINGS &amp; RECOMMENDATIONS</b>	<b>12 -19</b>
<b>2.1 FINDINGS</b>	
<b>2.2 RECOMMENDATIONS</b>	
<b>2.3 PART 1: LIST OF TABLES</b>	
<b>TABLE 1 SUMMARY OF SCHOOLS, CLASSROOMS, ENROLMENT AND TEACHERS IN PUBLIC PRIMARY AND SECONDARY SCHOOLS IN ONDO STATE</b>	<b>20</b>
<b>TABLE 2 DISTRIBUTION OF PUBLIC PRIMARY SCHOOLS BY PERIOD OF ESTABLISHMENT</b>	<b>21</b>
<b>TABLE 3 DISTRIBUTION OF PUBLIC SECONDARY SCHOOLS BY PERIOD OF ESTABLISHMENT</b>	<b>22</b>
<b>TABLE 4 LAND AREA SERVED BY A SCHOOL (SQUARE KILOMETER)</b>	<b>23</b>
<b>TABLE 5 DISTRIBUTION OF CLASSROOMS IN PUBLIC PRIMARY SCHOOLS BY PERIOD OF CONSTRUCTION</b>	<b>24</b>
<b>TABLE 6 DISTRIBUTION OF CLASSROOMS IN PUBLIC SECONDARY SCHOOLS BY PERIOD OF CONSTRUCTION</b>	<b>25</b>
<b>TABLE 7 DISTRIBUTION OF CLASSROOMS IN PUBLIC PRIMARY SCHOOLS BY PROVIDING AGENCIES</b>	<b>26</b>
<b>TABLE 8 DISTRIBUTION OF CLASSROOMS IN PUBLIC SECONDARY SCHOOLS BY PROVIDING AGENCIES</b>	<b>27</b>
<b>TABLE 9 AVAILABILITY OF OFFICE ACCOMODATION IN PUBLIC PRIMARY SCHOOLS</b>	<b>28</b>
<b>TABLE10 AVAILABILITY OF OFFICE ACCOMODATION IN PUBLIC SECONDARY SCHOOLS</b>	<b>29</b>

<b>TABLE 11</b>	<b>BUILDING FACILITIES BY TYPE OF MATERIALS IN PUBLIC PRIMARY SCHOOLS</b>	<b>30</b>
<b>TABLE 12</b>	<b>BUILDING FACILITIES BY TYPE OF MATERIALS IN PUBLIC SECONDARY SCHOOLS</b>	<b>31</b>
<b>TABLE 13</b>	<b>AVAILABILITY OF HEALTH FACILITIES IN PUBLIC PRIMARY SCHOOLS</b>	<b>32</b>
<b>TABLE 14</b>	<b>AVAILABILITY OF HEALTH FACILITIES IN PUBLIC SECONDARY SCHOOLS</b>	<b>33</b>
<b>TABLE 15</b>	<b>ACCESS TO POTABLE WATER SUPPLY IN PUBLIC PRIMARY SCHOOLS</b>	<b>34</b>
<b>TABLE 16</b>	<b>ACCESS TO POTABLE WATER SUPPLY IN PUBLIC SECONDARY SCHOOLS</b>	<b>35</b>
<b>TABLE 17</b>	<b>SANITATION FACILITIES IN PUBLIC PRIMARY SCHOOLS</b>	<b>36</b>
<b>TABLE 18</b>	<b>SANITATION FACILITIES IN PUBLIC SECONDARY SCHOOLS</b>	<b>37</b>
<b>TABLE 19</b>	<b>SOURCE OF ELECTRIC POWER SUPPLY IN PUBLIC PRIMARY SCHOOLS</b>	<b>38</b>
<b>TABLE 20</b>	<b>SOURCE OF ELECTRIC POWER SUPPLY IN PUBLIC SECONDARY SCHOOLS</b>	<b>39</b>
<b>TABLE 21</b>	<b>RECREATIONAL FACILITIES IN PUBLIC PRIMARY SCHOOLS</b>	<b>40</b>
<b>TABLE 22</b>	<b>RECREATIONAL FACILITIES IN PUBLIC SECONDARY SCHOOLS</b>	<b>41</b>
<b>TABLE 23</b>	<b>AVAILABILITY OF LIBRARIES AND LABORATORIES IN PUBLIC SECONDARY SCHOOLS</b>	<b>42</b>
<b>TABLE 24</b>	<b>LEVEL OF EQUIPPING OF LABORATORIES IN PUBLIC SECONDARY SCHOOLS</b>	<b>43</b>
<b>TABLE 25</b>	<b>INFORMATION TECHNOLOGY IN PUBLIC PRIMARY SCHOOLS</b>	<b>44</b>
<b>TABLE 26</b>	<b>INFORMATION TECHNOLOGY IN PUBLIC SECONDARY SCHOOLS</b>	<b>45</b>
<b>TABLE 27</b>	<b>MAJOR TEACHING AID AVAILABLE IN PUBLIC PRIMARY SCHOOLS</b>	<b>46</b>
<b>TABLE 28</b>	<b>MAJOR TEACHING AID AVAILABLE IN PUBLIC SECONDARY SCHOOLS</b>	<b>47</b>
<b>TABLE 29</b>	<b>SUMMARY OF PUBLIC PRIMARY SCHOOLS SHOWING STUDENT/CLASSROOM AND STUDENT TEACHER RATIOS</b>	<b>48</b>
<b>TABLE 30</b>	<b>SUMMARY OF PUBLIC SECONDARY SCHOOLS SHOWING STUDENT/CLASSROOM AND STUDENT/TEACHER RATIO</b>	<b>49</b>
<b>TABLE 31</b>	<b>NUMBERS OF SEATS AND DESKS IN PUBLIC PRIMARY SCHOOLS</b>	<b>50</b>
<b>TABLE 32</b>	<b>NUMBERS OF SEATS AND DESKS IN PUBLIC SECONDARY SCHOOLS</b>	<b>51</b>
<b>TABLE 33</b>	<b>SUMMARY OF PUBLIC SECONDARY SCHOOLS INDICATING BOARDING AND DAY SYSTEMS</b>	<b>52</b>
<b>TABLE 34</b>	<b>DISTRIBUTION OF PUBLIC SECONDARY SCHOOLS BY CO-EDUCATIONAL, BOYS AND GIRLS ONLY</b>	<b>53</b>
<b>TABLE 35</b>	<b>SUMMARY OF ROOFS, FLOORS, WINDOWS AND WALLS INDICATING NUMBERS IN BAD CONDITIONS IN PUBLIC PRIMARY SCHOOLS</b>	<b>54</b>

**TABLE 36**            **SUMMARY OF ROOFS, FLOORS, WINDOWS AND WALLS INDICATING NUMBERS IN BAD CONDITIONS IN PUBLIC SECONDARY SCHOOLS**

**55**

**PART 2**

**TABLE 37**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN AKOKO NORTH EAST LGA**

**TABLE 38**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN AKOKO NORTH WEST LGA**

**TABLE 39**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN AKOKO SOUTH EAST LGA**

**TABLE 40**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN AKOK SOUTH WEEST LGA**

**TABLE 41**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN AKURE NORTH LGA**

**TABLE 42**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN AKURE SOUTH LGA**

**TABLE 43**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN ESE-ODO LGA**

**TABLE 44**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN IDANRE LGA**

**TABLE 45**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN IFEDORE LGA**

**TABLE 46**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN ILAJE LGA**

**TABLE 47**            **INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN AKOKO NORTH EAST LGA**

**TABLE 48**            **INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN AKOKO NORTH WEST LGA**

**TABLE 49**            **INFRASTRUCTURAL FACILITIES IN PUBLIC SECONADRY SCHOOLS IN AKOKO-SOUTH EAST LGA**

**TABLE 50**            **INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN AKOKO SOUTH WEST LGA**

**TABLE 51**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN ILE OLUJI/OKE-IGBO LGA**

**TABLE 52**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN IRELE LGA**

**TABLE 53**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN ODIGBO LGA**

**TABLE 54**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN OKITIPUPA LGA**

**TABLE 55**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN ONDO-EAST LGA**

**TABLE 56**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN ONDO-WEST LGA**

**TABLE 57**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN OSE LGA**

**TABLE 58**            **INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN OWO LGA**

**TABLE 59**            **INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN AKURE NORTH LGA**

**TABLE 60**            **INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN AKURE SOUTH LGA**

**TABLE 61**            **INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN ESE-ODO LGA**

<b>TABLE 62</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN IDANRE LGA</b>
<b>TABLE 63</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN IFEDORE LGA</b>
<b>TABLE 64</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN ILAJE LGA</b>
<b>TABLE 65</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN ILE-OLUJI/ OKE-IGBO LGA</b>
<b>TABLE 66</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN IRELE LGA</b>
<b>TABLE 67</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN ODIGBO LGA</b>
<b>TABLE 68</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN OKITIPUPA LGA</b>
<b>TABLE 69</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN ONDO-EAST LGA</b>
<b>TABLE 70</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN ONDO-WEST LGA</b>
<b>TABLE 71</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN OSE LGA</b>
<b>TABLE 72</b>	<b>INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN OWO LGA</b>

## CHAPTER ONE

### INTRODUCTION AND SURVEY METHODOLOGY

#### 1.1 INTRODUCTION

School infrastructure consists of buildings, furniture, health/water and sanitation facilities, electric facilities, recreational facilities, libraries, laboratories, computer systems, school records and teaching aids. These infrastructures assist in teaching and learning activities in the schools.

Building infrastructure includes:

- i Classrooms
- ii Offices
- iii Hostels
- iv Staff quarters

Furniture includes:

- i. Seats
- ii. Desks
- iii. Chair
- iv. Tables

Health / Water and Sanitation facilities include:

- i. First Aid boxes
- ii. School clinics
- iii. Bore holes
- iv. Stand Piles
- v. Protected Wells
- vi. Water Closets
- vii. VIP/Traditional Pit Latrines
- viii. Wash hand basins

Electric facilities include:

- i PHCN connections
- ii Generating sets
- iii Solar equipment

Recreational facilities include:

- i Playgrounds
- ii School halls
- iii Table tennis facility

School records include:

- i Admission Register
- ii Attendance Register
- iii Syllabuses/Plan of work
- iv Supervision Book

Teaching aids include:

- i Chalk Board
- ii Slide
- iii Visual aid

## 1.2 OBJECTIVES OF THE SURVEY

1. To update the database on infrastructural facilities in state government owned primary and secondary schools.
2. To identify the gap in the supply and demand of infrastructural facilities in primary and secondary schools in the state.
3. To offer policy makers, administrators, planners and other stakeholders in education, a wealth of information on infrastructures on schools for planning and partnership.
4. To serve as instrument for monitoring future development in the schools.



### 1.3 COVERAGE OF THE SURVEY

The survey covered all the state owned primary and secondary schools in the State.

### 1.4 SCOPE OF THE SURVEY

#### Subject coverage

The Survey collects and presents information on the following:

1. Types of materials used for buildings
2. Period of construction (of buildings).
3. Providers of buildings (Federal Government, State Government, Communities, others)
4. Number of classrooms
5. Number of seats
6. Physical condition of classrooms (roofs, walls, windows, floor)
7. Teaching aids available
8. Availability of Head Teachers'/Principals' Office/Staff Room
9. Availability of libraries
10. Availability of laboratories and level of equipping
11. Availability of computer units
12. Availability of recreational facilities (Playground, School halls, Table tennis courts, Food vendors/Canteens, Swimming pools)
13. Availability of health facilities (School clinics, First Aid Boxes, Wash Hand Basins, Refuse Bins)
14. Access to potable water (within school premises)
15. Access to sanitary means of excreta disposal (within school premises)
16. Solid Waste disposal system/facilities available
17. Access to electric power

18. Availability of school records (admission registers, attendance registers, syllabus/module, plan of work, supervision books, text books, prospectus, timetables, visitors' books)
19. No of Primary and Secondary Schools in each LGA
20. No of Teachers in each school
21. Student Enrolment – 2008/2009 academic session
22. Pupils/Teacher ratio
23. Pupils/Classroom ratio

#### 1.5 METHOD OF DATA COLLECTION

Data collection was by the use of both close and open ended questionnaires. In view of the need to get quality data, the questionnaires were hand delivered to School Principals or Head teachers as applicable to complete. After completion, the enumerators carried out verification of the returns by direct observation and checking of records. Supervisors and Coordinators also made spot checks to validate the entries.

Some of the challenges encountered in the course of data collection include repeat calls, high cost of transportation especially in riverine areas and difficult terrains.

#### 1.6 TABULATION/ANALYSIS PROCEDURE

After editing of the questionnaires, tables for presentation of data were generated and the data were transcribed into the tables. Simple statistical analyses were then carried out using the Microsoft excel software package.

#### 1.7 REFERENCE PERIOD

The information contained in this report relates to 2008/2009 academic session in the primary and secondary schools.

## CHAPTER TWO

### FINDINGS & RECOMMENDATIONS

#### 2.1 FINDINGS

The data from the survey were tabulated in two major forms. One set of table was the summary on local government basis while the other set was school specific. In all, 72 tables were generated. The following are the summary statistics and findings from the survey:

##### 1. TOTAL NUMBER OF SCHOOLS AND STUDENTS

##### ENROLMENT

There are 1,164 primary schools, 300 junior secondary schools and 297 senior secondary schools in the State. The total enrolment in primary school was 459,521 in 2008/2009 academic session; this gives an average of 395 Pupils per primary school. The total enrolment was 136,203 for junior secondary schools and 117,201 senior secondary schools which gives an average of 454 and 395 per school respectively(Table 1).

##### 2. SCHOOLS BY PERIOD OF ESTABLISHMENT

The distribution of primary schools by period of establishment as contained in Table 2 is as follows: 57% (before 1960) 3 % (1960 -1969), 21% (1970 - 1979), 10% (1980 – 1989), 6% (1990 – 1999), 3% (2000 – 2009). Table 3 shows corresponding information for senior secondary schools, 9% (before

1960), 7% (1960 – 1969, 28% (1970 – 1979), 34% (1980 – 1989), 3% (1990 – 1999), 19% (2000 – 2009). The figures for junior secondary schools as follows: 8% (before 1960), 7% (1960 -1969), 32% (1970 – 1979), 41% (1980 – 1989), 2% (1990 – 1999), 9% (2000 – 2009).

### 3. ACCESSIBILITY TO SCHOOLS

Table 4 shows approximate land area served by a school in each Local Government Area (in square kilometers) and the approximate distance to get to a school, both primary and secondary. The data shows that approximate land area served by a primary school ranges from 4km<sup>2</sup> in Akure South LGA to 27Km<sup>2</sup> in Ose LGA while land area served by a secondary school ranges from 11 Km<sup>2</sup> in Akure South LGA to 154Km<sup>2</sup> in Idanre LGA.

### 4. CLASSROOMS BY PERIOD OF CONSTRUCTION

There are a total of 11,847 Classrooms in the 1164 Primary schools giving an average of about 10 classrooms per school as shown by Table 5. 17% of the classrooms were built before 1960, 7% (1969 – 1969), 15% (1970 -1979), 14% (1980 – 1989), 14% (1990 – 1999), 34% (2000 – 2009). The available classrooms represent about 72% of classrooms required based on the UNESCO Teacher Student Ratio (TSR) recommendation of 1 teacher to 28 pupils (a teacher usually handles a class).

Table 6 shows that there are 2711 and 2753 classrooms in the junior and senior secondary schools respectively. The table also reveals that in the junior secondary schools, 4% of the classrooms were built before 1960, 13% (1960 -1969), 21% (1970 -1979), 25% (1980 – 1989), 15% (1990 – 1999), 22% (2000 -2009). The corresponding figures for senior secondary schools are 5% of the classrooms were before 1960, 11% (1960 – 1969), 23% (1970 – 1979), 34% (1980 – 1989), 14% (1990 – 1999), 13% (2000 – 2009).

5. OFFICE ACCOMMODATION

82% of primary schools in the state have Headmaster's office (Table 9). 70% of junior secondary schools have principals' office and 52% have staff rooms while 88% and 64% of the senior secondary schools have principals' office & staff rooms respectively (Table 10).

6. HEALTH FACILITIES

Tables 13 and 14 show available health facilities in primary, junior secondary and senior secondary schools in the State. Out of the total of 1,164 public primary schools, less than 1% have school clinic, 86% have First Aid Boxes, 70% have Wash hand basins, while 37% have Refuse bins. For junior secondary schools, 2% have school clinics, 76% have First Aid Boxes, 61% have wash hand basins while 56% have refuse bins. For senior secondary

schools, 6% have school clinics, 78% have First Aid Boxes, 62% have wash hand basins while 59% have refuse bins.

7. WATER SUPPLY AND SANITATION

37% of primary schools have potable water source within their premises. The corresponding figures for junior secondary schools and senior secondary schools are 42% and 52% respectively.

Table 17 shows that 37% of primary schools have access to functional sanitary means of excreta disposal. The figures for junior secondary schools and senior secondary schools are 66% and 65% respectively (Table 18).

As regards solid waste disposal, majority of schools make use of dumpsites while few make use of incinerators.

8. ELECTRIC POWER SUPPLY

10% of primary schools are connected to Power Holding Company of Nigeria (PHCN), 5% make use of generating sets, 4% use both, 1% use solar and 80% have no source of power supply (Table 19). 45% of public junior secondary schools have access to PHCN, 12% make use of generating sets, 20% use both, 2% have solar while 21% have none. The table further reveals 42% of public senior secondary schools have access to PHCN, 15% make use of generating sets, 24% use both, 2% use solar while 16% have no source of power supply.

9. RECREATIONAL FACILITIES

Table 21 shows that 88% of primary schools have playgrounds, 3% have school halls, 1% have table tennis facilities and 18% enjoy the services of food vendors or canteens. 98% of public junior secondary schools have playgrounds, 51% have school halls, 6 % have table tennis facilities while 49% have access to food vendors or canteens and 3% have swimming pool. The corresponding information for senior secondary schools are: 95% have playgrounds, 66% have school halls, 9% have table tennis facilities while 51% have access to food vendors (canteens) and 1% school have swimming pool (Table 22).

10. LIBRARIES AND LABORATORIES

Table 23 shows that 48% of junior secondary schools and 68% of senior secondary schools have libraries. The table also shows that 42% of junior secondary schools have at least a (subject) laboratory. The figures for senior secondary schools show that 74% of the schools have at least a (subject) laboratory.

Table 23 reveals that 3% of laboratories in junior secondary schools were rated as well equipped, 54% fairly equipped, 43% not equipped. The table also reveals for senior secondary schools as follows: well equipped 6%, fairly

equipped 66% and not equipped 28% (Rating was done by the respective school authorities).

11. INFORMATION TECHNOLOGY

18 % of primary schools, 78% of junior secondary schools and 70% of senior schools have Computers (Tables 25 & 26).

12. TEACHING AID

Tables 27 and 28 reveal that the major teaching aid in primary and secondary schools is chalk board.

13. CLASSROOM ACCOMMODATION

Table 29 shows a ratio of 52 pupils to a classroom on the average in primary schools. Table 30 shows a ratio of 59 and 49 students to a classroom in junior secondary schools and senior secondary schools respectively.

14. CLASSROOM FURNITURE

Table 31 shows that only 58% of primary school pupils have seats while 59% have desks. The table also shows that only 61% of junior secondary school students and 65% of senior secondary school students have seats and desks.

15. HOSTEL FACILITY

Table 33 reveals that about 94% of junior secondary schools operate day system only, 4% operate both boarding and day system while 2% operate boarding only. For senior secondary schools, about 94% operate day system



only, 5% operate both boarding and day system while less than 2% operate boarding only.

16. DISTRIBUTION OF SCHOOLS BY CO-EDUCATIONAL/SINGLE SYSTEM

94% of secondary schools are co-educational, 3% male only and 3% female only (both junior and senior secondary schools)-Table34. All public primary schools are co-educational.

17. CONDITION OF CLASSROOMS

Tables 35 and 36 show the number of roofs, walls, floors and windows indicating those in bad condition.

18. SHORTFALLS IN INFRASTRUCTURAL FACILITIES

(i).CLASSROOMS: Using the UNESCO recommended Teacher Student Ratio

(TSR) of 1:28 and by extension classroom/student ratio, the report estimated shortfall in classrooms as follows: -

- Shortfall of 7,494 classrooms in Primary schools
- Shortfall of 2,534 classrooms in Junior Secondary Schools
- Shortfall of 1,757 classrooms in Senior Secondary Schools

**Note:**

Calculations based on functional classrooms at the time of the survey. (Functional Classrooms represent about 75% of total classrooms in the schools.)

(ii). PRINCIPALS'/ HEADMASTERS' OFFICES

- Shortfall of 90 Principals' office in Junior Secondary Schools
- Shortfall of 37 Principals' office in Senior Secondary Schools
- Shortfall of 204 Headmasters' office

(iii). STAFF ROOMS

- Shortfall of 143 Staff Rooms in Junior Secondary Schools
- Shortfall of 108 Staff Rooms in Senior Secondary Schools

(iv) WASH HAND BASINS

- Shortfall of 353 Wash hand basins in Primary Schools
- Shortfall of 118 Wash hand basins in Junior Secondary Schools
- Shortfall of 114 Wash hand basins in Senior Secondary Schools

(v) POTABLE WATER SOURCES

- Shortfall of 738 potable water sources in Primary Schools
- Shortfall of 174 potable water sources in Junior Secondary Schools
- Shortfall of 142 potable water sources in Senior Secondary Schools

(vi) VENTILATED IMPROVED PIT (VIP)/TRADITIONAL PIT LATERINES/WATER CLOSETS

- Shortfall of 482 Toilets in Primary Schools
- Shortfall of 103 Toilets in Junior Secondary Schools
- Shortfall of 104 Toilets in Senior Secondary Schools

(vii) LIBRARIES

- Shortfall of 155 Libraries in Junior Secondary Schools
- Shortfall of 94 Libraries in Senior Secondary Schools

(viii) FIRST AID BOXES

- Shortfall of 160 First Aid Boxes in Primary Schools
- Shortfall of 72 First Aid Boxes in Junior Secondary Schools
- Shortfall of 65 First Aid Boxes in Senior Secondary Schools

(ix) DESKS

- Shortfall of 190,177 Desks in Primary Schools
- Shortfall of 52,553 Desks in Junior Secondary Schools
- Shortfall of 41,254 Desks in Senior Secondary Schools

(x) SEATS

- Shortfall of 192,310 Seats in Primary Schools
- Shortfall of 52,613 Seats in Junior Secondary Schools
- Shortfall of 41,339 Seats in Senior Secondary Schools

It also reveals that the following are in state of disrepair and needed urgent rehabilitation.

- 15,562 Classroom walls in Primary Schools
- 4,454 Classroom walls in Junior Secondary Schools
- 4,682 Classroom walls in Senior Secondary Schools
  
- 4,491 Classroom Floors in Primary Schools
- 1,465 Classroom Floors in Junior Secondary Schools
- 1,290 Classroom Floors in Senior Secondary Schools
  
- 19,711 Classroom Windows in Primary Schools
- 5,860 Classroom Windows in Junior Secondary Schools
- 7,020 Classroom Windows in Senior Secondary Schools
  
- 3,968 Classroom Roofs in primary schools
- 944 Classroom Roofs in junior secondary schools
- 1,125 Classroom Roofs in senior secondary schools

It was observed that some schools did not have buildings of their own and are using rented apartments or make shift facilities and worship centers. The affected schools are:

- (1) L.A. Primary School, Kudola- Ondo West LGA
- (2) Motailatu Primary School, Italurowo- Ondo West LGA
- (3) Baptist Day Primary School, Ira, Ilu-titun- Okitipupa LGA
- (4) Community Primary School, Temitope- Odigbo LGA
- (5) L.A. Primary School, Moboro-Aye- Okitipupa LGA

## 2.2 RECOMMENDATIONS

1. Renovation of the identified structures that are in a state of disrepair
2. Provision of the identified shortfalls in infrastructural facilities.
3. Permanent sites for schools that are using rented apartments, worship centers and make shift facilities.
4. Perimeter fencing of all public primary and secondary schools in the state.

TABLE 1

## SUMMARY OF SCHOOLS, CLASSROOMS, ENROLMENT AND TEACHERS IN PUBLIC PRIMARY &amp; SECONDARY SCHOOLS IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	NO. OF SCHOOLS			NO OF FUNCTIONAL CLASSROOMS			NO OF STUDENTS (2008/2009)									NO OF TEACHERS							
		PRY	SEC		PRY	SEC		PRY			JSS			SSS			PRY			JSS			SSS	
			JSS	SSS		JSS	SSS	M	F	Total	M	F	Total	M	F	Total	M	F	Total	M	F	Total	M	F
1	AKOKO N/E	40	16	16	407	102	153	7733	8079	15812	3594	3535	7129	3169	2860	6029	214	593	807	133	168	301	220	126
2	AKOKO N/W	56	20	20	516	149	141	17336	18013	35349	2944	2705	5649	3123	3043	6166	275	509	784	133	125	258	218	76
3	AKOKO S/E	23	8	8	261	50	55	4926	5103	10029	1234	1022	2256	948	1012	1960	130	192	322	66	34	100	104	34
4	AKOKO S/W	51	17	17	477	134	148	12361	12626	24987	4030	3841	7871	3485	3213	6698	370	518	888	173	169	342	258	97
5	AKURE NORTH	48	8	6	377	68	70	6029	5993	12022	1761	1595	3356	1274	1115	2389	178	536	714	84	152	236	127	92
6	AKURE SOUTH	72	28	28	841	397	343	16061	16199	32260	11221	11227	22448	8551	8794	17345	122	1251	1373	184	932	1116	364	704
7	ESE-ODO	62	13	13	399	71	58	11804	10374	22178	2730	2249	4979	2585	1604	4189	274	194	468	95	37	132	133	17
8	IDANRE	71	10	10	464	94	80	9549	9546	19095	2651	2377	5028	2113	1573	3686	201	342	543	109	107	216	155	87
9	IFEDORE	46	11	10	386	85	67	5710	5790	11500	1746	1557	3303	1305	1318	2623	170	374	544	99	122	221	125	84
10	ILAJE	94	21	21	617	109	132	34216	33706	67922	6273	4921	11194	5627	4031	9658	455	440	895	114	34	148	164	26
11	ILE-OLUJI/OKE-IGBO	78	23	23	556	120	157	10679	11292	21971	3281	3263	6544	3388	3314	6702	268	484	752	187	110	297	289	94
12	IRELE	60	10	10	376	64	64	13323	13387	26710	2262	1964	4226	1752	1626	3378	278	239	517	71	45	116	98	25
13	ODIGBO	99	18	18	571	113	117	16988	17239	34227	4633	4404	9037	4682	4244	8926	493	710	1203	137	108	245	256	94
14	OKITIPUPA	87	23	23	614	167	204	14726	16627	31353	5351	5391	10742	5356	5003	<b>10359</b>	322	655	977	210	190	400	337	149
15	ONDO EAST	46	12	12	358	58	76	5156	5590	10746	1616	1506	3122	1770	1652	3422	238	358	596	71	104	175	115	78
16	ONDO WEST	96	32	32	661	293	295	19517	20539	40056	7514	8136	15650	6689	6197	<b>12886</b>	341	1178	1519	254	517	771	432	417
17	OSE	54	12	12	378	65	84	8158	11355	19513	2531	2207	4738	1969	1766	3735	293	335	628	109	65	174	254	342
18	OWO	81	18	18	658	198	144	12071	11720	23791	4765	4166	8931	3672	3378	7050	289	809	1098	183	244	427	288	171
	<b>TOTAL</b>	<b>1164</b>	<b>300</b>	<b>297</b>	<b>8917</b>	<b>2337</b>	<b>2388</b>	<b>226343</b>	<b>233178</b>	<b>459521</b>	<b>70137</b>	<b>66066</b>	<b>136203</b>	<b>61458</b>	<b>55743</b>	<b>117201</b>	<b>4911</b>	<b>9717</b>	<b>14628</b>	<b>2412</b>	<b>3263</b>	<b>5675</b>	<b>3937</b>	<b>2713</b>

TABLE 2

## DISTRIBUTION OF PUBLIC PRIMARY SCHOOLS BY PERIOD OF ESTABLISHMENT

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	PERIOD OF ESTABLISHMENT					
			BEFORE 1960	1960-1969	1970-1979	1980-1989	1990-1999	2000-2009
1	AKOKO N/E	40	27	1	4	3	4	1
2	AKOKO N/W	56	41	0	9	4	0	2
3	AKOKO S/E	23	20	0	1	0	1	1
4	AKOKO S/W	51	35	1	8	4	3	0
5	AKURE NORTH	48	23	1	11	7	4	2
6	AKURE SOUTH	72	33	1	17	15	5	1
7	ESE-ODO	62	32	1	17	5	2	5
8	IDANRE	71	26	10	10	8	9	8
9	IFEDORE	46	26	0	9	3	5	3
10	ILAJE	94	56	1	14	12	8	3
11	ILE-OLUJI/OKE-IGBO	78	29	4	29	12	2	2
12	IRELE	60	39	1	12	1	6	1
13	ODIGBO	99	40	0	31	14	11	3
14	OKITIPUPA	87	62	0	21	4	0	0
15	ONDO EAST	46	37	1	5	3	0	0
16	ONDO WEST	96	65	16	9	2	4	0
17	OSE	54	28	0	18	2	5	1
18	OWO	81	44	0	20	13	4	0
	<b>TOTAL</b>	<b>1164</b>	<b>663</b>	<b>38</b>	<b>245</b>	<b>112</b>	<b>73</b>	<b>33</b>
	%		57	3	21	10	6	3

TABLE 3

## DISTRIBUTION OF PUBLIC SECONDARY SCHOOLS BY PERIOD OF ESTABLISHMENT

S/N	LOCAL GOVERNMENT AREA	JUNIOR SECONDARY SCHOOL							SENIOR SECONDARY SCHOOL						
		PERIOD OF ESTABLISHMENT							PERIOD OF ESTABLISHMENT						
		BEFORE 1960	1960-1969	1970-1979	1980 - 1989	1990 -1999	2000-2009	TOTAL	BEFORE 1961	1960-1970	1970-1980	1981 - 1989	1991 -1999	2000-2010	TOTAL
1	AKOKO N/E	1	2	8	1	0	4	16	1	2	7	5	0	1	16
2	AKOKO N/W	0	1	10	7	2	0	20	0	1	10	6	1	2	20
3	AKOKO S/E	0	0	3	3	0	2	8	0	0	5	2	0	1	8
4	AKOKO S/W	2	0	6	7	0	2	17	2	0	7	6	1	1	17
5	AKURE NORTH	1	0	4	1	0	2	8	1	0	4	1	0	0	6
6	AKURE SOUTH	3	4	3	10	1	7	28	2	4	5	15	0	2	28
7	ESE-ODO	0	0	4	6	0	3	13	0	0	4	6	0	3	13
8	IDANRE	1	0	3	5	0	1	10	1	0	3	6	0	0	10
9	IFEDORE	1	0	4	4	0	2	11	1	0	5	4	0	0	10
10	ILAJE	0	0	6	9	2	4	21	0	0	6	9	2	4	21
11	ILE-OLUJI/OKE-IGBO	2	3	4	7	1	6	23	2	3	4	7	1	6	23
12	IRELE	0	1	2	4	0	3	10	1	0	2	6	0	1	10
13	ODIGBO	0	0	3	10	0	5	18	0	0	3	13	0	2	18
14	OKITIPUPA	4	0	8	4	0	7	23	3	0	13	7	0	0	23
15	ONDO EAST	4	2	2	2	1	1	12	4	2	2	2	1	1	12
16	ONDO WEST	5	2	4	14	1	6	32	5	1	5	18	1	2	32
17	OSE	0	2	6	4	0	0	12	0	2	6	4	0	0	12
18	OWO	2	4	5	5	1	1	18	2	5	5	5	0	1	18
	<b>TOTAL</b>	26	21	85	103	9	56	300	25	20	96	122	7	27	297
	%	9	7	28	34	3	19		8	7	32	41	2	9	

TABLE 4

## LAND AREA SERVED BY A SCHOOL (IN SQUARE KILOMETERS)

S/N	LOCAL GOVERNMENT AREA	AREA(SQKM)	NO OF PRY SCHOOLS	SQKM/PRY SCH	NO OF JSS	SQKM / JSS	NO OF SSS	SQKM / SSS	AVERAGE WALKING RADIUS TO SCHOOL (SQKM)
1	AKOKO N/E	398.8	40	10	16	25	16	25	11.3
2	AKOKO N/W	489.6	56	9	20	24	20	24	12.5
3	AKOKO S/E	462.0	23	20	8	58	8	58	12.1
4	AKOKO S/W	340.1	51	7	17	20	17	20	10.4
5	AKURE NORTH	676.7	48	14	8	85	6	113	14.7
6	AKURE SOUTH	318.0	72	4	28	11	28	11	10.1
7	ESE-ODO	1406.8	62	23	13	108	13	108	21.2
8	IDANRE	1543.4	71	22	10	154	10	154	22.2
9	IFEDORE	583.0	46	13	11	53	10	58	13.6
10	ILAJE	708.3	94	8	21	34	21	34	15.0
11	ILE-OLUJI/OKE-IGBO	824.1	78	11	23	36	23	36	16.2
12	IRELE	939.6	60	16	10	94	10	94	17.3
13	ODIGBO	1710.0	99	17	18	95	18	95	23.3
14	OKITIPUPA	650.0	87	7	23	28	23	28	14.4
15	ONDO EAST	360.0	46	8	12	30	12	30	10.7
16	ONDO WEST	950.8	96	10	32	30	32	30	17.4
17	OSE	1443.8	54	27	12	120	12	120	21.4
18	OWO	993.8	81	12	18	55	18	55	17.8
	<b>TOTAL</b>	<b>14798.8</b>	<b>1164</b>	<b>13</b>	<b>300</b>	<b>49</b>	<b>297</b>	<b>50</b>	<b>281.5</b>



TABLE 5

## DISTRIBUTION OF CLASSROOMS IN PUBLIC PRIMARY SCHOOLS BY PERIOD OF CONSTRUCTION IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	PERIOD OF CONSTRUCTION						TOTAL
		BEFORE 1960	1960-1969	1970-1979	1980-1989	1990-1999	2000-2009	
1	AKOKO N/E	112	48	77	50	81	159	527
2	AKOKO N/W	139	52	88	93	77	270	719
3	AKOKO S/E	35	5	32	19	24	113	228
4	AKOKO S/W	136	58	99	85	63	206	647
5	AKURE NORTH	43	8	97	52	66	170	436
6	AKURE SOUTH	146	45	172	193	155	410	1121
7	ESE-ODO	51	18	23	56	124	255	527
8	IDANRE	132	81	93	47	70	124	547
9	IFEDORE	89	20	75	85	63	183	515
10	ILAJE	36	43	88	118	210	390	885
11	ILE-OLUJI/OKE-IGBO	87	45	147	100	40	348	767
12	IRELE	65	25	91	49	67	182	479
13	ODIGBO	118	36	137	153	127	240	811
14	OKITIPUPA	245	50	194	112	103	298	1002
15	ONDO EAST	113	40	41	15	50	85	344
16	ONDO WEST	277	63	205	151	138	256	1090
17	OSE	71	46	116	40	86	182	541
18	OWO	81	170	33	184	91	102	661
	TOTAL	1976	853	1808	1602	1635	3973	11847
	% of Total	17	7	15	14	14	34	

Note: These include non-functional classrooms

TABLE 6

## DISTRIBUTION OF CLASSROOMS IN PUBLIC SECONDARY SCHOOLS BY PERIOD OF CONSTRUCTION

S/N	LOCAL GOVERNMENT AREA	JUNIOR SECONDARY SCHOOL							SENIOR SECONDARY SCHOOL						
		PERIOD OF CONSTRUCTION							PERIOD OF CONSTRUCTION						
		BEFORE 1960	1960-1969	1970-1979	1980 - 1989	1990 -1999	2000-2009	TOTAL	BEFORE 1961	1960-1970	1970-1980	1981 - 1989	1991 -1999	2000-2010	TOTAL
1	AKOKO N/E	4	28	17	29	20	19	117	16	16	41	54	4	8	139
2	AKOKO N/W	0	14	49	38	14	96	211	1	10	43	78	4	26	162
3	AKOKO S/E	0	0	35	6	18	16	75	0	18	18	28	10	4	78
4	AKOKO S/W	0	14	36	53	15	38	156	7	21	24	77	13	24	166
5	AKURE NORTH	5	12	20	18	25	16	96	6	0	32	18	14	6	76
6	AKURE SOUTH	11	57	75	100	64	80	387	12	78	30	93	95	25	333
7	ESE-ODO	0	6	10	27	3	39	85	0	5	11	40	6	23	85
8	IDANRE	1	1	34	21	24	13	94	10	0	19	43	8	0	80
9	IFEDORE	0	16	36	15	9	16	92	1	3	29	30	21	9	93
10	ILAJE	0	9	28	35	16	55	143	4	0	19	35	10	80	148
11	ILE-OLUJI/OKE-IGBO	10	13	17	71	23	36	170	8	16	31	83	23	26	187
12	IRELE	0	0	9	26	9	28	72	0	4	16	37	3	9	69
13	ODIGBO	0	12	18	56	21	31	138	0	6	31	71	16	28	152
14	OKITIPUPA	23	22	24	39	14	32	154	21	7	52	110	36	18	244
15	ONDO EAST	1	10	14	16	12	13	66	9	12	13	17	18	13	82
16	ONDO WEST	45	74	79	54	67	23	342	44	75	79	54	67	24	343
17	OSE	0	28	29	33	6	18	114	0	14	68	27	6	6	121
18	OWO	5	46	44	40	32	32	199	7	24	65	57	25	17	195
	<b>TOTAL</b>	105	362	574	677	392	601	2711	146	309	621	952	379	346	2753
	% of Total	4	13	21	25	14	22		5	11	23	35	14	13	

Note: These include non-functional classrooms

TABLE 7  
DISTRIBUTION OF CLASSROOMS IN PUBLIC PRIMARY SCHOOLS BY PROVIDING AGENCY IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	PROVIDING AGENCY					
			FEDERAL GOVT	STATE GOVT	LOCAL GOVT	COMMUNITY	MISSIONARY	OTHER
1	AKOKO N/E	40	42	231	60	172	12	10
2	AKOKO N/W	56	49	264	27	280	0	99
3	AKOKO S/E	23	12	125	16	64	0	11
4	AKOKO S/W	51	51	270	59	215	37	15
5	AKURE NORTH	48	40	218	46	93	0	39
6	AKURE SOUTH	72	88	695	89	165	0	84
7	ESE-ODO	62	42	228	123	70	0	64
8	IDANRE	71	57	335	44	93	0	18
9	IFEDORE	46	75	207	65	151	0	17
10	ILAJE	94	160	287	96	121	0	221
11	ILE-OLUJI/OKE-IGBO	78	71	347	71	258	0	20
12	IRELE	60	49	244	54	111	0	21
13	ODIGBO	99	197	138	113	83	51	229
14	OKITIPUPA	87	534	111	181	101	0	75
15	ONDO EAST	46	43	109	42	84	0	66
16	ONDO WEST	96	99	395	133	362	2	99
17	OSE	54	41	276	63	127	0	34
18	OWO	81	72	356	50	134	0	49
	<b>TOTAL</b>	<b>1164</b>	1722	4836	1332	2684	102	1171

TABLE 8

## DISTRIBUTION OF CLASSROOMS IN PUBLIC SECONDARY SCHOOLS BY PROVIDING AGENCY IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	PROVIDING AGENCY													
		FEDERAL GOVT		STATE GOVT		LOCAL GOVT		COMMUNITY		MISSIONARY		OTHER		TOTAL	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	1	2	65	49	0	9	51	65	0	0	0	14	117	139
2	AKOKO N/W	0	6	80	59	0	0	131	94	0	0	0	3	211	162
3	AKOKO S/E	8	0	26	31	0	0	41	40	0	0	0	7	75	78
4	AKOKO S/W	9	2	30	54	0	0	90	97	14	13	13	0	156	166
5	AKURE NORTH	4	12	34	36	9	0	45	28	0	0	4	0	96	76
6	AKURE SOUTH	67	22	148	172	0	0	125	76	13	16	34	47	387	333
7	ESE-ODO	2	3	10	8	17	7	40	53	0	0	16	14	85	85
8	IDANRE	8	0	23	16	2	0	61	64	0	0	0	0	94	80
9	IFEDORE	12	4	28	40	0	7	52	42	0	0	0	0	92	93
10	ILAJE	11	3	73	53	12	4	6	45	0	0	41	43	143	148
11	ILE-OLUJI/OKE-IGBO	0	4	43	46	5	5	92	94	0	0	30	38	170	187
12	IRELE	0	0	36	41	0	0	36	24	0	0	0	4	72	69
13	ODIGBO	0	2	42	28	0	0	96	118	0	0	0	4	138	152
14	OKITIPUPA	9	11	31	83	40	0	67	131	0	4	7	15	154	244
15	ONDO EAST	1	7	25	21	4	14	34	30	0	3	2	7	66	82
16	ONDO WEST	42	45	136	160	13	11	100	79	45	43	6	5	342	343
17	OSE	20	6	52	55	0	0	36	56	0	0	6	4	114	121
18	OWO	6	1	116	99	0	4	74	70	0	17	3	4	199	195
		200	130	998	1051	102	61	1177	1206	72	96	162	209	2711	2753

TABLE 9

## AVAILABILITY OF OFFICE ACCOMODATION IN PUBLIC PRIMARY SCHOOLS IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	NO OF SCHOOLS	
			WITH HEAD TEACHERS'S OFFICE	WITHOUT HEAD TEACHERS'S OFFICE
1	AKOKO N/E	40	34	6
2	AKOKO N/W	56	54	2
3	AKOKO S/E	23	20	3
4	AKOKO S/W	51	45	6
5	AKURE NORTH	48	42	6
6	AKURE SOUTH	72	66	6
7	ESE-ODO	62	47	15
8	IDANRE	71	71	0
9	IFEDORE	46	46	0
10	ILAJE	94	44	50
11	ILE-OLUJI/OKE-IGBO	78	62	16
12	IRELE	60	46	14
13	ODIGBO	99	72	27
14	OKITIPUPA	87	65	22
15	ONDO EAST	46	42	4
16	ONDO WEST	96	96	0
17	OSE	54	37	17
18	OWO	81	71	10
	<b>TOTAL</b>	<b>1164</b>	<b>960</b>	<b>204</b>
	%		82	18

TABLE 10

## AVAILABILITY OF OFFICE ACCOMODATION IN PUBLIC SECONDARY SCHOOLS IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS		NO OF SCHOOLS							
				WITH PRINCIPAL'S OFFICE		WITHOUT PRINCIPAL'S OFFICE		WITH STAFF ROOM		WITHOUT STAFF ROOM	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	13	15	3	1	7	11	9	5
2	AKOKO N/W	20	20	15	19	5	1	12	15	8	5
3	AKOKO S/E	8	8	5	7	3	1	4	5	4	3
4	AKOKO S/W	17	17	13	17	4	0	11	14	6	3
5	AKURE NORTH	8	6	8	5	0	1	5	6	3	0
6	AKURE SOUTH	28	28	26	25	2	3	16	19	12	9
7	ESE-ODO	13	13	9	9	4	4	6	6	7	7
8	IDANRE	10	10	10	10	0	0	8	6	2	4
9	IFEDORE	11	10	9	10	2	0	5	7	6	3
10	ILAJE	21	21	10	16	11	5	9	9	12	12
11	ILE-OLUJI/OKE-IGBO	23	23	11	19	12	4	12	17	11	6
12	IRELE	10	10	4	7	6	3	3	6	7	4
13	ODIGBO	18	18	11	18	7	0	8	9	10	9
14	OKITIPUPA	23	23	13	20	10	3	9	14	14	9
15	ONDO EAST	12	12	8	9	4	3	5	4	7	8
16	ONDO WEST	32	32	22	30	10	2	20	25	12	7
17	OSE	12	12	8	11	4	1	7	6	5	6
18	OWO	18	18	15	13	3	5	10	10	8	8
	<b>TOTAL</b>	<b>300</b>	<b>297</b>	<b>210</b>	<b>260</b>	<b>90</b>	<b>37</b>	<b>157</b>	<b>189</b>	<b>143</b>	<b>108</b>
	%			70	87	30	12	52	64	48	36

TABLE 11

## BUILDING FACILITIES BY TYPE OF MATERIALS IN PUBLIC PRIMARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	BUILDING MATERIALS			
			MUD ONLY	CEMENT/BURNT BRICKS ONLY	BOTH	OTHERS
1	AKOKO N/E	40	8	15	17	-
2	AKOKO N/W	56	6	31	19	-
3	AKOKO/S/E	23	2	12	9	0
4	AKOKO S/W	51	13	20	18	0
5	AKURE/N	48	10	31	7	-
6	AKURE/S	72	3	54	13	2
7	ESE-ODO	62	2	30	24	6
8	IDANRE	71	19	38	14	-
9	IFEDORE	46	2	19	25	-
10	ILAJE	94	1	46	25	22
11	ILE-OLUJI/OKE-IGBO	78	20	38	20	-
12	IRELE	60	15	26	19	-
13	ODIGBO	99	50	33	16	-
14	OKITIPUPA	87	14	49	24	-
15	ONDO/E	46	16	20	10	-
16	ONDO/W	96	40	30	26	-
17	OSE	54	5	39	10	-
18	OWO	81	10	56	14	1
	TOTAL	1164	236	587	310	31
	(%) of Total		20	50	27	3

Table 12

## BUILDING FACILITIES BY TYPE OF MATERIALS IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS		BUILDING MATERIALS							
				MUD ONLY		CEMENT/BURNT BRICKS ONLY		BOTH		OTHERS	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	1	1	13	14	2	1	0	0
2	AKOKO N/W	20	20	0	1	12	15	8	4	0	0
3	AKOKO S/E	8	8	2	1	6	7	0	0	0	0
4	AKOKO S/W	17	17	4	4	8	10	5	3	0	0
5	AKURE NORTH	8	6	0	0	8	5	0	1	0	0
6	AKURE SOUTH	28	28	0	0	23	24	5	4	0	0
7	ESE-ODO	13	13	2	2	7	7	2	3	2	1
8	IDANRE	10	10	1	2	8	8	1	0	0	0
9	IFEDORE	11	10	1	1	5	4	5	5	0	0
10	ILAJE	21	21	1	0	16	15	2	3	2	3
11	ILE-OLUJI/OKE-IGBO	23	23	6	4	10	7	7	12	0	0
12	IRELE	10	10	3	2	5	6	2	2	0	0
13	ODIGBO	18	18	6	4	9	9	3	5	0	0
14	OKITIPUPA	23	23	7	4	10	15	6	4	0	0
15	ONDO EAST	12	12	4	1	8	5	0	6	0	0
16	ONDO WEST	32	32	3	3	17	27	12	2	0	0
17	OSE	12	12	0	0	9	9	3	3	0	0
18	OWO	18	18	0	0	14	11	4	7	0	0
	<b>TOTAL</b>	<b>300</b>	<b>297</b>	<b>41</b>	<b>30</b>	<b>188</b>	<b>198</b>	<b>67</b>	<b>65</b>	<b>4</b>	<b>4</b>
	%			14	10	63	67	22	22	1	1



TABLE 13

## AVAILABILITY OF HEALTH FACILITIES IN PUBLIC PRIMARY SCHOOLS IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	NO OF SCHOOLS WITH:			
			SCHOOL CLINIC	FIRST AID BOX	WASH HAND BASINS	REFUSE BINS
1	AKOKO N/E	40	1	39	21	14
2	AKOKO N/W	56	0	49	41	15
3	AKOKO S/E	23	0	21	18	6
4	AKOKO S/W	51	0	49	39	15
5	AKURE NORTH	48	0	46	40	24
6	AKURE SOUTH	72	1	67	54	48
7	ESE-ODO	62	0	46	43	14
8	IDANRE	71	0	63	43	31
9	IFEDORE	46	0	46	37	20
10	ILAJE	94	0	56	75	25
11	ILE-OLUJI/OKE-IGBO	78	0	72	63	43
12	IRELE	60	1	42	35	11
13	ODIGBO	99	0	86	65	36
14	OKITIPUPA	87	0	76	48	28
15	ONDO EAST	46	0	40	37	16
16	ONDO WEST	96	0	85	68	43
17	OSE	54	0	45	30	11
18	OWO	81	0	76	54	30
	<b>TOTAL</b>	<b>1164</b>	<b>3</b>	<b>1004</b>	<b>811</b>	<b>430</b>
	% of Total		0	86	70	37

Table 14

## HEALTH FACILITIES IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS		NUMBER OF SCHOOLS WITH:							
				SCHOOL CLINIC		FIRST AID BOX		WASH HAND BASINS		REFUSE BINS	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	0	1	12	11	10	9	11	9
2	AKOKO N/W	20	20	0	0	19	19	9	15	7	18
3	AKOKO S/E	8	8	1	1	6	6	6	4	5	2
4	AKOKO S/W	17	17	0	0	1	6	13	14	12	14
5	AKURE NORTH	8	6	0	8	6	4	3	1	8	2
6	AKURE SOUTH	28	28	5	5	24	23	13	15	22	25
7	ESE-ODO	13	13	0	0	10	12	8	9	4	8
8	IDANRE	10	10	0	0	10	9	6	4	6	5
9	IFEDORE	11	10	0	0	9	10	6	6	8	9
10	ILAJE	21	21	0	0	15	16	16	20	13	12
11	ILE-OLUJI/OKE-IGBO	23	23	0	0	17	19	13	17	15	13
12	IRELE	10	10	0	0	9	9	8	8	4	6
13	ODIGBO	18	18	0	0	13	18	11	12	4	7
14	OKITIPUPA	23	23	0	1	18	19	13	10	4	7
15	ONDO EAST	12	12	0	0	12	7	11	5	9	4
16	ONDO WEST	32	32	0	1	23	23	17	19	17	18
17	OSE	12	12	0	0	8	6	6	5	6	6
18	OWO	18	18	1	1	16	15	13	10	14	10
	TOTAL	300	297	7	18	228	232	182	183	169	175
	% of Total			2	6	76	78	61	62	56	59

TABLE 15

## ACCESS TO POTABLE WATER IN PUBLIC PRIMARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	NO OF SCHOOLS	
			WITH POTABLE WATER SUPPLY	WITHOUT POTABLE WATER SUPPLY
1	AKOKO N/E	40	14	26
2	AKOKO N/W	56	29	27
3	AKOKO S/E	23	6	17
4	AKOKO S/W	51	17	34
5	AKURE NORTH	48	16	32
6	AKURE SOUTH	72	33	39
7	ESE-ODO	62	20	42
8	IDANRE	71	19	52
9	IFEDORE	46	19	27
10	ILAJE	94	25	69
11	ILE-OLUJI/OKE-IGBO	78	23	55
12	IRELE	60	27	33
13	ODIGBO	99	30	69
14	OKITIPUPA	87	37	50
15	ONDO EAST	46	16	30
16	ONDO WEST	96	51	45
17	OSE	54	19	35
18	OWO	81	25	56
	<b>TOTAL</b>	<b>1164</b>	<b>426</b>	<b>738</b>
	%		37	63

TABLE 16

## ACCESS TO POTABLE WATER SUPPLY IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS		NUMBER OF SCHOOLS:			
				WITH POTABLE WATER		WITHOUT POTABLE WATER	
		JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	4	7	12	9
2	AKOKO N/W	20	20	8	14	12	6
3	AKOKO S/E	8	8	3	5	5	3
4	AKOKO S/W	17	17	6	8	11	9
5	AKURE NORTH	8	6	3	0	5	6
6	AKURE SOUTH	28	28	17	14	11	14
7	ESE-ODO	13	13	4	3	9	10
8	IDANRE	10	10	6	7	4	3
9	IFEDORE	11	10	5	8	6	2
10	ILAJE	21	21	7	9	14	12
11	ILE-OLUJI/OKE-IGBO	23	23	12	11	11	12
12	IRELE	10	10	4	3	6	7
13	ODIGBO	18	18	7	8	11	10
14	OKITIPUPA	23	23	12	15	11	8
15	ONDO EAST	12	12	5	7	7	5
16	ONDO WEST	32	32	10	22	22	10
17	OSE	12	12	2	3	10	9
18	OWO	18	18	11	11	7	7
	TOTAL	300	297	126	155	174	142
	%			42	52	58	48

TABLE 17

## SANITATION FACILITIES IN PUBLIC PRIMARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	NO OF SCHOOLS		SOLID WASTE DISPOSAL: NO OF SCHOOLS USING:		
			WITH SANITARY MEANS OF EXCRETA DISPOSAL(WC) SANPLAT/VIP/TPL	WITHOUT SANITARY MEANS OF EXCRETA DISPOSAL(WC) SANPLAT/VIP/TPL	WASTE VAN	INCINERATOR	DUMP SITE
1	AKOKO N/E	40	14	26	1	10	29
2	AKOKO N/W	56	29	27	0	15	36
3	AKOKO S/E	23	6	17	0	5	19
4	AKOKO S/W	51	17	34	1	13	37
5	AKURE NORTH	48	16	32	1	9	35
6	AKURE SOUTH	72	33	39	0	40	44
7	ESE-ODO	62	20	42	6	20	35
8	IDANRE	71	19	52	0	13	41
9	IFEDORE	46	19	27	0	10	33
10	ILAJE	94	25	69	0	8	39
11	ILE-OLUJI/OKE-IGBO	78	23	55	0	19	53
12	IRELE	60	27	33	0	12	34
13	ODIGBO	99	30	69	0	18	63
14	OKITIPUPA	87	37	50	0	25	63
15	ONDO EAST	46	16	30	9	10	30
16	ONDO WEST	96	51	45	1	18	75
17	OSE	54	19	35	0	13	41
18	OWO	81	25	56	2	15	62
	<b>TOTAL</b>	<b>1164</b>	<b>426</b>	<b>738</b>	<b>21</b>	<b>273</b>	<b>769</b>
	%		37	63	2	23	66

TABLE 18

## SANITATION FACILITIES IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS		NO OF SCHOOLS WITH		NO OF SCHOOLS WITHOUT:		SOLID WASTE DISPOSAL: NO OF SCHOOLS USING					
				SANITARY MEANS OF EXCRETA DISPOSAL (WC) /SANPLAT /VIP/TPL		SANITARY MEANS OF EXCRETA DISPOSAL		WASTE VAN		INCINERATOR		DUMPSITE	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	10	9	6	7	1	0	5	5	10	11
2	AKOKO N/W	20	20	11	10	9	10	0	0	6	7	14	13
3	AKOKO/S/E	8	8	5	5	3	3	0	0	2	4	6	4
4	AKOKO S/W	17	17	10	11	7	6	0	0	5	7	12	10
5	AKURE/N	8	6	6	0	2	6	0	0	2	3	6	3
6	AKURE/S	28	28	21	21	7	7	0	0	13	10	14	18
7	ESE-ODO	13	13	5	5	8	8	0	0	4	3	9	10
8	IDANRE	10	10	7	4	3	6	0	0	2	3	5	6
9	IFEDORE	11	10	9	8	2	2	0	0	4	2	4	2
10	ILAJE	21	21	12	13	9	8	0	0	4	6	17	16
11	ILE-OLUJI/OKE-IGBO	23	23	15	17	8	6	0	0	6	6	10	13
12	IRELE	10	10	10	10	0	0	0	0	0	2	10	8
13	ODIGBO	18	18	8	11	10	7	0	1	6	8	7	9
14	OKITIPUPA	23	23	18	22	5	1	0	0	12	10	7	13
15	ONDO/E	12	12	7	7	5	5	0	0	3	2	8	9
16	ONDO/W	32	32	20	20	12	12	0	0	8	4	26	29
17	OSE	12	12	7	8	5	4	0	0	6	3	6	9
18	OWO	18	18	16	12	2	6	0	0	9	8	9	9
	TOTAL	300	297	197	193	103	104	1	1	97	93	180	192
	(%) of Total			66	65	34	35	0	0	32	31	60	65

TABLE 19

## SOURCE OF ELECTRIC POWER IN PUBLIC PRIMARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	SOURCE OF ELECTRIC POWER				
			PHCN)	GENERATOR	BOTH	SOLAR	NONE
1	AKOKO N/E	40	3	1	0	3	33
2	AKOKO N/W	56	20	1	2	0	33
3	AKOKO/S/E	23	1	1	1	0	20
4	AKOKO S/W	51	5	1	1	0	44
5	AKURE/N	48	7	3	0	0	38
6	AKURE/S	72	12	5	1	0	54
7	ESE-ODO	62	3	2	8	0	49
8	IDANRE	71	13	1	1	0	56
9	IFEDORE	46	7	1	2	1	35
10	ILAJE	94	10	10	0	0	74
11	ILE-OLUJI/OKE-IGBO	78	8	5	6	4	55
12	IRELE	60	0	4	1	0	55
13	ODIGBO	99	3	7	5	1	83
14	OKITIPUPA	87	7	5	3	1	71
15	ONDO/E	46	5	3	3	0	35
16	ONDO/W	96	8	2	6	2	78
17	OSE	54	2	1	1	0	50
18	OWO	81	8	5	3	2	63
	TOTAL	1164	122	58	44	14	926
	(%) of Total		10	5	4	1	80

TABLE 20

## SOURCE OF ELECTRIC POWER IN PUBLIC SECONDARY SCHOOLS IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	SEC	PHCN		GENERATOR		BOTH		SOLAR		NONE		
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	6	7	-	-	6	4	-	-	4	5
2	AKOKO N/W	20	20	15	14	-	-	4	4	-	-	1	2
3	AKOKO S/E	8	8	4	4	1	1	2	2	-	-	1	1
4	AKOKO S/W	17	17	8	8	-	1	7	6	1	1	1	1
5	AKURE NORTH	8	6	4	3	2	1	1	-	-	-	1	2
6	AKURE SOUTH	28	28	13	12	1	3	10	12	-	-	4	1
7	ESE-ODO	13	13	1	-	-	-	3	5	3	3	6	5
8	IDANRE	10	10	6	4	2	2	2	4	-	-	-	-
9	IFEDORE	11	10	8	7	-	-	2	3	-	-	1	-
10	ILAJE	21	21	2	-	9	15	-	-	1	1	9	5
11	ILE-OLUJI/OKE-IGBO	23	23	5	5	3	7	6	8	-	-	9	3
12	IRELE	10	10	-	1	4	3	3	2	1	1	2	3
13	ODIGBO	18	18	8	7	3	5	-	3	-	-	7	3
14	OKITIPUPA	23	23	13	15	1	2	3	3	-	-	6	3
15	ONDO EAST	12	12	6	6	3	3	3	3	-	-	-	-
16	ONDO WEST	32	32	20	20	5	2	1	5	-	-	6	5
17	OSE	12	12	6	4	1	-	4	3	-	1	1	4
18	OWO	18	18	9	9	1	-	4	4	-	-	4	5
	<b>TOTAL</b>	<b>300</b>	<b>297</b>	<b>134</b>	<b>126</b>	<b>36</b>	<b>45</b>	<b>61</b>	<b>71</b>	<b>6</b>	<b>7</b>	<b>63</b>	<b>48</b>
	% of Total			45	42	12	15	20	24	2	2	21	16



TABLE 21

## RECREATIONAL FACILITIES IN PUBLIC PRIMARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	NO OF SCHOOLS WITH:				
			PLAYGROUND	SCHOOL HALL	TABLE TENNIS COURT	FOOD VENDOR CANTEEN	SWIMMING POOL
1	AKOKO N/E	40	27	3	0	10	0
2	AKOKO N/W	56	54	2	0	7	0
3	AKOKO/S/E	23	23	0	1	0	0
4	AKOKO S/W	51	43	2	1	2	0
5	AKURE/N	48	48	0	0	4	0
6	AKURE/S	72	55	8	0	15	0
7	ESE-ODO	62	52	1	3	2	3
8	IDANRE	71	67	0	0	5	0
9	IFEDORE	46	41	3	0	11	0
10	ILAJE	94	71	1	2	10	2
11	ILE-OLUJI/OKE-IGBO	78	70	5	1	28	0
12	IRELE	60	54	0	0	9	0
13	ODIGBO	99	94	2	1	30	0
14	OKITIPUPA	87	82	2	0	12	0
15	ONDO/E	46	25	1	0	19	0
16	ONDO/W	96	82	7	0	25	0
17	OSE	54	55	0	0	10	0
18	OWO	81	79	3	0	8	0
	TOTAL	1164	1022	40	9	207	5
	(%) OF TOTAL		88	3	1	18	0

TABLE 22  
RECREATIONAL FACILITIES IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	NO OF SCHOOLS WITH:									
		PLAYGROUND		SCHOOL HALL		TABLE TENNIS		FOOD VENDOR/ CANTEEN		SWIMMING POOL	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	7	13	0	1	6	7	0	0
2	AKOKO N/W	20	19	16	18	2	1	11	8	2	1
3	AKOKO/S/E	7	6	4	6	1	1	5	4	0	0
4	AKOKO S/W	17	17	14	17	2	4	5	10	0	0
5	AKURE/N	8	6	5	5	0	0	5	4	0	0
6	AKURE/S	25	28	14	16	0	4	18	20	0	0
7	ESE-ODO	13	11	-	1	2	4	1	5	7	2
8	IDANRE	10	7	6	7	0	0	9	3	0	0
9	IFEDORE	11	10	6	6	2	0	3	3	0	0
10	ILAJE	21	21	5	5	2	2	16	13	0	0
11	ILE-OLUJI/OKE-IGBO	23	18	11	17	2	1	10	15	0	0
12	IRELE	10	10	7	9	1	0	6	3	0	0
13	ODIGBO	16	18	10	14	0	2	10	10	0	0
14	OKITIPUPA	23	23	11	17	1	4	9	13	0	0
15	ONDO/E	12	12	9	10	1	0	4	6	0	0
16	ONDO/W	32	32	14	15	2	1	9	8	0	0
17	OSE	12	12	3	8	1	1	6	7	0	0
18	OWO	18	18	11	13	0	1	13	11	0	0
	TOTAL	294	284	153	197	19	27	146	150	9	3
	(%) OF TOTAL	98	95	51	66	6	9	49	50	3	1

TABLE 23

## AVAILABILITY OF LIBRARIES AND LABORATORIES IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS		NO OF SCHOOLS							
				WITH LIBRARY		WITHOUT LIBRARY		WITH AT LEAST A LABORATORY		WITHOUT LABORATORY	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	5	13	11	3	3	14	13	2
2	AKOKO N/W	20	20	15	20	5	0	11	20	9	0
3	AKOKO/S/E	8	8	4	5	4	3	4	6	4	2
4	AKOKO S/W	17	17	13	15	4	2	9	10	8	7
5	AKURE/N	8	6	6	4	2	2	5	4	3	2
6	AKURE/S	28	28	14	12	14	16	8	20	20	8
7	ESE-ODO	13	13	3	5	10	8	3	6	10	7
8	IDANRE	10	10	2	7	8	3	5	8	5	2
9	IFEDORE	11	10	4	10	7	0	3	5	8	5
10	ILAJE	21	21	5	6	16	15	3	18	18	3
11	ILE-OLUJI/OKE-IGBO	23	23	10	16	13	7	4	19	19	4
12	IRELE	10	10	6	4	4	6	2	6	8	4
13	ODIGBO	18	18	11	4	7	14	11	4	7	14
14	OKITIPUPA	23	23	14	18	9	5	13	16	10	7
15	ONDO/E	12	12	7	7	5	5	8	8	4	4
16	ONDO/W	32	32	8	31	24	1	21	29	11	3
17	OSE	12	12	5	11	7	1	5	11	7	1
18	OWO	18	18	13	15	5	3	9	15	9	3
	TOTAL	300	297	145	203	155	94	127	219	173	78
	(%) OF TOTAL			48	68	52	32	42	74	58	26

TABLE 24

## LEVEL OF EQUIPING OF LABORATORIES IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	NO OF SCHOOLS WITH LABORATORIES		TOTAL NO OF LABORATORIES		NO OF LABORATORIES					
						WELL EQUIPED		FAIRLY EQUIPED		NOT EQUIPED	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	3	14	5	29	0	0	3	20	2	9
2	AKOKO N/W	11	20	13	55	0	2	11	46	2	7
3	AKOKO/S/E	4	6	6	16	1	4	4	6	1	6
4	AKOKO S/W	9	10	13	32	0	1	8	30	5	1
5	AKURE/N	5	4	7	15	1	0	2	6	4	9
6	AKURE/S	8	20	8	20	0	0	6	20	2	0
7	ESE-ODO	3	6	7	14	0	2	1	8	6	4
8	IDANRE	5	8	5	8	0	0	3	4	2	4
9	IFEDORE	3	5	5	12	0	0	2	5	3	7
10	ILAJE	3	18	6	38	0	7	6	24	0	7
11	ILE-OLUJI/OKE-IGBO	4	19	8	38	0	6	3	24	5	8
12	IRELE	2	6	4	24	0	2	4	16	0	6
13	ODIGBO	11	4	14	12	0	0	7	7	7	5
14	OKITIPUPA	13	16	15	43	0	0	6	13	9	30
15	ONDO/E	8	8	8	8	0	0	5	5	3	3
16	ONDO/W	21	29	22	63	1	3	11	48	10	12
17	OSE	5	11	6	32	1	1	3	30	2	1
18	OWO	9	15	23	54	1	1	9	26	13	27
	TOTAL	127	219	175	513	5	29	94	338	76	146
	(%) OF TOTAL	42	74			3	6	54	66	43	28

TABLE 25

## INFORMATION TECHNOLOGY IN PUBLIC PRIMARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS	NO OF SCHOOLS WITH COMPUTERS	NO OF SCHOOLS WITHOUT COMPUTERS	TOTAL NO OF COMPUTERS AVAILABLE
1	AKOKO N/E	40	4	36	8
2	AKOKO N/W	56	24	32	63
3	AKOKO/S/E	23	4	19	8
4	AKOKO S/W	51	5	46	10
5	AKURE/N	48	3	45	10
6	AKURE/S	72	7	65	15
7	ESE-ODO	62	43	19	12
8	IDANRE	71	5	66	5
9	IFEDORE	46	4	42	4
10	ILAJE	94	5	89	8
11	ILE-OLUJI/OKE-IGBO	78	6	72	12
12	IRELE	60	4	56	7
13	ODIGBO	99	11	88	17
14	OKITIPUPA	87	8	79	15
15	ONDO/E	46	35	11	16
16	ONDO/W	96	22	74	29
17	OSE	54	6	48	19
18	OWO	81	8	73	13
	TOTAL	1164	204	960	271
	(%) of Total		18	82	

TABLE 26

## INFORMATION TECHNOLOGY (IT) IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS		NO OF SCHOOLS WITH COMPUTERS		NO OF SCHOOL WITHOUT COMPUTERS		TOTAL NO OF COMPUTERS AVAILABLE	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	13	7	3	9	105	42
2	AKOKO N/W	20	20	15	13	5	7	91	80
3	AKOKO/S/E	8	8	7	5	1	3	32	37
4	AKOKO S/W	17	17	14	14	3	3	67	64
5	AUKRE/N	8	6	5	1	3	5	57	3
6	AKURE/S	28	28	21	17	7	11	129	91
7	ESE-ODO	13	13	12	7	1	6	48	29
8	IDANRE	10	10	10	6	0	4	93	42
9	IFEDORE	11	10	11	9	0	1	27	18
10	ILAJE	21	21	21	13	0	8	73	58
11	ILE-OLUJI/OKE-IGBO	23	23	20	20	3	3	46	46
12	IRELE	10	10	8	6	2	4	58	142
13	ODIGBO	18	18	8	11	10	7	42	46
14	OKITIPUPA	23	23	16	15	7	8	25	30
15	ONDO/E	12	12	8	9	4	3	24	33
16	ONDO/W	32	32	20	30	12	2	98	115
17	OSE	12	12	8	8	4	4	52	31
18	OWO	18	18	18	18	0	0	129	77
	TOTAL	300	297	235	209	65	88	1196	984
	(%) OF TOTAL			78	70	22	30		

TABLE 27

## MAJOR TEACHING AID AVAILABLE IN PUBLIC PRIMARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	NO OF SCHOOLS	NO OF SCHOOLS USING:		
			CHALK BOARD	SLIDE	VISUAL AID
1	AKOKO N/E	40	38	2	4
2	AKOKO N/W	56	55	1	5
3	AKOKO/S/E	23	24	-	3
4	AKOKO S/W	51	49	1	5
5	AUKRE/N	48	45	1	9
6	AKURE/S	72	77	1	5
7	ESE-ODO	62	59		2
8	IDANRE	71	67	1	6
9	IFEDORE	46	45	-	1
10	ILAJE	94	86	2	12
11	ILE-OLUJI/OKE-IGBO	78	73	1	6
12	IRELE	60	60	1	7
13	ODIGBO	99	90	3	5
14	OKITIPUPA	87	81	1	7
15	ONDO/E	46	42	3	-
16	ONDO/W	96	97	1	1
17	OSE	54	53	1	5
18	OWO	81	78	2	9
	TOTAL	1164	1119	22	92
	(%) OF TOTAL		96	2	8

TABLE 28

## MAJOR TEACHING AID AVAILABLE IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	NO OF SCHOOLS		NO OF SCHOOLS USING					
				CHALK BOARD		SLIDE ONLY		VISUAL AID	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	16	16	-	-	2	1
2	AKOKO N/W	20	20	20	20	-	1	-	1
3	AKOKO/S/E	8	8	8	8	-	-	-	-
4	AKOKO S/W	17	17	17	17	-	-	3	3
5	AKURE/N	8	6	8	6	-	-	-	1
6	AKURE/S	28	28	28	28	-	-	2	-
7	ESE-ODO	13	13	13	13	-	-	-	-
8	IDANRE	10	10	10	10	-	-	2	-
9	IFEDORE	11	10	11	10	-	-	-	-
10	ILAJE	21	21	21	21	-	2	1	7
11	ILE-OLUJI/OKE-IGBO	23	23	23	23	-	-	-	-
12	IRELE	10	10	10	10	-	-	-	-
13	ODIGBO	18	18	18	18	-	-	-	-
14	OKITIPUPA	23	23	23	23	-	-	-	-
15	ONDO/E	12	12	12	12	-	1	-	1
16	ONDO/W	32	32	32	32	-	1	-	2
17	OSE	12	12	12	12	-	-	-	1
18	OWO	18	18	17	16	-	-	1	2
	TOTAL	300	297	299	295	0	5	11	19



TABLE 29

## SUMMARY OF PUBLIC PRIMARY SCHOOLS SHOWING STUDENT/CLASSROOM RATIO AND STUDENT/TEACHER RATIO IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	NO OF CLASSROOMS	TOTAL OF STUDENTS ENROLLMENT (2008/2009)			STUDENT/ CLASSROOM RATIO	NUMBER OF TEACHERS (2008/2009)			PUPIL/ TEACHER RATIO
			M	F	Total		M	F	Total	
1	AKOKO N/E	407	7733	8079	15812	39	214	593	807	20
2	AKOKO N/W	516	17336	18013	35349	69	275	509	784	45
3	AKOKO S/E	261	4926	5103	10029	38	130	192	322	31
4	AKOKO S/W	477	12361	12626	24987	52	370	518	888	28
5	AKURE NORTH	377	6029	5993	12022	32	178	536	714	17
6	AKURE SOUTH	841	16061	16199	32260	38	122	1251	1373	24
7	ESE-ODO	399	11804	10374	22178	56	274	194	468	47
8	IDANRE	464	9549	9546	19095	41	201	342	543	35
9	IFEDORE	386	5710	5790	11500	30	170	374	544	21
10	ILAJE	617	34216	33706	67922	110	455	440	895	76
11	ILE-OLUJI/OKE-IGBO	556	10679	11292	21971	40	268	484	752	29
12	IRELE	376	13323	13387	26710	71	278	239	517	52
13	ODIGBO	571	16988	17239	34227	60	493	710	1203	28
14	OKITIPUPA	614	14726	16627	31353	51	322	655	977	32
15	ONDO EAST	358	5156	5590	10746	30	238	358	596	18
16	ONDO WEST	661	19517	20539	40056	61	341	1178	1519	26
17	OSE	378	8158	11355	19513	52	293	335	628	31
18	OWO	658	12071	11720	23791	36	289	809	1098	22
	<b>TOTAL</b>	<b>8917</b>	<b>226343</b>	<b>233178</b>	<b>459521</b>	<b>52</b>	<b>4911</b>	<b>9717</b>	<b>14628</b>	<b>31</b>

TABLE 30

## SUMMARY OF PUBLIC SECONDARY SCHOOLS SHOWING STUDENT/CLASSROOM RATIO AND STUDENT/TEACHER RATIO IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	NO OF CLASSROOMS		TOTAL OF STUDENTS ENROLLMENT (2008/2009)						STUDENT/CLASSROOM RATIO		NO OF TEACHERS (2008/2009)						STUDENT / TEACHER RATIO	
		SEC		JSS			SSS			SEC		JSS			SSS			SEC	
		JSS	SSS	M	F	Total	M	F	Total	JSS	SSS	M	F	Total	M	F	Total	JSS	SSS
1	AKOKO N/E	102	153	3594	3535	7129	3169	2860	6029	70	39	133	168	301	220	126	346	24	17
2	AKOKO N/W	149	141	2944	2705	5649	3123	3043	6166	38	44	133	125	258	218	76	294	22	21
3	AKOKO S/E	50	55	1234	1022	2256	948	1012	1960	45	36	66	34	100	104	34	138	23	14
4	AKOKO S/W	134	148	4030	3841	7871	3485	3213	6698	59	45	173	169	342	258	97	355	23	19
5	AKURE NORTH	68	70	1761	1595	3356	1274	1115	2389	49	34	84	152	236	127	92	219	14	11
6	AKURE SOUTH	387	333	11221	11227	22448	8551	8794	17345	58	52	184	932	1116	364	704	1068	20	16
7	ESE-ODO	71	58	2730	2249	4979	2585	1604	4189	70	72	95	37	132	133	17	150	38	28
8	IDANRE	94	80	2651	2377	5028	2113	1573	3686	53	46	109	107	216	155	87	242	23	15
9	IFEDORE	85	67	1746	1557	3303	1305	1318	2623	39	39	99	122	221	125	84	209	15	13
10	ILAJE	109	132	6273	4921	11194	5627	4031	9658	103	73	114	34	148	164	26	190	76	51
11	ILE-OLUJI/OKE-IGBO	120	157	3281	3263	6544	3388	3314	6702	55	43	187	110	297	289	94	383	22	17
12	IRELE	64	64	2262	1964	4226	1752	1626	3378	66	53	71	45	116	98	25	123	36	27
13	ODIGBO	113	117	4633	4404	9037	4682	4244	8926	80	76	137	108	245	256	94	350	37	26
14	OKITIPUPA	140	204	5351	5391	10742	5356	5003	10359	77	51	210	190	400	337	149	486	27	21
15	ONDO EAST	58	71	1616	1506	3122	1770	1652	3422	54	48	71	104	175	115	78	193	18	18
16	ONDO WEST	293	295	7514	8136	15650	6689	6197	12886	53	44	254	517	771	432	417	849	20	15
17	OSE	65	84	2531	2207	4738	1969	1766	3735	73	44	109	65	174	254	342	596	27	6
18	OWO	198	144	4765	4166	8931	3672	3378	7050	45	49	183	244	427	288	171	459	21	15
	<b>TOTAL</b>	<b>2300</b>	<b>2373</b>	<b>70137</b>	<b>66066</b>	<b>136203</b>	<b>61458</b>	<b>55743</b>	<b>117201</b>	59	49	<b>2412</b>	<b>3263</b>	<b>5675</b>	<b>3937</b>	<b>2713</b>	<b>6650</b>	24	18

TABLE 31

## NUMBER OF SEATS AND DESKS IN PUBLIC PRIMARY SCHOOLS IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	NO OF SINGLE SEATS	NO OF DOUBLE SEATS	TOTAL NO OF SITTING	TOTAL NUMBER OF DESKS	TOTAL NO OF STUDENTS
1	AKOKO N/E	1051	3840	8731	8747	15812
2	AKOKO N/W	1385	10351	22087	21919	35349
3	AKOKO S/E	134	3461	7056	6879	10029
4	AKOKO S/W	1062	6124	13310	13597	24987
5	AKURE NORTH	616	4556	9728	9768	12022
6	AKURE SOUTH	3943	10427	24797	25061	32260
7	ESE-ODO	650	5062	10774	11031	22178
8	IDANRE	737	5564	11865	12156	19095
9	IFEDORE	293	4168	8629	8655	11500
10	ILAJE	1363	12355	26073	25476	67922
11	ILE-OLUJI/OKE-IGBO	1329	7752	16833	16785	21971
12	IRELE	1327	5969	13265	13156	26710
13	ODIGBO	3270	5641	14552	14293	34227
14	OKITIPUPA	1773	9745	21263	21014	31353
15	ONDO EAST	950	3615	8180	8512	10746
16	ONDO WEST	7007	8704	24415	24470	40056
17	OSE	300	5121	10542	10599	19513
18	OWO	1103	7004	15111	17226	23791
	TOTAL	28293	119459	267211	269344	459521
	% of Total			58	59	

TABLE 32  
NUMBER OF SEATS AND DESKS IN PUBLIC SECONDARY SCHOOLS IN ONDO-STATE

S/N	LOCAL GOVERNMENT AREA	NO OF SINGLE SEATS		NO OF DOUBLE SEATS		TOTAL SITTINGS		TOTAL DESKS		TOTAL NO OF STUDENTS	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	3526	3917	0	65	3526	4047	3868	4219	7129	6029
2	AKOKO N/W	4347	3953	125	240	4597	4433	4730	4377	5649	6166
3	AKOKO S/E	1750	1614	0	0	1750	1614	1794	1614	2256	1960
4	AKOKO S/W	3711	3552	42	17	3795	3586	3930	3828	7871	6698
5	AKURE NORTH	1410	1419	170	233	1750	1885	1980	1560	3356	2389
6	AKURE SOUTH	16425	11583	0	0	16425	11583	16816	11933	22448	17345
7	ESE-ODO	1649	2103	638	274	2925	2651	1795	2593	4979	4189
8	IDANRE	3485	2233	0	0	3485	2233	3485	2428	5028	3686
9	IFEDORE	2268	1899	0	0	2268	1899	2340	2265	3303	2623
10	ILAJE	2781	2941	1822	1890	6425	6721	6263	5510	11194	9658
11	ILE-OLUJI/OKE-IGBO	3369	4835	0	0	3369	4835	3674	5035	6544	6702
12	IRELE	1952	1861	253	0	2458	1861	2384	1767	4226	3378
13	ODIGBO	4201	4926	235	0	4671	4926	4009	4682	9037	8926
14	OKITIPUPA	6000	7994	188	0	6376	7994	6593	8290	10742	10359
15	ONDO EAST	1357	1607	260	160	1877	1927	1916	2250	3122	3422
16	ONDO WEST	9001	6705	92	100	9185	6905	9314	6905	15650	12886
17	OSE	2328	1949	105	205	2538	2359	2709	2308	4738	3735
18	OWO	6170	4403	0	0	6170	4403	6050	4383	8931	7050
	<b>TOTAL</b>	75730	69494	3930	3184	83590	75862	83650	75947	136203	117201
	% of Total					61	65	61	65		

TABLE 33

## SUMMARY OF PUBLIC SECONDARY SCHOOLS INDICATING BOARDING AND DAY SYSTEM IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS		NO OF SCHOOLS WITH BOARDING SYSTEM ONLY		NO OF SCHOOLS WITH DAY SYSTEM ONLY		NO OF SCHOOLS WITH BOTH	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	-	-	14	14	2	2
2	AKOKO N/W	20	20	-	-	19	19	1	1
3	AKOKO/S/E	8	8	1	1	7	7	0	0
4	AKOKO S/W	17	17	-	-	16	16	1	1
5	AKURE/N	8	6	-	-	8	6	-	-
6	AKURE/S	28	28	1	1	22	22	5	5
7	ESE-ODO	13	13	-	-	13	13	-	-
8	IDANRE	10	10	-	-	10	10	1	1
9	IFEDORE	11	10	-	-	11	10	-	-
10	ILAJE	21	21	-	-	20	20	-	-
11	ILE-OLUJI/OKE-IGBO	23	23	-	-	23	23	-	-
12	IRELE	10	10	-	-	10	10	-	-
13	ODIGBO	18	18	-	-	18	18	-	-
14	OKITIPUPA	23	23	1	1	22	22	-	-
15	ONDO/E	12	12	-	-	12	12	-	-
16	ONDO/W	32	32	1	1	29	29	2	2
17	OSE	12	12	-	-	12	12	-	-
18	OWO	18	18	1	1	17	15	-	2
	TOTAL	300	297	5	5	283	278	12	14
	(%) OF TOTAL			1.7	1.7	94.3	93.6	4	4.7

TABLE 34

## DISTRIBUTION OF PUBLIC SECONDARY SCHOOLS IN ONDO STATE BY CO-EDUCATIONAL, BOYS ONLY AND GIRLS ONLY

S/N	LOCAL GOVERNMENT AREA	TOTAL NO OF SCHOOLS		CO-EDUCATIONAL SCHOOLS		BOYS ONLY		GIRLS ONLY	
		JSS	SSS	JSS	SSS	JSS	SSS	JSS	SSS
1	AKOKO N/E	16	16	14	14	1	1	1	1
2	AKOKO N/W	20	20	20	20	-	-	-	-
3	AKOKO/S/E	8	8	8	8	-	-	-	-
4	AKOKO S/W	17	17	17	17	-	-	-	-
5	AKURE/N	8	6	8	6	-	-	-	-
6	AKURE/S	28	28	24	24	2	2	2	2
7	ESE-ODO	13	13	13	13	-	-	-	-
8	IDANRE	10	10	8	8	1	1	1	1
9	IFEDORE	11	10	11	10	-	-	-	-
10	ILAJE	21	21	21	21	-	-	-	-
11	ILE-OLUJI/OKE-IGBO	23	23	23	23	-	-	-	-
12	IRELE	10	10	10	10	-	-	-	-
13	ODIGBO	18	18	18	18	-	-	-	-
14	OKITIPUPA	23	23	23	23	-	-	-	-
15	ONDO/E	12	12	12	12	-	-	-	-
16	ONDO/W	32	32	26	26	3	3	3	3
17	OSE	12	12	12	12	-	-	-	-
18	OWO	18	18	15	15	1	1	2	2
	TOTAL	300	297	283	280	8	8	9	9
	(%) OF TOTAL			94	94	3	3	3	3

Table 35

SUMMARY OF ROOFS, FLOORS, WINDOWS AND WALLS INDICATING NUMBERS IN BAD CONDITIONS IN PUBLIC PRIMARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	NO OF SCHOOLS	TOTAL NO OF ROOFS	NO OF ROOFS IN BAD CONDITION		TOTAL NO OF FLOORS	NO OF FLOORS IN BAD CONDATIONS		TOTAL NO OF WINDOWS	NO OF WINDOWS IN BAD CONDITIONS		TOTAL NO OF WALLS	NO OF WALLS IN BAD CONDITIONS	
				NO	% OF TOTAL		NO	% OF TOTAL		NO	% OF TOTAL		NO	% OF TOTAL
1	AKOKO N/E	40	527	189	36	527	206	39	1593	738	46	1593	659	41
2	AKOKO N/W	56	719	199	28	719	204	28	2772	975	35	2772	1060	38
3	AKOKO S/E	23	228	43	19	228	54	24	1100	335	30	1100	208	19
4	AKOKO S/W	51	647	207	32	647	282	44	2516	1179	47	2516	806	32
5	AKURE NORTH	48	436	109	25	436	111	25	1764	465	26	1764	405	23
6	AKURE SOUTH	72	1121	303	27	1121	285	25	4484	1699	38	4484	1234	28
7	ESE-ODO	62	527	74	14	527	94	18	1596	434	27	1596	208	13
8	IDANRE	71	547	176	32	547	220	40	2174	930	43	2204	778	35
9	IFEDORE	46	515	186	36	515	186	36	2080	762	37	2080	614	30
10	ILAJE	94	885	172	19	885	272	31	2973	1380	46	2973	1113	37
11	ILE-OLUJI/OKE-IGBO	78	767	225	29	767	240	31	2864	1204	42	2864	926	32
12	IRELE	60	479	141	29	479	161	34	1504	708	47	1504	568	38
13	ODIGBO	99	811	347	43	811	348	43	2304	1623	70	2304	1123	49
14	OKITIPUPA	87	1002	423	42	1002	468	47	2472	2194	89	2472	1607	65
15	ONDO EAST	46	344	110	32	344	129	38	1444	584	40	1444	528	37
16	ONDO WEST	96	1090	563	52	1090	650	60	4544	2491	55	4544	2320	51
17	OSE	54	541	157	29	541	171	32	832	570	69	832	329	40
18	OWO	81	661	344	52	661	410	62	8248	1440	17	8248	1076	13
	TOTAL	1164	11847	3968		11847	449	1	47264	1971	1	47294	1556	2
	% OF TOTAL				33			38			42			33

TABLE 36

## SUMMARY OF ROOFS, FLOORS, WINDOWS AND WALLS INDICATING NUMBERS IN BAD CONDITIONS IN PUBLIC SECONDARY SCHOOLS IN ONDO STATE

S/N	LOCAL GOVERNMENT AREA	NO OF SCHOOLS		TOTAL NO OF ROOFS		NO OF ROOFS IN BAD CONDITION				TOTAL NO OF FLOORS		NO OF FLOORS IN BAD CONDITIONS				TOTAL NO OF WINDOWS		NO OF WINDOWS IN BAD CONDITIONS				TOTAL NO OF WALLS		NO OF WALLS IN BAD CONDITIONS			
						NO	% OF TOTAL	NO	% OF TOTAL			NO	% OF TOTAL	NO	% OF TOTAL			NO	% OF TOTAL	NO	% OF TOTAL			NO	% OF TOTAL	NO	% OF TOTAL
1	AKOKO N/E	16	16	117	139	73	62	56	40	117	139	80	68	88	63	468	556	326	70	294	53	468	556	144	31	117	21
2	AKOKO N/W	20	20	211	162	45	21	68	42	211	162	44	21	73	45	844	648	274	32	322	50	844	648	210	25	268	41
3	AKOKO S/E	8	8	75	78	34	45	35	45	75	78	31	41	27	35	300	312	228	76	276	88	300	312	162	54	128	41
4	AKOKO S/W	17	17	156	166	64	41	34	20	156	166	80	51	33	20	624	664	456	73	332	50	624	664	228	37	192	29
5	AKURE NORTH	8	6	96	76	30	31	39	51	96	76	50	52	60	79	384	304	216	56	224	74	384	304	124	32	42	14
6	AKURE SOUTH	28	28	387	333	78	20	105	32	387	333	217	56	155	47	1548	1332	1012	65	886	67	1548	1332	706	46	598	45
7	ESE-ODO	13	13	85	85	7	8	40	47	85	85	27	32	32	38	340	340	137	40	226	66	340	340	74	22	74	22
8	IDANRE	10	10	94	80	24	26	37	46	94	80	56	60	53	66	376	320	162	43	224	70	376	320	160	43	178	56
9	IFEDORE	11	10	92	93	34	37	35	38	92	93	43	47	23	25	368	372	110	30	224	60	368	372	96	26	168	45
10	ILAJE	21	21	143	148	27	19	55	37	143	148	88	62	54	36	572	592	324	57	324	55	572	592	232	41	289	49
11	ILE-OLUJI/OKE-IGBO	23	23	170	187	88	52	100	53	170	187	97	57	80	43	680	748	395	58	448	60	680	748	323	48	400	53
12	IRELE	10	10	72	69	28	39	18	26	72	69	36	50	22	32	288	276	146	51	232	84	288	276	140	49	51	18
13	ODIGBO	18	18	138	152	43	31	89	59	138	152	54	39	95	63	552	608	312	57	378	62	552	608	262	47	279	46
14	OKITIPUPA	23	23	154	244	78	51	92	38	154	244	96	62	107	44	616	976	543	88	744	76	616	976	268	44	497	51
15	ONDO EAST	12	12	66	82	43	65	33	40	66	82	45	68	29	35	264	328	158	60	177	54	264	328	140	53	124	38
16	ONDO WEST	32	32	342	343	4	42	183	53	342	343	4	60	19	58	1368	1372	919	67	760	55	1368	1372	649	47	775	56
17	OSE	12	12	114	121	40	35	41	34	114	121	53	46	62	51	456	484	260	57	328	68	456	484	235	52	326	67
18	OWO	18	18	199	195	64	32	65	33	199	195	164	82	98	50	796	780	579	73	621	80	796	780	301	38	176	23
	TOTAL	300	297	2711	2753	944		1125		2711	2753	1465		1290		10844	11012	5860		7020		10844	11012	4454		4682	
	% OF TOTAL						35		41				54		47				54		64				41		43



TABLE 37

**AKOKO NORTH EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
1	A.U. D Pry Sch. Igbede Ikare Akoko	3	10	5	20	20	6	10	240	240	N	N	Y	1,5	1	1-5, 8, 9	5	154	138	7	11
2	A.U. D Pry School. Ii, Iku Ikare	3	6	3	12	12	4	6	120	120	Y	N	Y	1	-	1-5, 8, 9	1	159	183	7	14
3	A.U.D. Pry. School , Okoja Ikare	2	9	6	6	12	6	10	76	86	N	N	Y	-	-	1-6, 8, 9	5	87	99	3	7
4	A.U.D. Sch Iv Ikare	2	14	8	20	25	8	10	196	204	N	N	Y	1	1	1-5, 8, 9	5	215	215	11	7
5	Abadaka Community School Ikare	2	6	-	-	-	-	6	60	60	N	N	N	1,5	1	1-5, 8, 9	5	13	17	4	2
6	All Saints Anglican Pry. Ilepa Ikare	1	12	6	6	6	6	12	300	300	Y	Y	Y	3,6	-	1-6, 8, 9	5	219	246	11	50
7	Ansaru Deen Sch, Odoruwa Ikare	1	6	-	-	-	-	-	160	320	Y	N	Y	5	-	1-5, 8, 9	5	97	104	6	8
8	A.U.D Isalm Pry Sch Isaknmi Ikare	3	9	5	16	16	3	8	189	192	Y	N	Y	1	1	1-5, 8, 9, 10	5	118	134	7	11
9	Community Pry Sch. Ugbe Akoko	2	4	-	8	8	1	5	465	250	N	N	Y	-	1,4	2,-5, 7, 8, 9	5	205	221	2	12
10	Community Pry Sch Odo Ikare	2	6	6	6	18	3	1	110	110	N	N	Y	-	1	1-5, 8, 9	5	68	57	3	8

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6	
(P)	SCHOOL RECORDS			6 (Q)	SOURCE OF ELECTRIC POWER
	Admission Register	1			PHCN
	Attendance Register	2			Generator
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			Solar
	Visitors Book	5			None
					1 Other
					2
					3
					4
					5
					6

TABLE 37 Contd

**AKOKO NORTH EAST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	Community Pry. Iku, Ikare	3	9
12	Community Pry. Sch. Ayegule	3	6	-	3	-	3	12	42	42	N	N	Y	-	1	1-5, 8, 9	5	37	32	4	2
13	Ebenezer African Church Pry School, Osele Ikare	1	7	3	12	12	3	8	100	100	Y	N	Y	1,5	1,4	2-10	5	151	152	11	41
14	Emmanuel Ang Pry Sch. Edo	1	6	5	12	12	1	6	146	148	N	N	Y	1,3	-	1-5, 8, 9, 10	5	135	178	1	11
15	Ese Moslem Pry. Sch. I Kare	3	18	10	20	20	9	10	346	346	Y	N	Y	5	1	1-5, 8, 9	5	141	164	3	23
16	L. A. Pry Sch. Ilepa Ikare	3	26	22	88	88	22	44	259	349	Y	N	Y	-	1,4	1-5, 8, 9	5	493	466	5	32
17	L.A Primary Sch. Ikado Ikare	2	8	9	32	32	9	16	202	202	N	N	Y	6	1	1-5, 8, 9, 10	5	147	138	2	14
18	Moselm Pry Ilepa, Ikare	2	8	4	12	12	4	5	32	32	N	N	Y	5	1	1-4, 8, 9	5	107	129	2	19
19	Moselm Pry Okela Ikare	1	6	5	12	12	4	8	240	240	N	N	N	1	4	1-5, 8, 9, 10	5	272	270	3	12
20	Nomadic Pry Sch. Akunu	2	3	2	6	6	-	3	14	16	N	N	Y	1	1	2-5, 8, 9	5	15	10	4	1

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 37 Contd

**AKOKO NORTH EAST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers	M	F
11	Community Pry. Iku, Ikare	3	9	3	4	10	4	10	440	448	N	N	Y	-	-	1-3, 8, 9	5	329	360	3	13
12	Community Pry. Sch. Ayegule	3	6	-	3	-	3	12	42	42	N	N	Y	-	1	1-5, 8, 9	5	37	32	4	2
13	Ebenezer African Church Pry School, Osele Ikare	1	7	3	12	12	3	8	100	100	Y	N	Y	1,5	1,4	2-10	5	151	152	11	41
14	Emmanuel Ang Pry Sch. Edo	1	6	5	12	12	1	6	146	148	N	N	Y	1,3	-	1-5, 8, 9, 10	5	135	178	1	11
15	Ese Moslem Pry. Sch. I Kare	3	18	10	20	20	9	10	346	346	Y	N	Y	5	1	1-5, 8, 9	5	141	164	3	23
16	L. A. Pry Sch. Ilepa Ikare	3	26	22	88	88	22	44	259	349	Y	N	Y	-	1,4	1-5, 8, 9	5	493	466	5	32
17	L.A Primary Sch. Ikado Ikare	2	8	9	32	32	9	16	202	202	N	N	Y	6	1	1-5, 8, 9, 10	5	147	138	2	14
18	Moselm Pry Ilepa, Ikare	2	8	4	12	12	4	5	32	32	N	N	Y	5	1	1-4, 8, 9	5	107	129	2	19
19	Moselm Pry Okela Ikare	1	6	5	12	12	4	8	240	240	N	N	N	1	4	1-5, 8, 9, 10	5	272	270	3	12
20	Nomadic Pry Sch. Akunu	2	3	2	6	6	-	3	14	16	N	N	Y	1	1	2,-5, 8, 9	5	15	10	4	1

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6			
(P)	SCHOOL RECORDS			(Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 37 Contd

**AKOKO NORTH EAST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
31	St. Michael's C.A.C. Pry. Sch. Ilepa Ikare	2	15	-	12	12	4	-	210	210	N	N	Y	1	4	1-5, 7, 8, 9	5	152	166	3	16
32	St. Moses Orimolade C&S Pry Sch, Okorun	3	10	5	12	12	5	5	244	225	N	N	Y	4,5,6	-	1-5, 8, 9, 10	4	147	149	4	11
33	St. Paul's Primary Sch I, Auga Akoko	3	8	2	16	16	2	10	273	273	N	N	N	1,3,6	1	1-5, 8, 9	5	92	107	6	3
34	St. Paul's Pry. Sch, II Auga Akoko	2	3	2	8	6	2	4	40	80	N	N	Y	1,3,6	1	2-5, 8, 9	4	29	34	2	2
35	St. Peter Ang Sch, Okoja Ikare	1	20	10	40	40	10	20	364	294	N	N	Y	5	-	1-3, 9, 10	5	337	315	6	20
36	St. Philips Ang. Pry. Sch. Ikakumo-Akoko	1	6	3	8	11	2	5	102	192	N	N	Y	1,3,5	1	1-5, 8, 9, 10	5	146	137	3	-
37	St. Silas Anglican Pry School Ise-Akoko	2	2	1	5	6	-	2	111	111	N	N	Y	1, 5	1,4	1-5, 8, 9	5	208	199	9	5
38	St. Stephens Ang Pry Sch, Ilepa Ikare	2	10	-	-	40	-	-	308	308	Y	N	Y	1,4, 5	4	1-9	5	166	162	3	15
39	St. Thomas Ang Pry Sch Ese Akoko	3	8	2	23	23	2	6	196	223	Y	N	N	6	1, 4	1-5, 8, 9	5	418	497	4	26
40	St. Thomas's R.C.M Oyinmo	3	4	2	10	10	2	4	120	120	N	N	Y	1, 5	5	1-5, 8, 9	1	137	148	5	6

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1			PHCN	1 Other 6
	Attendance Register	2			Generator	2
	Syllabus/Plan of Work	3			PHCN/Generator/	3
	Supervision Book	4			Solar	4
	Visitors Book	5			None	5

TABLE 38

AKOKO NORTH EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Agbaode/ Orimolade Grammar School, Ikare	2	5	-	-	-	-	1	120	120	N	N	-	Y	-	1	2-5,8-9	1	174	161	7	13
2	Agboriki Comp. High School, Ikare	1	3	12	12	36	10	11	225	225	N	N	-	Y	1	1,4	2-4,8-9	3	363	385	11	16
3	Agolo High Ikare	3	6	6	6	6	-	6	185	202	Y	N	1,2,3	N	-	1,2,4	1-5,7-10	5	235	220	6	9
4	Akunu Grammar School, Akunu Akoko	3	3	6	6	6	6	6	250	250	N	N	-	Y	1,5	1,2,4	2-6,8,9	3	121	122	3	3
5	Ansar Vd Deen Grammar School, Ikare	2	9	12	12	48	12	24	220	220	N	N	4	Y	1,4,5	1	1-3,5,8,9	3	225	232	7	12
6	Auga Community Grammar School	2	3	-	-	3	-	3	75	75	N	N	-	Y	1	1,2	1-5,8-10	3	79	52	6	1
7	Ayegbe Comp. High School, Ise Akoko	2	3	-	-	3	-	3	42	36	N	N	4	Y	-	1	1-4,8-9	5	53	48	8	-
8	Community High School Iborona	2	6	12	48	32	12	24	120	120	N	N	6	Y	1,5	1	1-5,7-9	5	114	124	7	2

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 38

AKOKO NORTH EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Agbaode/ Orimolade Grammar School, Ikare	2	5	-	-	-	-	1	120	120	N	N	-	Y	-	1	2-5,8-9	1	174	161	7	13
2	Agboriki Comp. High School, Ikare	1	3	12	12	36	10	11	225	225	N	N	-	Y	1	1,4	2-4,8-9	3	363	385	11	16
3	Agolo High Ikare	3	6	6	6	6	-	6	185	202	Y	N	1,2,3	N	-	1,2,4	1-5,7-10	5	235	220	6	9
4	Akunu Grammar School, Akunu Akoko	3	3	6	6	6	6	6	250	250	N	N	-	Y	1,5	1,2,4	2-6,8,9	3	121	122	3	3
5	Ansar Vd Deen Grammar School, Ikare	2	9	12	12	48	12	24	220	220	N	N	4	Y	1,4,5	1	1-3,5,8,9	3	225	232	7	12
6	Auga Community Grammar School	2	3	-	-	3	-	3	75	75	N	N	-	Y	1	1,2	1-5,8-10	3	79	52	6	1
7	Ayegbe Comp. High School, Ise Akoko	2	3	-	-	3	-	3	42	36	N	N	4	Y	-	1	1-4,8-9	5	53	48	8	-
8	Community High School Iborona	2	6	12	48	32	12	24	120	120	N	N	6	Y	1,5	1	1-5,7-9	5	114	124	7	2

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 38 Contd

AKOKO NORTH EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Agbaode/ Orimolade Grammar School, Ikare	2	15	-	14	14	14	13	400	400	Y	N	3	Y	2	1,2	1-6,8,9	1	220	202	32	33
2	Agboriki Comp. High School, Ikare	2	15	2	9	15	15	13	200	200	Y	N	1,2,3	N	-	1	1-9	5	259	252	17	8
3	Agolo High Ikare	2	9	-	-	9	-	9	409	409	Y	N	1,2,3	N	1	1,2,4	1,2,4,5,6,8-10	5	-	-	5	12
4	Akunu Grammar School, Akunu Akoko	3	4	3	3	3	3	3	300	300	N	N	1,2,3	N	5	1,2,4	1-6,8,9	3	103	106	7	1
5	Ansar ud Deen Grammar School, Ikare	2	9	7	9	19	4	9	150	242	Y	Y	1-3,6	Y	1,3,5	1,2	1,2,4,6,8,9	1	223	189	13	5
6	Auga Community Grammar School	2	6	-	-	24	3	12	130	352	N	N	1,2,3	N	1	1,2,4	2-6,8-10	1	138	84	6	1
7	Ayegbe Comp. High School, Ise Akoko	2	3	-	-	-	-	-	100	100	Y	N	1,2,3	Y	1,4,5	1,2	1-9	5	110	97	8	-
8	Community High School Iboropa	2	7	14	56	56	5	-	100	196	Y	N	3	-	1,5	1,4	1-5,8,9	5	106	96	10	2

KEY

(B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

(M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

(O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

(P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

(Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

(R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 38 Contd

AKOKO NORTH EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
9	Comprehensive High School, Ikare	2	9	6	6	10	6	10	545	545	Y	Y	1,2,3	N	-	1,2	2-4,8-9	1	189	197	14	10
10	Ikare Grammar School, Ikare	2	12	-	7	28	13	44	200	100	Y	N	2,3	Y	5	1,2,4	1-6,8,9	1	226	239	16	8
11	Lennon Road Ikare Akoko	1	16	16	-	64	12	18	325	325	Y	N	2,5	N	1,5,6	1,2	1,4,5,6	1	225	342	19	10
12	Mount Armel Girls Sech. Ikare	2	12	6	5	12	5	12	200	200	Y	Y	1-6	Y	1,3,5	1,2,3,4	1-9	1,2	-	442	16	12
13	Osele High School Ikare	2	8	-	-	8	-	8	230	230	Y	N	1,2,3	Y	-	1,2	2-9	5	224	256	12	6
14	Ugbe Community High School Ise Akoko	2	4	2	8	8	2	4	100	100	Y	N	-	Y	1,5	1	1-6,8,9	3	134	143	10	9
15	Victory College Ikare	2	18	-	-	-	-	50	418	280	Y	N	1,2,3	N	4,5	1,2,4	1,2,4,6,8,9	1	718	-	22	8
16	Irepodun comp. High Sch. Ikakumo Akoko	2	6	-	6	24	6	12	240	240	N	N	1,2,3	N	1	1,2	1-10	2	52	42	13	0

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		



TABLE 39

**AKOKO NORTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	Local Authority, Ikaram	2	14
2	Local Authority, Primary School, Ajowa	3	13	7	36	47	13	12	312	312	N	-	Y	1,3,5	1	1-5	1	755	661	20	11
3	Moslem Primary School, Ajowa	2	8	4	20	18	4	8	200	200	N	-	Y	1,3	1	1-5	1	245	243	3	5
4	L. A. Primary School Igasi-Akoko	2	7	7	30	56	2	1	160	160	N	-	N	5	1	1-5	5	74	86	7	2
5	Ansar Ud Deen Primary School Ajowa	3	6	-	36	36	-	16	268	268	N	-	Y	1,3,6	1	1-5	1	155	112	5	4
6	Moslem Primary School, Ikaram	2	7	2	8	18	2	8	200	234	N	-	Y	-	1	1-5	1	73	90	2	8
7	Baptist Day School, Eriti-Akoko	1	7	-	-	-	-	-	210	200	N	-	N	5	1,4	1-5	5	170	174	4	3
8	United Ang. Primary School, Ajowa	2	12	10	40	32	6	10	650	700	N	-	Y	1,3	1	1-5	1	262	298	4	13
9	United Anglican School, Ikaram/Ibaram	2	11	-	12	12	-	-	774	774	N	-	Y	3,6	1	1-5	1	311	284	5	6
10	St. Paul's Ang. School, Iyoke Ikaram	2	12	-	6	17	-	2	250	250	N	-	N	1,3	1,4	1-5	1	237	230	14	17

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 39 Contd

**AKOKO NORTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
11	St. Paul's Ang. Primary School, Gedegede	2	12	3	48	48	3	3	312	312	N	-	Y	1,3	1	1-5	1	160	172	3	5
12	Community Primary School Ikaram	3	6	-	-	-	-	-	270	270	N	-	Y	1,3	1	1-5	1	248	263	2	7
13	Community Primary School Ajowa-Akoko	2	6	2	20	8	2	4	220	220	N	-	Y	1,3,5	1,2	1-5	1	130	123	6	5
14	St. Jame's Ang. Primary School Ikaram	2	6	-	-	-	-	-	300	300	N	-	Y	1,3	1	1-5	1	125	104	6	5
15	Baptist Day Primary School, Erusu	1	12	-	-	-	-	-	512	512	N	-	Y	1,3,5	1	1-5	1	112	124	2	10
16	St. Thomas Ang. Primary School. Erusu	2	18	-	-	-	-	-	1128	736	N	-	Y	1,3,5,6	1,4	1-5	1	265	390	7	16
17	St. John's A?C Primary School Erusu	2	8	4	30	4	-	4	240	244	N	-	Y	1,3	1	1-5	1	270	320	5	9
18	L. A. Primary School, Surulere-Irun-Akoko	3	6	3	10	14	3		154	154	N	-	N	1	1	1-5	5	76	78	3	0
19	St. Luke's Anglican Primary School 'C' Irun	1	8	4	20	24	8	10	416	416	N	-	N	1,5		1-5	5	692	717	3	7
20	Ansar-Un-Deen Primary School Afin-Akoko	3	10	2	24	24	2	14	120	120	N	-	N	6	-	1-5	5	630	625	4	5

**KEY**

<p>(B) NATURE OF BUILDING:</p> <p>Mud 1</p> <p>Cement/Burnt Brick 2</p> <p>Both 3</p> <p>Others 4</p>	<p>(N) HEALTH/WATER/SANITATION FACILITIES:</p> <p>1 Wash Hand Basin</p> <p>2 Pipe Borne Water</p> <p>3 Bore Hole</p> <p>4 Protected Well</p> <p>5 VIP/Traditional Pit Latrine</p> <p>6 Water Closet</p>	<p>(O) RECREATIONAL FACILITIES</p> <p>1 Play Ground</p> <p>2 School Hall</p> <p>3 Table Tennis Court</p> <p>4 Food Vendor/Canteen</p> <p>5 Swimming Pool</p>	<p>6 (Q) SOURCE OF ELECTRIC POWER</p> <p>1 PHCN</p> <p>2 Generator</p> <p>3 PHCN/Generator/</p> <p>4 Solar</p> <p>5 None</p>	<p>1 Other 6</p> <p>2</p> <p>3</p> <p>4</p> <p>5</p>
---	---	--	--	--

TABLE 39 Contd

**AKOKO NORTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
21	A.U.D Primary School, Ogbagi Akoko	2	10	17	30	26	17	17	322	322	N	-	Y	4,6	1	1-5	1	432	446	17	40
22	Moslem Primary School, Irun-Akoko	2	11	-	-	-	-	-	940	880	N	-	N	1,6	1	1-5	5	705	816	5	5
23	Community Primary School, Afin	2	2	8	20	30	4	15	300	300	N	-	N	1,3,5	1	1-5	5	123	93	3	4
24	The Salvation Army Pny, School, Ogbagi-Akoko	3	8	2	26	18	12	14	240	240	N	-	N	1,4	1,4	1-5	5	164	212	6	8
25	St. John's Ang. Primary School Ese-Akoko	3	18	10	30	24	10	10	452	452	N	-	N	1,4,6	1	1-5	5	381	394	9	2
26	St. Bebedict's Cath. Primary School, Irun	3	14	8	14	14	2		1336	1336	N	-	Y	5,6	1	1-5		638	698	10	12
27	St. George's C.A.C. School, Ogbagi	3	18	12	32	20	10	19	320	320	N	-	Y	6	1	1-5	5	249	314	4	13
28	St. John's Ang. Primary School, Ogbagi	3	19	7	30	20	13	10	700	700	N	-	Y	1,5	2	1-5	1	353	410	6	10
29	Our Savior's Primary School, Ogbagi	3	8	8	26	36	8	8	360	360	N	-	N	1,4,6	1	1-5	5	282	265	2	8
30	St. Luke's Ang. Primary School (A) Irun-Akoko	3	7	-	32	28	-	9	420	450	Y	-	N	1,3,6	1	1-5	3	260	270	7	5

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6	
(P)	<b>SCHOOL RECORDS</b>			(Q)	<b>SOURCE OF ELECTRIC POWER</b>
	Admission Register	1		PHCN	1 Other
	Attendance Register	2		Generator	2
	Syllabus/Plan of Work	3		PHCN/Generator/	3
	Supervision Book	4		Solar	4
	Visitors Book	5		None	5

TABLE 39 Contd

**AKOKO NORTH WEST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		31	St. Luke's Anglican School 'B' Irun-Akoko	3	9
32	Community Primary School Ogbagi-Akoko	2	7	1	-	20	3	10	992	992	N	-	N	1	1	1-5	5	674	634	4	6
33	St. Peter's C.A.C. Primary School Irun-Akoko	2	7	5	32	32	4	16	1000	1000	N	-	N	1,3,6	1	1-5	5	762	676	7	7
34	Community Primary School Irun-Akoko	3	6	2	20	16	2	16	320	320	N	-	N	1,5	1	1-5	1	437	434	4	2
35	LA. Primary School, Okeagbe-Akoko	2	8	3	-	-	-	4	196	202	N	-		6	1	1-5	5	164	169	3	6
36	A.U.D.Primary School Okeagbe-Akoko	2	8	2	10	20	4	4	94	86	N	-	N	1	1	1-5	-	104	143	6	3
37	Ansar-Ud Deen Primary School, Oyin-Akoko	1	5	-	10	-	-	-	430	430	N	-	N	-	1,4	1-5	5	411	423	2	5
38	A.U.D. Primary School Arigidi-Akoko	2	6	-	-	-	-	-	83	84	Y	N	Y	1,4	1	1-5	5	143	133	2	11
39	Baptist Day Primary School, Arigidi-Akoko	3	8	8	32	32	8	16	152	150	N	-	N	1	1	1-5	5	154	167	1	13
40	Baptist Day Primary School, Oyin-Akoko	2	6	-	16	-	-	-	240	240	N	-	N	6	1	1-5	5	237	235	4	5

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
(P)	<b>SCHOOL RECORDS</b>		Water Closet	6	(Q) <b>SOURCE OF ELECTRIC POWER</b>
	Admission Register	1		PHCN	1 Other
	Attendance Register	2		Generator	2
	Syllabus/Plan of Work	3		PHCN/Generator/	3
	Supervision Book	4		Solar	4
	Visitors Book	5		None	5

TABLE 39 Contd

AKOKO NORTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
41	Holy Rosary R.C.M. School Iye-Akoko	2	6	6	24	24	6	12	168	168	N	-	N	4	1	1-5	5	119	167	2	11
42	Christ Anglican Primary School, Iye-Akoko	2	9	-	16	5	3	1	80	80	N	-	N		1	1-5	5	106	113	5	8
43	St. Paul's Anglican Primary School, Arigidi-Akoko	2	5	16	64	64	16	32	300	300	N	-	N	1,4	1,4	1-5	5	385	404	4	15
44	St. Jame's Ang. School, Arigidi Akoko	2	9	2	24	-	-	6	600	700	N	-	Y	1,6	1	1-5	5	395	361	5	21
45	St. George's Ang. Primary School Okeagbe	2	11	5	14	10	5	5	420	420	Y	N	N	1,2,4,6	1,4	1-5	1	943	927	7	12
46	St. Theresas Catholic Pry Sch, Okeagbe-Akoko	1	10	4	30	-	-	16	184	280	N	-	N	1,3	1	1-5	5	115	120		
47	St. John's Ang Primary School Oyin-Akoko	2	3	-	24	44	6	15	126	118	N	-	N	-	1	1-5	5	452	515	2	6
48	St. Matthew C.A.C. School, Oyin-Akoko	2	9	4	20	18	4	2	700	700	N	-	Y	1	1	1-5	2	207	264	4	14
49	St. Stephen's Primary School, Imo Arigidi Akoko	3	8	0	12	28	7	14	882	899	N	-	Y	1,6	1	1-5	3	615	661	2	16
50	St. Jame's C.A.C Primary School, Imo Arigidi-Akoko	2	7	-	-	-	-		492	492	N	-	N	1	1	1-5	5	562	587	3	14

KEY

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
			Water Closet	6		
(P)	SCHOOL RECORDS			(Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 39 Contd

**AKOKO NORTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		51	Community Primary School, Agbaluku Arigidi-Akoko	3	11
52	Ifesowapo Community Primary School, Arigidi	3	16	2	-	-	-	10	300	312	N	-	Y	1,6	1	1-5, 8, 9	5	110	123	1	11
53	St. Moses Orimolade Pry Sch Okeagbe	1	11	-	44	-	-	-	400	400	N	-	N	1	1	1-5, 8, 9	5	130	136	3	11
54	St. Micheal's Ang. Primary School Arigidi-Akoko	3	7	6	24	24	6	12	244	244	N	-	N	1,6	1	1-5, 8, 9		236	244	3	26
55	Community Primary School. Ese-Akoko	2	14	-	-	-	-	-	150	150	N	-	N	1,4,6		1-5, 8, 9		457	421	2	5
56	Ansarul Islam Afin-Akoko	2	6	-	-	-	-	-	88	88	N	-	N	5	1	1-5, 8, 9	5	158	176	4	2

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
(P)	<b>SCHOOL RECORDS</b>		Water Closet	6 (Q)	<b>SOURCE OF ELECTRIC POWER</b>
	Admission Register	1		PHCN	1 Other
	Attendance Register	2		Generator	2
	Syllabus/Plan of Work	3		PHCN/Generator/	3
	Supervision Book	4		Solar	4
	Visitors Book	5		None	5

TABLE 40

AKOKO NORTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Adougbo Grammar School, Afin-Akoko	3	14	4	18	22	4	6	250	250	Y	N	4,5	Y	1,5	1-3	1-9	1	122	119	6	6
2	Ahmadiyya G/S, Ogbagi-Akoko	2	12	-	-	-	-	-	360	360	N	N	-	Y	6	1,2,4	2-5,8,9	1	289	260	7	5
3	Ajowa Comm. Grammar School, Ajowa Akoko	2	8	-	7	9	-	9	120	120	Y	N	4	Y	-	1,2,4	2-5,8,9	1,2	190	153	6	3
4	Ajuroke Tech High School, Arigidi-Akoko	2	6	7	28	28	7	14	360	360	Y	N	4	Y	4,5	2	1-6,8,9	1	105	103	4	14
5	Ajuta High School, Ogbagi-Akoko	3	6	4	4	4	4	4	150	148	Y	Y		N	5	1,2,4	1-6,8,9	3	230	232	9	3
6	Ajuwa Grammar School, Okeagbe	2	11	-	10	40	-	20	322	322	Y	Y	1-3	N	1,4,5	1,2,4,5	1-7,8,9	1	236	216	8	14
7	Akoko Anglican G/S, Arigidi-Akoko	3	10	2	8	32	8	11	360	360	N	N	-	Y	5,6	1	1-4, 6, 8,9	1	305	289	20	21
8	Anglican Grammar School, Irun/Ogbagi-Akoko	3	6	8	-	8	-	8	240	240	Y	Y	-	Y	1,4	1,4	1-10	5	48	30	7	5
9	Comm C.H.S., Ikara-Akoko	2	6	-	18	20	-	10	370	370	Y	N	4	N	1,2	1,2	1-6,8,9	1	183	131	7	6
10	Comprehensive High School Ajowa-Akoko	2	5	-	19	18	-	12	120	120	Y	N	4	Y	4	1,2,4	2-5,8,9	5	120	110	5	-

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 40 Contd

AKOKO NORTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Comprehensive High School, Erusu	2	6	5	10	16	1	10	210	210	N	N	-	Y	4,5	1,2	1-5,8,9	1	100	88	13	15
12	Comprehensive High School, Igashi-Eriti	3	6	-	3	3	3	1	240	240	N	N	-	Y	5	1	2-5,8,9	1	70	35	6	1
13	Eyo-Oke High School, Oyin	2	10	-	-	-	-	-	120	120	Y	N	-	Y	3,6	1,2,4	2-10	1	107	101		
14	Ilemopo High School, Irun-Akoko	3	6	-	1	7	2	4	41	120	N	N	-	N	1,5	1,2,4	2-5,8,9	1	183	172	7	1
15	Irepodun C.H.S, Irun- Akoko	2	6	2	-	16	4	8	120	120	Y	N	-	N	1	1,2,4	1-6,8,9	5	130	106	1	7
16	Iyamoye C.H.S, Ese	2	6	-	4	2	-	6	120	120	Y	N	6	Y	1	1,2	1-6,8,9	1	99	91	5	3
17	Okeagbe High School, Oke Agbe-Akoko	3	4	5	20	20	5	10	230	230	N	N	-	Y	6	1,4	1-5,8-10	1	118	157	6	4
18	Okota High School, Arigidi-Akoko	2	9	5	36	17	-	18	152	203	Y	N	4	Y	1,4	1,4	1-6,8,9	1	131	136	6	13
19	Omolore High School, Irun-Akoko	3	6	-	-	-	-	-	632	632	N	N	4	Y	1	1	2-4,8-10	1	111	103	3	1
20	Otolomi High School, Ikaram-Akoko	3	6	3	24	12	6	6	80	85	N	N	-	N	1	1,2	1-6,8-10	5	67	73	7	3

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		



TABLE 40 Contd

AKOKO NORTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Adougbo Grammar School, Afin-Akoko	2	6	7	16	32	-	7	280	300	Y	N	1-3	N	1,4,5	1-4	1-5,8,9	1	185	183	12	-
2	Ahmadiyya G/S, Ogbagi-Akoko	3	12	4	24	19	9	12	320	320	Y	N	2,3	Y	1,5	1,2,4	1-10	1,3,4	274	315	17	4
3	Ajowa Comm. Grammar School, Ajowa Akoko	2	9	4	4	4	4	8	240	240	Y	N	1-3,6	Y	-	1,2	1-6,8-10	1	106	85	9	1
4	Ajuroke Tech High School, Arigidi-Akoko	2	6	-	12	16	-	8	180	180	Y	N	1-3	N	1,4	1,2,4	1-6,8,9	1	96	98	5	9
5	Ajuta High School, Ogbagi-Akoko	3	4	-	24	24	6	6	120	120	Y	N	1-3	Y	1,5	1,2,4	1-6,8,9	3	270	333	15	2
6	Ajuwa Grammar School, Okeagbe	2	10	9	24	36	8	24	360	360	Y	N	1-3	Y	1,4,5	1,2,4,5	1-10	1	218	194	13	6
7	Akoko Anglican G/S, Arigidi-Akoko	2	13	-	-	-	-	20	400	400	Y	N	1-3	Y	1,4,5,6	1,2	1-6,8,9	1	272	248	14	13
8	Anglican Grammar School, Irun/Ogbagi-Akoko	2	8	-	-	-	-	-	240	240	Y	Y	1-4	N	4	1,2	1-9	1	113	102	11	4
9	Comm C.H.S., Ikara-Akoko	2	5	-	-	14	-	12	350	350	N	N	1-3	N	-	1,2	1-6,8-10	1	145	129	17	-
10	Comprehensive High School Ajowa-Akoko	2	7	5	18	20	5	10	120	120	Y	N	1-3	N	1,4	1,2	1-6,8-10	5	136	124	7	1

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 40 Contd

AKOKO NORTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Comprehensive High School, Erusu	2	5	2	12	20	4	12	164	109	Y	N	1-3	Y	1,4,5	1,2,4	1-9	1	157	144	12	4
12	Comprehensive High School, Igashi-Eriti	3	3	3	16	9	6	2	240	240	N	N	1,2	Y	1,4,5	1	2,,4,5,8,9	1	182	114	8	2
13	Eyo-Oke High School, Oyin	2	12	6	18	10	10	10	230	230	Y	N	1-3	Y	3	1,2	1-10	3	110	121	9	2
14	Ilemopo High School, Irun-Akoko	2	2	3	12	6	-	6	153	153	Y	N	1-3	Y	1,4,5	1,2	1-67,8,9	3	133	111	9	6
15	Irepodun C.H.S, Irun- Akoko	2	4	6	24	24	6	6	200	200	N	N	-	N	1	2	2-5,8,9	3	129	137	8	2
16	Iyamoye C.H.S, Ese	1	6	-	24	-	6	6	110	89	Y	N	1-3	Y	1,4,5	1,2	1-5,7-9	1	124	91	4	4
17	Okeagbe High School, Oke Agbe-Akoko	3	11	5	-	18	-	6	240	240	N	Y	1-3	Y	1,4,5	1,2,4	1-5,7-9	1	71	84	9	4
18	Okota High School, Arigidi-Akoko	2	9	6	-	48	6	24	226	226	Y	N	1-3,6	Y	4	1,2	2-5,8,9	5	200	223	17	11
19	Omolore High School, Irun-Akoko	2	3	4	40	20	-	10	200	200	N	N	-	Y	1,4	1	1-6,8-10	1	124	118	10	-
20	Otolomi High School, Ikaram-Akoko	2	6	4	-	2	3	6	60	60	N	N	4	N	1,5	1,2,4	1-9	5	78	89	12	1

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 41

AKOKO SOUTH EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	Alao Ademua Memorial Model School Isua	2	10
2	C.A.C. Muslem United School Epinmi -Akoko	2	8	3	12	12	3	6	336	336	N	N	N	8'-10	1	1-5,8-10	5	175	193	5	12
3	Com. Demonstration Pry Schl Epinmi	3	7	5	20	20	5	10	240	240	N	N	N	2, 5,9	1	2-5,9	5	51	42	4	10
4	Ebenezer A/C Primary School Isua -Akoko	2	8	4	28	32	6	16	98	98	N	N	N	8'-10	1	1-5,8-10	5	150	127	6	7
5	Everlasting Rock A/C Pry Sch Epinmi Akoko	3	14	-	-	-	-	-	370	384	Y	N	N	1,6,8,10	1	1-6,8-10	5	252	253	5	10
6	Jehovah Jire A/C School Epinmi-Akoko	3	7	4	16	8	-	6	300	300	Y	N	N	1,6,8,9	1	1-6,8-9	5	356	428	2	10
7	L.A Primary School II, Isua	3	15	-	-	-	-	8	240	240	N	N	Y	1,5,8,10	1	1-3,5,8,10	5	156	138	2	11
8	Local Authoprity Primary I Isua	2	16	6	24	6	9	12	564	660	N	N	N	1	1	1-5,8,9	5	111	119	4	10
9	Local Authority Primary School Ifira-Akoko	2	12	-	-	-	-	-	260	260	N	N	N	1,5	1	2-5,8-9	5	233	199	10	6
10	St Andrew's Ang. Primary School Sosan	2	6	-	-	6	3	4	600	300	N	N	N	1,3,5	1	1-5,7-10	5	286	300	4	-

**KEY**

(B) NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
Mud	1	Wash Hand Basin	1	Play Ground
Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
Both	3	Bore Hole	3	Table Tennis Court
Others	4	Protected Well	4	Food Vendor/Canteen
		VIP/Traditional Pit Latrine	5	Swimming Pool
(P) SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER
Admission Register	1			PHCN
Attendance Register	2			Generator
Syllabus/Plan of Work	3			PHCN/Generator/
Supervision Book	4			Solar
Visitors Book	5			None
				1 Other
				2
				3
				4
				5
				6

TABLE 41 Contd

AKOKO SOUTH EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	St. Andrew's A/C Pry Schl Ipe-Akoko	2	15
12	St. James R C M . Pry Schl Ipe Akoko	3	15	3	12	12	1	2	280	280	N	N	N	1,6	1	2-5,8-10	5	532	535	2	7
13	St. John A/C School Ipe -Akoko	3	14	4	16	14	3	6	520	520	Y	Y	Y	1,3,5	1,3	1-6,8,9	1	240	252	8	6
14	St. John's Ang. Primary School Ipesi-Akoko	2	16	4	16	40	7	14	140	140	N	N	N	1,3,5	1	2-5,8-9	5	116	91	15	5
15	St. Joseph's Rcm School, Isua-Akoko	3	13	-	-	44	-	14	210	210	Y	Y	Y	1,6	1	2-6,8-9	3	133	120	6	18
16	St. Michael's A/C School Isua	1	4	-	-	16	4	8	60	60	N	N	N	5	1	2-5,8-10	5	34	30	2	6
17	St. Michael's Anglican Primary School Ipe	3	22	-	-	32	-	20	900	900	Y	N	N	1,5	1	2-5,8-10	3	522	597	5	18
18	St. Patrick Ang. Primary School Isua-Akoko	2	14	4	16	16	7	8	310	310	N	N	Y	1,4,6	1	1-5,7-9	5	116	135	3	13
19	St. Peter's Ang. Primary School Ifira	2	10	2	16	16	-	-	230	230	N	N	N	1,4,6	1	1-5,7-9	5	168	169	6	6
20	St. Peter's C.A.C. Primary. Sosan	3	6	2	8	8	2	4	200	200	N	N	N	1,3	1	1-5,8-10	5	45	52	5	2

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

**70**

TABLE 41 Contd

**AKOKO SOUTH EAST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		21	St. Rcm School Ipesi	2	10
22	United C.A.C. Primary School Ifira-Akoko	2	12	-	-	17	-	-	181	169	N	N	N	1,5		1-5,8-9	5	104	105	7	16
23	Zumra Tul Islamnyan Pry Schl Ifira-Akoko	1	7	-	-	-	2	-	160	160	N	N	N	1	1	1-5,8-9	5	68	60	2	9

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	<b>SCHOOL RECORDS</b>		Water Closet	6 (Q)	<b>SOURCE OF ELECTRIC POWER</b>		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 42

AKOKO SOUTH EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	A/C Unity Secondary Sch. Epinmi	2	6	3	16	24	3	12	150	150	Y	Y	1-6	Y	3, 5	1,2,3,	1'-10	3	72	53	10	4
2	Communiity Grammar School Ifira Akoko	2	8	-	-	60	7	28	480	480	N	N	4	Y	1	1,2,4	2-5,8,9,	1	232	163	14	3
3	Isua Community Grammar School Isua	2	4	12	48	48	-	24	120	154	N	N	N	Y	1	1,4,	2-,5,8,9,	1	183	125	7	3
4	Ipe Junior High School Ipe Akoko	1	3	4	16	24	3	12	360	360	Y	N	N	Y	1, 4	1	1-5,8-10	1	188	170	8	6
5	Isua High School, Isua	2	8	-	12	12	3	6	80	80	N	N	N	Y	5	1,2,4,	1-5,7,9,10,	3	175	163	8	4
6	Obaahoho Comp. High Sch Epinmi	1	5	5	20	20	5	10	150	150	Y	N	N	N	1	1,2,4	2-6	1	176	183	7	5
7	Omuroko Community High School Ipesi	2	6	6	24	24	6	12	110	120	N	N	N	Y	1	1	1,2,3,4,5,8,9,	1	88	75	4	4
8	Awodua Gram. Sch, Ipe, Akoko	2	10	4	16	16	4	8	300	300	Y	n	N	Y	1,2,5	4	2,4,5,8,9	2	120	90	8	5

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 42 Contd

AKOKO SOUTH EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	A/C Unity Secondary Sch. Epinmi	2	8	12	40	72	12	36	100	100	Y	N	1-5	Y	3, 5	3,5	2-4,6-9	1	65	88	16	4
2	Awodua Gram. Sch. Ipe Akoko	2	7	8	12	44	3	22	300	300	N	N	-	Y	1, 5	-	1-10	2	43	39	8	6
3	Communiity Grammar School Ifira Akoko	2	8	6	24	40	1	20	392	392	Y	N	1-3	Y	1	1,2,4	1-10	3	206	206	18	2
4	Isua Community Grammar School Isua	1	4	-	16	16	-	8	80	80	N	N	1, 2	N	4	N	2-5,8,9,	1	166	174	8	3
5	Ipe High School Ipe Akoko	2	9	-	-	36	-	18	350	350	Y	N	1,2,3,6	Y	1	1,2,3,4	1-6,8,9	1	172	149	15	4
6	Isua Senior High School Isua Akoko	2	9	7	28	28	7	14	150	150	N	N	2	Y	-	1,2,4	1,-5,7-10	1	129	175	17	8
7	Obaahoho Comp. High Sch Epinmi	2	6	-	-	24	-	12	120	120	N	Y	2	N	1,4,5	1,2,4	1-6,8,9,	3	91	95	11	6
8	Omuroko Community High School Ipesi	2	4	2	8	16	4	8	122	122	Y	N	1,2,3	N	5	1,2,	1-6,8,9,	5	76	86	11	1

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 43

**AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	A.C/C.A.C. United School Akungba Akoko	2	21
2	A.U.D Pry. School, Ibaka-Oka	1	7	3	12	24	4	11	200	200	Y	N	Y	1,5	1,3	1-6,8,9	5	8	8	16	16
3	Comm. Primary School Supare- Akoko	2	6	6	24	24	1	8	172	172	N	N	Y	1	1	1-5, 8,-10	5	458	456	6	3
4	Baptist Day School Oba-Akoko	2	9	6	24	24	6	12	216	216	Y	N	Y	1,5,6	1	1- 6, 8,-10	3	434	438	14	14
5	Christ Anglican Pry. School Akungba Akoko	2	12	6	24	24	6	12	528	432	N	N	Y	1,3,6	-	1- 6, 8,-10	1	400	412	9	14
6	Comm. Primary School Ikanmu Oka	2	4	8	32	48	48	14	100	100	N	N	Y	1,3,5,	1	1-5, 7-9	5	474	484	11	10
7	Comm. Pry. Sch. Korowa Oka Akoko	1	4	3	8	24	4	12	80	80	N	N	Y	1	1	1,-5, 8, 9	5	88	94	7	3
8	Comm. U.P.E School, Oba	2	9	7	28	13	10	20	172	172	Y	N	Y	1,5	1, 2	1,2,3,4,5,7,8,9	1	261	200	7	14
9	Comm. Pry. School Ayepe Iwaro Oka Akoko	3	6	-	-	-	3	-	102	102	N	N	Y	1	1	1,2,3,4,5,8,9,10	5	63	62	4,	10
10	Comm. Pry. School Igboegun Supare	2	5	3	-	20	2	3	84	68	N	N	Y	1	1	1,2,3,4,5,8,9	5	85	93	8	-

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6 (Q)	SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5



TABLE 43 Contd

**AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
11	Comm. Pry. School, Ago-Ajayi Oba-Akoko	2	4	-	-	-	-	-	166	166	N	N	-	1	1	1-6,8,9,10	5	125	146	7	2
12	Ebenezer A/C School Oka Akoko	1	13	-	2	8	2	4	200	100	Y	N	Y	1,4,5,6	1	1-6,8,9,10	5	317	351	2	12
13	Holy Trinity Ang. Pry Sch. Akungba Akoko	2	5	6	24	24	9	18	223	116	N	N	Y	1,5	1	1,2,3,4,5,8,9,10	5	183	144	5	16
14	Holy Trinity Ang. Pry. Sch Iwaro Oka- Akoko	3	7	4	16	16	7	8	204	204	N	N	Y	1	1	1,2,3,4,5,8,9,10	5	266	306	8	11
15	Holy Trinity Pry. School. Ikun Akoko	2	11	3	8	12	2	4	217	224	Y	N	Y	1	-	1-5, 8-10	3	122	127	5	2
16	L.A School Ose Oba Akoko	2	12	-	12	12	3	8	31	442	N	N	Y	3	1,4	1-5,8,9	5	384	360	11	2
17	L.A. School Ii, Iwaro-Oka-Akoko	3	17	8	32	36	10	24	240	240	N	N	Y	1	1,5	1-5, 8, 9, 10	5	366	347	7	16
18	L.A. School Iwaro-Oka-Akoko	2	17	15	60	60	17	17	500	500	Y	N	Y	1	1,5	1-5, 8, 9	5	211	292	6	17
19	Muslim Pry School Egunre Street. Epinmi	3	9	-	12	36	3	6	224	222	Y	N	Y	1	1	1-5, 8-10	1	454	460	7	3
20	Owalusin Comm. Pry Sch. Iwaro Oka- Akoko	2	6	6	24	24	-	12	122	134	N	N	Y	1	1	1-5, 8,9	1	127	121	5	11

**KEY****(B) NATURE OF BUILDING:**

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

**(P) SCHOOL RECORDS**

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

**(N) HEALTH/WATER/SANITATION FACILITIES:**

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6 (Q)

**(O) RECREATIONAL FACILITIES**

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

**6 (Q) SOURCE OF ELECTRIC POWER**

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 43 Contd

**AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
21	Saint Peter's R.C.M Iwaro Oka	2	8	8	32	56	14	28	86	86	N	N	Y	1	1	1-5,8,9	5	288	273	11	13
22	Saviour's A.C Pry School Oka Akoko	3	11	9	36	80	20	28	324	324	Y	N	Y	-	1	1-4, 8, 9, 10	1	328	297	10	13
23	St Peter's C.A.C Primary School, Ikun, Akoko	2	12	-	-	24	3	12	316	316	N	N	Y	1,3	1	1-5, 8, 9	5	167	161	9	4
24	St. Mary's Catholic School, Oka- Akoko	2	11	5	8	14	4	-	360	360	N	N	N	5	1	1-5, 8, 9	5	472	463	8	17
25	St. Andrew's A/C School Ibaka Oka	1	4	2	8	20	-	10	166	160	N	N	Y	-	1	1-5, 8, 9	5	111	114	4	11
26	St. Anthony's R.C.M. Ayegunle Oka	3	6	-	-	8	-	4	176	184	N	N	Y	5	-	2-5, 8, 9	5	122	183	5	6
27	St. Clara's R.C.M. Pry School Iwaro- Oka	2	12	-	36	-	-	15	360	350	Y	N	Y	5	1	1,2,5,8,9	5	336	348	15	12
28	St. Davids A/C Primary School Okia, Oka- Akoko	1	10	3	12	10	5	10	195	195	N	N	N	5	1	2-6,8,9	5	192	237	8	1
29	St. John's Ang. Pry. School Ikese Oka	3	14	12	-	28	12	14	260	260	N	N	N	1	1	1-5, 8, 9	5	306	289	11	11
30	St. Joseph's C.A.C Pry Schl. Korowa Qurts Oka Akoko	3	26	5	8	4	-	-	618	618	N	N	Y	1,5	-	1-5, 8, 9, 10	5	368	312	7	17

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>			
	Mud	1	Wash Hand Basin	1	Play Ground	1		
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2		
	Both	3	Bore Hole	3	Table Tennis Court	3		
	Others	4	Protected Well	4	Food Vendor/Canteen	4		
			VIP/Traditional Pit Latrine	5	Swimming Pool	5		
			Water Closet	6				
(P)	<b>SCHOOL RECORDS</b>			(Q)	<b>SOURCE OF ELECTRIC POWER</b>			
	Admission Register	1			PHCN	1	Other	6
	Attendance Register	2			Generator	2		
	Syllabus/Plan of Work	3			PHCN/Generator/	3		
	Supervision Book	4			Solar	4		
	Visitors Book	5			None	5		

TABLE 43 Contd

**AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		31	St. Joseph's R.C.M Pry School Uba-Oka Akoko	1	8
32	St. Luke A/C Pry Sch, Abulenla Supare	1	9	-	-	-	-	-	90	90	N	N	Y	3	1	1-5, 8, 9	5	105	131	6	2
33	St. Luke's Anglican Pry. Sch. Ayegunle Oka- Akoko	1	6	-	40	40	3	20	102	102	N	N	Y	-	1	1,2,3,4,8,9	5	119	125	3	7
34	St. Mark's A/C School, Ibaka Oka	3	7	3	4	24	5	12	207	194	N	N	Y	1,5	-	1-5, 8, 9, 10	5	83	107	3	14
35	St. Micheal's School Iwaro-Oka	3	12	7	12	20	7	14	450	420	Y	Y	Y	1	1	1-6, 8, 9, 10	5	477	526	9	8
36	St. Patrick's R.C.M Primary School, Ebinrin Quarter Oka	3	7	4	16	36	-	18	27	20	Y	N	Y	1,3	1	2-5, 8, 9	5	154	186	5	9
37	St. Peter's Pry School Oba- Akoko	3	8	12	72	72	6	36	84	114	N	-	Y	1	1	1,2,3,4,5,8,9	5	220	210	5	6
38	St. Plus R.C.M. School Agba-Oka	3	14	-	20	24	12	26	864	864	N	-	Y	1,4	1	2-5, 8, 9, 10	5	481	446	8	23
39	St. Matthew's Ang School, Oka	1	6	-	-	-	-	-	154	154	N	N	N	-	-	2, 3, 4, 8, 9	5	168	197	9	16
40	Z.I. Primary School Ikana Quarters, Iku, Akoko	3	8	-	-	-	3	-	124	128	N	-	Y	1,3	1	1-5,8,9	5	62	48	5	5

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6	
(P)	<b>SCHOOL RECORDS</b>			(Q)	<b>SOURCE OF ELECTRIC POWER</b>
	Admission Register	1		PHCN	1 Other
	Attendance Register	2		Generator	2
	Syllabus/Plan of Work	3		PHCN/Generator/	3
	Supervision Book	4		Solar	4
	Visitors Book	5		None	5
					6

TABLE 43 Contd

**AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
41	Z.I. Pry School Oba Akoko	2	10	-	-	28	-	14	309	299	N	N	Y	1,3,5	1	1-5, 8, 9, 10	1	211	212	4	7
42	Z.I. Pry. School, Ikese Oka-Akoko	3	6	6	24	24	6	12	418	422	N	-	Y	1,3,6	1	1-5, 8, 9	5	331	478	15	19
43	Christ Anglican Pry. School Supare Akoko	2	6	-	-	24	-	5	480	480	N	N	N	1,3	1	1-5, 8, 9	5	206	207	4	6
44	The Salvation Army Sch. Supare- Akoko	2	14	4	8	8	2	7	624	624	Y	Y	N	1,3	1	1-5, 8, 9, 10	5	344	330	10	8
45	Salvation Army Pry. Schl. Etioro	1	7	1	4	4	1	8	50	70	N	N	Y	1,3	1	2-4, 8, 9	5	122	100	5	4
46	A.U.D. Pri Sch. Akungba	1	10	4	-	40	4	12	160	360	Y	N	N	3,5	1	1-5, 8, 9	5	310	271	9	14
47	Comm. U.P.E. School, Akungba	3	6	6	24	26	6	12	808	808	Y	N	N	1	1	1-5, 8, 9, 10	5	348	355	5	19
48	Comm. Pry. School, Ibaka Oka	2	5	5	12	20	5	10	165	160	Y	N	N	1	1	1-6, 8, 9	5	152	160	5	10
49	Christ A/C Pri, Ibaka Oka	3	11	5	12	32	8	14	424	424	Y	N	N	1,4,5	2	1-5, 8, 9	5	328	297	7	18
50	St. Sylverius R.C.M. Pry Sch. Simerin Oka	1	6	5	20	20	5	12	400	400	N	N	Y	2,5	1	1-5, 8, 9	5	71	66	5	6

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6 (Q) SOURCE OF ELECTRIC POWER	
Admission Register 1	PHCN 1 Other 6	
Attendance Register 2	Generator 2	
Syllabus/Plan of Work 3	PHCN/Generator/ 3	
Supervision Book 4	Solar 4	
Visitors Book 5	None 5	

TABLE 43 Contd

AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
51	St. Jame's Ang. Pry, School Supare Akoko	3	13	5	8	16	2	12	266	260	Y	N	Y	1,3,5,6	1,4	1-5, 8,9	5	180	287	9	9

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6 (Q)	SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5

TABLE 44

AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	A.U.D Grammar School, Akungba Akoko	1	2	2	8	8	2	4	150	150	N	N	-	Y	1	1,2	1-5,8-10	5	151	100	10	4
2	African Church Grammar Sch, Oka-Akoko	2	14	-	32	56	14	28	250	250	Y	N	4,6	Y	1.6	1,2	1-5,6-10	3	434	515	13	20
3	Agbogbo Grammar School, Supare Akoko	3	9	9	36	36	9	18	249	249	Y	Y	4	Y	1,3,5	1-4	1-5,6-10	3	205	184	11	10
4	Ajagbakun High School Ikun Akoko	1	6	-	-	32	-	20	102	101	Y	N	-	Y	1,5	1,2,4	2-5,8-10	1	156	115	7	6
5	Ate Ikanmu Grammar School Oka Akoko	2	3	8	32	32	8	16	245	245	Y	N	-	Y	1	-	2-5,8,9	1	153	127	7	3
6	Ayegunle High School Aiyegunle Oka Akoko	1	4	10	24	40	6	20	108	144	Y	N	-	Y	1,5	1,2,4	1-6,8-10	3	143	114	11	11
7	Christ High Schl Ikanmu Oka Akoko	2	5	5	-	20	5	10	150	150	Y	N	-	Y	1	1,2	1-3,8,9	5	84	66	9	4
8	Comm. Comp. High School Akungba Akoko	1	6	4	-	16	0	8	120	115	Y	N	4	Y	1	1,2	1-3, 5, 6, 8, 9	1	132	130	8	15
9	Esedo Comp. High Schl Iwaro Oka	2	14	9	-	36	9	18	275	275	Y	N	-	Y		1,2	1-6, 8, 9	1	337	250	11	9
10	Ogoso High School Korowa Oka Akoko	2	10	-	-	-	-	-	130	120	Y	Y	4	Y	1,3,6	1,2,4	1-10	1	272	222	14	5

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 44 Contd

AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Ojomirin High School, Agba Oka Akoko	3	13	-	-	32	-	16	229	327	Y	Y	4	Y	1,6	1,2	2-6,9	1	292	276	8	8
12	Okeede Comm. High Schl. Supare Akoko	3	6	4	16	16	6	12	154	140	N	N	6	Y	1	1,2,4	1-5, 8, 9	3	214	218	9	7
13	Ola Oluwa Grammar Schl Oka Akoko	2	7	-	28	28	7	14	309	335	N	N	-	N	5	1,2	2-5,8,9	1	400	388	14	19
14	Oludaye Grammar School, Oba-Akoko	3	11	8	32	32	9	16	240	240	Y	N	4,5,6	Y	1,4	1-4	2-6, 8-10	1	193	235	9	11
15	Oroke High School Akungba Akoko	2	7	5	20	48	5	24	297	297	Y	N	4,5	Y	4,5	1,2	1-6, 8-10	3	277	286	7	17
16	St. Patricks College Iwaro-Oka	2	13	-	-	24	-	26	631	636	Y	N	4	Y	1,4,5	1	2-6, 8, 10	3	480	495	14	14
17	Oyinle High School, Oba Akoko	3	4	-	-	-	-	-	156	156	N	N	-	Y	1,3,5,6	1,2	2-6, 8, 10	1,2,4	107	119	11	5

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 44 Contd

AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	A.U.D Grammar School, Akungba Akoko	3	5	1	4	24	6	12	126	178	Y	N	6	N	1,4	1,2	2-5, 8,9	2	131	103	13	4
2	African Church Grammar Sch, Oka-Akoko	2	18	-	-	72	6	36	200	200	Y	N	1,2,3	Y	3,5	1,2	2-5, 8, 9	1	465	426	23	7
3	Agbogbo Grammar School, Supare Akoko	2	7	-	-	-	-	10	132	147	Y	N	1,2,3	Y	1,3,5	1,2,3,4	1-5, 8, 9	3	151	130	18	2
4	Ajagbakun High School Ikun Akoko	1	6	2	8	8	2	32	103	107	Y	N	6	Y	1,5	1,2,4	1-5, 8, 9	1	167	142	8	4
5	Ate Ikanmu Grammar School Oka Akoko	2	8	-	8	8	-	16	380	384	Y	N	6	N	1	1,2	1-5, 8, 9	1	191	160	13	4
6	Ayegunle High School Aiyegunle Oka Akoko	1	8	10	-	40	-	20	108	144	Y	N	6	Y	1,5	1,2,4	1-5, 8, 9	3	165	148	16	6
7	Christ High Schl Ikanmu Oka Akoko	1	6	-	-	-	-	-	242	242	Y	N	1,2,3	Y	1	1,2	2, 3, 4, 8, 9	5	164	141	8	1
8	Comm. Comph. High School Akungba Akoko	2	12	6	48	32	-	14	78	83	Y	N	1,2	Y	-	1,2,4	1-5, 8, 9	1	149	145	21	13
9	Esedo Comp. High Schl Iwara Oka	3	7	-	-	28	-	-	260	260	Y	N	6	Y	1,6	1,2,4	1-9	1	224	223	14	7
10	Ogoso High School Korowa Oka Akoko	1	13	8	52	48	13	32	200	300	Y	Y	1,2,3	Y	4,5	1,2,3,4	1-9	1	250	207	15	3

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		



TABLE 44 Contd

AKOKO SOUTH WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Ojomirin High School, Agba Oka Akoko	3	12	-	-	-	-	24	60	60	Y	N	1,2,3	Y	1,5	1,2,4	1-5, 8, 9	1	244	227	15	6
12	Okeede Comm. High Schl. Supare Akoko	2	6	1	24	24	-	12	146	160	N	N	6	Y	1	1,2,4	1-5, 8, 9	3	186	182	15	9
13	Ola Oluwa Grammar Schl Oka Akoko	2	7	-	24	24	6	14	450	450	Y	N	1,2	Y	1	1,2	2-5, 8, 9	1	332	273	16	5
14	Oludaye Grammar School, Oba-Akoko	2	9	4	16	16	4	22	220	220	Y	N	Y	Y	1,4,6	1,2,4	1-6, 8, 9	1	175	159	17	7
15	Oroke High School Akungba Akoko	2	9	2	8	8	2	4	407	407	Y	N	1,2,3	Y	1,4,5	1,2	1-5, 8, 10	3	185	227	21	7
16	St. Patricks College Iwaro-Oka	2	13	13	52	52	13	26	414	426	Y	N	1,2,3	Y	1,4,5,6	1,2,3,4	1-9	1,2	246	257	-	-
17	Oyinle High School, Oba Akoko	2	2	-	-	-	-	-	60	60	N	N	N	Y	1,3,5	1,2,3	2,3,5,8,10	3,4	60	63	7	2

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 45 Contd

AKURE NORTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (y/N)	L Library well stocked? (y/N)	M Availability of Computer (y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers		
11	The Apostolic Primary School Itaogbolu	2	7	1	4	4	1	2	101	101	Y	N	-	1,5	1	1-5,8,9	-	100	111	2	9
12	Ilado-Odudu Community Primary School Ilado	2	8	-	-	-	-	-	256	264	N	N	-	1,4,5	1	1-3,5,8,9	5	49	33	1	12
13	Local Authority Primary School Owode-Araromi	2	6	3	12	12	3	6	190	190	N	N	-	1	1	2-6,8,9	-	225	265	1	20
14	St. Luke's C.A.C. Primary School Bolorunduro	2	14	6	24	24	6	12	184	184	N	N	N	3,5	1	1-4,8-10	5	170	148	4	9
15	Ondo State Special Primary School Oba-Ile	2	6	-	-	-	4	12	210	210	N	N	-	1,3,6	1	1-5,6,8,9	1	106	115	1	23
16	St. Paul's C.A.C Primary School Itaogbolu	2	9	7	-	36	2	4	140	140	Y	N	N	1	1	1-9	5	71	75	1	12
17	The Apostolic Primary School Iju	2	5	5	20	20	5	10	160	180	N	N	N	1	1	1-5,8,9	-	268	219	3	15
18	Ebenezer African Church Primary School Itaogbolu	3	13	1	4	4	1	2	195	195	N	N	Y	1,5	1,4	1-5,8,9	2	98	123	4	25
19	St. John's Ang Primary School Itaogbolu	2	12	2	8	8	2	4	340	340	Y	N	N	1,4,5	1	1-5,8,9	5	168	139	2	11
20	St. Mary's RCM School Ayede Ogbese	3	5	3	12	12	3	6	175	175	Y	N	-	1,5	1	1-5,8-10	1	231	211	3	15

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6 (Q) SOURCE OF ELECTRIC POWER	
Admission Register 1	PHCN 1	Other 6
Attendance Register 2	Generator 2	
Syllabus/Plan of Work 3	PHCN/Generator/ 3	
Supervision Book 4	Solar 4	
Visitors Book 5	None 5	

TABLE 45 Contd

**AKURE NORTH**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		21	L.A Primary School Owode Ogbese	2	6
22	St. Paul's Ang Primary School Kajola/Ilado	3	17	3	12	12	4	6	250	250	Y	N	N	1,3,6	1	1-5,8-10	5	188	245	3	20
23	Community Primary Sch Surulere 1/Tedibomi	1	2	-	-	8	-	4	62	62	N	N	-	1	1	2-5,8-10	5	40	34	2	0
24	L.A Primary School Makanju	-	8	2	8	8	2	4	160	80	Y	N	-	6	1	2,3,4,9	5	68	25	4	6
25	L.A. Primary School Igbatoro Familugba	1	2	1	4	4	1	2	84	84	N	N	N	1,4	1	1-5,6-9	5	92	88	3	0
26	St. Michael's C&S Primary School Iju	2	12	-	-	-	-	-	40	40	N	N	Y	6	1	1,2,3,4,8,9	2	186	199	3	9
27	L.A Primary School Itaogbolu	2	8	6	24	24	6	12	140	140	N	N	-	1,4,6	-	1-5,8-10	1	81	84	3	8
28	Local Authority Primary School, OKE AGUNLA	2	4	-	-	-	-	4	42	44	N	N	N	5	1	1-5,8-10	5	95	110	2	2
29	Muslim Primary School Itaogbolu	2	6	6	24	24	4	12	110	110	N	N	N	1	1	1-5,8-10	5	117	89	4	7
30	L.A Primary School, Isagba	1	3	3	12	6	2	3	64	118	N	N	N	-	1	1-5	5	92	84	9	12

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 45 Contd

AKURE NORTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	No of Pupils		No of Teachers	
																		M	F	M	F
																		31	Community Pry Sch, Ago Daada, Igbatoro	2	8
32	Dayo Jegede Pry Sch, Orojuda-Igoba, Ado Road	2	6	2	8	8	2	4	222	222	N	N	N	1,5	1,4	1-5,8-10	5	277	285	3	13
33	St. Thomas Ang. Primary School, Isinigbo	2	4	-	-	2	-	-	200	200	N	N	N	1,5	1	1-5,8,9	5	30	49	4	8
34	St. David's Primary School, Agamo	2	6	2	8	8	2	4	375	375	N	N	N	-	1	1-5,7-10	5	47	57	10	-
35	St. Stephen's Primary School, Ajagbusi, Igbatoro	1	4	2	8	8	2	4	200	200	Y	Y	N	1,5	1	1-6,8,9	5	68	78	3	3
36	Methodist primary School, Idera st. Iju	3	7	6	24	24	6	12	236	236	N	N	N	1	1	1-6,8,9	5	135	131	3	18
37	L.A Primary School Ago-Oyinboi	1	3	-	-	-	2	12	25	25	N	N	N	1	1	1-5	5	88	94	4	1
38	L.A Primary School, Adejuba, akure	1	5	-	-	20	-	10	200	200	N	N	N	4,5	1	1-5	5	153	135	10	22
39	L.A Primary School, Kajola Igbatoro	1	5	1	4	4	1	2	340	340	N	N	N	1	1	1-5,8,9	5	67	74	4	11
40	St. Peter's Anglican Sch, Olobi- Igbatoro	2	8	2	8	8	2	4	322	352	N	N	N	4	1	1-5,8-10	5	73	100	5	16

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 45 Contd

AKURE NORTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils		No of Teachers	
41	C.A.C Primary School, Moferere st. Iju	2	6	-	-	-	-	-	77	77	N	N	N	1,5	1	1-5,8,9	5	77	89	3	25
42	St. Augustine primary School, Ode Igede	1	4	2	8	8	2	4	70	70	N	N	N	1,3,5	1	2-6,8,9	5	66	61	12	-
43	St. Mathew's Ang. Primary School Igoba	2	12	2	8	8	2	4	288	294	N	N	N	1,5	1	2-5,8,9	5	57	50	3	10
44	St. Paul's Ang Pry sch, Mission Road, Oba-Ile	3	7	-	-	-	-	-	662	662	N	N	Y	1,5	-	2-5,8,9	1	348	345	2	26
45	St. Anthony's RCM, Primary Alayere	2	9	3	12	12	3	6	200	200	N	N	N	1	1	1-5,8,9	5	119	117	4	4
46	St. Mathew's Ang. Pry Sch, Moferere st. Iju	3	12	1	4	4	1	2	194	194	N	N	Y	1,5	1	1-5,7-10	2	130	113	2	16
47	St. John's RCM Ago-paanu ,Igbatoro Akure	2	8	3	12	12	3	6	140	140	N	N	Y	1,3,6	1	1-5,8,9	2	99	118	4	8
48	St. Joseph's RCM, Ajimoko, Bolorunduro, off Ogbese Road	1	3	1	4	4	1	2	200	200	Y	Y	N	1	1	1-5,6,8,9	5	43	37	3	1

**KEY**

(B) NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
Mud	1	Wash Hand Basin	1	Play Ground	1
Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
Both	3	Bore Hole	3	Table Tennis Court	3
Others	4	Protected Well	4	Food Vendor/Canteen	4
		VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P) SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
Admission Register	1			PHCN	1 Other 6
Attendance Register	2			Generator	2
Syllabus/Plan of Work	3			PHCN/Generator/	3
Supervision Book	4			Solar	4
Visitors Book	5			None	5

TABLE 46

AKURE NORTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Alamo Grm School, Itaogbolu	2	18	6	-	48	-	24	200	150	N	N	5,6	Y	1,4,5	1,2,4	1-10	1	400	347	11	29
2	Anglican Grm School, Iju-Itaogbolu	2	3	14	56	68	17	34	120	120	N	N	4	Y	1	1,2	1-6,8,9	1	135	128	12	16
3	Comm Comp High School, Ayede Ogbese	2	9	-	-	20	10	10	400	400	Y	N	4	Y	1,4,5	1,4	2-6,8,9	1	312	313	12	28
4	Eji Oba High School, Oba Ile	2	12	-	16	8	-	12	510	510	Y	N	4	N	6	1,2	1,2,8,9	1	345	268	7	28
5	Elu Iju High School, Iju	2	12	5	20	28	9	18	310	310	Y	N	-	Y	5,6	1,4	1-9	3	228	241	15	12
6	Igbatoro Comp High Sch, Otokuta, Akure	2	4	2	-	12	2	8	120	120	Y	N	-	-	-	1,2	2-6,8,9	5	128	123	10	7
7	Iguba Community Junior High School	2	6	-	20	20	6	6	30	320	N	N	-	N	6	1,4	1-6,8-10	3	148	128	10	19
8	C.A.C Grammar School, Iju	2	4	3	12	12	6	8	60	50	y	n	6	y	1,4,5	1,2,4	1-6,8-10	2	65	47	7	13

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 46 Contd

AKURE NORTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Alamo Grm School, Itaogbolu	3	18	12	48	72	12	36	200	200	N	N	-	N	-	1,2,4	1,2,4,5,8,9	1	234	222	29	21
2	Anglican Grm School, Iju-Itaogbolu	2	13	5	20	52	5	26	350	300	Y	N	1,2,4,5	-	-	1,4	1,2,4,5,6,8,9	1	211	190	36	22
3	Comm Comp High School, Ayede Ogbese	2	12	-	-	24	12	-	610	568	Y	N	-	-	-	1,2	-	-	276	244	16	10
4	Eji Oba High School, Oba Ile	2	11	6	20	44	6	22	162	162	Y	N	1-5	-	-	1,2,4	2-9	1	214	210	9	25
5	Elu Iju High School, Iju	2	10	10	8	8	5	-	180	180	N	N	1-3	Y	-	1,2,4	1-10	1,2	163	125	26	11
6	Igbatoro Comp High Sch, Olokuta, Akure	2	6	6	24	24	2	4	149	150	Y	Y	1,2,3	N	1	1,2	1-6,8,9	5	176	124	11	3

KEY

(B) NATURE OF BUILDING:

- Mud 1
- Cement/Burnt Brick2 2
- Both 3
- Others 4

(M) LABORATORY:

- Physics 1
- Chemistry 2
- Biology 3
- Intro. Tech. 4
- Home Econs. 5
- Others 6

(O) HEALTH/WATER/SANITATION FACILITIES:

- Wash Hand Basin 1
- Pipe Borne Water 2
- Bore Hole 3
- Protected Well 4
- VIP/Traditional Pit Latrine 5
- Water Closet 6

(P) RECREATIONAL FACILITIES

- Play Ground 1
- School Hall 2
- Table Tennis Court 3
- Food Vendor/Canteen 4
- Swimming Pool 5

(Q) SCHOOL RECORDS

- Admission Register 1
- Attendance Register 2
- Syllabus/Plan of Work 3
- Supervision Book 4
- Visitors Book 5

(R) SOURCE OF ELECTRIC POWER

- PHCN 1
- Generator 2
- PHCN/Generator/ 3
- Solar 4
- None 5
- Other 6

TABLE 47

AKURE SOUTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers	M	F
1	St. Micheal's RCM Pry. Sch. Igboliki	3	19	-	16	16	4	4	1150	1150	N	N	N	3	4	1,2,3,4,8,9	1	326	338	1	28
2	St. Luke Ang Pry Sch. Ijomu	2	6	-	20	44	5	5	236	236	N	N	Y	1,5	1	1,2,3,4,5,8,9	1	120	147	1	15
3	St. Luke Cac. Pry. Sch. Oja Osohdi, Akure	2	6	4	-	4	4	4	240	240	N	N	Y	1	-	1,2,3,4,5,8,9	5	229	178	1	14
4	St. Lukes Ang Pry. Sch. Idigba	3	13	-	-	-	-	-	427	434	N	N	Y	5	4	2,3,5,9,10	2	274	221	5	27
5	St. Paul Ang Pry Sch. Idigba	3	14	2	8	52	7	22	212	200	Y	N	Y	1,4,6	1,4	2,3,4,5,6,8,9	3	315	323	2	29
6	St. Thomas's Ang Pry. Sch. Isikan,	2	9	2	35	4	-	12	540	540	Y	Y	N	4,6	1	1-5,8,9	5	198	196	2	15
7	St. Pat. Scm Pry. Sch. Oke Aro	2	10	-	-	-	-	-	408	414	N	N	Y	6	4	1-5,8,9	1	172	161	5	16
8	Ijapo Estate Pry. Sch. Ijapo	2	31	16	-	124	6	6	900	900	N	N	Y	1,6	2	1-5,8,9	5	469	487	2	26
9	St. Mary's Ang Pry Sch Adofure	1	6						326	400	N	N	Y	1	1	1-5,8,9	5	215	265	4	14
10	Medayese Memo R.C.M Pry Sch Idiagba Titun	2	8	2	8	8	2	4	270	270	N	N	Y	1	1	1-5,8,9,10	5	187	198	-	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	



TABLE 48

AKURE SOUTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	A/C Compr. High School, Akure	2	8	-	32	32	8	16	100	100	N	N	-	Y	1,3	1,4	1-6,8,9	2	39	33	7	2
2	Adegbola Memorial Grammar Sch; Akure	2	14	-	56	56	14	28	733	733	N	N	-	Y	1,6	4	1, 2, 4, 5, 8, 9	1,2	370	443	5	31
3	African Church Comp Schl, Akure	2	7	-	28	28	-	14	340	340	N	N	-	Y	-	1,4			236	285	4	31
4	Akure High School, Akure	2	20	4	20	4	15	-	1300	1300	N	N	-	Y	4,6	1	2-5,8,9	3	527	527	13	44
5	Akure Muslim College, Akure	2	12	-1	-	40	6	24	402	418	Y	N	1,2,4,5	Y	5	1,4	2-4,6-8	1	320	289	7	30
6	Akure Secondary Commercial School, Akure	2	20	10	80	80	18	40	200	200	Y	Y	4,5	Y	1,5	1,2,4	1-9	1	744	766	11	30
7	Alakure Comp. High School, Akure	2	7	4	-	64	5	4	200	200	N	N	4,5	Y	1,4	1	2-5,7-9	5	281	239	2	27
8	Aponmu Community High School, Aponmu	2	6	-	24	24	6	12	150	150	N	N	-	-	1,2,6	1	2-5,8,9	1	122	118	8	12
9	Aquinas College Akure	2	28	-	16	-	-	56	1000	1200	N	N	4,6,7	Y	3,6	1,2,4	2-9		1808	0	11	69
10	Army Comprehensive High School, Akure.	2	10	10	-	40	10	36	300	300	N	N	4,5	Y	1,5,6	1,2,4	2-9	3	346	271	7	38

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 48 Contd

**AKURE SOUTH**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS**

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Baptist High School, Alure	2	10	4	40	40	9	20	99	99	Y	N	-	Y	1,6	1	1-10	1	188	241	6	21
12	C.A.C Adu Memorial School, Akure	2	10	-	-	40	5	20	300	500	N	N	-	Y	1,5	1	1-9	1	251	308	5	14
13	C.A.C Grammar School, Akure	3	26	-	104	104	26	52	800	800	Y	N	-	Y	3,6	1,2,4	2-9	1	579	1015	7	53
14	Celestial Grammar School, Akure	2	5	5	20	20	5	10	140	160	Y	N	-	-	1	4	2-6,8-10	3	144	151	3	9
15	Estate High School, Akure	2	15	-	40	40	11	22	576	576	Y	N	-	Y	-	1,4	2-5,7-9	5	288	285	8	27
16	Fiwasaye Grammar School, Akure	2	21	1	36	56	12	32	1411	1411	Y	Y	1-5	Y	1-6	1,2,4	1-10	1-3	0	1156	3	46
17	Ijapo High School Akure	2	17	2	14	16	-	6	1000	1000	N	N	-	Y	4,5	1,2,4	2-5,7-10	3	489	451	5	38
18	Ijo Mimo High School, Akure	2	12	-	40	48	12	24	734	722	Y	N	4	Y	1,4,5	1	1-3,5-9	1	419	520	4	38
19	Ogbe High School, Akure	3	8	2	8	8	2	4	220	220	N	N	4,5	Y	4	1,2,4	1-3,5,8-10	3	96	68	3	16
20	Omoluorogbo Grammar School, Akure	3	14	-	4	40	4	18	601	671	N	N	-	-	4,5	1	1-5,8,9	1	658	702	14	44

**KEY****(B) NATURE OF BUILDING:**

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

**(M) LABORATORY:**

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

**(O) HEALTH/WATER/SANITATION FACILITIES:**

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

**(P) RECREATIONAL FACILITIES**

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

**(Q) SCHOOL RECORDS**

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

**(R) SOURCE OF ELECTRIC POWER**

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 48 Contd

AKURE SOUTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
21	Oyemekun Grammar School, Akure	3	25	-	-	24	6	2	1156	1200	Y	N	-	-	3,5	1,2,4	1-5,7-9	3	1500	-	18	58
22	St. Dominic, Akure	2	14	14	56	56	14	14	715	700	Y	N	-	Y	-	1,2	1-10	1,2	387	532	6	43
23	St. Francis High School, Akure	2	12	12	24	20	12	12	120	120	Y	N	-	Y	3,6	1	1-6,8,9	1	185	181	9	30
24	St. Louis Grammar School, Akure	2	21	-	-	-	-	-	1680	1680	N	N	4,5	Y	1,3,4,5,6	1,2	1-9	3	0	1449	7	56
25	St. Michael Ang. High School, Akure	2	14	11	28	32	8	22	832	700	N	N	-	Y	3,6	1,2,4	1-9	2,3	490	629	4	41
26	St. Peter Unity Secondary School, Akure	2	21	-	36	60	-	15	650	650	Y	N	-	N	3,5	1,2,4	1-9	3	401	249	4	33
27	St. Thomas Ang. Comp. High School, Akure.	2	10	-	-	-	-	-	406	406	Y	N	4	Y	1,4,6	1,2,4	2-9	1	197	183	2	26
28	United C.A.C High School, Akure	3	10	-	-	40	9	16	260	260	Y	N	-	N	-	1,4	1-9	5	156	136	1	25

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 48 Contd

AKURE SOUTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Adun Comm. Compr. High School, Akure	1	3	3	12	12	3	6	60	60	N	N	1-4	Y	-	1,4	1-5,8,9	2	31	26	7	3
2	Adegbola Mem Gra. Sch, Akure	2	11	0	32	44	11	22	289	448	N	N	4,5	Y	1,5	4	1-5,7-9	3	194	232	9	25
3	African Church Comp. High Sch. Alagbaka Akure	2	10	3	0	40	5	20	380	380	Y	N	2	N	1,6	1,2,4	1-6,8,9	1,3	160	208	8	15
4	Akure High School, Akure	2	18	6	24	72	6	36	1120	1120	Y	N	1-3,5	N	5	1,2,4	2-10	1	674	612	36	16
5	Akure Muslim College, Akure (SSS)	2	9	1	16	12	3	6	204	204	Y	N	1,2,3,5	Y	5	1,4	2,5,8,9	1	250	233	10	20
6	Akure Secondary Commercial School, Akure	3	17	10	32	40	0	24	820	820	Y	Y	1,2,3,5		4,5,6	1,2	2-10	1,,2,3	452	629	20	34
7	Alakure Comp. High School, Akure	2	6	3	12	8	2	8	80	80	Y	N	2,5	Y	1,4,6	1,2,4	2,4,5,7,8,9,10	1	201	209	7	22
8	Aponmu Community High School, Aponmu	3	9	0	36	36	9	18	180	180	Y	N	1	N	5	1,4	1-6,8-9	1	142	85	18	5
9	Aquinas College Akure	2	25	3	12	12	12	50	987	987	Y	N	1,2,3	Y	2,3,5,6	1,2,4	1,2,3,6,8,9	1, 2	1329	-	20	41
10	Army Comprehensive High School, Akure.	2	9	9	0	36	0	18	30	185	Y	N	1-5	Y	0	1,2,4	1,2,4,5,7,9	3	276	211	10	33

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 48 Contd

AKURE SOUTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Baptist High School, Alure	2	10	4	40	40	9	20	99	99	Y	N	-	Y	1,6	1	1-10	1	188	241	6	21
12	C.A.C Adu Memorial School, Akure	2	7	3	28	40	2	20	140	160	Y	N	2	Y	5,6	1,2,4	1-9	5	135	186	5	16
13	C.A.C Grammar School, Akure	3	19	14	0	76	19	38	1158	1158	Y	N	1,2,3,5	Y	1,3,5	1,2,4	2-9	1	381	767	22	33
14	Celestial Grammar School, Akure	2	12	4	32	24	7	12	70	165	Y	N	1-5	N	1,5	1,4	1-6,8-9	3	190	150	6	18
15	Estate High School, Akure	2	11	0	0	44	2	22	483	483	Y	Y	1-3	Y	0	4	1-9	1	239	293	12	26
16	Fiwasaye Grammar School, Akure	2	21	1	34	56	12	32	719	719	Y	Y	1-5	Y	1,2,3,6	1,4	1-10	3		719	15	32
17	Ijapo High School Akure	2	13	-	28	28	9	18	480	460	Y	N	5	Y	1,4	1,2	1-9	1	288	320	8	32
18	Ijo Mimo High School, Akure	2	12	2	12	8	0	10	287	262	Y	N	1,2,3,5	N	4,5	1,4	1-10	1	360	427	20	27
19	Ogbe High School, Akure	2	4	4	0	10	4	8	173	173	Y	N		Y	1,	1,2	1-6,8-10	2	85	88	10	15
20	Omoluorogbo Grammar School, Akure	3	3	7	48	64	12	32	400	400	Y	N	1,3,5	N	4,5	1,2,3	1-10	2	422	488	12	31

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 48 Contd

AKURE SOUTH  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
21	Oyemekun Grammar School, Akure	3	20	0	32	24	-	-	500	500	Y	N	1-5	N	1,3,5	1,2,4	2-9	3	1247		19	43
22	St. Dominic, Akure	2	14	4	8	40	0	14	600	600	Y	Y		Y	5	1,2,4	1-10	1,2,3	245	343	7	36
23	St. Francis High School, Akure	2	9	9	36	36	9	18	80	80	Y	N		Y	1,5	2	2-6,8,9	1	153	141	15	20
24	St. Louis Grammar School, Akure	2	25	-	-	-	-	-	800	850	Y	N	1-6	Y	1,3,5	1,2,4	2-9	1,2		1155	12	49
25	St. Michael Ang. High School, Akure	2	14	12	40	-	-	-	402	525	Y	N	1,4,5	Y	1,3,5	1,2	1-9	3	263	492	18	25
26	St. Peter Unity Secondary School, Akure	3	12	0	48	48	12	12	430	430	Y	N	1-3,5	N	3,5,6	1-4	1-9	3	248	147	13	17
27	St. Thomas Ang. Comp. High School, Akure.	2	11	0	0	0	0	22	205	205	Y	N		Y	4	1,2	1-9	1	271	264	15	21
28	United C.A.C High School, Akure	2	9	3	36	36	7	-	200	200	Y	Y	6	N	1,6	1,4	1-6,8-10	3	127	128	4	28

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 50

ESE-ODO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Apoi National High School , Igbotu	1	6	-	8	16	1	10	85	115	N	N	4	Y	1,5	1,2,4	1'-6,8,9	5	193	194	5	3
2	Arogbo City Academy. Arogbo	3	6	6	24	24	6	12	-	-	N	N	N	Y	-	1,4	1'-5,8,9	5	307	265	10	1
3	Community Comp High School Igbekbebo	2	3	-	-	3	-	3	240	240	N	N	N	Y	1,3,5	1,4	1'-5,7,9	3	156	174	3	4
4	Community Comp High, Biagbini	3	5	-	-	10	-	5	250	250	Y	Y	N	N	-	1	1'-6,8,10	2	188	133	7	2
5	Community Comp High School Sabomi	1	3	-	6	6	3	6	120	103	N	N	N	Y	5	1	1'-4,8,9	3	106	93	5	3
6	Community High School Kiribo	2	6	-	-	15	3	-	360	360	Y	N	N	Y	1,4,5	1,2,4	1'-5,8-'10	5	157	123	8	3
7	Comprehensive High School, Igbobini	2	12	-	-	6	-	6	221	198	N	N	4,6	Y	1,5	1,4	1,2,3,4,5	3	132	121	7	5
8	Ijaw National High School, Arogbo	2	9	-	4	16	3	8	292		N	N	N	Y	1	1,4	1'-5,8-10	2	486	310	14	3
9	Ojuala Community High School, Ojuala	2	4	-	-	16	4	8	80	80	N	N	N	Y	-	1,4	2'-5,8,9	1	95	100	5	3
10	Okhuba-Ama High School, Ajapa	3	5	1	8	1	1	1	88	88	N	N	N	Y	1	1	1,2,8,9	2	255	197	9	1

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econ.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 50 Contd

ESE-ODO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	St. Arenibaro Memorial High School	2	6	-	-	-	-	-	157	157	N	N	N	Y	-	1	2'-5,8,9	2	125	126	6	4
12	Ukparauma Grammar School , Bolowoghu	4	6	-	24	24	6	12	105	105	Y	N	N	Y	1	1,4	1'-6,8-9	5	392	294	10	3
13	Ebikiri Model College Adoloseimo	4	-	-	-	-	-	-	73	99	N	N	N	Y	1		1'-5,8,9	5	138	119	6	2

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		



TABLE 50 Contd

ESE-ODO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

SENIOR																						
S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Laboratories Available	N Availability of Computer (Y/N)	O Health / Water Supply / Sanitation Facilities available	P Recreational facilities available	Q School Records available	R Source of Electric power	S No of Pupils		T No of Teachers	
																			M	F	M	F
																			1	Apoi National High School , Igbotu	1	3
2	Arogbo City Academy. Arogbo	2	5	-	-	-	-	5	166	226	N	N	6	N	1	1,4	1-5,8-10	5	255	145	13	1
3	Community Comp High School Igbekbebo	2	3	6	24	36	8	8	120	120	N	N	1,2,3	N	5	1,2,4	1-5,8-10	3	94	68	8	1
4	Community Comp High, Biagbini	4	6	6	24	24	6	12	520	520	N	N	N	Y	1	1	2,,4,5,6,8,9	2	325	130	19	2
5	Community Comp High School Sabomi	3	4	-	16	54	-	24	195	228	Y	N	1,2,3	N	1	2	1-5,8,9	3	105	102	6	2
6	Community High School Kiribo	3	6	-	12	12	-	4	-	-	Y	N	6	N	1,4,5	1,2	2-6,8,9	2	226	173	8	2
7	Comprensive High School, Igbobini	2	7	4	16	28	-	7	131	131	Y	N	2,3	Y	5,6	1,4	1-6,8-10	1	154	121	15	-
8	Ijaw National High School, Arogbo	2	5	8	42	32	8	9	194	237	N	N	N	Y	1	1	1-3,5,8-10	2	413	142	15	2
9	Ojuala Community High School, Oljuala	2	3	3	12	12	3	3	80	80	Y	N	6	Y	1,5	1,3,4	2-6,8,9	3	69	81	5	2
10	Okhuba-Ama High School, Ajapa	4	4	-	-	-	-	-	342	365	N	N	N	Y	1	1,4	1-5,8-10	5	286	194	10	1

KEY

(B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

(M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

(O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

(P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

(Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

(R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 50 Contd

ESE-ODO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of	No of Functi	No of roofs	No of walls	No of windo	No of floors	No of doors	Total access	Total access	Availa bility	Library well	Labora tories	Availa bility	Health / Water	Recrea tional	School Record	Source of	No of Pupils		No of Teachers	
																				M	F	M
11	St. Arenibaro Memorial High School	2	7	7	28	28	7	14	244	294	Y	N	1,2,3	Y	1,3	1	2 <sup>1</sup> -6,8,9	2	151	77	11	1
12	Ukparauma Grammar School , Bolowoghu	3	4	-	-	-	-	-	150	150	N	N	N	N	1	1	1 <sup>1</sup> -6,9	5	312	197	11	2
13	Ebikiri Model College Adoloseimo	4	1	-	-	-	-	-	40	59	N	N	N	N	1	-	1 <sup>1</sup> -5,8,9	5	75	58	-	-

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		



TABLE 51

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	St. Thomas Ang Primary School Aseigbo- Idanre	2	9
2	All Saints Pls Owobamibo- Idanre	1	2	2	8	8	2	4	160	160	N	N	N	1,5	1	1-5, 8, 9, 10	5	102	124	4	-
3	Baptist Primary School Igbelowowa	2	9	3	20	16	3	10	240	240	N	N	N	1,4,6	1	1-5, 8, 9	5	98	107	2	8
4	Baptist Primary School, Idanre	2	4	6	12	24	2	12	42	54	N	N	N	1	-	1-5, 8, 9	5	97	148	4	2
5	Baptist Primary School, Omilaje-Idanre	1	2	2	8	8	-	4	8	8	N	N	N	-	1	1-5, 8, 9, 10	5	49	51	2	1
6	C.A.C. Primary School Ala-Aladura	1	2	-	8	8	-	4	120	120	N	N	N	5	1	1-5, 8, 9	5	84	82	2	-
7	Christ Anglican Pry School Idanre	2	17	-	18	30	-	-	500	500	Y	Y	Y	1,5	1,5	1, 2, 4, 5, 7, 8, 9, 10	1	283	250	5	16
8	Community Primary School Legbira- Idanre	3	6	-	-	-	-	-	28	28	N	N	N	5	1	2, 3, 5, 8, 9, 10	5	129	119	2	1
9	Community Primary School Omifunfun Idanre	2	2	-	-	-	-	-	20	20	N	N	N	1,5	1	1, 2, 3, 4, 5, 8, 9	5	93	120	2	1
10	Community Primary School, Yaba- Idanre	2	13	-	-	-	-	-	440	440	N	N	N	1,5,6	1,4	1-5, 8, 9, 10	1	204	169	-	13

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
			Water Closet	6		
(P)	SCHOOL RECORDS			(Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 51 Contd

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	Holy Trinity Primary School Ayede Iwonja	1	3
12	L.A Primary School Odoko Idanre	3	10	2	10	20	10	10	60	60	N	N	N	1,6	1	1-10	5	93	95	2	1
13	L.A Primary School - Owomofewa	1	4	3	10	5	5	10	8	8	N	N	N	5	1	1, 2, 4, 5, 9	5	94	85	2	-
14	L.A Primary School Aboekan	1	3	-	-	-	-	-	160	160	N	N	N	1	1	1-5, 8, 9	5	54	66	3	-
15	L.A Primary School Ago Joshua	2	3	-	12	-	-	8	40	40	N	N	N	-	1	1-4, 9	5	94	100	2	-
16	L.A Primary School Arisin	2	3	4	16	16	4	8	50	50	N	N	N	1	-	1-5, 9	5	117	106	2	-
17	L.A Primary School Atosin Idanre	2	18	2	8	8	2	4	400	400	Y	N	Y	5	1,4	2-5, 8, 9	1	229	246	2	17
18	L.A Primary School Gbalegi	3	5	-	-	24	6	12	260	260	N	N	N	1,3	1	1,2,3,4,5, 8,9	5	122	131	6	-
19	L.A Primary School Otapete	2	6	-	-	-	-	12	316	316	N	N	N	5	1	2-5, 8, 9	5	170	170	2	14
20	L.A Primary School Owobamibo Ofosu	2	8	-	12	20	4	10	24	24	N	N	N	1,5	1	1-5, 8, 9, 10	5	360	328	5	3

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6	(Q) SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5
		1 Other 6

TABLE 51 Contd

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		21	L.A Primary School Owobamibo Ofosu	2	5
22	L.A. Primary School , Jimgbe	2	2	2	8	8	7	4	120	120	N	N	N	-	1	1-5, 8, 9	5	112	123	2	-
23	L.A. Primary School Apokin, Idanre	2	2	2	-	8	2	4	20	20	N	N	N	1,5	1	1-5, 8, 9	5	115	96	3	-
24	L.A. Primary School Ayefemi Idanre	3	4	4	16	16	4	8	150	200	N	N	N	1,3,5	1	1-5, 8, 9	5	78	71	2	2
25	L.A. Primary School Eripose	1	2	4	16	16	4	8	100	100	N	N	N	1,5	1	1-5, 8, 9	5	84	84	6	3
26	L.A. Primary School Ita-Oloorun	2	18	0	20	-	-	-	616	616	N	N	N	1,3,6	1	1-5, 8, 9	1	270	252	3	15
27	L.A. Primary School Olorunredo Idanre	2	3	3	2	12	-	6	100	102	N	N	N	5	1	1-5, 8, 9	5	59	73	2	1
28	L.A. Primary School Opa, Idanre	3	9	3	12	12	3	6	240	240	N	N	N	1,6	1	1-5, 8, 9	5	177	207	4	2
29	L.A. Primary School, Agotun-Tun- Idanre	3	2	N	10	8	N	9	12	4	N	N	N	-	1	1-6, 8, 9, 10	5	27	40	4	-
30	L.A. Primary School, Ajegunle Asunrin	1	2	1	4	8	2	4	100	100	N	N	N	1	1	1-5, 7, 8, 9, 10	5	52	63	1	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 51 Contd

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		31	L.A. Primary School, Bajare-Idanre	2	4
32	L. A. Prry Sch, Farm Settlement Onisere	1	2	3	20	20	10	15	50	50	N	N	N	1,5	1	1-10	5	160	126	5	2
33	Local Authority Primary School Ayede- Idanre	1	6	6	24	24	4	8	10	10	N	N	N	-	1	1-4, 8, 9, 10	5	66	52	2	-
34	Local Authority Primary School, Ijama	1	4	4	16	16	4	8	34	30	N	N	N	5	1	1,2,3,4,5, 8,9	5	77	73	4	-
35	Methodist Ajegunle Akindana Idanre	1	3	1	4	12	3	6	240	240	N	N	N	5	1	1-5, 8, 9	5	98	87	4	1
36	Methodist Primary School Ajobambo- Idanre	2	2	4	16	16	1	8	24	16	N	N	N	1,5	1	1-5, 8, 9	5	73	90	1	-
37	Methodist Primary School Ajipowo Idanre	2	6	4	18	22	4	12	240	240	N	N	N	1,5	1	1,2,3,4,5, 8,9	5	76	75	3	-
38	Methodist Primary School Ayede Ajagbusi	2	6	6	24	24	6	12	240	240	N	N	N	1,4	1	2,3,4,5,8, 9	5	106	75	4	-
39	Methodist Primary School Idale-Idanre	3	13	12	42	22	15	15	504	504	N	N	N	1,3,5	1,4	1,2,3,4,5, 8,9	1	326	285	4	19
40	Methodist Primary School Isalu Idare	3	8	9	26	24	9	8	325	475	N	N	2	1,6	1,4	1-8,10	3	256	251	20	4

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER
	Admission Register	1			PHCN
	Attendance Register	2			Generator
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			Solar
	Visitors Book	5			None
					1 Other
					2
					3
					4
					5
					6

TABLE 51 Contd

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		41	Methodist Pry Schl Ipinlerere- Idanre	1	4
42	Methodist Pry School Ajegunle Iwonja	2	4	3	5	18	3	8	100	100	N	N	N	5	1	2,3,4,5,8,9	5	12	20	-	-
43	Muslim Primary School, Isalu-Idanre	2	6	6	24	32	6	16	240	240	N	N	N	1,4,5	1	2,3,4,5,8,9,10	1	94	68	1	6
44	Our Savious Ang Primary Owena	2	9	-	-	-	-	-	250	250	Y	N	1	1,2,3	1	2,3,4,5,8,9,10	5	232	227	3	13
45	St. Andrew's Ang. Pry Sch, Alade- Idanre	2	13	-	9	-	-	-	342	352	N	N	N	1,6	1	1,2,3,4,5,9,10	1	148	153	-	34
46	St. Barnaba's Pry School,S Alade- Idanre	1	6	6	18	6	6	6	40	40	N	N	N	-	-	1,2,3,4,9	5	125	112	3	5
47	St. Colman's R.C.M Primary School Asoko	2	6	-	4	-	-	6	116	116	N	N	N	1,5	1	1,2,3,4,5,8,9	5	122	118	2	3
48	St. David's Anglican Primary School Igboepo	3	8	-	10	2	4	10	56	64	N	N	N	5	1	1,2,3,4,5,8,9	5	78	53	2	-
49	St. Davids C.A.C Primary School Abalaka- Idanre	1	3	-	1	10	1	2	120	120	N	N	N	5	1	1,2,3,4,5,8,9	5	54	60	1	3
50	St. Edward's RCM Primary School, Okeida	1	4	-	12	12	4	4	60	40	N	N	N	1,5	1	1,2,3,4,5,8,9,10	5	135	124	1	2

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	



TABLE 51 Contd

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		51	St. Georges And Primary School, Idanre	2	8
52	St. James's Ang Pry Schl Oporun Idanre	2	9	2	14	10	2	2	422	400	N	N	N	1,6	1,4	1,2,3,4,5,8,9	1	286	266	2	10
53	St. Johns's (RCM) Pry Schl, Ala Apafa, Idanre	3	5	-	8	8	-	4	100	100	N	N	N	-	1	1,2,3,4,5,8,9,10	5	79	93	1	2
54	St. Joseph C.A.A Primary Schooll Idanre	2	6	-	8	6	2	2	240	240	N	N	N	1,5	1	1,2,3,4,5,8,9	5	125	135	2	8
55	St. Luke's Alc Primary School, Ipoba	2	3	-	-	-	-	6	40	40	N	N	N	5	1	1,2,3,4,5,8,9	5	98	110	3	-
56	St. Luke's Ang. Primary School, Egbeda- Idanre	1	3	2	10	5	2	10	40	40	N	N	N	1,3,5	1	1,2,3,4,5,8,6	5	147	163	3	1
57	St. Marks Ang. Primary School Ajegunle Arun	2	2	1	4	12	1	6	200	200	N	N	N	-	-	1,2,3,4,5,9	5	87	83	1	1
58	St. Matthew's C.A.C Islu Idanre	2	12	6	18	20	6	4	200	100	N	N	N	5	4	2,3,4,5,8	5	176	160	-	13
59	St. Michael's C&S Pry Schl Yaba Idanre	3	16	5	-	40	5	20	240	240	N	N	N	1,4,6	-	1,2,3,4,5,8,9	1	374	415	3	15
60	St. Michael's Primary School Utaja	2	5	2	8	20	-	10	50	50	N	N	N	1,5	1	1,2,3,4,5,8,9	5	55	25	2	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 51 Contd

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers	M	F
61	St. Micheal's Ang. Pry Schl, Ala- Elefosan	2	19	10	40	64	10	2	240	460	N	N	N	5	1,4	2,3,4,5,8,9	5	251	308	4	7
62	St. Patricks RCM Pry. School Idanre	3	21	12	14	30	12	9	260	260	N	N	N	6	4	1,2,3,4,5,6,9,10	1	260	305	3	13
63	St. Paul's Primary School, Idale	2	8	-	6	6	1	9	180	180	N	N	N	1,5	-	1,2,3,4,5,9	1	143	157	4	10
64	St. Peter's Ang. Primary School Onisere	1	2	-	6	8	-	6	16	16	N	N	N	1	1	1,2,3,4,5,8,9,10	5	44	37	3	-
65	St. Peter's C.A.C Primary School Alade- Idanre	2	14	4	12	28	6	12	330	331	Y	N	N	1,6	1	1,2,3,4,5,8,9,10	5	215	151	4	26
66	St. Peter's Pry Schl Abababubu- Idanre	2	3	-	6	4	3	3	50	50	N	N	N	-	1	2,3,4,5,7,8,9,10	5	84	95	-	-
67	St. Philips A/C Primary School Abusoro	2	3	2	10	8	2	2	200	200	N	N	N	1,6	1	1,2,3,4,5,8,9,10	5	97	159	3	-
68	St. Stephen's A/C Pry Schl, Okejebu Idanre	2	12	-	-	-	-	12	240	240	N	N	N	1,4,6	1	2,3,4,5,8,9	1	211	198	-	-
69	St. Stephen's R.C.M Pry Schl, Owomofewa- Ala	1	3	N	6	12	1	-	24	24	N	N	N	1,5	1	1,2,4,6	5	69	78	3	-
70	St. Theresa's Primary School's Alade- Idanre	2	12	2	16	20	5	8	80	80	N	N	2	1,5	1	1-5,7,10	1	175	191	-	18

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6	(Q) SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5

123

TABLE 51 Contd

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		61	St. Micheal's Ang. Pry Schl, Ala- Elefosan	2	19
62	St. Patricks RCM Pry. School Idanre	3	21	12	14	30	12	9	260	260	N	N	N	6	4	1,2,3,4,5,6,9,10	1	260	305	3	13
63	St. Paul's Primary School, Idale	2	8	-	6	6	1	9	180	180	N	N	N	1,5	-	1,2,3,4,5,9	1	143	157	4	10
64	St. Peter's Ang. Primary School Onisere	1	2	-	6	8	-	6	16	16	N	N	N	1	1	1,2,3,4,5,8,9,10	5	44	37	3	-
65	St. Peter's C.A.C Primary School Alade- Idanre	2	14	4	12	28	6	12	330	331	Y	N	N	1,6	1	1,2,3,4,5,8,9,10	5	215	151	4	26
66	St. Peter's Pry Schl Abababubu- Idanre	2	3	-	6	4	3	3	50	50	N	N	N	-	1	2,3,4,5,7,8,9,10	5	84	95	-	-
67	St. Phillips A/C Primary School Abusoro	2	3	2	10	8	2	2	200	200	N	N	N	1,6	1	1,2,3,4,5,8,9,10	5	97	159	3	-
68	St. Stephen's A/C Pry Schl, Okejebu Idanre	2	12	-	-	-	-	12	240	240	N	N	N	1,4,6	1	2,3,4,5,8,9	1	211	198	-	-
69	St. Stephen's R.C.M Pry Schl, Owomofewa- Ala	1	3	N	6	12	1	-	24	24	N	N	N	1,5	1	1,2,4,6	5	69	78	3	-
70	St. Theresa's Primary Schoo's Alade- Idanre	2	12	2	16	20	5	8	80	80	N	N	2	1,5	1	1-5,7,10	1	175	191	-	18

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER
(P)	SCHOOL RECORDS				
	Admission Register	1			PHCN
	Attendance Register	2			Generator
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			Solar
	Visitors Book	5			None
					1 Other
					2
					3
					4
					5
					6

TABLE 51 Contd

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
71	St.Peter's A/C Primary School, Abababubu Idanre	2	3	2	10	20	4	8	240	240	N	N	N	-	1	1,2,3,4,5,8,9	5	69	84	4	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1			PHCN	1 Other 6
	Attendance Register	2			Generator	2
	Syllabus/Plan of Work	3			PHCN/Generator/	3
	Supervision Book	4			Solar	4
	Visitors Book	5			None	5

TABLE 52

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	C.A.C Grammar School Odode Idanre	1	10	10	40	40	10	20	105	105	Y	N	-	Y	4,5	1,2,4	2,3,5,8,9	3	167	163	11	8
2	Saint Joseph Cath Grammar School, Idanre	2	15	2	12	19	9	9	240	240	Y	N	-	Y	1,4,6	1,2,4	2,4-6,8,9	1	453	419	18	16
3	Idanre Hihg School, Alade Idanre	2	8	-	-	-	8	8	400	400	N	N	4	Y	1,6	1,4	1-6,8,9	3	172	126	9	17
4	Olofin Ang Grammar School, Idanre	2	14	14	-	-	-	-	630	630	N	N	4	Y	1,4,6	1,4	1-5,8,9	3	610	-	15	6
5	Ilemobola Girls, High School Idanre	2	6	-	-	24	6	12	421	421	N	N	4	Y	4,5	1,2,3,4	1-9	1	-	476	7	11
6	Methodist High School, Idanre	2	12	10	48	48	10	12	701	701	Y	N	1,2,3	Y	1,5	1,2,4	2-9	1	366	391	13	14
7	Ala Comm High School Alaelefosan	3	6	-	24	12	4	6	120	120	N	N	-	Y	-	1	1-5,8-10	2	176	160	12	8
8	Ebun Ogunyimika Comp College Atosin Idanre	2	11	-	-	-	7	22	338	338	N	N	-	Y	1,5	1,2,4	2-5,8,9	1	299	317	10	15
9	Onisere Community High School Ofosu /Idanre	2	6	-	24	19	6	12	300	300	N	N	-	Y	1,4	1,4	2-4,8-9	2	206	146	6	4
10	Baptist High School Odoko Road, Idane	2	6	2	12	-	2	2	230	230	N	N	4,5	Y	3,6	1,2,4	1-9	1	202	179	8	8

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 52 Contd

IDANRE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	C.A.C Grammar School Odode Idanre	2	9	-	36	36	9	18	420	515	Y	N	-	Y	1,4,5	1,2	1-4,8,9	1,2,3	193	176	19	5
2	Saint Joseph Cath Grammar School, Idanre	2	11	9	44	40	11	22	178	178	Y	N	1,2,3,6	Y	1,4	1,2	1-6,8,9	1	304	272	23	7
3	Idanre Hing School, Alade Idanre	2	4	3	12	4	4	8	28	128	Y	N	1,2,3	N	4	1,4	2-5,8,9	3	220	179	12	9
4	Olofin Ang Grammar School, Idanre	2	14	-	-	6	4	4	350	350	Y	N	1,2,3	Y	4,5,6	1,2,4	1-9	3	498	-	21	10
5	Ilemobola Girls, High School Idanre	2	7	2	-	28	1	14	257	257	N	N	-	N	4,5	1,2	2-4,8,9	1	-	216	12	7
6	Methodist High School, Idanre	1	13	13	52	52	13	26	120	120	N	N	-	N	5	1,2,4	1-9	1	234	183	14	15
7	Ala Comm High School Alaelefosan	1	3	3	12	12	3	6	150	150	N	N	-	Y	1	1,2	1-6,8,9	2	150	111	9	6
8	Ebun Ogunyimika Comp College Atosin Idanre	2	10	2	10	30	2	4	377	377	Y	N	1,2,3	Y	1,4,5	1,2,4	1-6,8,9	1	203	174	16	19
9	Onisere Community High School Ofosu /Idanre	2	3	3	-	12	3	6	80	80	Y	N	-	Y	5	1,2	2-6,8,9	2	123	102	14	4
10	Baptist High School Odoko Road, Idane	2	6	2	12	4	3	6	273	273	Y	N	1,2,3	Y	1,4	1,2,4	1,2,4'1-6,8,9	3	188	160	15	5

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 53

IFEDORE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	St. Peters Anglican Pry Sch, Bolorunduro	2	7
2	Christ Ang Pry Sch Oresun/Ajagboto	3	4	4	14	13	2	7	160	170	-	-	-	1	-	1,2,3,4,5	5	120	145	13	0
3	Community Primary School Aro-Igbara-Oke	1	3	6	13	16	3	6	92	92	N	N	N	1,5	1	1,2,3,4,5	5	41	46	4	3
4	Community Primary School Eriji-Isarun	3	2	8	8	20	-	16	96	96	N	N	N	1,3	1,4	1,2,3,4,5	5	117	92	11	0
5	Community Primary School Ero	3	4	-	6	10	-	-	-	154	N	N	N	4,5	1	1,2,3,4,5	5	116	201	3	5
6	Community Primary School Ijare	3	8	8	8	8	8	8	60	88	N	N	N	1	1,4	1-5	5	70	80	2	12
7	Community Primary School Osinsin Isarun	3	6	3	-	4	3	-	114	114	N	N	N	5	1	1,2,3,4,5	5	83	75	7	4
8	Community Pry Sch Ibutitan Ilara-Mokin	2	3	-	3	12	3	6	-	-	N	N	N	1,3	1	1-5	5	21	26	3	-
9	Community Pry School Molete Igara-oke	3	10	3	18	16	2	16	370	400	N	N	N	1,2,6	1	1,2,3,4,5	5	144	157	1	11
10	Emmanuel Ang Primary School Ikota	2	16	-	20	48	5	2	-	-	N	N	N	1	1	1,2,3,4,5	5	96	100	2	13

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1			PHCN	1 Other 6
	Attendance Register	2			Generator	2
	Syllabus/Plan of Work	3			PHCN/Generator/	3
	Supervision Book	4			Solar	4
	Visitors Book	5			None	5

TABLE 53 Contd

IFEDORE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	Holy Trinity Pry Sch, Araromi Omoladan	2	4
12	L.A Primary School Ajegunle Elemo Igbara	2	5	3	6	6	3		86	84	N	N	N	1,5	1	1,2,3,4,5	5	64	62	-	0
13	L.A Primary School Olorunda, Igbara-Oke	2	6	4	6	4	-	5	230	240	N	N	N	1,3,5	1	1-5	5	58	71	5	1
14	Local Authority Primary School Owode Owena	2	14	2	10	12	2	2	-	-	N	N	N	1,5	1,4	1,2,3,4,5	5	170	163	5	4
15	Local Authority Pry Sch. Iloro Igbara-Oke	3	6	7	10	26	6	7	240	240	N	N	N	1	1	1,2,3,4,5	5	47	44	1	8
16	Muslim Primary School Ilarra Mokin	3	9	7	60	42	7	4	151	151	N	N	N	1,5	1	1-4,7-9	5	88	64	-	13
17	Muslim Primary School Ipogun	2	6	8	20	25	14	5	200	200	Y	N	N	-	1	1,2,3,4,5	1	120	134	8	4
18	St. Andrew's Primary School Ilara Mokin	3	15	0	13	15	2	14	440	440	N	N	N	1,5	1,4	1-5	5	206	224	2	18
19	St. Anthony's RCM Primary School Igbara-Oke	2	12	6	2	25	5	-	134	138	N	N	N	1	1	1,2,3,4,5	5	168	173	-	-
20	St. David's Ang Primary School Ibulesoro	3	6	4	24	28	9	12	276	276	N	N	N	1,5	1	1,2,3,4,5	1	117	151	3	12

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	



TABLE 53 Contd

IFEDORE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils		No of Teachers	
21	ST. David's Pry Sch. Ijare	3	10	3	10	10	1	5	125	125	Y	N	Y	5	1,2	1-4,7,8	5	12	12	4	5
22	St. John's Ang Primary School Ijare	2	6	6	10	14	3	5	100	100	N	N	N	1,5	1	1,2,3,4,5	5	35	43	3	9
23	St. Joseph's C.A.C Pry Sch, Ilara Mokin	2	5	12	14	19	12	10	108	108	N	N	N	1,	1	1-5	5	239	278	1	8
24	St. Joseph's Rcm Primary School Igbara-Oke	3	11	-	-	20	-	8	420	420	N	N	N	1,3	1	1,2,3,4,5	1	214	198	2	14
25	St. Jude's Ang Primary School Ipogun	3	14	4	29	27	4	7	180	180	N	N	N	1	1	1,2,3,4,5	3	177	199	9	6
26	St. Luke's Anglican Primary School Isarun	2	9	3	13	12	3	1	180	180	N	N	N	1	1,4	1,2,3,4,5	5	165	147	3	11
27	St. Mary's RCM Primary Schol, Ijare	3	15	0	25	20	6	20	236	224	N	N	N	1	1,2,4	1-5	5	123	123	5	
28	St. Mathias Ang Primary School Ibuji	2	9	-	10	-	-	8	294	294	N	N	N	1,5	1,4	1,2,3,4,5	5	180	153	9	2
29	St. Michael's Ang Primary Ijare	3	12	5	10	10	6	6			N	N	N	1,3,5	1,4	1,2,3,4,5	1	244	205	3	17
30	St. Michael's Ang Primary School Ero	3	8	-	10	10	1	2	246	246	N	N	N	1	1	1,2,3,4,5	1	113	90	3	6

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6	(Q) SOURCE OF ELECTRIC POWER		
(P)	SCHOOL RECORDS				PHCN	1 Other	6
	Admission Register	1			Generator	2	
	Attendance Register	2			PHCN/Generator/	3	
	Syllabus/Plan of Work	3			Solar	4	
	Supervision Book	4			None	5	
	Visitors Book	5					

TABLE 53 Contd

IFEDORE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		21	ST. David's Pry Sch. Ijare	3	10
22	St. John's Ang Primary School Ijare	2	6	6	10	14	3	5	100	100	N	N	N	1,5	1	1,2,3,4,5	5	35	43	3	9
23	St. Joseph's C.A.C Pry Sch, Ilara Mokin	2	5	12	14	19	12	10	108	108	N	N	N	1,	1	1-5	5	239	278	1	8
24	St. Joseph's Rcm Primary School Igbara-Oke	3	11	-	-	20	-	8	420	420	N	N	N	1,3	1	1,2,3,4,5	1	214	198	2	14
25	St. Jude's Ang Primary School Ipogun	3	14	4	29	27	4	7	180	180	N	N	N	1	1	1,2,3,4,5	3	177	199	9	6
26	St. Luke's Anglican Primary School Isarun	2	9	3	13	12	3	1	180	180	N	N	N	1	1,4	1,2,3,4,5	5	165	147	3	11
27	St. Mary's RCM Primary Schol, Ijare	3	15	0	25	20	6	20	236	224	N	N	N	1	1,2,4	1-5	5	123	123	5	
28	St. Mathias Ang Primary School Ibuji	2	9	-	10	-	-	8	294	294	N	N	N	1,5	1,4	1,2,3,4,5	5	180	153	9	2
29	St. Michael's Ang Primary Ijare	3	12	5	10	10	6	6			N	N	N	1,3,5	1,4	1,2,3,4,5	1	244	205	3	17
30	St. Michael's Ang Primary School Ero	3	8	-	10	10	1	2	246	246	N	N	N	1	1	1,2,3,4,5	1	113	90	3	6

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
(P)	SCHOOL RECORDS				PHCN	1 Other	6
	Admission Register	1			Generator	2	
	Attendance Register	2			PHCN/Generator/	3	
	Syllabus/Plan of Work	3			Solar	4	
	Supervision Book	4			None	5	
	Visitors Book	5					

TABLE 53 Contd

IFEDORE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers	M	F
31	St. Michael's Ang Priy Sch Ilara Mokin	1	7	18	16	46	18	15	80	80	N	N	N	-	1	1,2,3,4,5	5	100	83	1	11
32	St. Paul's Ang Primary School Igbarra-Oke	3	21	3	39	55	2	22	600	600	N	N	N	1,2,5	1,2,4	1-5	3	232	215	2	19
33	St. Paul's C.A.C School Ipogun	3	5	6	20	20	3	16	102	102	N	N	N	-	-	1,2,3,4,5	-	46	38	4	4
34	St. Paul's RCM Primary School Ibulesoro	3	7	0	16	10	4	10	330	330	N	N	N	-	-	1,2,3,4,5	5	139	179	3	11
35	St. Peter's Anglican Primary School Ijare	2	14	6	10	20	5	14	600	600	N	N	N	3,5	1,4	1,2,3,4,5	1	272	266	2	30
36	St. Peter's C.A.C Pry Sch, Igbara-Oke	3	9	6	17	17	5	14	214	-	N	N	N	1,2	1,4	1,2,3,4,5	5	218	237	1	11
37	St. Peters Claver's R.C.M. Pry Sch, Ilara Mokin	3	14	0	15	15	0	15	380	380	N	N	N	1,3,5	1	1-5	1	176	162	2	15
38	St. Stephen's Primary School Igbara-Oke	2	8	-	4	5	3	12	80	80	N	N	N	1	1	1-5	5	50	57	1	3
39	ST.John's Ang. Pry Sch. Igbara Oke	3	6	6	12	20	6	10	125	125	Y	N	N	1	1	1-5	5	105	110	1	8
40	Surajudeen Muslem Pry Sch Igbara-Oke	2	5	-	10	4	3	6	180	178	N	N	N	1	1	1,2,3,4,5	5	105	100	3	7

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1			PHCN	1 Other 6
	Attendance Register	2			Generator	2
	Syllabus/Plan of Work	3			PHCN/Generator/	3
	Supervision Book	4			Solar	4
	Visitors Book	5			None	5

TABLE 53 Contd

IFEDORE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
41	The Apostolic Primary School, Igbara Oke	2	8	6	5	10	6	4	72	76	N	N	N	1,3	1	1-5	5	74	96	2	7
42	The Apostolic Primary Sxhool I. Ilara Mokin	3	10	6	24	20	3	10	164	168	Y	N	N	1,3,5	1	1,2,3	5	180	152	2	16
43	L. A Pry Sch Ajebamidele, Igbara-Oke	3	7	-	8	8	2	7	180	180	N	N	N	-	1	1-5,8,9	5	97	133	8	1
44	ST. David's Ang. Pry. Sch., Irese	2	11	9	-	4	3	6	124	136	N	N	Y	1	1	1-5,8-9	5	140	136	5	13
45	ST. David's CAC Sch. Ijare	3	3	6	20	20	3	6	250	250	N	N	Y	1,4,5	-	1-5,8,9	-	166	106	3	14
46	ST. JOHN'S CAC Pry. Sch; Ilara-Mokin	2	6	-	-	-	-	5	400	400	N	N	N	3,6	1	1-3,5,8-9	4	68	83	1	13

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 54

IFEDORE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Alasagba Comm. High Sch, Ibuji	3	3	-	-	-	-	-	65	65	N	N	-	Y	1,5	1,4	2-5,9-10	5	47	25	4	5
2	Ang. Gramm. Sch, Ijare	3	9	6	10	16	6	5	110	110	N	N	1	Y	-	1,2	1-4,8-9	1	198	239	13	15
3	Anglican Grammar School, Ero.	3	3	3	10	12		6	77	82	Y	N		Y		1,2,4	1-5,8,9	1	89	69	7	10
4	Anglican Grammar School, Igbara-Oke	2	12	8	5	15	15	15	580	580	N	N	4	Y	2,5,6	1-4	2-5,8,9	1	396	304	13	11
5	Ayo Grammar School	2	3	3	-	10	-	6	260	260	N	N	-	Y	1,	1	1-10	-	108	125	5	4
6	C.A.C Comprehensive High, Ijare	2	5	3	15	-	-	2	67	134	N	N	-	Y	3,6	1,2	1-4,8-10	1	146	119	7	21
7	Community High Sch. Isarun	1	8	-	10	2	-	10	120	120	N	N	4	N	1	1,4	1-5,8,9,	3	127	104	11	12
8	Community –Olua H/S Igbara-Oke	2	10	-	10	20	10	10	442	442	N	N	1,2,3,5	Y	1	1,3	2-5,8,9	1	222	213	16	10
9	Community Scondary School Ilara Mokin	3	18	3	8	12	9	8	-	-	N	N	-	Y	1,5	1,2	1-10	1	137	113	31	12
10	Jooro High School, Ibulesoro	3	6	5	18	8	-	4	125	125	Y	N	-	Y	1	1	1-5,8,9	1	65	55	6	14

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 54 Contd

**IFEDORE**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS**

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of	No of Functi	No of roofs	No of walls	No of windo	No of floors	No of doors	Total access	Total access	Availa bility	Library well	Labora tories	Availa bility	Health / Water	Recrea tional	School Record	Source of	No of Pupils		No of Teachers	
																				M	F	M
11	The Apostolic High School Ilara	2	8	3	10	15	3	10	422	422	N	N	-	N	1	1	2-5,8,9	1	211	191	12	22

**KEY**

**(B) NATURE OF BUILDING:**

- Mud 1
- Cement/Burnt Brick 2
- Both 3
- Others 4

**(M) LABORATORY:**

- Physics 1
- Chemistry 2
- Biology 3
- Intro. Tech. 4
- Home Econs. 5
- Others 6

**(O) HEALTH/WATER/SANITATION FACILITIES:**

- Wash Hand Basin 1
- Pipe Borne Water 2
- Bore Hole 3
- Protected Well 4
- VIP/Traditional Pit Latrine 5
- Water Closet 6

**(P) RECREATIONAL FACILITIES**

- Play Ground 1
- School Hall 2
- Table Tennis Court 3
- Food Vendor/Canteen 4
- Swimming Pool 5

**(Q) SCHOOL RECORDS**

- Admission Register 1
- Attendance Register 2
- Syllabus/Plan of Work 3
- Supervision Book 4
- Visitors Book 5

**(R) SOURCE OF ELECTRIC POWER**

- PHCN 1 Other 6
- Generator 2
- PHCN/Generator/ 3
- Solar 4
- None 5

TABLE 54 Contd

IFEDORE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Anglican Grammar School, Ero.	3	8	6	12	12	-	16	65	65	Y	N	1,2,3,	Y	1	1,2,	2,5,8,9,	1	96	83	11	8
2	Anglican Grammar School, Igbara-Oke	2	10	-	8	14	-	6	44	250	Y	Y	2,3	Y	1	1,2.	2,6-9	1	175	230	25	13
3	Ayo Grammar School, Ipogun	2	10	3	18	6	4	5	170	340	Y	N	1,3	Y	4	1	2-10	1	70	40	17	9
4	C.A.C Comprehensive High, Ijare	3	9	-	12	7	3	9	100	90	N	N	-	Y	1	1,4	2-6,8,9,	1	119	94	21	12
5	Community High Sch. Isarun	2	9	7	25	10	7	10	250	250	N	N	-	Y	1	,1,2,	1-9	3	137	113	17	9
6	Community –Olua H/S Igbara-Oke	2	9	3	16	20	2	8	100	100	1,3	Y	1	N	1	1,2	2,5,8,9.	3	219	231	12	8
7	Community Secondary Sch. Ilara Mokin			6	40	13	7	16	120	120	Y	N	2	Y	1,4	1,2	1-10	1	117	120	10	6
8	Jooro High School, Ibulesoro	3	3	3	3	4	-	3	115	115	N	N	-	Y	1	1,2	1,6,8,9,	1	42	52	10	11
9	The Apostolic High School Ilara	-	-	5	15	10	-	3	600	600	N	N	-	Y	1	1	2,5,6,8,9,	3	210	220	2	8
10	Ang. Gramm. Sch, Ijare	3	9	2	19	10	3	10	335	335	Y	Y	4	Y	1,3,5	1	2-6,8-8	1	120	135	10	9

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 55

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	Baptist Pry Scool Igbobi	2	6
2	Community Primary Sch. Ebiwon	3	6	-	-	-	-	-	100	100	N	-	-	1	1	2,3,4,5,8,9	5	349	362	8	2
3	L.A School Ogororo	2	9	3	28	48	4	8	679	236	N	N	N	-	1,3,4	1,2,3,8,9	5	464	407	8	2
4	Baptist Day Pry Sch Atijere	4	6	6	24	24	6	10	126	126	N	N	N	1,3,5	1	2,3,4,5,8,9	3	504	432	4	5
5	C&S Comm. Pry Sch Agbala, Obinehin	2	6	3	4	4	1	4	375	360	Y	N	Y	1	1	2 <sup>1</sup> 5,8,9	5	183	251	4	3
6	C/S Community Pry Sch. Oropo	2	6	-	-	-	-	-	240	240	N	-	Y	1, 5	1	1 <sup>1</sup> 5,8,9	5	321	202	9	3
7	C/S Pry Sch Yonrin/Itiola	3	6	-	-	24	-	12	280	280	N	-	Y	1,	1, 2	1 <sup>1</sup> 6,8,9	5	125	115	4	2
8	Christ Ang. School Aboto	2	6	-	-	-	-	-	260	260	Y	N	N	1	1	1,2,3,5,8,9,10	5	440	441	4	10
9	Christ F.A.C Pry Sch. Odo-Nla	3	6	4	16	16	4	8	280	280	N	-	N	1	-	2,3,4,8,9	5	445	433	7	8
10	Church Of Christ Pry Sch, Ori-Oke, Harama	2	6	3	12	12	3	6	200	200	N	-	Y	1, 5	-	1-8-10	5	131	134	1	2

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
			Water Closet	6		
(P)	SCHOOL RECORDS			(Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	



TABLE 55 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	Comm. Pry Sch. Mofere	2	7
12	Comm. Pry School Ayetitun	2	6	6	24	24	6	12	600	600	N	-	Y	1,3,5	1	1-4,8,9	2	504	481	1	7
13	Comm. Pry School Ayetoro	3	8	7	8	12	7	10	440	440	N	N	-	-	1	1,2,3,4,5,8,9	5	494	622	6	7
14	Comm. Pry School, Kurugbene	2	1	2	8	8	2	4	478	456	N	-	Y	-	1,4	1,2,3,8,9	2	417	287	2	1
15	Comm. Pry. Sch. Ehinmore	3	6	-	-	16	-	12	800	800	N	N	Y	-	-	2,3,4,9	5	411	400	5	2
16	Comm. Pry. Sch. Elumalero	2	3	-	-	-	-	-	120	120	N	-	-	1	1	1,2,3,4,5,8,9	-	189	99	3	1
17	Comm. Pry School Olotu	3	6	-	-	-	-	12	130	90	N	N	Y	1,5	1,5	1,2,3,4,5,8,9,10	2	285	140	6	6
18	Community Pry. Sch. Oke Ewa	2	6	-	-	32	-	4	200	200	N	-	Y	-	1	1,2,3,4,8,9,10	5	402	349	5	2
19	Community Primary Idigho	2	4	-	16	16	4	8	18	14	N	-	-	-	1	1,2,3,4,5,8,9,10	5	613	392	3	-
20	Community Primary Sch. Oke Shillo	4	6	-	-	24	-	-	160	300	N	N	-	1	-	1,2,3,4,5,8,9	5	545	368	5	1

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
			Water Closet	6 (Q)		
(P)	SCHOOL RECORDS			SOURCE OF ELECTRIC POWER		
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 55 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		21	Community Primary School, Ebijimi	4	6
22	Community Pry Sch. Magbehinwa	4	6	-	-	-	-	8	208	208	N	-	Y	1	-	1-5,8-10	-	547	368	9	3
23	Community Pry Sch. Okesiri	2	9	-	-	-	-	-	416	360	Y	N	-	1	1,4	2-5,8,9	5	247	260	8	3
24	Community Pry School Holy Centre	2	6	-	-	-	-	-	400	400	N	-	N	1, 5	1	1,2,4,5,8,9	5	198	196	5	-
25	F.A.C Primary Odo Fado	3	6	-	-	-	-	-	200	200	N	-	-	1	1	2,3,4,5,8,9,10	5	527	398	5	2
26	Facm Pry School, Igbokoda	2	26	1	32	30	7	20	1152	1140	N	-	Y	1,3,5,6	1,3,4	2,3,4,5,8,9	1,2	801	1043	11	49
27	Holy Trinity Ang Pry Igbokoda	2	13	-	20	16	-	14	760	760	N	N	Y	1	1,4	1,2,3,4,5,8,9,10	2	792	777	11	44
28	L .A. Pry Sch Ikorigho	4	6	-	-	-	-	12	480	480	N	N	N	-	1	1,2,3,4,	5	399	428	3	3
29	L.A Primary School Idogun	4	12	-	-	-	-	6	290	294	Y	N	N	1	1	1,2,3,4,5,8,9,10	5	215	189	9	5
30	L.A Pry Sch. Ogboti	3	10	-	-	-	-	-	180	180	N	N	N	1	1	2,3,4,5,8,9	5	185	201	7	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 55 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		31	L.A Pry Sch. Piawe	-	-
32	L.A Pry, School Ubale	3	6	2	12	24	3	12	750	740	N	N	Y	1	1	1-3,8,9	5	409	376	4	2
33	L.A Pry. School Ile-Funfun	3	6	-	-	-	-	4	160	160	N	-	N	1, 5	1	1-5,8,9	5	368	343	3	2
34	L.A School, Awoye	4	6	-	-	8	2	6	120	120	N	-	-	1,5	-	2-5,8,9	5	295	398	4	2
35	L.A. Pilot Pry. Sch. Ode Mahin	2	9	2	8	4	2	4	240	240	N	-	Y	1,5	1	1,2,3,4,5,8,9,10	5	433	430	6	6
36	L.A. Pry Sch Ajegunle Sea Side	3	7	-	-	-	-	-	240	240	N	-	Y	1	-	1,2,3,4,5,8,9	5	391	428	2	2
37	L.A. Pry Sch Molutehin	4	6	12	88	55	12	22	240	240	N	-	N	5	1,4	1,2,3,4,5,8,9	5	450	398	7	-
38	L.A. pry sch. obe idapo	4	12	-	-	48	-	-	240	240	N	-	N	1	N	1,2,3,4,5,8,9,10	5	402	418	-	1
39	L.A. Pry School Araromi Seaside	2	9	3	36	24	6	9	200	200	N	N	N	1	1	1,2,3,4,5,8,9,10	5	525	577	7	1
40	L.A. Pry School Ipepe	2	6	5	20	15	6	7	200	200	N	-	-	1,6	1	1,2,3,4,5,8,9	5	423	376	3	1

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 55 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		41	L.A. Pry School Iwamimo	2	6
42	L.A. Pry School Yaye	3	6	-	-	20	-	4	180	180	N	-	Y	1, 5	1	1-5,8,9	5	425	425	5	2
43	L.A. Pry School Zion-Pepe	2	9	8	3	5	12	5	155	155	N	-	N	1	1	1,2,3,4,5,8,9,10	5	494	574	10	8
44	L.A. Pry Sch, Ode Ugbo	2	6	6	12	24	6	12	213	200	N	N	N	1	1	1,2,3,4,5,8,9	5	364	357	7	6
45	L.A. Sch Odun-Ogun	-	-	-	-	-	-	-	57	57	N	N	N	1	1	2-5,8,9	5	425	404	3	2
46	L.A. Sch. Rama Shillo	3	3	3	12	3	3	6	120	120	N	-	-	1, 5	-	1-4,8,9,10	-	435	390	4	3
47	Local Auth Pry Sch. Erunna	3	2	4	24	24	6	12	240	240	N	N	Y	-	1	1,2,3,4,8,9	5	537	565	6	8
48	Local Authority Pry Sch Obe Rewoye	4	6	3	12	12	3	6	600	620	N	-	-	1,5	1	1,2,3,4,8,9,10	5	409	412	14	9
49	Local Authority Pry Sch, Orotu	3	6	-	-	-	-	4	234	234	N	-	N	1	1	1,2,3,4,5,8,9	5	393	380	7	3
50	Local Authority Pry Sch. Ajegunle Enoma	2	13	7	16	28	13	14	273	273	N	-	Y	1	1	2-5,8,9	5	580	588	10	7

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 55 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		51	Local Authority Pryb Sch Abeoroyo	2	6
52	Local Authority Pry School, Idibengben	2	6	-	-	20	3	-	120	120	N	N	N	1	1	1-4,8,9	5	455	478	6	1
53	Methodist Pry Sch Ilepete	4	6	2	24	-	6	12	152	152	N	-	Y	1,3	-	1,2,3,4,5,8,9	5	795	800	4	6
54	Methodist Sch. Orere-Ara	2	-	4	16	-	-	-	154	154	N	N	N	1	1	2-9	5	143	163	2	5
55	Migrant Fisher Men Sch Iloro	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
56	Saint Paul's Ang Sch Idiogba	4	11	-	44	-	-	22	101	101	Y	N	Y	1	1	2,3,4,5,8,9	5	442	478	4	6
57	Saint peter's F.A.C. Pry Sch Obe Adun/ Obe Nla	4	6	-	24	24	-	2	144	144	Y	N	-	1	1	1,2,3,4,5,8,9	5	407	435	5	2
58	Saint Saviour's Ang . Pry Agerige	2	6	-	-	-	3	6	240	240	N	-	Y	1,4	1	1,2,3,4,5,8,9	5	395	432	-	-
59	St Barnabas Ang P.S Mahintedo	2	6	5	20	20	9	10	250	264	N	N	Y	1,5	1,4	1,2,3,4,5,8,9,10	4	128	101	7	8
60	St John Ang School, Imoluwa	2	3	4	16	16	4	8	168	168	N	N	-	1	1	2,3,4,5,8,9	5	87	88	4	3

KEY

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER
	Admission Register	1			PHCN
	Attendance Register	2			Generator
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			Solar
	Visitors Book	5			None
					1 Other
					2
					3
					4
					5
					6



TABLE 55 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		61	St John F.A.C Sch Ojumole	3	6
62	St Paul's F.A.C. Pry Sch Ilowo	4	6	-	-	24	-	12	200	200	N	N	N	1	-	1,2,3,4,5,8,9	-	368	378	4	4
63	St Philip's Ang School Ereke	2	6	-	24	24	6	6	320	320	N	-	-	1	1	1,2,3,4,5,8,9	5	220	215	6	7
64	St Saviour's F.A.C. Pry School, Etigbo	4	6	4	40	40	10	20	460	440	N	-	Y	1	4	1,2,3,4,5,8,9	5	686	819	5	4
65	St. Andrew Ang. Sch. Agbala Olope	2	6	5	24	24	6	12	200	200	Y	Y	-	-	-	1,2,3,4,5,8,9	-	422	389	2	2
66	St. Anne's Rcm Igbo-Egunrin	2	5	3	48	8	5	4	200	200	N	-	N	1	1	1-4,8,9	5	161	156	6	10
67	St. Ben. Ang School Igbolomi	2	2	-	-	8	2	4	144	144	N	-	N	3	1	1-3,8,9	5	106	121	2	5
68	St. Catherine Rcm Pry Ebute Ipare	2	8	4	16	34	8	24	180	180	N	N	Y	1	1	1,2,3,4,5,8,9	5	119	136	9	1
69	St. Emmanuel F.A.C Pry Sch. Akata	2	6	-	24	-	-	-	164	152	N	N	N	1	1	2-5,8,9	5	88	96	1	4
70	St. John F.A.C Apatá Obe	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER
(P)	SCHOOL RECORDS				
	Admission Register	1			PHCN
	Attendance Register	2			Generator
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			Solar
	Visitors Book	5			None
					1 Other
					2
					3
					4
					5
					6

TABLE 55 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		71	St. John Fac School Seja Odo	3	8
72	St. John's Ang Pry School, Mоторо	4	3	-	8	4	2	6	120	120	N	-	Y	1	5	1-5,8,9	5	372	288	4	1
73	St. Jude's Ang Pry Sch. Atijere	2	8	-	-	6	-	-	200	200	N	-	N	1,4	1	1,2,3,4,5,8,9	5	376	422	5	7
74	St. Luke's Ang. Sch. Ode Etikan	2	19	7	64	53	3	26	520	400	Y	N	N	1,5	1	1,2,3,4,5,8,9,10	5	479	463	8	4
75	St. Lukes Ang Igboegunrin	2	13	-	8	8	-	12	388	388	Y	N	Y	1,3,5	1	1,2,3,4,5,8,9	5	130	290	4	6
76	St. Luke's Ang Pry,School, Itebu-Kunmi	2	6	3	12	-	3	6	200	220	N	N	N	1	1	1-5,8,9	5	360	366	9	4
77	St. Matthew's Fac Jinrinwo	4	6	-	-	5	-	6	216	216	N	-	-	1,3	-	1,2,3,4,5,8,9,10	5	371	371	4	4
78	St. Moses Cs Pry Sch, Orotо	2	9	3	12	12	3	10	600	600	N	N	Y	1	1	1,2,3,4,5,8,9,10	5	420	355	5	8
79	St. Paul's F.A.C. Pry School, Kugbonre	4	6	-	-	24	-	12	160	160	N	N	N	1	-	1-5,8,9	5	244	241	2	2
80	St. Peter's Fac Sch Idapo Asisa	1	6	6	24	-	11	12	100	100	Y	N	N	1,5	1	1,2,3,4,5,8,9	5	138	155	3	5

KEY

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	



TABLE 55 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		81	St.Jude's Fac Alagbon	4	6
82	St.Jude's Fac Obinehin	2	6	3	4	4	3	6	414	400	N	-	Y	1	1	1-5,8-10	5	232	189	3	1
83	Surulere Comm. Pry. Sch. Zion Igbokoda	2	6	3	8	8	3	8	744	760	N	N	Y	1, 5	1, 4	1-5,8-10	-	396	408	6	27
84	United Anglican Abe-Alala	3	8	2	-	24	1	12	414	414	N	N	N	1	1	1-5,8-10	5	456	478	5	3
85	Zion C & S Pry Sch. Ugbo nla	2	15	2	-	8	2	4	700	680	Y	-	Y	1,5	1,4	1-5,8-10	2	491	500	7	12
86	Zion C&S Pry Sch Abe-Okun Ipin	2	8	3	12	24	2	12	60	50	N	N	Y	1	1	1,2,3,4,5,8,9	5	303	229	1	7
87	Zion C&S Pry Sch. Abereke	4	6	4	6	12	-	12	660	660	N	N	Y	1, 5	1	2-4,8,9,10	2	409	367	5	3
88	Zion C&S Pry Sch. Okonla	2	6	-	12	-	-	-	240	240	N	-	-	1, 4	1	2-5,8,9	5	402	474	4	6
89	Zion C&S Pry School Ilu-Ayo	2	6	-	-	-	-	8	200	200	N	N	-	1, 5	1	2-4,8,9,10	5	308	166	4	4
90	Zion C/S Comm. Pry Sch Abetobo	4	4	1	20	20	5	10	80	80	N	-	N	1	1	2-5,8-10	5	430	348	4	1

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6	
(P)	SCHOOL RECORDS		6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other 6
	Attendance Register	2		Generator	2
	Syllabus/Plan of Work	3		PHCN/Generator/	3
	Supervision Book	4		Solar	4
	Visitors Book	5		None	5

TABLE 55 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
91	Zion C/S Sch, Odun-Oyinbo	4	4	2	-	8	-	6	206	206	N	-	Y	1	-	1,2,3,4,5,8,9,10	2	359	481	4	-
92	Zion Cherubim/ Seraphim, Oke-Ipare	2	6	-	-	24	-	12	140	140	N	-	N	1	1	2-4,5,8,9	5	361	400	3	3
93	Zion Fac Pry School Gbabijo	3	8	2	20	44	8	22	300	300	N	-	Y	1	1	2,3,4,5,8,9	5	533	566	5	7
94	Zion Primary Sch. Ibila	4	3	-	-	12	-	6	200	200	N	N	N	-	1	2,4,8,9	5	354	384	5	1

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 56

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Cherubim & Seraphim Academy Ugbonla	2	3	3	12	12	3	6	440	220	Y	N	-	Y	5	1,4	2,5,8,9	1	187	188	6	1
2	Aheri Jnr Grammar School, Agerige	2	3	6	24	24	6	12	324	260	N	N	-	Y	-	1,2	1-3,8,9	5	121	81	2	-
3	Aheri Jnr Grammar School, Ereke	2	5	1	-	20	-	12	328	328	N	N	-	N	1,5	1	2-5,8-10	2	223	197	8	-
4	Comm Gram Schl, Orioke-Iwamimo	2	6	6	24	24	6	12	563	563	N	N	-	N	1,5	1,4	1-5,8-10	5	295	268	4	1
5	Community Grammar School, Araromi Sea Side	2	5	-	-	20	-	12	446	446	N	N	-	N	1,5	1,4	1-5,8,9	5	302	269	4	-
6	Community Grammar School, Idi-Ogba	4	6	-	24	24	6	12	320	320	N	N	-	Y	1	1,4	1-6,8-10	2	177	162	6	-
7	Community Grammar School, Igboegunrin	2	3	-	-	16	1	8	120	120	Y	N	-	Y	5	1,4	2-6,8,9	2	70	60	10	1
8	Community Grammar School, Ilepote	2	3	-	-	-	-	-	90	100	N	N	-	Y	1,3,5	1,3,4	2-5,8,9	2	311	213	7	2
9	Community Grammar School, Obe-Idapo	2	3	-	12	12	3	6	264	264	N	N	-	Y	1	1,4	1-5,8,9	5	133	131	7	1
10	Community Grammar School, Zion Pepe	2	8	-	20	20	-	10	200	200	N	N	-	Y	1,4,5	1	1-5,8,9	2	280	215	3	2

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 56 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Etikan High School, Etikan	2	8	5	28	20	2	26	379	379	N	N	6	Y	1,5	1,4	1-6,8,9	2	297	204	8	-
12	Gbabijo High School, Orioke	2	3	-	-	-	-	-	200	200	N	N	-	Y	1	1,4	1-5,8-10	5	388	312	5	-
13	Happy City College, Ayetoro	3	5	5	32	40	10	20	300	320	N	N	-	Y	1	1,3,4	2-4,8,9	2	437	385	6	3
14	Igbokoda Grammar School, Igbokoda	3	8	4	4	14	4	14	350	410	N	N	-	Y	1	1,4	1-10	5	1266	573	7	9
15	Igomoni Community Grammar School, Ipare	2	3	-	-	8	-	6	320	320	Y	N	-	Y	-	1	1-6,8,9	5	211	190	3	1
16	Ilaje Grammar School, Atijere	2	10	3	12	0	0	16	150	150	N	N	N	Y	1	1,4	2-5,8,9	5	167	158	8	6
17	Ilaje High School, Igbokoda	2	12	-	48	48	12	24	1120	1120	Y	N	-	Y	1,5,6	1,2,4	1-6,8,9	1,3	734	703	3	4
18	Ilumeje Comm. Grammar School, Mahintedo	2	3	-	-	-	-	-	87	87	N	N	-	Y	2,5	1,2,4	1-5,8,9	3	132	104	7	4
19	Mahin Community Hig School, Odemahin	1	3	-	-	12	3	6	150	150	N	N	-	Y	1,5	1	1-4,8-10	4	102	91	4	5
20	Mogunhen High School, Okorigho	4	3	-	-	12	3	6	100	150	N	N	-	Y	1,3,5	1	1-6,8,9	5	192	202	3	-

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 56 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
21	Molutehin Comprehensive College, Imoluwa	2	6	1	4	-	-	-	156	156	Y	N	-	N	1,5	1,2,4	2-5,8-10	5	248	215	6	-

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 56 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Cherubim & Seraphim Academy Ugbonla	2	6	9	12	60	6	30	189	207	Y	Y	1,2	Y	1,5	1,3,4	1-10	2	296	202	14	5
2	Aheri senior Grammar School, Agerige	2	3	3	12	12	3	6	145	145	N	N	1-3	Y	1	1,2	2-4,8,9	2	-	-	-	-
3	Aheri senior Grammar School, Ereke	2	12	6	-	24	6	12	240	332	N	N	1-3	Y	1	1,4	1-5,8,9	2	443	241	7	1
4	Comm Gram Schl, Orioke-Iwamimo	2	6	3	24	-	-	12	460	460	N	N	6	Y	1,5	1,2,4	1-4,8-10	2	385	215	12	1
5	Community Grammar School, Araromi Sea Side	2	4	-	-	-	-	4	320	320	N	N	6	Y	1,4,5	1,4	1-5,8,9	2	228	238	9	1
6	Community Grammar School, Idi-Ogba	3	6	-	-	-	-	-	210	130	N	N	-	N	1,5	1	1-10	2	258	246	9	4
7	Community Grammar School, Igboegunrin	2	8	4	16	16	4	8	120	120	Y	N	1-3	N	1	1,2,4	1-6,8-10	5	113	78	27	2
8	Community Grammar School, IllepEte	2	6	-	-	-	-	-	120	120	N	N	-	Y	1,3,5	1,2	1-6,8,9	2	227	190	6	1
9	Community Grammar School, Obe-Idapo	3	3	-	-	-	-	-	84	84	N	N	1-3	N	1	1,4	1-5,8,9	5	-	-	-	-
10	Community Grammar School, Zion Pepe	2	7	1	44	33	-	2	158	146	N	N	1,2,3,6	N	1,5	1,4	1-4,8-10	5	349	221	7	-

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 56 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Etikan High School, Etikan	2	9	3	-	12	-	6	290	290	N	N	1-3	Y	1	1	2-4, 6, 8,9	2	226	170	7	-
12	Gbabijo High School, Orioke	2	9	6	-	-	-	-	210	233	N	N	6	N	1	1,4	1-10	2	333	219	14	1
13	Happy City College, Ayetoro	4	4	6	32	48	6	16	436	436	N	N	1-3	Y	1,3	1	1,5,8,10	2	377	279	19	2
14	Igbokoda Grammar School, Igbokoda	2	8	-	3	3	3	3	200	200	N	N	-	N	1,3,6	1	1-3,8,9	2	491	296	17	9
15	Igomoni Community Grammar School, Ipare	2	3	3	12	24	3	12	160	160	Y	N	1-3	Y	1,3,5	1	1-6,8,9	5	213	179	10	-
16	Ilaje Grammar School, Atijere	2	10	4	32	28	7	14	401	350	Y	Y	Y	Y	1,6	1,3,4	1-10	2	327	207	23	8
17	Ilaje High School, Igbokoda	2	11	-	20	20	5	10	552	952	N	N	1-3	Y	4,5,6	1,2,4	1-6,8,9	3	536	395	2	4
18	Ilumeje Comm. Grammar School, Mahintedo	2	-	5	20	24	6	12	120	120	Y	Y	6	N	1,2,5	1,4	1-6,8,9	3	219	194	18	4
19	Mahin Community Hig School, Odemahin	2	5	-	-	20	-	-	350	350	N	N	6	Y	1	1,4	1-6,8,9	3,4	113	85	17	-
20	Mogunhen High School, Okorigho	3	6	-	24	24	6	12	300	320	N	N	-	N	1	1	1-5,8,9	5	219	164	9	1

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 56 Contd

ILAJE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

SENIOR																						
S/N	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	No of Pupils		No of Teachers	
																				M	F	M
21	Molutehin Comprehensive College, Imoluwa	4	6	6	24	24	6	12	40	35	Y	N	1-3	Y	1	1,2,4	2-6,8-10	2	274	212	4	-

KEY

(B) NATURE OF BUILDING:

Mud 1  
Cement/Burnt Brick 2  
Both 3  
Others 4

(M) LABORATORY:

Physics 1  
Chemistry 2  
Biology 3  
Intro. Tech. 4  
Home Econs. 5  
Others 6

(O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin 1  
Pipe Borne Water 2  
Bore Hole 3  
Protected Well 4  
VIP/Traditional Pit Latrine 5  
Water Closet 6

(P) RECREATIONAL FACILITIES

Play Ground 1  
School Hall 2  
Table Tennis Court 3  
Food Vendor/Canteen 4  
Swimming Pool 5

(Q) SCHOOL RECORDS

Admission Register 1  
Attendance Register 2  
Syllabus/Plan of Work 3  
Supervision Book 4  
Visitors Book 5

(R) SOURCE OF ELECTRIC POWER

PHCN 1  
Generator 2  
PHCN/Generator/ 3  
Solar 4  
None 5



TABLE 57

ILE-OLUJI  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers		
1	St. Peter's (Ang) Primary School, Ile Oluji	2	14	11	29	47	13	11	404	404	Y	N	N	1,5	1	1,2,3,5,6,8,9	3	265	240	1	15
2	Local Authority Primary School, Olorunsogo, Ile Oluji	2	3	-	-	36	9	18	112	98	N	N	N	-	1	1,2,3,5,8,9	5	63	104	4	1
3	Adelogba Gomm. Pry Komowa Ile Oluji	1	5	6	24	24	4	12	120	120	N	N	N	1	1	1,2,3,4,5,8,9	5	111	129	5	3
4	All Saint Ang Primary School, Alarere, Okeigbo	3	8	4	16	24	2	6	115	115	N	N	N	1,4,5	1,4	1,2,3,4,5,7,8,9	5	206	225	2	1
5	All Saint Primary School, Ojokopohun	1	5	2	8	8	2	8	-	210	N	N	N	5	1	2,3,4,5,8,9	5	126	126	8	-
6	All Saint's Pry Sch, Olorunkemilrowa, Okeigbo	1	7	-	18	12	-	7	146	168	N	N	N	1,4,5	1,4	1,2,3,4,5,8,9,10	5	96	121	2	2
7	Ansarudeen Primary School, Okeigbo	2	11	6	24	-	-	12	406	406	N	N	N	1,2,5	1	1,2,3,4,5,8,9	1	110	113	3	8
8	Ayorinde Baptist Primary School, Iyire	3	7	5	21	20	4	10	302	302	N	N	N	1,5	1	1,2,3,4,5,8,9	5	239	251	3	7
9	Baptist Day Primary School, Ile Oluji	3	18	10	17	17	13	17	464	464	Y	N	N	1,4,5	1,2,4	2,3,5,6,8,9	1	463	447	4	22
10	C& S Primary School Ayesan	2	6	-	8	-	-	4	168	84	N	N	N	1	1	1,2,3,4,5,8,9	5	85	88	1	2

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 57 Contd

ILE-OLUJI  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers	M	F
11	C.A.C. Primary School, Ayegun, Ile Oluji	1	5	-	10	12	4	8	112	90	Y	N	N	1,3,5	1	2,3,4,5,8,9	5	116	129	4	2
12	Cherubim & Seraphim Pry Sch, Oke Igbala Odolu	3	6	2	12	30	4	10	200	200	N	N	N	1,5	4	1,2,3,4,5	5	59	75	1	10
13	Christ Ang. Primary School Araromi, Oke Igbo	3	3	3	-	12	-	6	66	66	Y	N	N	1,3,5	1	1,2,3,4,5	5	52	64	4	1
14	Christ Apostolic Church Community Primary School, Okeigbo	2	8	2	-	-	-	4	318	300	N	N	N	1,6	1,4	1,2,3,4,5,6,7,8,9,10	5	95	106	1	8
15	Christ Apostolic Church Primary	2	9	2	5	8	2	6	320	320	Y	N	N	1	1,4	2-10	5	159	170	1	13
16	Community Pimary School, Ayede Oja Ile Oluji	3	5	5	20	20	5	10	124	137	N	N	N	1	1	1,2,3,4,5,8,9,10	5	142	114	7	2
17	Community Pry Sch, Idi- Iroko, Okeigbo	3	6	-	-	6	6	6	126	132	N	N	N	1,5	1	1,2,3,4,5,8,9,10	5	148	168	1	6
18	Community Primary Kajola Leyeko Ile Oluji	3	11	9	42	40	9	20	136	136	N	N	N	5	1	1,2,3,4,5,8,9	5	102	118	5	1
19	Community Primary School Aba-Amuda	2	4	-	4	19	3	-	200	200	N	N	N	1,5	1	1,2,3,4,5,8,9	5	88	108	2	3
20	Community Pry Sch Farm Settlement, Ile Oluji	2	6	2	-	6	2	2	301	301	N	N	N	1,6	1	1-5,7-10	5	105	103	9	12

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	<b>SCHOOL RECORDS</b>		Water Closet	6 (Q)	<b>SOURCE OF ELECTRIC POWER</b>	
	Admission Register	1			PHCN	1 Other 6
	Attendance Register	2			Generator	2
	Syllabus/Plan of Work	3			PHCN/Generator/	3
	Supervision Book	4			Solar	4
	Visitors Book	5			None	5

TABLE 57 Contd

ILE-OLUJI  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		21	Community Pry Sch, Abojupa 2, Okeigbo	1	3
22	Community Pry Sch, Adigbolu, Okeigbo	1	2	9	27	27	9	18	256	254	N	N	N	1	1,4	1-5,7-10	5	252	290	2	4
23	Community Primary School, Ajegunle, Okeigbo	3	4	5	-	22	-	10	118	124	N	N	N	1,5	1,4	1,2,3,4,5,8,9	5	184	219	6	1
24	Community Pry Sch, Araomi Ajana Ile Oluji	1	5	5	15	15	5	8	39	30	N	N	N		1	1,2,3,4,5,8,9,10	5	132	135	4	1
25	Community Primary School, Ayedaade, Ile Oluji	1	4	2	10	10	3	7	100	100	N	N	N	1	1	1,2,3,4,5,8,9,10	5	44	58	-	3
26	Community Primary School, Badeji, ILE Oluji	1	2	2	8	8	2	4	120	120	N	N	N	1	1	1,2,3,4,5,8,9,10	5	88	78	4	2
27	Community Primary School, Balagbe, Okeigbo	2	5	-	-	10	6	6	115	115	Y	N	N	1,5	1,4	1,2,3,4,5,6,8,9	-	168	172	3	3
28	Community Primary School, Ehinoke-Okeigbo	2	4	2	8	8	-	-	192	192	N	N	N	5	1	1,2,3,4,5,8,9,10	5	101	90	2	5
29	Community Primary School, Erintuntun, Okeigbo	1	3	-	9	2	-	3	100	126	N	N	N	1		2,3,4,5,8,9	5	82	92	4	0
30	Community Primary School, Gberinlegi	3	4	3	12	20	5	10	112	112	Y	N	N	1,5	1	1,2,3,4,5,8,9	5	70	65	2	6

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6	(Q) SOURCE OF ELECTRIC POWER		
(P)	SCHOOL RECORDS				PHCN	1 Other	6
	Admission Register	1			Generator	2	
	Attendance Register	2			PHCN/Generator/	3	
	Syllabus/Plan of Work	3			Solar	4	
	Supervision Book	4			None	5	
	Visitors Book	5					

TABLE 57 Contd

ILE-OLUJI  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		31	Community Primary School, Iloro	1	6
32	Community Primary School, Ipoti, Ile Oluji	1	4	-	-	-	-	8	80	80	N	N	N	5	1	1,2,3,4,5,8,9	5	75	45	5	7
33	Community Primary School, Labosipo, Ile-oluji	3	4	4	16	16	4	8	160	100N	N	N	N	1,5	1	2,3,4,5,8,9	5	84	122	0	3
34	Community Primary School, Leegun Ile Oluji	1	4	-	2	2	1	6	108	108	N	N	N	1,5	1	1,2,3,4,5,8,9,10	5	100	99	2	3
35	Community Primary School, Oloju Fagunwa, Okeigbo	3	7	3	13	23	7	13	6	80	Y	N	N	1	1,4	2,3,4,5,8,9,10	5	74	106	5	-
36	Community Primary School, Orisunmibare Awo	3	3	3	12	12	3	8	74	54	N	N	N	1	1	1,2,3,4,5,8,9	5	93	86	3	2
37	Community Primary School, Orisunmibare Okeigbo	1	4	2	10	12	2	2	410	410	N	N	N	1,5	1	1,2,3,4,5	5	114	86	3	3
38	Community Primary School, Wasimi Odunwo, Ile Oluji	1	5	1	-	12	1	6	158	158	N	N	N	1	1,4	1,2,3,4,5,8,9	5	105	109	6	1
39	Community Primary School, Arowolo, Okeigbo	1	5	5	5	15	3	5	144	150	N	N	N	1,5	1	1,2,3,4,5,8,9	5	61	81	4	2
40	Community Pry Sch, Asana Fatanmi, Okeigbo	2	9	2	8	-	-	4	208	190	N	N	Y	1,5,6	1,4	1,2,3,4,5,8,9	2	140	147	4	2

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1			PHCN	1 Other 6
	Attendance Register	2			Generator	2
	Syllabus/Plan of Work	3			PHCN/Generator/	3
	Supervision Book	4			Solar	4
	Visitors Book	5			None	5



TABLE 57 Contd

ILE-OLUJI  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		41	Community Pry Sch, Bolorunduro Seriki, Okeigbo	1	5
42	Comm Pry Sch, Bolorunduro-Idiosan, Okeigbo.	2	6	6	8	16	-	6	80	80	N	N	N	1,4	1	1,2,3,4,5,8,9	5	197	205	2	3
43	Community Pry. Schl. Kajola Sanni, Okeigbo	2	6	0	10	6	-	6	240	240	N	N	N	1,4,6	1	1,2,3,4,5,8,9	5	86	85	4	2
44	Emmanuel Ang. Pry. Schl, Aratu/Olojo Oke Igbo	1	6	0	12	24	-	18	250	250	N	N	N	1,5	1	1,2,3,4,5,6,8,9	5	83	83	4	2
45	L. A. Primary School, Ayetoro-Agunla, Ile Oluji	3	6	2	2	8	-	4	240	240	N	N	N	1,5	1	1,2,3,4,5,8,9,10	5	164	147	9	1
46	L. A Primary School, Araromi Akinye, Ile Oluji	3	11	3	2	16	3	6	240	240	N	N	N	1,6	1	1,2,3,4,5,8,9	5	112	144	7	1
47	L. A. Primary School Ayetoro, Okeigbo	3	8	-	12	22	2	12	256	242	N	N	N	1,5,6	1,4	1,2,3,4,5,8,9,10	5	94	106	5	1
48	L. A. Primary School, Ile Oluji	1	6	-	18	18	3	10	85	98	N	N	N	1,3,4	1	1,2,3,4,5,8,9,10	5	58	62	2	1
49	L.A. Primary School Eyingun	2	6	4	22	24	5	8	240	240	N	N	N	1,6	1	1,2,3,4,5,8,9,10	5	193	182	4	3
50	L.A. Primary School, Okealaafia, Okeigbo	2	3	1	-	16	6	6	-	84	N	N	N	1,4,5	1,5	2,3,4,5,8,9	5	112	149	3	6

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 57 Contd

ILE-OLUJI  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		51	L.A. Primary School, Uloen, Ile Oluji	2	8
52	Local Authority Primary School, Igbolodunmare	1	2	1	12	12	2	3	140	140	N	N	N	1,4,5	1,4	2,3,4,5,8,9	-	98	93	6	1
53	Local Authority Pry Sch, Ile Oluji Ajiferere	3	9	2	6	7	-	2	400	372	N	N	N	1,4,5	1,4	1,2,3,4,5,8,9	1	71	63	1	10
54	Local Authority Primary School, Lota Ile Oluji	2	4	2	24	-	-	5	152	138	N	N	Y	1,3,5	1	1,2,3,4,5,8,9	2	83	89	5	-
55	Mcgee Memorials Baptist Pry. Sch, Ile Oluji	3	6	2	1	3	5	2	262	262	Y	N	N	1,4,5,6	4	1,2,3,4,5,6,8,9	1	85	122	4	17
56	Muslim Primary School Ile Oluji	3	22	-	-	-	-	10	260	270	N	N	Y	1,5	1	2,3,4,6,8,9,10	2	206	156	2	10
57	Muslim Primary School, Bamikemo	3	6	-	14	8	-	8	286	270	N	N	N	1,5	1,4	2,3,4,5,8,9,10	5	165	168	4	10
58	Saint Paul's (Ang) Primary School Bamikemo	3	12	4	24	24	4	14	336	324	N	N	Y	1	1	1,2,3,4,5,8,9	5	266	307	8	15
59	Saint Jame's Anglical Pry Sch, Bolorunduro, Okeigbo	3	6	2	20	24	2	4	240	240	N	N	N	5	4	2,3,4,5,8,9,10	4	46	68	1	6
60	Saint James Catholic School, Okeigbo	3	12	3	12	12	3	6	240	240	N	N	Y	5	1,4	2,3,4,5,8,9	2	116	123	2	9

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 57 Contd

ILE-OLUJI  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		61	Saint Joseph's R.C.M. School, Okeigbo	2	16
62	Saint Mark's Angelical Primary School, Okeigbo	3	7	8	24	24	6	12	228	228	N	N	N	1,5	1,4	1,2,3,4,5,8,9	5	163	148	3	11
63	Saint Matthews Primary School, Lipanu	2	14	12	20	50	2	30	500	500	Y	N	N	1,4,5	1	1,2,3,4,5,8,9	3	259	265	3	10
64	Saint Peter's Ang. Primary School, Oloruntele	2	13	5	20	15	10	-	150	150	N	N	N	1,5	1	1,2,3,4,5,8,9	-	78	88	1	13
65	Saint Peter's Primary Kajola Leyeko, Ile Oluji	2	6	4	10	10	4	8	372	372	N	N	N		4	1,2,3,4,5,8,9,10	5	120	156	4	3
66	St Michael's Primary School Odunwo Ile Oluji	2	6	-	-	4	-	-	185	185	N	N	Y	1,3,5	1	2,3,5,8,9	2	79	126	5	-
67	St. Andrew's Anglican Primary School, Okeigbo	2	11	3	-	12	-	4	262	254	N	N	N	1,5,6	1,2,4	1-5,7-10	5	144	129	1	10
68	St. Gabriel's (C & S) Primary School Okeigbo	2	9	3	24	24	6	18	340	340	N	N	N	1,2,6	1	1,2,3,4,5,8,9	4	124	161	2	7
69	St. George's Catholic Primary School, Ile Oluji	2	16	-	10	-	-	-	562	562	N	N	N	5	1,4	1,2,3,4,8,9,10	5	270	281	2	25
70	St. James's Primary School Ile Oluji	3	12	6	26	13	7	9	366	366	N	N	N	1,5	1,4	2,3,4,5,8,9	1	245	241	2	16

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	<b>SCHOOL RECORDS</b>		Water Closet	6 (Q)	<b>SOURCE OF ELECTRIC POWER</b>	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	



TABLE 57 Contd

ILE-OLUJI  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
71	St. John's Ang. Pny Sch, Awo Ile Oluji	3	4	4	8	30	4	10	180	180	N	N	N	1,5	1	1,2,3,4,5,8,9,10	5	123	127	2	10
72	St. John's Ang. Primary School, Okeigbo	2	6	-	-	-	-	12	72	76	N	N	N		1	1,2,3,4,5,8,9	5	44	58	1	7
73	St. Luke's (Ang) Primary School Ile Oluji	3	10	1	17	17	-	6	434	434	N	N	N	1,5	1,3	1,2,3,4,5,8,9,10	3	292	285	2	18
74	St. Luke's Primary School, Okeigbo	2	13	5	-	28	-	1	430	430	N	N	N	1,2,5	1,2,4	2,3,4,5,8,9	1	135	159	1	15
75	St. Matthias (Cath) Primary School, Ile Oluji	3	15	3	15	14	3	3	403	403	Y	N	N	1,3,5,6	1	1,2,3,4,5,8,9	1	459	491	2	21
76	St. Paul's Ang. Pny Sch, Awopeju-Okeigbo	2	6	-	40	48	10	28	360	340	N	N	N	1,5	1,4	1,2,3,4,5,8,9,10	-	364	393	5	12
77	St. Pauls School Idi-Iroko Okeigbo	1	3	8	16	24	8	14	192	135	Y	N	N	1,5	1,2,4	1,2,3,4,5,8,9	5	93	107	1	8
78	St. Philip's Primary School, Kajola, Ile Oluji	1	6	6	24	24	6	12	130	120	N	N	N	1,5	1,4	1,2,3,4,5,7,8,9	4	87	94	6	3
79	Surajudeen Primary School, Ayetoro Okeigbo	1	3	3	12	24	3	6	320	160	N	N	N		1,4	1,2,3,4,5,8,9	4	79	134	2	2

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
(P)	SCHOOL RECORDS				PHCN	1 Other	6
	Admission Register	1			Generator	2	
	Attendance Register	2			PHCN/Generator/	3	
	Syllabus/Plan of Work	3			Solar	4	
	Supervision Book	4			None	5	
	Visitors Book	5					

TABLE 58

ILE-OLUJI/OKEIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Abari Comp College, Lipanu	2	6	4	4	24	7	14	126	150	N	N	Y	Y	4,5	1,4	1-9	1	160	155	9	8
2	Adeboware Mem Comp Gram Sch, Temidire-Ile-Oluji	2	6	3	11	24	6	12	140	160	N	N	N	Y	-	1,2,4	2-5,8,9	5	141	139	10	2
3	Ademulegun High School Bamikemo, Ile-Oluji	1	9	9	20	36	6	18	120	120	N	N	N	Y	1,	1,3,4	2,3,4,5,8,9	1	239	243	17	4
4	Awaye Comp College . Hihg Sch Oloruntedo	3	3	5	20	20	8	16	120	120	N	N	N	Y	5,4	1,2	1,2,3,4,8,9	5	159	211	7	-
5	Awopeju Comm Gram Sch, Ramonu-Okeigbo	3	3	-	-	12	-	3	80	300	N	N	N	Y	1,5	1	1-9	2	140	103	13	6
6	Ayotoro Comm.Gram School Ramonu-Okeigbo	1	3	3	15	14	3	8	75	65	N	N	N	Y	1	1,2	2,3,4,5,8,9	5	110	100	6	2
7	Baptist High School, Ile-Oluji	2	10	4	4	4	4	4	230	230	N	N	N	Y	1,3,5,6	1,2,4	2-6,8-10	1	155	165	8	11
8	Community Grammar School Akinye, Ile-Oluji	1	6	5	11	12	5	6	90	90	N	N	Y	Y	4,5	1,2	1-5,7-10	2	61	80	15	7
9	Comm. Comprehensive High Sch, Idi-Iroko Okeigbo	1	6	-	24	24	-	6	240	240	Y	Y	N	Y	1,3,5	1,4	2,3,4,5,6,7,8,9	5	181	157	13	7
10	Community High School Oloruntele-Okeigbo	2	3	-	-	-	-	6	120	120	Y	Y	Y	Y	1,5	1,2	1,2,3,4,5,6,8,9	1	131	121	8	8

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 58 Contd

ILE-OLUJI/OKEIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Fagunwa Memorial High Sch, Igbo-Olodumare	2	3	-	-	-	-	9	55	55	Y	N	N	Y	1	1,2	1,2,3,4,5,7,8,9	5	84	108	12	-
12	Gboluji (Ang) Gram. School, Ile-Oluji	2	9	16	38	40	16	28	585	585	Y	Y	Y	Y	6	1,2,3,4	2,3,4,5,6,8,9	3	282	279	12	11
13	Holy Saviour's High School, Oke - Alafia West	3	6	11	44	44	7	44	80	100	Y	N	Y	Y	5,4	1,2,4	2,3,4,5,8	3	318	267	13	12
14	Oke-Alafia Comm Gram. Sch., Oke Igbo	1	3	3	12	12	3	3	150	150	N	N	N	N	5	1	2,4,8,9,10	5	139	125	9	3
15	Okeigbo Grammar School, Ondo- lfe, Okeigbo	2	11	4	33	11	10	11	320	320	N	N	N	Y	1,2,5	1,4	2,3,4,5,8,9,10	1	206	232	13	8
16	Oloroke Grammar School, Okeigbo	2	8	3	-	12	-	8	286	303	N	N	N	Y	6	1	1,2,3,4,5,7,8,9	3	298	217	5	5
17	Oluwa Comm. Gram Sch, Oluwasola Ile-Oluji	2	3	-	2	12	2	3	91	91	Y	N	N	Y	1,5	1,2,4	2,3,4,5,8,9	5	40	35	5	-
18	Orere- Gramm School, Ile-Oluji	2	7	5	20	28	7	14	60	80	Y	N	Y	Y	1,4,5	1	2-6-10	2	112	232	11	10
19	St Francis (Cath) High School, Ileoluji	3	2	5	20	28	5	12	90	90	Y	N	Y	Y		1,2	1,2,3,4,5,8,9	4	43	32	8	11
20	Uleon Comm High School Ile-Oluji	1	3	3	20	22	3	6	146	140	N	N	N	Y	5	1,4	1-6,8,9	5	91	74	2	5

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 58 Contd

ILE-OLUJI/OKEIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Abari Comp College, Lipanu	2	9	9	28	26	7	14	350	350	N	N	Y	Y	1,4,5	1,2,4	2-6,8-10	3	195	209	14	5
2	Adeboware Mem Comp Gram Sch, Temidire-Ile-Oluji	2	5	-	10	20	-	10	230	230	N	N	Y	Y	1,5	1,2	2,3,4,5,6,8,9	2	167	150	18	2
3	Ademulegun High School Bamikemo, Ile-Oluji	3	10	8	8	24	-	18	305	486	Y	N	Y	Y	1,4,5	1,3,4	1-10	1,2	238	156	20	6
4	Awaye Comp College . Hihg Sch Oloruntedo	2	6	-	10	-	-	-	250	250	Y	N	Y	Y	1,4,5	1,2,4	1-9	2	174	154	31	3
5	Awopeju Comm Gram Sch, Ramonu-Okeigbo	3	3	4	4	-	4	4	120	120	N	N	Y	N	1	1,2,4	1-6,8,9	5	118	76	15	7
6	Ayotoro Comm.Gram School Ramonu-Okeigbo	3	6	8	12	28	8	8	180	180	N	N	Y	N	5	1,2,4	2,3,4,5,8,9	5	111	109	11	2
7	Baptist High School, Ile-Oluji	3	7	-	13	15	-	7	240	240	Y	N	Y	N	1,5,6	2	1-6,8,9	3	105	126	15	10
8	Community Grammar School Akinye, Ile-Oluji	1	6	-	8	16	2	10	110	110	Y	N	Y	Y	1,4,5	1,2,4	1-10	3	132	107	18	2
9	Comm. Comprehensive High Sch, Idi-Iroko Okeigbo	1	10	6	40	40	-	10	120	150	Y	N	Y	N	1,3,5	1,4	1-6,8,9	5	175	183	20	4
10	Community High School Oloruntele-Okeigbo	2	3	3	20	24	4	6	100	100	N	N	Y	N	5	1,2,4	1,2,3,4,5,6,8,9	1	180	124	22	4

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

TABLE 58 Contd

ILE-OLUJI/OKEIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Fagunwa Memorial High Sch, Igbo-Olodumare	3	9	-	12	12	-	8	425	412	Y	N	Y	Y	5	1,2,4	2,3,4,5,6,8,9	2	121	110	19	2
12	Gboluji (Ang) Gram. School, Ile-Oluji	2	14	10	44	48	11	28	460	462	Y	N	Y	Y	1,4	1,2,4	2,3,4,5,8,9	3	226	230	28	12
13	Holy Saviour's High School, Oke - Alafia West	3	12	12	12	24	12	-	50	50	N	N	Y	N	5	1,2	1-10	3	279	276	22	7
14	Oke-Alafia Comm Gram. Sch., Oke Igbo	1	3	4	15	6	3	6	200	200	Y	N	Y	Y	1,5	1,2,5	1-8-10	2	45	52	17	3
15	Okeigbo Grammar School, Ondo- lfe. Okeigbo	2	9	1	12	16	1	10	400	400	Y	Y	Y	N	2,5	1,2,5	2,3,4,5,6,8,9	1	388	463	35	24
16	Oloroke Grammar School, Okeigbo	3	9	12	50	48	12	24	500	500	Y	N	Y	Y	5	1,4	2-9	1,2	376	411	22	8
17	Oluwa Comm. Gram Sch, Oluwasola Ile-Oluji	3	7	3	10	28	3	16	120	120	Y	N	Y	Y	1,4,5	1,2,4	1-9	2	63	57	14	2
18	Orere- Gramm School, Ile-Oluji	2	9	-	36	4	-	18	180	180	Y	N	Y	Y	1,4,5	1,2	1-10	1,2	57	64	15	24
19	St Francis (Cath) High School, Ile-Oluji	1	5	8	22	32	8	16	220	220	Y	N	Y	Y	1,4	1,2	1-6,8,9	2	88	127	18	9
20	Uleon Comm High School Ile-Oluji	3	6	3	21	24	3	12	150	150	Y	N	Y	N	1,5	1,4	1-6,8,9	2	48	44	12	3

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 59

IRELE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	Methodist Primary School, Ode-Irele	2	9
2	Baptist Day Primary School, Ode-Irele	2	11	3	12	12	3	12	312	312	N	N	Y	3,6	1	1-5, 8, 9	5	172	186	-	-
3	C.A.C Primary School Salawa-Ajagba	3	9	2	8	8	2	4	360	360	N	N	Y	3,5	1	1-5, 8, 9	5	197	192	5	3
4	C.A.C Primary School, Ode-Irele	1	2	6	24	24	6	12	700	700	N	N	N	1,3,5	1	1-5, 8, 9	5	215	244	4	11
5	Community Primary School, Atoranse-Ayadi, Irele	3	6	-	12	12	3	-	150	150	N	N	Y	1,4,5	1,4	1-5, 8, 9	5	185	219	7	1
6	Community Primary School, Litoto-Irele	1	3	-	-	-	-	-	100	100	N	N	N	5	1	1-5, 8, 9	5	152	160	4	-
7	Community Primary School, Osowe-Irele	1	4	-	-	-	-	-	63	61	Y	N	Y	1, 5	1	2,3,4,5,8,9	5	182	195	5	1
8	L.A Primary School Salawa-Ajagba	3	8	-	-	-	-	-	260	260	N	N	Y	1, 5	1	1-5, 8, 9	5	298	284	6	1
9	L.A Primary School, Ajagba	2	8	5	12	24	7	14	400	195	N	N	N	1,3,5	1	1,2,3,4,8,9	5	273	256	6	9
10	L.A Primary School, Awo-Irele	2	4	1	16	16	4	16	20	10	N	N	N	1	1	1-5, 8, 9	5	88	110	7	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 59 Contd

IRELE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	L.A Primary School, Barogbo	2	2
12	L.A Primary School, Bgogunron, Irele	3	5	-	-	-	-	20	840	840	N	N	Y	1,3,5	1	2-5, 8, 9	5	450	422	4	-
13	L.A Pry Sch, Gbeleju Ewu-Oke Ode-Irele	2	4	1	4	8	-	2	284	285	N	N	Y	4,5	1	1-7, 8, 9	5	200	187	2	2
14	L.A Primary School, Gbogi, Irele	3	6	1	8	20	2	12	80	80	N	N	N	-	1	2-5, 8, 9	5	97	101	8	1
15	L.A Primary School, Gboroye-Ajagba	1	4	4	8	12	6	12	146	146	N	N	Y	1	1	1-5, 8, 9	5	63	55	3	1
16	L.A Primary School, Iditala-Yasere, Irele	2	4	1	4	4	1	2	87	80	N	N	Y	5	1	1-5, 8, 9	50	39	50	12	-
17	L.A Primary School, Idogun Irele	2	3	3	12	12	3	6	260	260	N	N	Y	4	1	2-5, 8, 9	-	124	121	5	-
18	L.A Primary School, Idogun-Temenu, Irele	2	9	3	13	6	3	6	300	300	Y	Y	N	1,4,5	1	2, 3, 5, 8, 9	5	156	153	5	2
19	L.A Primary School, Igbo-Akinyomi, Irele	2	2	10	4	4	-	-	36	36	N	N	Y	-	1	2-4, 7, 8, 9	2	31	41	2	2
20	L.A Primary School, Iyara-Akingboye, Irele.	2	2	-	-	1	-	-	276	276	N	N	N	-	1	1, 2, 8, 9	5	209	207	1	3

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 59 Contd

IRELE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		21	L.A Primary School, Iekon Ode-Irele	2	5
22	L.A Primary School, Lutako-Irele	1	2	1	4	4	1	8	108	108	N	N	N	1, 5	1	2-5, 8, 9	5	109	114	3	2
23	L.A Primary School, Orialeoyo	3	6	5	20	20	3	10	714	775	N	N	N	1	1	3, 4, 5, 8, 9	5	499	468	6	2
24	L.A Primary School, otuloye, Ode Irele.	2	3	1	12	12	-	6	62	60	N	N	Y	-	1	2, 3, 4, 8, 9, 10	5	114	103	5	-
25	L.A Primary School, Petu, Irele.	1	6	2	-	12	-	-	160	160	N	N	N	5	1	1-5, 8, 9	5	126	124	6	-
26	L.A Pry Sch, Gbogbolowo-Ajagba	3	3	3	10	12	6	24	138	129	N	N	Y	3, 5	1	2-5, 8, 9	5	55	47	11	-
27	L.A Pry Schl Araromi/Likanran	1	3	-	-	-	-	-	210	210	N	N	Y	5	1	1-5, 8, 9	5	109	108	4	1
28	L.A Pry. Schl. Ipinle-Irele	1	5	5	8	4	2	6	140	132	N	N	Y	4	1, 4	1-5, 8, 9	5	187	223	3	3
29	L.A Pry. Schl. Olofunjare, Ode-Irele	2	1	2	8	4	-	4	146	146	N	N	Y	1	-	2-5, 8, 9	5	105	111	2	-
30	L.A Pry. Schl. Olowomeye, Ode-Irele	2	2	4	-	6	6	12	120	130	N	N	Y	1, 5	1	1-5, 7, 8, 9	5	132	150	4	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
(P)	SCHOOL RECORDS				PHCN	1 Other	6
	Admission Register	1			Generator	2	
	Attendance Register	2			PHCN/Generator/	3	
	Syllabus/Plan of Work	3			Solar	4	
	Supervision Book	4			None	5	
	Visitors Book	5					



TABLE 59 Contd

IRELE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		31	L.A School, Yopiara	1	2
32	L.A. Primary School, Akotogbo	2	3	-	-	-	-	-	120	156	N	N	N	3	1	1-5, 8, 9	5	132	100	4	1
33	Local Authority Primary School, Legbogbo Irele.	2	11	-	-	27	5	22	256	256	N	N	Y	5	1	1-5, 8, 9	5	136	152	4	3
34	Local Authority Primary School, Lumako-Irele	1	6	-	6	6	6	6	54	54	N	N	-	1	-	2-5, 8, 9	5	104	115	3	-
35	Local Authority Primary School, Ode-Irele	2	10	2	26	28	2	-	84	84	N	N	Y	1,3,5	1	1-5, 8, 9	5	196	181	5	10
36	Local Authority Primary School, Ufan-Irele	2	2	1	4	4	-	2	114	114	N	N	Y	1	1	1-4, 7, 8, 9	-	84	83	7	2
37	Lurowo /Ogunmola Community Pry School, Irele.	1	4	-	-	-	-	-	320	320	N	N	Y	-	1	1-5, 8, 9	5	229	275	4	3
38	Methodist Primary School, Ajagba	2	9	2	16	-	2	4	350	350	N	N	Y	3,5	1	1-5, 8, 9	5	176	193	5	14
39	Methodist Primary School, Akotogbo	3	8	-	-	-	-	-	360	360	N	N	Y	0	1	1-5, 8, 9	5	437	377	8	3
40	Methodist Primary School, Ode-Irele	3	24	5	20	52	13	26	424	424	Y	N	Y	5	1,4	1-5, 8, 9	5	982	952	5	33

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
(P)	SCHOOL RECORDS				PHCN	1 Other	6
	Admission Register	1			Generator	2	
	Attendance Register	2			PHCN/Generator/	3	
	Syllabus/Plan of Work	3			Solar	4	
	Supervision Book	4			None	5	
	Visitors Book	5					

TABLE 59 Contd

IRELE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		41	Methodist Primary School, Ode-Irele	3	10
42	Salvation Army Primary School Ode-Irele	3	10	-	12	8	4	10	290	290	N	N	Y	1,3,5	1	1-5, 8, 9, 10	5	414	425	3	13
43	Salvation Army Primary School, Akingboye-Irele	1	3	1	4	6	1	4	139	139	N	N	Y	1	1	1-5, 8, 9, 10	5	120	123	4	-
44	Salvation Army Primary School, Kidimu-Irele.	2	4	-	-	16	-	-	80	86	N	N	Y	1	1	1-5, 8, 9, 10	5	389	391	3	1
45	Salvation Army Primary School, Otoporu-Irele	1	2	1	2	20	3	10	82	82	N	N	Y	-	1	1-5, 8, 9	5	64	70	3	-
46	Salvation Army School, Ode-Omi	3	17	-	-	-	-	16	440	440	N	N	Y	1,3,6	1	1-5, 8, 9	5	468	464	3	8
47	St. Andrew's Anglican Pry. Schl., Ode-Irele	3	24	12	64	94	24	38	520	518	N	N	Y	3,6	1	1-7, 8, 9	5	680	624	5	32
48	St. Andrew's School, Akotogbo	2	8	-	-	-	-	-	90	90	N	N	Y	1,3,5	1	1-5, 7, 8, 9	5	113	102	2	2
49	St. David's Primary School, Ode-Irele	3	3	4	16	16	4	8	225	215	N	N	Y	-	1	1-5, 8, 9	5	384	306	7	-
50	St. Fanbarr's Rcm School, Owode-Irele.	3	4	4	16	16	4	8	100	100	N	N	Y	-	4	1-6, 8, 9	5	289	358	10	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 59 Contd

IRELE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		51	St. George's Rcm School, Ijuosun	2	9
52	St. Hellen's Pry. Schl. Omi Funfun	3	2	-	16	16	-	8	36	36	N	N	N	0	1	1-5, 8, 9	5	77	89	2	-
53	St. Mathew's Anglican Primary School, Irele	2	4	-	-	8	-	8	240	240	N	N	Y	4,5	-	1-5, 8, 9	-	113	262	7	4
54	St. Patrick's R.C.M School, Akotogbo	3	9	10	24	-	-	6	240	240	N	N	Y	1,3,5	1,4	1-3, 5, 6, 8, 9	5	189	190	7	2
55	St. Pauls R.C.M Ajagba	2	5	6	24	28	6	16	160	160	N	N	N	3,5	1	1-5, 8, 9	2	330	255	5	5
56	St. Peter's Anglican Primary School, Igbo-Oke, Irele	2	4	-	-	-	-	-	115	115	N	N	N	3,4	1	1-5, 8, 9	5	142	169	5	-
57	St. Peter's C/S Primary School, Ode-Irele	2	9	3	12	5	1	5	500	500	N	N	Y	4,5	4	1-5, 8, 9	5	257	280	2	15
58	St. Peter's R.C.M Primary School, Ode-Irele	2	13	-	28	6	2	4	292	292	N	N	Y	1,3,5	1, 4	2-5, 8, 9	5	224	209	3	13
59	St.Saviour's Anglican Primary School, Ekama-Irele	1	2	-	-	-	-	-	76	76	N	N	N	-	1	2-6, 8, 9	5	114	144	-	3
60	The Apostolic Primary School, Ode-Irele	3	14	6	24	32	8	8	175	212	N	N	N	3,5,6	1	1-5, 8, 9	5	588	573	1	17

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
			Water Closet	6		
(P)	SCHOOL RECORDS			(Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 60

IRELE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	United Grammar School, Ode-Irele	2	10	-	16	8	2	8	220	220	N	N	-	Y	1,5	1,2,4	1-5,8,9	1,3	167	165	10	4
2	Jowiri Comm. Comp. High Sch, Ajagba, Irele	1	6	11	44	44	11	22	200	200	Y	N	-	Y	1,3,5	1,2	1-9,8-10	3	215	231	6	5
3	Compressive High School Ajagba Irele	2	14	3	12	12	3	6	500	500	N	N	-	Y	3,5,6	1,2,4	1-6,8-10	3	448	391	8	11
4	Community High School, Akotogbo.	1	5	-	-	20	2	10	165	200	N	N	-	Y	1,5	1,4	2-5,8,9	2	253	182	7	-
5	Oyenusi Memorial Grammar schI, Ode Irele	2	8	4	16	16	2	4	754	574	Y	N	-	Y	3,5	1,4	2-5,8-10	2	370	350	10	6
6	Aerin Grammar School, Ode-irele	3	8	8	32	32	8	16	200	200	N	N	-	-	1,3,5	1	1-5,8,9	2	350	312	6	11
7	Community Grammar School, Gbelejuloda	2	3	2	4	4	3	12	240	240	N	N	-	Y	1,5	1,2	1-5,8-10	5	133	97	10	4
8	Laragunsin Grammar School, Ode-Iyansan	3	5	-	16	10	5	10	60	60	Y	N	-	-	1,6	1	1-6,8,9	2	118	93	4	1
9	Comm. High SchI, Temidire Atorinse-Ayadi Ode-irele	2	3	-	-	-	-	-	199	90	N	N	-	Y	1,4,5	1,2,4	1-5,7-9	-	118	79	3	-
10	Omi Community Grammar SchI, Ode-Omi	1	2	-	-	-	-	-	100	100	N	N	-	Y	1,5	1,2,4	1-3,,5-9	4	90	64	7	2

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 60 Contd

IRELE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	United Grammar School, Ode-Irele	2	11	1	3	44	-	22	220	220	Y	N	2,3,4	Y	1,5	1,2	1-6, 8, 9	1,3	159	164	15	2
2	Jowiri Comm. Comp. High Sch, Ajagba, Irele	3	7	4	16	40	10	8	130	130	Y	N	-	Y	3,5	3	2-6, 8-10	3	218	206	-	-
3	Compressive High School Ajagba Irele	3	12	-	-	48	-	-	352	367	Y	N	1-3	N	1,3,5,6	1,2	1-6, 8-10	3	299	312	14	4
4	Community High School, Akotogbo.	2	6	-	-	-	-	-	200	200	Y	N	1-3	N	1,3,5	1,2	1-6, 8, 9	5	170	118	6	4
5	Oyenusi Memorial Grammar schl, Ode Irele	1	8	4	16	16	4	8	300	300	N	N	-	Y	1,3,5	1,2	2-6, 8, 9	2	279	281	16	6
6	Aerin Grammar School, Ode-irele	2	9	-	-	40	4	8	120	120	N	N	1,3	Y	1,3,5	1,2	1-5, 8-10	2	210	247	14	4
7	Community Grammar School, Gbelejuloda	2	3	3	-	24	-	12	120	120	N	N	2	N	5	1,2	1,2,5,8	2	135	104	13	
8	Laragunsin Grammar School, Ode-Iyansan	1	3	-	-	12	-	6	120	120	N	N	-	N	5	1,2,4	2-5, 8, 9	5	140	71	4	2
9	Comm. High Schl, Temidire Atorinse-Ayadi Ode-irele	2	3	-	-	-	-	-	199	90	N	N	-	Y	1,4,5	1,2,4	1-5, 7-9	5	142	123	8	-
10	Omi Community Grammar Schl, Ode-Omi	3	2	6	16	8	4	6	100	100	N	N	-	Y	1,5	1,2	2-5, 8, 9	4	-	-	-	-

KEY

(B) NATURE OF BUILDING:

- Mud 1
- Cement/Burnt Brick 2
- Both 3
- Others 4

(M) LABORATORY:

- Physics 1
- Chemistry 2
- Biology 3
- Intro. Tech. 4
- Home Econs. 5
- Others 6

(O) HEALTH/WATER/SANITATION FACILITIES:

- Wash Hand Basin 1
- Pipe Borne Water 2
- Bore Hole 3
- Protected Well 4
- VIP/Traditional Pit Latrine 5
- Water Closet 6

(P) RECREATIONAL FACILITIES

- Play Ground 1
- School Hall 2
- Table Tennis Court 3
- Food Vendor/Canteen 4
- Swimming Pool 5

(Q) SCHOOL RECORDS

- Admission Register 1
- Attendance Register 2
- Syllabus/Plan of Work 3
- Supervision Book 4
- Visitors Book 5

(R) SOURCE OF ELECTRIC POWER

- PHCN 1
- Generator 2
- PHCN/Generator/ 3
- Solar 4
- None 5
- Other 6

TABLE 61

**ODIGBO**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	All Saints Aang Pry. School Orotedo	1	9
2	Ansar-Ud-Deen PRY School, Kajola	1	5	1	4	7	1	3	172	104	N	N	-	1,4,5	1	1-5,8,9	5	97	108	9	4
3	Army Children Pry School, Otu-Costain	2	6	11	44	44	11	8	200	200	N	N	Y	1, 4	1, 4	1-5,8-10	3	190	208	5	19
4	Beulah Baptist pry school,ORE	2	8	12	6	16	-	12	183	183	N	N	N	1,4,5	1,4	1-5,9	5	534	466	3	18
5	Beulah Baptist pry school,ORE	2	12	-	-	-	-	-	200	200	Y	N	Y	1	1	1,2,3,4,5,8,9,	5	175	164	5	7
6	C & S Primary School, Ore	1	8	8	8	2	8	16	200	200	N	N	Y	5	1	1,2,3,4,5,8,9,	5	71	64	5	3
7	Christ Pry. School Onitea	1	7	3	4	16	3	6	60	60	N	N	Y	1,5	1,4	1-5,8-10	5	189	229	2	8
8	Commnity Primary School, Ominla	1	4	4	16	16	4	8	25	25	N	N	-	5	1	1,2,3,4,5,8,9,10	5	104	127	9	-
9	Commuinty Primary School, Sakoto I	1	2	2	8	8	2	4	24	30	N	N	Y	-	1	1,2,3,4,5,8,9,10	5	75	95	2	6
10	Community Primary School Aperin	1	3	-	-	-	-	-	64	32	N	N	Y	1	1	1,2,3,4,5,8,9	5	104	116	6	1

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	<b>SCHOOL RECORDS</b>		Water Closet	6 (Q)	<b>SOURCE OF ELECTRIC POWER</b>	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 61 Contd

ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers		
11	Community Primary School, Temidaara	2	4	-	4	16	-	8	225	225	N	N	Y	1, 5	1	1,2,3,4,5,8,9	5	134	124	8	1
12	Community Pry School ,Oladapo	3	6	2	8	8	2	4	200	200	N	N	N	1, 4	1, 4	3,4,5,8,9	5	13	19	9	2
13	Community Primary School Lasia	1	-	-	-	-	-	-	60	60	N	N	Y	1	1	1,2,3	5	93	94	3	8
14	Community Primary Sch, Ifara- Paanu	1	6	8	36	32	8	16	118	136	N	N	Y	5	1	1,2,3,4,5,8,9	5	383	434	6	2
15	Community Primary Sch, Temidire	1	3	6	24	24	6	12	186	186	N	N	Y	-	1	1,2,3,4,5,8,9,10	5	158	165	4	1
16	Community Primary School ,Onirogbo	2	3	-	-	12	3	6	160	145	Y	N	Y	1, 5	1	1,2,3,4,5,8,9	5	172	196	6	2
17	Community Primary School Agbabu	1	4	-	16	16	4	-	100	100	N	N	Y	1, 4	1	1,2,3,4,5,8,9	5	151	124	6	5
18	Community Primary School Ago-Alaye	1	-	6	24	24	6	12	260	260	N	N	Y	1, 3, 5	1	1,2,3,5,8,9	5	71	83	5	2
19	Community Primary School oLadosa	1	-	4	16	16	4	8	40	20	N	N	-	1	-	1,2,3,4,5,8,9	5	120	63	4	1
20	Community Primary School Laliepa	1	6	-	-	-	-	-	150	150	N	N	-	1, 5	1	1,2,3,4,5,8,9,10	-	71	59	5	0

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
			Water Closet	6		
(P)	SCHOOL RECORDS			(Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 61 Contd

**ODIGBO**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		21	Comm Pry Sch Orunsunbare Oladapo	2	4
22	Community Primary School, Ayesan	2	5	3	12	12	3	12	100	100	N	N	Y	1	1	1,2,3,4,5,8,9,10	5	142	159	3	1
23	Community Primary Sch, Oloruntedo- Ajue	1	4	4	16	16	4	8	50	50	N	N	Y	1, 5	5	1,2,3,4,5,8,9	-	78	75	4	6
24	Community Pry Sch, Igbekoyi	1	3	-	24	-	1	12	52	52	N	N	Y	-	1	1,2,3,4,5,8,9	5	47	33	6	-
25	Community Pry Sch, Qwosunmomi	2	9	3	15	22	3	3	200	200	N	N	-	-	1	1,2,3,4,5,8,9	5	200	241	5	5
26	Community pry school Fesojoye/Ajibodu	1	3	-	-	-	-	-	-	-	N	N	Y	13,6	1	1-5,8-10	5	78	68	6	1
27	Community Pry School Mobolorunduro	1	3	-	1	-	-	-	21	12	N	N	Y	1	1	2,3,4,5,8,9	5	109	77	2	1
28	Community Pry School Olorintedo Araromi Obu	2	6	2	2	8	2	4	20	20	N	N	Y	1, 5	1	1,2,3,4,5,8,9	5	76	77	6	2
29	Community Pry School Onipetesi	1	3	-	-	12	2	6	20	20	N	N	Y	-	1	2,3,4,5,8,9	5	83	73	2	6
30	Community Pry School, Ajana 1	1	4	1	1	16	1	2	30	30	N	N	N	1, 5	1, 4	1,2,3,4,5,8,9	5	72	53	5	2

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1			PHCN	1 Other 6
	Attendance Register	2			Generator	2
	Syllabus/Plan of Work	3			PHCN/Generator/	3
	Supervision Book	4			Solar	4
	Visitors Book	5			None	5



TABLE 61 Contd

**ODIGBO**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		31	Community Pry school, Ifaraiwaju Oba	1	6
32	Community Pry School, Itamerin	2	5	1	4	6	2	3	240	240	N	N	Y	-	1, 4	1,2,3,4,5,8,9	5	107	86	6	1
33	Community Pry school, Jagoodo	1	6	6	24	24	6	12	160	168	N	N	Y	1,5	1	1-5,8,9	5	84	121	2	3
34	Community Pry School, Kajola-Ojuirin	3	9	4	-	6	6	10	235	218	N	N	Y	5	1	1,2,3,4,5,8,9	5	176	155	7	5
35	Community Pry school, OBADOORE	3	6	6	6	36	6	24	144	144	Y	N	N	1,5	1,4	1-6,8,9	5	163	169	3	4
36	Community Pry School, Obasasa	1	3	3	3	3	3	3	196	196	N	N	Y	5	1	1,2,3,4,8,9	5	32	50	-	-
37	Community Pry School, Olugbomudu	1	6	6	24	-	-	-	20	20	N	N	Y	-	1	1,2,3,5,8,9	5	157	183	5	-
38	Community Pry School, Orisunmibare	1	2	2	8	8	2	4	30	30	N	N	Y	1	1	1'-10	5	207	169	4	3
39	Community pry sch, Temitope	2	-	-	-	-	-	-	-	-	N	N	N	-	4	1,2,3,4,5,8,9,10	-	-	-	-	-
40	Community pry school,Ajana 2	1	8	8	32	32	8	16	30	30	N	N	N	-	1	1-5,8,9	5	358	424	5	1

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	<b>SCHOOL RECORDS</b>		Water Closet	6 (Q)	<b>SOURCE OF ELECTRIC POWER</b>	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 61 Contd

ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		41	Community Pry school, Kiniso	3	6
42	Comm pry sch, Orisun Mibare Oladapo	3	6	2	8	8	2	4	200	200	N	N	N	1,4	1,4	3-5,8,9	5	13	19	10	2
43	Community Pry school, Orita	1	6	-	-	-	-	-	380	380	N	N	N	1	1,4	1-5,8-10	5	274	330	4	14
44	Community Pry. Sch, Araromi -Obu	3	6	9	36	36	9	22	220	220	N	N	Y	5	1	1,2,3,4,5,8,9	5	292	324	5	8
45	Community Pry. Sch, Onipanu	2	6	3	12	12	3	6	240	240	N	N	Y	5	1	1,2,3,4,5,8,9	5	121	137	5	-
46	Community Pry. Sch. Ayeferere-Makinde	1	3	4	16	16	-	12	171	171	N	N	N	-	1	2,3,5,8,9	5	87	83	6	1
47	Community Pry. Sch., Sokoto II	1	3	2	8	20	5	10	97	97	N	N	N	1	1,5	2,3,5,8,9	5	73	68	2	1
48	Ebenezer A/C Pry School, Olorunsogo	1	6	6	24	24	6	12	40	36	N	N	Y	5	1	2,3,5,8,9	5	111	119	5	1
49	Holy Ttinity Ang Pry school, Olowo	3	3	4	16	24	6	24	252	252	N	N	N	1,5	1	1-5,8,9	5	174	179	5	19
50	Ifelodun Comm.Pry School, Gbegude	1	4	4	16	16	4	8	35	35	N	N	Y	1,5	1	1,2,3,4,5,8,9	5	116	110	2	5

KEY

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6	(Q) SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5



TABLE 61 Contd

ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R		S	
		Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	No of Pupils		No of Teachers	
																		M	F	M	F
51	L. A. Pry Sch Temidayo /Oke Igburowo	1	5	5	20	20	5	10	50	50	N	N	Y	5	1	1,2,3,4,5,8,9	5	169	154	4	2
52	L. A. Primary School, Otu-Oyegunwa	2	5	5	20	20	5	10	20	16	N	N	Y	5	1	1,2,3,4,5,8,9	5	78	70	4	3
53	L. A Primary School, Koseru	1	-	7	28	289	7	14	240	240	N	N	N	1	1	2,3,5,8,9	5	80	100	2	4
54	L.A Primary School Basola	1	5	-	-	-	-	-	148	148	N	N	Y	5	1	1,2,3,4,5,9	5	91	97	6	2
55	L.A Primary School, Likaju	1	6	2	-	8	-	24	104	104	N	N	Y	1,5	1	2,3,4,5,8,9	5	87	117	3	4
56	L.A Pry school. Kajola Agbabu	1	2	3	12	3	3	6	160	160	N	N	Y	1	4	2-6,8,9	5	115	111	3	14
57	L.A School Komowa	1	3	3	4	12	4	6	94	94	N	N	Y	1	1	1-5,8-10	5	78	68	1	5
58	L.A School, Odigbo	2	9	-	-	-	-	-	360	360	N	N	Y	-	1	1-5,8,9	1	407	478	2	12
59	L.A. Primary School, Araromi-Obu	2	9	4	8	16	4	8	160	160	N	N	Y	1,2,5	1	1-9	2	481	542	5	7
60	Local Authority Pry Sch, Araromi R/Estate	2	14	-	-	-	-	-	66	66	N	N	Y	1,5	1	1,2,3,4,5,8,9	2	201	265	18	16

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6	
(P)	SCHOOL RECORDS			(Q)	SOURCE OF ELECTRIC POWER
	Admission Register	1			PHCN
	Attendance Register	2			Generator
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			Solar
	Visitors Book	5			None
					1 Other
					2
					3
					4
					5
					6

TABLE 61 Contd

ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		61	Local Authority Primary School, Lafe	3	5
62	Local Authority Primary, School Aponla	2	3	3	3	-	-	-	68	70	N	N	Y	1, 4	1	1,2,3,4,5,8,9	5	60	56	5	3
63	Local Authority Primary, School Ebijaw	2	4	-	-	-	-	-	24	24	N	N	Y	1,4,5	1	1,2,3,4,5,8,9,10	2	90	94	5	-
64	Methodist Primary Mulekangbo	1	4	4	16	16	4	8	30	30	N	N	N	0	1	1,2,3,4,5,8,9,10	5	42	49	4	4
65	Methodist Pry school, ORE	2	15	10	32	32	10	20	500	500	Y	Y	N	1,4,6	1	1-10	2	433	336	4	6
66	Muslim Primary School, Ore	2	9	1	1	2	2	2	160	160	N	N	Y	4, 5	-	1,2,4,5,8,9	5	336	244	7	42
67	ST Andrew's pry sch m/10 Bolorunduro Onisere Zone	1	2	-	-	-	-	-	38	38	N	N	N	1,4,5	1	1-5,8,9	5	150	165	9	2
68	ST Andrew's pry school Ogunlepa	1	3	6	24	24	6	12	24	24	N	N	N	-	1	1-3,5,8,9	5	147	185	3	1
69	ST John's R.C M school, Adaja	2	12	8	32	32	8	1	109	102	N	N	Y	5	1	1,2,3,5,8,9	2	511	619	11	56
70	ST Matthew's U.N.A Pry school, Asejire	3	6	4	16	16	4	8	120	119	N	N	Y	5	1	2-5,8-10	5	96	105	3	5

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 61 Contd

ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		71	ST Matthew's Ang pry school, ORO	2	6
72	ST Peter Ang Pry school, AKINFOLARIN	3	9	4	4	6	8	6	89	89	N	N	Y	1,4,5	1,4	1-5,8,9	1	207	241	6	10
73	St Stephen's Primary School, A jeg unle	1	4	-	16	16	4	8	100	100	N	N	Y	1, 4	1	1,2,3,4,5, 8,9	5	552	70	1	1
74	ST Stephen's pry school,Ore	2	7	-	4	28	-	10	120	120	N	N	Y	1	3	1-5,8-10	5	449	479	5	13
75	St. Peters Ang. Pry School, Ajobamijoko	1	4	3	12	16	1	8	119	119	N	N	Y	1, 5	1	1,2,3,4,5, 8,9,10	5	93	83	5	1
76	St. Peters Ang. Pry School, Araromi-Obu	2	9	4	16	12	4	8	199	197	N	N	Y	6	1	1,2,3,4,5, 8,9	2	120	120	4	4
77	St. Philips Ang. Pry School, Oniparaga	2	10	-	-	12	-	-	400	400	N	N	Y	3, 6	1, 2	1,2,3,4,5, 9	5	-	-	7	7
78	St. Philips Ang. Pry School, Otugbemibo	1	4	-	-	16	-	8	120	120	N	N	-	1	1,4	1,2,3,4,5, 8,9	-	115	127	4	-
79	St. Andrews Ang Pry. Sch, Bolorunduro onisere	1	2	-	-	-	-	-	38	38	N	N	Y	1,4,5	1	1,2,3,4,5, 8,9	5	150	45	9	2
80	St. Andrews Pry School, Oja-Bale	2	8	2	2	0	2	0	365	365	N	N	Y	1,4,6	1	1,2,3,4,5, 8,9,10	1	287	254	5	11

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 61 Contd

ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		81	St. Andrews Pry Shool, Omifon	2	6
82	St. Brendians R.C.M Lamudifa	1	4	6	6	16	6	8	28	24	N	N	N	1	1	1,2,3,4,5,8,9	5	48	53	2	5
83	St. Jerome's Primary School, Ayetimbo	1	4	4	16	16	4	8	16	16	N	N	Y	5	0	1'-9	5	151	124	3	2
84	St. Johns Ang Lican Primary, Igburowo	2	9	-	-	-	-	2	280	280	N	N	Y	1, 5	1, 4	2,3,4,5,8,9,10	1	180	192	3	15
85	St. Johns Ang Pry Sch, Ajebambo	1	6	-	-	6	6	12	240	240	N	N	Y	1, 5	1, 4	1,2,3,4,5,6,8,9,10,1	2	185	149	5	3
86	St. Johns A/C Ajue	2	18	-	-	-	-	-	200	200	N	N	N	1,3,6	1,2,4	1,2,3,4,5,8,9	1	274	275	6	24
87	St. Josephs Primary School, Asewele	3	11	8	32	32	8	16	80	80	N	N	N	1, 5	1, 4	1,2,3,4,5,8,9,10	5	85	93	11	12
88	St. Lukes Ajebamidle /Paye	3	7	5	20	20	5	10	254	214	N	N	Y	1, 5, 6	1, 4	1,2,3,4,5,8,9	5	161	158	5	8
89	St. Marks Ang Pry School, Asewele-Oja	3	6	-	-	-	-	-	240	240	N	N	Y	1,3,5	1	1,2,3,4,5,6,8,9,10	5	149	160	7	14
90	St. Marks Ang Pry, Ore	2	12	8	32	32	8	16	109	102	N	N	Y	1,5	1	1,2,3,5,8,9	2	511	619	12	56

KEY

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 61 Contd

**ODIGBO**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		91	St. Mark's Ang Pry, Ore	2	6
92	St. Matthews Ang Pry School, Asejire	3	6	4	16	16	4	8	120	119	N	N	Y	5	1	2,3,4,5,8,9,10	5	96	105	3	5
93	St. Paul's R.C Primary School, Ore	3	14	6	56	56	-	28	320	320	N	N	Y	1,5,6	1,4	1,2,3,4,5,8,9,10	5	430	469	1	29
94	St. Stephens Ang. Pry. Sch. Kajola	3	12	6	28	12	13	12	230	202	N	N	Y	1,5	1,4	1-5,8-10	5	311	300	10	17
95	St. Theresa R.C .M Owobambo	2	8	-	4	-	-	4	230	230	N	N	Y	1,6	1,4	1,2,3,4,5,8,9	5	101	126	4	2
96	ST. thoma's RCM Pry. Sch. Odigbo	3	6	6	6	30	6	15	126	104	N	N	Y	1,3,5	1,4	1-5,8,9	5	446	468	5	10
97	St. Timothy's A/C Pry School Taribor	2	3	-	-	-	-	-	50	50	N	N	Y	1	1	1,2,3,4,5,8,9,10	5	151	158	4	-
98	The Apostolic Pry school, B / Kajola	1	6	4	16	16	6	10	336	336	N	N	Y	5	1	1-5,8-10	1	407	425	5	2
99	Zion C/S Primary School, Oke-Oluwa	1	4	-	-	-	-	-	36	36	N	N	N	1	1	2,3,4,5,8,9	4	35	28	7	12

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6	(Q) SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5
		1 Other 6



TABLE 62

ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Akinfolarin Comp. High Sch, Akinfolarin	1	5	2	15	16	3	8	45	13	Y	N	6	0	1,5	1,2	2,3,4,8,9	1	287	279	8	5
2	Adewale High Sch. Ajewunle, Onisere	1	5	1	4	12	2	2	600	84	N	N	2	Y	4,5	1,4	1-6,8,9	2	132	131	9	4
3	Agbabu Community High School, Agbabu	2	6	-	4	2	-	6	105	110	Y	N	4	Y	1,5	1,4	1-3,5,8,9	5	99	121	8	2
4	Ajue Grammar School	2	6	-	24	24	6	12	100	100	Y	N	4	Y	1,4	1	1-5,8,9	1	243	204	8	6
5	Araromi-Obu Comm Gram Schl Araromi, Obu	3	6	-	18	9	-	6	361	361	N	N	-	Y	5	-	1-5,8,9	2	-	-	3	3
6	Com Junior High Sch Araromi Rubber Estate	1	4	-	24	24	-	12	125	125	N	N	-	N	1,3	1,2,4	1-4,8,9	2	126	149	6	3
7	Com Junior High Sch, Ajebamidele-Onitea	1	12	2	18	56	6	-	105	112	N	N	4	Y	-	1,2,4	2,3,4,8,9	5	399	229	6	8
8	Community High School, Asewele	2	6	7	28	28	5	14	290	200	N	N	4	Y	1,3,5	1	2-5,8,9	1	471	465	11	5
9	Community High School, Igburowo	1	3	3	12	12	-	6	100	100	Y	N	4	Y	1	1,2	1-5,8,9	1	164	124	4	2
10	Imoru comp. High Sch. Lege-Imoru	3	6	7	12	-	9	12	160	90	Y	N	6	N	1,3,5	1,2,4	2-6,8-10	5	307	296	6	2

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 62 Contd

**ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS**

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Isero Grammar School, Odigbo	2	6	6	4	6	6	6	528	600	N	N	4,5	Y	1,4,6	1,2,4	2-5,8,9	1	275	232	7	4
12	Kajola Com Junior Gram Sch, Kajola	2	6	6	36	36	5	18	240	240	N	N	-	N	-	1,2	1-6,8,9	5	415	387	8	4
13	Muslim Junior High Sch. Ore	2	12	-	28	28	6	14	518	547	Y	N	4,5,6	N	1,4,5	1,2,4	2-10	5	471	465	8	14
14	Odigbo Junior High School, Odigbe	3	4	6	24	24	-	12	174	170	Y	N	4,5,6	N	-	1	1	1'-9	146	145	8	8
15	Oro Com Junior High School, Oro	2	3	-	-	3	3	3	90	90	N	N	-	N	1	1,4	1-4,8,9	5	104	99	4	4
16	Otu- Costain Comm High Sch, Otu-Costain	2	3	3	3	3	3	3	30	30	N	N	5	Y	-	1,2,4	1-3,9	1	305	415	9	12
17	Ore Comm High Sch. Old Ore-Benin Rd, Ore	2	13	-	-	25	-	5	740	677	N	N	1,2,3	Y	1	1,2,4	2-5,7-9	1,2	491	441	12	22
18	Comm High Sch; Oniparaga	2	7	-	8	4	-	-	360	360	Y	Y	1,2,3	Y	-	2,3,4	1-9	2	198	222	12	-

KEY

(B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

(M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

(O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

(P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

(Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

(R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 62 Contd

ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Comprehensive High School, Akinfolarin	2	6	6	24	24	6	12	186	186	Y	N	-	Y	1,5	1,2	1-6,8,9	1	275	240	19	3
2	Adewole high School, Ajegunle Onisere	1	5	1	4	12	2	7	600	44	N	N	2	N	2	1,4	1-5,8,9	2	132	131	8	4
3	Ajue Grammar School	2	5	6	-	24	-	12	140	150	Y	N	-	Y	1,4,5	1,2	1-5,8,9	1	205	180	15	4
4	Araromi-Obu Comm Gram Sch Araromi, Obu	3	12	2	8	32	8	16	400	400	Y	N	1,2,3,6	Y	1,5	1,2	1-6,8-10	5	201	184	12	3
5	Comm High Sch, Ajebamidele-Onitea	1	7	2	1	7	2	2	400	400	Y	N	1,2,3	Y	2,5,6	1,2,4	1-6,8,9	2	334	280	9	5
6	Comm High Sch, Asewele-Korede	2	12	8	32	32	8	8	320	400	Y	N	4	Y	1,4,5,6	1,2	1-6,8,9	1	268	198	12	7
7	Community High School, Agbabu	2	3	7	-	-	-	6	53	62	Y	N	6	Y	3,5	1,2,4	2-6,8,9	2	103	73	12	1
8	Community High School Araromi Rubber Estate	3	3	-	8	4	-	4	120	150	Y	N	1,2,3,4,6	Y	1,2	1,2,4	1	2	162	145	11	1
9	Community High School, Igburowo	1	6	4	24	26	6	30	321	321	Y	N	1,2,4	N	1	1,2,4	1-6,8-10	1	174	180	8	1
10	Comprehensive High sch. Leese/moru	3	7	-	20	15	10	20	274	274	Y	Y	6	Y	1	1,4	1-6,8,9	2	300	177	11	-

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 62 Contd

ODIGBO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Isero Senior Grammar School, Odigbo	2	3	14	14	14	10	16	250	250	Y	N	1,2	Y	1,5	1,2	1-9	1	278	259	17	3
12	Kajola Community Grammar School, Kajola	2	5	6	36	36	6	24	282	270	Y	N	1	N	1	1,2,4	1,2,4,5,6,8,9	5	545	421	17	4
13	Muslim High School, Ore (Senior)	3	7	7	28	28	7	14	235	382	Y	N	6	Y	4	1,2,4	1-9	3	396	358	16	11
14	Odigbo High School, Odigbo	1	8	8	32	32	8	16	435	435	N	N	1	Y	1,3	1,4	1 <sup>5</sup> ,6,8,10	1	223	190	20	6
15	Odigbo Senior High School, Odigbo	2	8	8	32	32	8	16	435	435	N	N	1,2	Y	5	1-4	1-6,8-10	1	223	190	24	13
16	Otu- Comm High Sch, Otu-Costain	2	5	1	4	36	9	16	49	76	N	N	1,2,3	N	1	1,2	1,2,4,5,8,9,10	1	340	345	16	9
17	Oro Community High School Oro.	3	7	-	-	-	-	-	36	36	N	N	3	N	1	1,2,4	2-5,8,9	1	153	172	11	1
18	Ore Com Senior Sec. Sch. Sabo Ore	2	8	9	12	24	5	11	390	411	Y	N	1,2,3	N	5	1,2	2-5, 8-9	3	370	521	18	18

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 63

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (y/N)	L Library well stocked? (y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
1	St. John's, Okitipupa	3	17	2	16	131	24	58	760	760	N	N	Y	2,5,6	1	1,2,3,4,8,9	1,2	225	286	4	21
2	Ansarul Islam Okitipupa	2	11	7	28	72	8	36	160	160	N	N	N	3,5	1	1,2,3,4,5,8,9,10	5	325	341	3	12
3	Army Children Sch. II, Okitipupa	2	10	5	20	10	5	10	200	200	N	N	N	1	3,5	1,2,3,4,5,8,9,10	5	198	203	1	18
4	Army Children, Okitipupa	2	20	-	-	-	-	10	304	346	Y	N	N	1,3,5	1	1,2,3,4,5,6,8,9	1	361	378	1	25
5	Bapisit Day School, Okitipupa	2	11	10	40	200	18	56	390	390	N	N	-	1,6	1,4	1,2,3,4,5,8,9	5	368	410	-	-
6	Baptist Day School, Igbotako	1	5	1	-	-	1	-	200	200	N	N	N	5	1	2,3,4,5,8,9	4	107	101	1	4
7	Baptist Day Ode-Aye	2	11	3	28	12	3	24	480	425	N	N	N	1	1,4	1,2,3,4,5,8,9,10	1	182	387	4	11
8	Baptist Ira, Ilutitun	2	6	-	-	-	-	-	110	112	N	N	N	1,5	1	1,2,3,4,5,8,9	5	139	154	-	12
9	C A C School. Ode-Aye	2	6	-	-	-	-	-	300	300	N	N	N	1,5	4	1,2,3,4,5,8,9	5	191	211	2	10
10	C&S Zion, Ilutitun	2	6	-	-	6	-	6	-	240	N	N	N	1,5	1	1,2,3,4,5,8,9	5	173	183	1	7

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6 (Q)	SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5

TABLE 63 Contd

## OKITIPUPA

## INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	C.A.C Primary School Adewinle	3	8
12	Community Primary School Ayetoro	3	4	4	16	16	4	12	360	360	N	N	N	-	1	1,2,3,4,8,9,10	5	183	204	6	5
13	Community Primary School Ayetoro II	1	5	6	24	24	6	12	120	120	N	N	N	5	1	1-9	5	75	61	3	2
14	Community Primary School Eleron Ilutitun	2	-	7	-	28	7	14	30	30	N	N	N	-	-	1,2,3,4,5,8,9	5	63	69	2	2
15	Community Primary School Idogun Omowole	2	3	9	28	36	7	14	138	138	N	N	-	3,5	-	1,2,3,4,5,8,9	-	2	-	4	1
16	Community Primary School Mobolorunduro	2	4	4	16	16	4	8	15	10	N	N	N	5	-	1,2,3,5,8,9,10	5	296	338	4	2
17	Community Primary School Ode Igbo digbo	2	4	6	24	32	6	16	180	180	N	N	N	2	1	1-5, 8,9	5	75	105	1	-
18	Community Primary School Onagunte	1	3	3	12	12	3	12	240	240	N	N	N	1	1	1,2,3,4,5,7,8,9	5	52	71	5	0
19	Community Primary School, Agbaje	2	2	2	8	16	8	48	30	30	N	N	-	1,5	1	1,2,3,4,5,8,9	-	60	67	4	2
20	Community Primary School, Orokin Aye	3	3	-	-	-	-	-	120	120	N	N	N	1,5	1	1,2,3,4,5,8,9	5	112	140	6	1

## KEY

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1			PHCN	1 Other 6
	Attendance Register	2			Generator	2
	Syllabus/Plan of Work	3			PHCN/Generator/	3
	Supervision Book	4			Solar	4
	Visitors Book	5			None	5

TABLE 63 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		21	Community Primary School, Wakajaye	1	5
22	Community School, Ode - Erinje	2	4	6	24	32	6	16	180	189	N	N	N	5	1	1,2,3,4,5,8,9	5	75	105	5	2
23	Ebenezer Ang. School, Ilu Titun	3	9	10	40	40	10	20	200	150	N	N	N	1,5	1	1,2,3,4,5,8,9,10	1	291	348	7	24
24	Ebenezer Unna, Okitipua	2	10	-	-	-	-	-	240	240	N	N	N	3,6	1	1,2,3,4,5,8,9	1	102	97	4	7
25	L A School, Igboluwoye	1	-	9	44	44	-	22	20	30	N	N	-	1,5	1	1,-8-10	5	74	70	6	2
26	L.A. School, Moboro Aye	3	-	-	-	-	-	-	90	90	N	N	N	-	-	1,2,3,4,5,8,9	5	59	66	4	5
27	L. A Practising Ode- Aye	3	8	23	92	92	23	46	330	330	Y	N	N	1,5	1	1,2,3,4,5,8,9	1	295	443	3	15
28	L. A School, Okitipupa	1	10	4	16	20	4	8	134	134	N	N	N	1,5	1,2	1,2,3,4,5,8,9	5	153	158	1	15
29	L. A. School, Igedege	1	4	7	28	24	7	13	336	336	N	N	N	1,5	1	1,2,3,4,8,9	5	66	59	5	-
30	L. A. School, Ilutitun	2	15	-	-	-	-	-	94	94	Y	Y	N	1,3,5	1	1,2,3,4,5,6,8,9	-	349	366	6	14

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 63 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		31	L.A School Fram Settlement	2	5
32	L.A School, Agbetu	2	9	4	20	24	7	12	80	80	N	N	-	3,5	1	1,2,3,4,5,8,9	5	69	67	5	4
33	L.A School, Ajewole	2	5	2	8	24	6	4	360	360	N	N	-	1,5	1	1,2,3,4,5,8,9,10	5	142	90	3	2
34	L.A School, Akinfosile	2	4	6	-	6	6	6	100	120	N	N	-	1,4,5	1	1,2,3,4,8,9	5	62	83	3	3
35	L.A School, Ereti Jomo	1	4	4	16	16	4	2	60	60	N	N	-	1,5	1	1,2,3,4,5,8,9,10	5	55	60	3	-
36	L.A School, Idiobilayo	2	4	3	16	-	3	6	178	172	Y	Y	-	5	1	1,2,3,4,5,8,9,10	5	99	162	4	1
37	L.A School, Igbo Odofin	2	4	4	16	16	4	8	66	66	N	N	-	-	1	1,2,3,4,5,8,9	5	49	59	4	-
38	L.A SCHOOL, IJU ODO	3	6	10	40	40	10	20	180	180	N	N	Y	1,3,5	1	1,2,3,4,8,9	5	99	150	2	6
39	L.A SCHOOL, ILADO MARKET	2	4	2	-	-	-	-	35	35	N	N	N	1,5	1	1,2,3,4,5,6,8,9	5	56	55	2	2
40	L.A School, Okegbe	2	4	-	-	16	-	8	30	20	N	N	-	-	1	2,3,4,8,9	5	62	74	3	2

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	



TABLE 63 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers		
41	L.A SCHOOL, SOGBON	2	10	10	40	40	10	20	32	32	N	N	-	5	1	1,2,3,4,8,9	-	43	54	3	-
42	L.A. School, Ikoya	2	8	8	16	64	8	16	438	392	N	N	N	1,5	1	1,2,3,4,5,7,8,9	-	255	211	6	10
43	Methodist Sch Okitipupa	2	13	4	16	16	4	12	360	300	Y	N	N	3,5	1	1,2,3,4,5,8,9	5	192	181	3	16
44	Methodist Abusoro, Idepe	2	1	2	8	8	1	2	70	56	N	N	N	3,5	-	1,2,3,4,5,8,9	-	90	75	3	-
45	Methodist Araromi Ayeka	2	18	8	8	-	-	-	300	300	N	N	N	-	1	1,2,3,4,5,8,9	5	42	66	3	2
46	Methodist Idepe, Okitipupa	3	18	-	16	15	-	8	254	254	Y	N	-	5	1,2	1,2,3,4,8,9	5	133	129	3	17
47	Methodist Igodanlisa primary School,	2	14	6	24	16	3	6	120	120	N	N	N	3, 5	1	1 <sup>5</sup>	-	182	218	4	11
48	Methodist Okerisa, Ode-Aye	2	-	-	-	-	-	-	120	120	Y	N	N	1,5	-	1,2,3,4,5,8,9	5	61	87	2	4
49	Methodist School Ode - Erinje	2	8	10	40	20	10	20	320	320	N	N	Y	2,5	1,4	1,2,3,4,5,8,9	5	137	136	8	1
50	Methodist School, Igborisa Aye	1	7	7	7	28	7	14	25	25	N	N	N	5	1	2,3,4,5,8,9	5	43	50	1	2

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6	(Q) SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5

TABLE 63 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		51	Methodist School, Igbotako	2	8
52	Methodist School, Ode-Aye	3	12	6	20	24	3	12	500	500	Y	Y	Y	3,5	1	2,3,4,5,6,8,9	1,2,3	277	322	5	16
53	Methodist Primary School, Ilutitun	2	8	-	-	-	-	-	100	100	N	N	-	1,5	1	2,3,4,5,6,7,8,9	5	86	94	2	8
54	St. Gregory Primary School Rcm Ode-Aye	3	7	9	24	28	7	-	400	392	N	N	N	1	1	1,2,3,4,5,8,9	5	179	153	3	12
55	St. Andrew's Remiju Market	2	8	8	32	32	8	16	142	135	N	N	-	5	1	1,2,3,4,5,8,9	5	103	104	5	-
56	St. Andrew's, Abusoro	2	1	1	4	4	1	2	16	16	N	N	-	5	1	2,3,4,5,8,9	5	94	102	2	2
57	St. Anthony's Rcm, Omotoso	2	6	7	28	28	7	14	280	280	N	N	N	1,3,5	1	1,2,3,4,5,8,9	5	292	301	8	6
58	St. Augustine's Rcm, Ilutitun	2	10	2	8	8	2	4	292	292	N	N	Y	1,2,6	1,4	2,3,4,8,9,10	2	126	111	1	12
59	St. Banabas Ang. Ode Erinje	2	7	3	40	40	8	22	552	538	N	N	N	1,5	1	1,2,3,4,5,8,9	5	219	261	7	7
60	St. Benedict's Ilada	2	4	4	16	16	4	8	44	44	N	N	-	1,5	1	1,2,3,4,5,8,9	5	69	62	4	1

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6	(Q) SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5

TABLE 63 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers	M	F
61	St. Benedicts Rcm, Oloto	3	4	1	-	-	2	10	94	72	N	N	N	1,3,5	1	2,3,4,5,8,9,10	5	140	140	5	-
62	St. Christophers, Ode –Aye	3	6	3	24	16	2	4	1200	1200	N	N	N	1,3,5	1,4	2,3,4,5,8,9	5	441	435	5	16
63	St. Columcille's RCM Pry School, Irowa	2	2	14	32	32	14	16	24	22	N	N	N	1,5	1	1,2,3,4,5,8,9	5	51	73	3	1
64	St. Dominic S Ayeka Igbo-digo	2	13	12	40	76	19	38	588	594	N	N	N	1,2,5	1,4	2,3,4,5,8,9	5	462	471	15	25
65	St. Edwards Rcm, Okitipupa	2	8	2	12	12	3	6	428	306	N	N	N	5	1	1,2,3,4,5,8,9	2	143	157	3	11
66	St. John's Araromi Idepe	2	6	-	-	12	3	6	150	150	Y	N	N	1,5	1	1-9	5	209	193	3	5
67	St. John's Igbotako, Oke-Awaye	2	7	2	8	32	8	28	400	400	N	N	N	4,5	1	1,2,3,4,5,8,9	5	327	465	2	9
68	St. John's Okerisa Ilutitun	1	2	7	28	28	7	14	120	120	N	N	-	3	1	1,2,3,4,5,8,9	5	95	70	2	-
69	St. Joseph,S Rcm, Ikoya	3	2	5	20	20	5	10	200	200	N	N	-	1,3,5	1	1,2,3,4,5,8,9	5	197	236	2	22
70	St. Joseph's C.A.C Okitipupa	2	8	6	44	44	11	22	375	410	N	N	N	5	1,4	1,2,3,4,5,8,9,10	5	261	281	4	19

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 63 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers	M	F
71	St. Josephs Rcm, Ode-Erinje	3	3	8	32	17	14	28	100	103	N	N	N	3,6	1	1,2,3,4,5,8,9	2	111	113	7	1
72	St. Mary Rcm, Okitioupa	3	25	6	48	24	-	6	480	480	N	N	N	3,5	1	1,2,3,4,5,8,8,10	5	391	727	5	25
73	St. Marys C&S Okitipupa	3	11	3	12	3	3	8	128	128	N	N	N	2,5	-	1,2,3,4,5,8,9	5	151	176	2	24
74	ST. Mathew's Pry. Sch. IJU Oke	2	6	4	16	40	6	16	60	60	N	N	-	1	1	1,2,3,4,5,8,9,10	5	40	37	2	2
75	St. Matthews Rcm Oloto	2	14	2	8	36	2	20	240	240	Y	N	N	1,5	1	1,2,3,4,5,8,9	5	132	178	5	3
76	St. Matthias Rcm, Ode-Aye	3	3	10	8	10	8	10	460	460	N	N	N	1,5	1	2,3,4,5,8,9	1	157	161	5	8
77	St. Patricks Rcm Okunmo	3	7	8	12	48	10	16	300	300	N	N	N	3,6	1,4	2,3,4,5,8,9,10		186	174	5	9
78	St. Paul S Ang, Ikoya	3	-	9	36	16	9	2	173	173	N	N	N	5	1	1,2,3,4,5,8,9,10	5	189	196	4	6
79	St. Paul's Ang. Ilutitun	1	11	1	24	-	6	-	500	500	N	N	N	1,5	1,4	2,3,5,8,9	5	165	172	9	22
80	St. Paul's Erekiti luwoye	2	-	-	-	-	-	-	338	338	N	N	Y	1,3,5	1	1,2,3,4,5,8,9	5	157	181	4	5

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 63 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		81	St. Paul's Ilado olowosusi	3	9
82	St. Paul's School, Iju- Odo	2	10	4	-	-	-	-	226	226	Y	N	Y	1,3,5,6	1	2,3,4,5,8,9	2	189	235	4	9
83	St. Peter's School, Ilutitun	1	13	8	32	8	8	16	1072	1072	N	N	N	5	1	1,2,3,8,9	5	569	516	3	9
84	St. Pius Pry School, Igbotako	1	-	6	24	24	6	12	400	400	N	N	-	5	1	1,2,3,4,5,8,9,10	5	678	963	5	8
85	St. Rapehels C&S Oke-Igbala	2	6	8	12	48	10	16	100	100	N	N	N	5	1	1-5, 8,9	5	300	350	2	4
86	St. Stephen's School, Igbotakon's School, Igbotako	3	15	9	60	20	2	4	72	62	N	N	N	1,5	1	1,2,3,4,5,8,9	5	115	108	4	8
87	St.Pauls Ang ,Okitipupa	2	6	6	8	24	5	9	240	240	Y	N	Y	1,5	1	1,2,3,5,8,9,10	2	126	123	5	9
88	The Apostolic, Okitipupa	1	-	10	40	40	10	10	240	240	N	N	N	1,3,5	1	1,2,3,5,8,9	5	189	172	1	16

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 64

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Manuwa Memorial Grammar School, Iju-odo	3	6	12	24	96	9	9	400	380	Y	N	1,2,3,4	Y	1,2,3,5	1,2,4	1-9	3	273	272	19	7
2	Ayeka / Igbo-digo/Oke Igala High Sch, Ayeka	2	6	9	29	16	9	18	232	263	Y	N	N	N	2,5	1,2	1-9	1	181	163	12	5
3	Baptist Grammar School Ode-Aye	2	14	4	16	56	-	14	460	460	Y	N	1,2,3	Y	1,4,5	1,2,4	1-5,8-10	1	133	130	8	8
4	Comm. Grammar School, Igbotako	2	11	6	72	72	9	-	340	340	Y	N	1,2,3	N	1,4,5	1,2,4	1-9	1	232	263	16	4
5	Community High Sch. Moboluwaduro	2	3	3	24	24	5	8	120	135	Y	N	1,2,3	Y	3,5	1,2,4	1-6,8-10	5	234	109	10	2
6	Community High School, Erekiti/luwoye	2	6		24	24	1	12	277	277	Y	N	6	N	1,3,5	1,2	1-5,7,8,9	1	154	115	11	4
7	Comprehensive High School, Ode-Aye	2	12	6	72	48	22	22	240	240	N	N	N	Y	1,5	1	1,2,3,4,7,8,9	1	160	110	19	14
8	Comprehensive high School, Ode-Ilutitun	3	14	2	48	56	12	14	480	500	Y	N	1	N	3,5	1	1,2,3,4,7,8	1	332	456	13	9
9	Daniken High Sch, Ode-Aye	2	9	9	12	36	9	14	200	200	Y	N	N	Y	5	1	1-4,7,8	1	68	71	6	3
10	Idepe High School, Okitipupa	2	9	3	12	44	-	9	240	300	Y	N	4,6	Y	3,5	1,2,4	1,2,3,4,5,7,8	3	342	261	24	7

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 64 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Igodanlisa/Okumo High Sch. , Igodan Lisa	1	12	-	28	44	-	10	260	280	Y	N	6	N	3,5	1,2	1,2,3,4,5,6,7,8	1	148	149	17	1
12	Ikale High School, Igashin-oloti	1	4	2	4	16	4	8	30	49	N	N	-	Y	1,3,5	1,4	1-9	2	78	58	7	0
13	Ikoya Grammar School, Okitipupa	3	9	-	24	24	-	6	350	350	N	N	-	Y	5	1,2,4	1,2,3,4,5,7,8	1	146	164	14	4
14	Labuku Comprehensive high School, Igbotako	2	6	-	-	24	-	12	346	346	Y	N	2	N	5	1,2,4	1,2,3,4,5,7,8	1	215	202	19	7
15	Layelu High School, Ode-Aye	3	11	3	12	32	7	8	350	400	Y	N	1,2,3	N	1,2,5	1,4	1-5,7,8,9	1	248	268	16	3
16	Methodist high School, Okitipupa	2	15	-	-	-	-	-	1200	1200	Y	Y	1,2,3,5	Y	3,5	1,2,3,4	1-9	3	596	458	10	12
17	Moribodo College, Ilutitun	2	8	6	24	24	6	6	240	240	Y	N	1,2,3,4	Y	1,2,5	1,2,3,4	1,2,3,4,5,7,8	1	250	214	14	4
18	Ode erinje Grammar School, Ode- Erinje	2	4	3	20	18	2	18	100	100	Y	N	1,2	N	3,5	1,2	1,2,3,4,5,7,8	1	115	137	14	2
19	Ofedepe Comprehensive School ,Okitipupa	2	11	11	20	52	3	26	460	460	N	N	-	N	3,5	1,4	1,2,3,4,5,7,8	1	249	253	21	8
20	Ogundibuja High School, Okitipupa	3	6	6	12	24	6	12	240	240	Y	Y	-	Y	1,5	1,2	1-9	2	148	138	10	17

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 64 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
21	Omotoso Community Gram. Sch, Omotoso	1	1	1	4	4	1	-	181	192	N	-	4	N	1,3,5	1	1,2,3,4,5,7,8,9	2	152	107	17	10
22	Stella Maris college Okitipupa	2	14	2	-	-	-	28	548	638	Y	N	1,2,3	N	3,5	1,2,4	1,2,3,4,5,6,7,8	1	432	585	18	17
23	Unity Sec. Schl, Ode-Aye	2	13	4	16	10	2	12	700	700	Y	Y	1,2,3,4,5	Y	1,2,3,4,5	1-3	1,2,3,5,6,7,8	1	470	320	22	1

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		



TABLE 64 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Manuwa Memorial Grammar School, Iju-odo	3	12	12	24	96	9	24	400	380	Y	N	1,2,3,4,5	Y	1,2,3,5,6	1,2,3,4	1-9	2	268	242	14	5
2	Ayeka / Igbo-digo/Oke igala high School, Aeka	2	4	9	29	16	9	18	232	263	Y	N	-	N	3,5	1,2	1-9	1	247	258	8	12
3	Baptist Grammar School Ode-aye	2	6	4	16	56	-	14	460	460	Y	N	1,2,3	Y	1,3,5	1,2,4	1-9	1	186	177	7	8
4	Comm High School, Mobolorunduro	2	3	3	24	24	5	8	120	135	Y	N	1,2,3	Y	3,5	1,2,4	1-9	5	205	223	15	4
5	Comm. Grammar School, Igbotako	2	10	-	24	24	1	12	277	277	Y	N	-	N	1,3,5	1,2	1-9	1	255	222	5	10
6	Comprehensive high School, Ilutitun	3	9	2	48	56	12	14	480	500	Y	N	1	N	3,5	1	1-9	1	312	394	10	9
7	Comprehensive High School, Ode-Aye	2	12	8	12	48	12	12	240	240	Y	Y	1,2,3	Y	1,5	1,2	1-8	1	87	104	14	11
8	Daniken High School, Ode- Aye	2	9	9	12	36	9	14	200	200	Y	N	-	Y	5	1	1-9	1	146	160	5	3
9	Idepe high school, Okitipupa	2	9	3	12	36	-	9	240	300	Y	N	1,2,3,4	Y	3,5	1,2,4	1-9	3	278	243	15	5
10	Igbokoda Comm Grammar School, Igbokoda	2	3	6	72	72	9	-	340	340	Y	-	1,2,3	-	1,3,5	1,2,4	1-9	1	175	195	8	1

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 64 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Igodan –Lisa Okumo high School igodan	2	6	-	8	44	-	10	260	280	Y	N	-	N	2,5	1,2	1-9	2	243	235	7	5
12	Ikale High School, Igshin-Oloti	1	5	2	4	16	4	8	30	49	N	N	-	Y	1,3,5	1,4	1-9	2	34	39	8	1
13	Ikoya Grammar School, Okitipupa	3	3	-	24	24	-	6	350	350	N	-	-	Y	5	1,2,4	1-9	1	169	174	10	7
14	Labokun Comprehensive high School, Igbotako	2	4	-	-	24	-	12	346	346	Y	N	2	Y	6	1,2,4	1-9	1	201	228	-	-
15	Layelu high Sch, Ode-Aye	3	7	3	12	32	7	8	400	400	Y	N	1,2,3	N	1,2,5	1,4	1-9	1	280	308	13	5
16	Methodst high School, Okitipupa	2	17	-	-	-	-	-	1200	1200	Y	Y	1,2,3,5	Y	3,5,6	1,2,3,4	1-10	3	568	501	7	22
17	Moribodo College, Ilutitun	2	6	6	24	24	6	6	240	240	Y	N	1,2,3,4	Y	1,2,5	1,2,3,4	1-9	1	161	193	5	9
18	OdeErinje Grammar School, Ode-erinje	2	3	3	20	9	2	18	100	100	Y	N	1,2	N	3,5	1,2	1-9	1	194	205	11	2
19	Ofedepe Comprehensive School ,Okitipupa	2	15	11	20	52	3	26	460	460	-	N	-	N	2,5	1,4	1-9	1	369	386	8	21
20	Ogundibuja high School, Okitipupa	3	6	6	6	24	6	12	240	240	Y	Y	-	N	1,5	1,2	1-9	2	158	138	8	16

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 64 Contd

OKITIPUPA  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
21	Omotoso Comp. Gramm School	2	1	7	12	14	4	8	240	240	Y	N	1,2,3	Y	3,5,6	1,4	1-8	1	141	128	9	3
22	Stella Maris college Okitipupa	2	7	3	-	92	9	28	548	638	Y	N	1,2,3	N	3,5	1,2,4	1-9	1	526	508	9	25
23	Unity Sec. Schl, Ode-Aye	2	10	6	28	14	2	8	500	500	Y	N	1,2,3	Y	2,5	1,2,4	1-9	1	148	130	14	6

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 65

ONDO EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	L.A. Pry School Oke-Oya	1	2
2	Bishop Vining Primary School Epe	3	16	5	20	44	10	16	200	200	N	N	N	1, 5	1	2,3,4,5,8,9	1	136	114	6	11
3	Community Primary School Mobolade	1	6	4	-	18	3	6	190	190	Y	N	Y	4	1	1,2,3,4,5,9	5	111	117	5	2
4	Community Primary School Atamo	2	9	3	12	12	3	6	166	167	Y	N	Y	1, 5	1, 4	1,2,3,4,5,8,9	5	112	111	7	6
5	Community Primary School Olorunsogo	1	8	4	16	16	4	8	50	50	N	N	Y	1, 4	1	2,3,4,5,6,7,8,9	5	217	265	6	1
6	Community Primary School Owena Tepo	3	6	-	12	-	-	-	130	130	Y	N	N	1, 3	1	1,2,3,4,5,8,9	5	215	297	4	3
7	Community Pry Sch, Obada Oke Owena	2	6	-	-	-	-	-	262	260	N	-	Y	1, 6	1	2,3,4,5,8,9	5	100	98	2	2
8	Community Pry School, Olorunsefunmi	1	8	4	16	32	4	8	300	300	Y	N	Y	1, 5	1	1,2,3,4,5,8,9,10	5	69	83	4	8
9	Ebenzer Ang Pry School Kajola	2	7	-	-	8	-	4	240	240	N	N	Y	1, 5	1, 4	1,2,3,4,5,8,9,10	5	181	186	5	11
10	Holy Trinity Ang Pry Sch Kolawole Oke Owena	1	7	4	-	-	-	-	255	260	N	-	Y	1, 3	1	1,2,3,4,5,8,9	5	129	124	6	4

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6	(Q) SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5

TABLE 65 Contd

ONDO EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	L. A Primary School Mofere	1	11
12	L. A Primary School, Sokoto	2	6	-	-	-	-	-	80	80	N	N	N	3	1	1,2,5,8,9	5	73	88	6	5
13	L. A Priy Sch,Asantan Fibe	2	10	3	14	14	3	6	240	240	N	N	Y	1	1	1,2,3,4,5,8,9,10	5	50	57	8	1
14	L. A. Pry School, Orisunbare	1	6	2	24	16	4	6	80	80	N	-	N	1	1	2,3,4,5,8,9	5	62	65	10	4
15	L. A. Pry School,Okia	1	6	4	16	16	4	6	70	70	N	N	Y	1	1	1,2,3,4,5,8,9	5	176	209	4	2
16	L.A Primary School Okeopa	3	6	3	14	12	3	5	70	70	N	N	Y	5	1	1,2,3,4,5,8,9,10	5	80	87	6	3
17	L.A Primary School Oke-opa	3	3	3	14	12	3	5	70	70	N	N	Y	5	1	1-5,8-10	5	80	87	5	5
18	St. William's RCM Omifunfun	1	6	6	12	24	6	12	160	160	Y	N	Y	1, 5	1	2,3,4,5,6,8,9	5	103	118	3	11
19	St. Barnabass C/S Araromi Awo	2	8	-	-	-	-	-	160	160	N	-	Y	1, 6	1, 4	2,3,5,8,9	2	67	75	18	4
20	St. Benediect S Rcm Pry Sch Ojojo	1	3	3	12	12	3	6	84	84	N	N	Y	1	1	1-10	5	84	82	3	12

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 65 Contd

ONDO EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
21	St. David's A/C Primary School Asantan Oja	2	3	1	-	12	1	6	76	76	N	-	Y	1, 4	1	1,2,3,4,5,8,9	5	213	292	2	3
22	St. Dominio's RCM Ayefere	2	6	1	16	16	3	8	54	54	N	N	N	1	1	1,2,3,4,5,7,8,9	5	73	88	9	2
23	St. Edward's RCM Primary School Igba.	3	14	6	24	24	6	12	250	250	N	N	Y	1,4,5	1	1-5,8-10	3	178	166	3	18
24	St. Endas Rcm Pry School Lafiaji	2	7	-	-	-	-	-	180	190	N	N	Y	1, 5	1, 4	1,2,3,4,5,8,9	5	108	118	4	1
25	St. Gerald's Rcm Pry School, Awoduyilemi	2	14	6	10	16	6	12	240	240	N	N	Y	1	1	1,2,3,4,5,8,9	5	102	97	7	1
26	St. Helens Ang Pry, School Obun-Ewi	1	6	2	6	6	2	4	48	48	N	N	Y	1	1	1,2,3,4,5,8,9,10	5	46	47	5	7
27	St. Itas Rcm Pry School, Sasere	2	11	2	8	8	2	4	208	220	N	-	Y	3, 5	1, 4	1,2,3,5,8,9	2	194	193	11	7
28	St. John's Agn Primary School Fagbo-Oja	3	9	9	36	12	3	18	360	360	N	N	Y	1, 3	1	1,2,3,4,5,8,9	5	232	223	5	8
29	St. Johns A/C Pry School, Lalagba	2	9	-	12	10	-	6	260	260	N	N	Y	1,4,5	1, 4,5,6	2,3,4,5,6,8,9	5	195	161	4	37
30	St. John's Ang Pry. Sch, Igbo-Oja	2	12	-	8	6	3	8	216	216	N	N	N	1, 5	1	1,2,3,4,5,8,9,10	5	140	161	7	24

KEY

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6 (Q)	
(P)	SCHOOL RECORDS			SOURCE OF ELECTRIC POWER	
	Admission Register	1		PHCN	1 Other 6
	Attendance Register	2		Generator	2
	Syllabus/Plan of Work	3		PHCN/Generator/	3
	Supervision Book	4		Solar	4
	Visitors Book	5		None	5

TABLE 65 Contd

ONDO EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
31	St. Lawrence Rem Pry School Otasun	1	2	2	4	4	-	4	280	280	N	N	Y	1	1	1,2,3,4,5,8,9,10	5	32	27	5	12
32	St. Like's Ang Primary School Oboto	2	11	1	12	14	-	6	350	350	N	-	Y	1, 6	1	1,2,5,8,9	1	105	123	3	17
33	St. Lukes Ang Pry School, Laworo	2	3	-	6	6	-	-	72	68	N	N	Y	1	1	2,3,4,8,9	5	69	64	3	3
34	St. Machael's RCM Pry Sch Fagbo Pdre	2	9	-	-	24	-	12	400	400	N	N	Y	1	1	2,3,4,5,8,9	5	52	65	5	9
35	St. Mariaan's RCM Pry Sch Ajebambo Orin	1	4	-	4	4	-	4	128	128	N	-	Y	1, 5	1	2,3,5,8,9	5	46	56	7	9
36	St. Matthews A/C Pry Ateru	1	6	6	24	24	3	12	54	128	Y	N	Y	1	1	1-10	5	127	207	3	6
37	St. Matthews Ang School, Owena Elesin	3	12	3	12	12	6	-	240	240	Y	N	N	2, 5	1	1,2,3,4,5,6,8,9	1	118	109	2	13
38	St. Pauls (Ang) Pry Sch. Waasimi	2	6	-	-	-	1	2	320	320	N	N	Y	1, 3,5	1, 4	1,2,3,4,5,8,9,10	2	51	59	-	22
39	St. Peter's Ang Primary School Bolorunduro	3	15	-	24	24	6	10	220	220	Y	Y	Y	1, 3	1,2,4	1,2,3,4,5,6,8,9	3	175	199	-	2
40	St. Peter's Ang Primary School Onigbo	2	8	-	-	-	3	4	120	120	Y	Y	Y	1, 6	1	1,2,3,4,6,8,9,10	1	88	124	9	30

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 65 Contd

**ONDO EAST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		41	St. Peter's Ang Primary School Orisunbare	1	7
42	St. Peters Rcm Pry School Baikin	2	16	-	40	40	10	20	12	240	N	N	Y	1, 5	1	1,2,3,4,5,8,9,10	5	2	10	2	10
43	St. Philomena RCM, Tekuile	3	8	3	12	10	8	12	215	235	N	-	N	1,5	1	2,3,4,5,8,9	5	172	179	5	1
44	St. Phips WS Primary School Omiluri O.E. 35	2	8	2	16	8	6	4	222	250	N	-	Y	5	1, 4	1,2,3,4,5,8,9	5	54	57	3	8
45	St. Pius Rcm Pry School, Lipepeyiwe	3	6	4	16	16	4	8	100	100	N	N	Y	1	1	1,2,3,4,5,8,9,10	5	86	82	5	4
46	Stephen's Agn Primary School Lawure	3	6	3	12	24	-	12	260	260	N	-	Y	1	1	1,2,3,4,5,8,9	5	103	112	5	3

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6	
(P)	SCHOOL RECORDS			(Q)	SOURCE OF ELECTRIC POWER
	Admission Register	1			PHCN
	Attendance Register	2			Generator
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			Solar
	Visitors Book	5			None
					1 Other
					2
					3
					4
					5
					6



TABLE 66

ONDO EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Community Comprehensive High School, Egbho	2	8	6	8	8	2	6	160	160	Y	N	4, 5	Y	1, 3, 5	1, 2	2-5,8,9	3	89	71	3	7
2	Community Grammar school, Tekunle	2	2	1	4	10	2	4	120	120	Y	N	4	Y	1, 5	1, 2	2-5,8,9	1	110	108	9	7
3	Ekimogun Com Grm Sch, Bororunduro	2	8	4	12	18	5	8	200	200	Y	N	N	Y	5	1,2,4	2-5,8-10	3	188	164	6	10
4	Epe Community Grammar School Epe-Ondo	1	3	3	12	12	3	6	238	238	N	-	N	Y	1,5	1	2'-5,8,9	1	137	130	6	2
5	Holy Trinity Grammar School Ondo	1	6	6	24	24	12	12	200	200	Y	N	4	Y	1,4,5	1,2,4	1'-10	3	233	222	4	25
6	Ogo Oluwa Community Grammar School, Oboto	1	4	1	4	8	-	6	120	120	Y	N	4	Y	1, 5	1, 2	1'-6,8,9	1	113	104	9	8
7	Oladapo Community high School, Oke- Owena	2	6	-	24	24	6	12	35	93	N	N	N	Y	5	1,2,4	2'-5,8,9	2	144	129	7	2
8	Orisunmibare Community High School ,Orisunmibare	2	3	-	12	12	-	6	100	115	Y	N	N	Y	1	1,2,4	2-6,8-10	2	112	102	6	2
9	Owena Community Grammar school, Owena	2	8	2	20	22	6	10	254	222	N	-	N	Y	1	1, 2	1'-5,8,9	1	208	204	6	15
10	Sokoto /Ogundele Com high school, Ondo	1	2	14	4	2	3	2	280	280	Y	N	Y	Y	1,4,5	1	1'-6,8,9	1	113	104	9	8

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 66 Contd

ONDO EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Temidire Community Grammar Igbooja	2	3	3	6	6	3	4	150	148	N	-	4	N	4, 5	1,2,4	2- '5,8,9,10	1	102	118	4	14
12	Community Grammar school. Asantan-Oja	1	5	3	10	12	3	5	20	20	N	N	4	Y	1,4,5	1	1-5,6-10	1	67	50	2	4

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 66 Contd

ONDO EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Community Comprehensive High School, Faabo	2	4	1	4	10	2	4	120	120	Y	N	6	Y	1, 5	1, 2	2-5,8,9	1	110	108	10	7
2	Community Grammar school, Tekunle	3	4	4	6	6	3	3	180	180	N	N	6	Y	1, 5	1, 4	1-5,8-10	2	60	63	6	9
3	Ekimogun Com Grm Sch, Bororunduro	2	9	3	12	20	3	12	278	278	Y	N	1-4	Y	4, 5	1, 2	2-6,8-10	1	165	153	13	7
4	Epe Community Grammar School, Epe-Ondo	3	5	3	12	15	1	4	120	180	Y	N	6	N	3, 5	1, 2	1,2,4,5,8,9,10	1	137	129	10	5
5	Holy Trinity Grammar School, Ondo	2	12	4	12	12	-	24	250	262	Y	N	6	Y	1, 5	1,2,4	1-5,8-10	1	259	243	14	17
6	Ogo Oluwa Community Grammar School, Oboto	3	4	2	8	16	2	8	55	55	Y	N	1-4	Y	1,4,5	1,2,4	2,4,5,6,8,9	1	85	89	13	2
7	Oladapo Community high School, Oke-Owena	2	6	-	24	24	6	12	34	45	N	N	4, 6	Y	5	1,2,4	2-5,8,9	2	88	75	7	2
8	Orisunmibare Community High School, Orisunmibare	3	6	5	12	12	2	6	300	500	Y	N	1, 2	Y	1	1,2,4	1-6,8,9	2	310	221	9	2
9	Owena Community Grammar school, Owena	2	11	6	8	22	-	11	200	200	Y	N	6	Y	5	1,2,4	2-6,8,9	3	195	170	16	13
10	Sokoto /Ogundele Com high school, Ondo	3	6	4	12	16	1	4	200	240	N	N	1-3	N	1,4,5	1, 2	1-5,8-10	2	96	101	9	4

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 66 Contd

ONDO EAST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (y/N)	Library well stocked? (y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Temidire Community Grammar Igbooja	1	4	1	4	16	4	8	150	150	Y	-	1,4,5	N	1	1,2	1,2,4,5,8,9	1	241	282	7	5
12	Community Grammar school. Asantan-Oja	1	5	-	10	8	5	3	40	40	Y	N		Y	1,4,5	1	1-5,6-10	1	24	18	3	5

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 67

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	A.U.D Primary School, Yemaja-Ondo	3	17
2	Adeyemi College of Edu Public Pry Sch, Ondo	2	32	10	20	30	10	20	194	194	N	N	N	6	4	1-5,8,9	1	328	319	5	37
3	All Saint's (Ang) Pry School, Ayeyemi-Ondo	2	17	-	-	32	7	8	166	166	N	N	N	1,6	1	2,3,4,5,8,9,10	1	111	114	2	8
4	All Saints Ang Pry Sch igunsin, Ore Rd, Ondo	2	2	3	8	8	3	8	168	168	N	N	N	1,4,6	1,4	1,2,3,4,5,7,8,9	5	49	55	1	3
5	Ansar-Ud-Deen Pry School, Okelisa, Ondo	2	10	20	70	90	20	40	510	510	N	N	N	1,4,5	1,4	1,2,3,4,5,8,9,10	3	481	644	5	29
6	Awosika Memorial Pry Sch, Yaba, Ondo	3	10	-	24	72	-	-	364	364	N	N	Y	1,4,5	1,2,4	1,2,3,4,5,8,9	1	305	319	1	25
7	Babalola Memorial C.A.C Pry Sch Akinjagunla	3	3	7	7	24	7	4	296	292	N	N	Y	6	1	1,2,3,5,8,9	1	187	233	-	18
8	Bishop Philip's Memorial Pry Sch Surulere, Ondo	3	10	10	36	36	12	20	259	254	N	N	N	1,5	1	1,2,4,5,8,9	5	231	245	2	17
9	Christ Anglican Pry Sch Obunkeko Irowa Ondo	2	16	16	64	64	16	32	410	410	N	N	N	1	1	1-5,7-10	5	185	196	6	-
10	Christ Anglican Primary School, Ayeyemi, Ondo	2	10	23	24	88	16	64	600	600	N	N	N	4,5,6	1,4	1,2,3,5,8,9,10	3	625	460	1	33

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 67 Contd

**ONDO WEST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	Name of Institution	A Nature of building Materials	B No of Functional classrooms	C No of roofs in bad condition	D No of walls in bad condition	E No of windows in bad condition	F No of floors in bad condition	G No of doors in bad condition	H Total access to Seat	I Total access to Desk	J Availability of library (Y/N)	K Library well stocked? (Y/N)	L Availability of Computer (Y/N)	M Health / Water Supply / Sanitation Facilities available	N Recreational facilities available	O School Records available	P Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	Christ Anglican Primary School, Egure-Oba, Ondo	1	5
12	Cmmunity Primary School, Oluwabasiri, Ondo	1	3	7	28	28	3	17	126	126	N	N	N	1,5	1	1,2,3,4,5,8,9	5	102	97	2	1
13	Com Pry Schl Ayetoro-Igbindo, Ondo	1	7	7	17	15	-	14	172	172	N	N	N	1	1	1,2,3,8,9	5	93	102	3	2
14	Com Pry Schl, Olorun Gbadurami, Ondo	1	1	6	6	6	6	6	24	24	N	N	N	-	1	2,3,4,5,8,9,10	5	75	71	3	-
15	Com Pry Schl, Temidire-Orimolade Ondo	1	6	6	18	18	6	6	80	80	N	N	N	1	1	1,2,3,4,5,8,9	5	52	55	4	2
16	Com Pry School, Owode-Eleepo, Ondo	1	8	4	16	16	5	8	210	106	N	N	N	-	-	1,2,3,4,5,8,9		103	112	4	1
17	Comm Primary School Osun-Ondo	1	1	2	24	18	4	12	80	117	N	N	N	1	1	1-5,8,9,10	5	54	48	4	-
18	Comm Pry Sch, Legiri	1	4	2	14	10	4	4	58	42	N	-	N	-	-	2,5,9	5	149	162	2	2
19	Comm Pry,Schl Orisunmibare II,	1	6	6	14	14	6	6	-	-	N	N	Y	1,3,5	1	1,4,5,8,9	5	104	110	7	5
20	Community Primary School Adebajo-Ondo	1		6	24	24	6	12	160	160	N	N	N	-	1	2,3,4,5,8,9	5	52	92	9	-

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	<b>SCHOOL RECORDS</b>		Water Closet	6 (Q)	<b>SOURCE OF ELECTRIC POWER</b>	
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 67 Contd

**ONDO WEST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers		
21	Community Primary School Orisunmibare, Ondo	1	4	-	4	4	4	4	271	271	N	N	N	1,5	1	1,2,4,5,8-10	4	139	132	1	5
22	Community Primary School Orisunmibare, Ondo	1	2	3	13	15	3	5	90	90	N	N	N	1	1	1,2,3,4,5,8,9,10	5	34	33	4	3
23	Community Primary School Tokunbo Ondo	2	7	20	20	10	20	52	120	120	N	N	Y	1,5	1,4	1-10	5	419	473	5	3
24	Aratu Olojo, Gbagialaje Road Ondo	1	4	4	16	16	4	8	76	84	N	N	N	1,3,6	1	1,2,4,8,9	5	152	170	3	3
25	Ebenezer Ang Pry Schl, Ajagba-Alafia Ondo	1		3	12	12	3	6	40	40	N	N	N	-	-	1,2,3,4,5,8,9		62	55	3	7
26	Emmanuel Anglican Primary School, Odojomu-Ondo	3	9	4	13	13	4	20	359	410	N	N	N	1,6	1	1-5,8,9,10	5	397	373	3	47
27	Holy Flock of Christ Pry. Sch. Adeyemi Ondo	2	17			32	7	8	70	70	N	N	N	1,6	1	1,2,4,5,8,9	5	263	315	1	19
28	Holy Trinity Ang. Pry Schl, Agbogboke- Ondo	1	3	6	20	32	6	16	617	596	N	N	N	1,4	4	2,3,4,5,8,9	5	321	343	3	36
29	L. A. Primary School Oloruntedo-Ondo	2	3	3	9	12	-	12	80	80	N	N	N	-	1	1,2,3,5,8,9,10	5	111	105	3	2
30	L.A Primary School Araromi Oko, Ondo	1	5	4	4	4	4	4	200	200	N	N	N	2,3	1	1-5,8,9	5	168	186	6	3

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER
(P)	SCHOOL RECORDS				PHCN
	Admission Register	1			1 Other
	Attendance Register	2			2
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			3
	Visitors Book	5			Solar
					4
					None
					5

TABLE 67 Contd

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers	M	F
31	L.A Primary School Okegbonawa-Ondo	2	-	-	-	-	-	4	240	240	N	N	N	6	1	1,2,3,4,5,8,9	5	103	96	3	-
32	L.A Primary School Olosan-Laje, Ondo	1		6	24	24	6	12	100	100	N	N	N	1	1	2,3,4,5,8,9	5	43	55	3	2
33	L.A Primary School, Aboba-Ondo	1	6	7	7	7	7	7	181	181	N	N	Y	1,5	1	1-9,10	5	142	159	4	3
34	L.A Primary School, Ajebambo- Ondo	3	18	7	9	9	9	9	56	42	N	N	N	5	1	2,3,4,5,8,9	5	94	111	6	8
35	L.A Primary School, Lisaluwa Ondo	3	6	6	12	30	7	16	106	106	N	N	N	-	-	1,2,3,4,5,8,9	5	59	65	-	9
36	L.A Primary School, Oke-Alafia, Ondo	1		6	24	20	6	12	88	88	N	N	N	4,6	1	1,2,3,4,5,8,9,10	5	222	199	5	2
37	L.A Pry School Olorunsogo -Okeruku, Ondo	2	10	4	20	20	10	20	240	240	N	N	N	-	1	1,2,3,4,5,8,9,10	-	47	64	7	7
38	L.A. Model Pry Sch, Igbado	2	9	3	27	33	-	4	400	400	N	N	Y	3	1	1,2,3,4,5,8,9	1	145	156	1	9
39	L.A. Pry Sch, Epaluwa	3	5	-	18	3	-	3	76	40	N	-	N	1	-	1,2,3,4,5,7,8,9,10	5	58	62	1	5
40	L.A. Pry Sch, Kudola	1	3	3	12	12	3	3	78	78	N	-	N	-	1	1,2,3,4,5,8,9	5	98	104	5	7

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	



TABLE 67 Contd

**ONDO WEST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
41	L.A. Pry Sch, Okegun	1	6	6	24	24	5	-	68	66	N	N	N	1	1	1,2,3,4,5,8,9	5	101	112	3	4
42	Local Authority I Pry Schl, Odosida, Ondo	3	10	8	15	8	10	8	280	280	N	N	N	1,4	1,4	1,2,3,4,5,8,9	1	178	180	2	17
43	Local Authority Primary School Lamu Ondo	2	-	-	5	10	5	10	288	288	N	N	N	1	1,4	1,2,3,4,5,8,9,10	5	176	170	5	1
44	Local Authority Primary School Erinla-Ondo	1	8	1	27	16	1	14	380	380	Y	N	Y	1,5	1	1,2,3,5,6,8,9,10	1	144	156	1	9
45	L. A. Pry Schl, Igbokuta-Abusoro	1	4	4	24	20	-	12	76	76	N	N	N	3	1	1,2,3,4,5,8,9,10	5	38	35	2	0
46	Messiah A/C Primary School, Oke Agunla, Ondo	2	8	4	30	30	7	16	160	160	N	N	N	1,6	1	1,2,3,4,5,8,9		132	130	2	10
47	Methodist Pry Schl , Oke Agunla Street Ondo	3	3	10	40	40	10	20	100	100	N	N	N	1,6	1,4	1,2,4,5,8,9	5	385	418	1	27
48	Motailatu Primary Sch, Oke-Iwosan, Ondo	2	2	6	15	15	6	10	50	50	N	N	Y	1,4,6	-	1,2,3,4,5,8,9	5	249	229	-	8
49	Motailatu Pry Schl, Italurowo, Ondo	3	-	-	-	-	-	-	160	160	N	N	N	1	-	1,2,3,4,5,8,9	5	51	47	-	8
50	Mount Bethel Primary School, Sabo- Ondo	2	5	3	3	3	3	3	28	28	N	N	N	6	-	1,2,4,8,9	5	115	168	3	14

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6 (Q)	
(P)	<b>SCHOOL RECORDS</b>				<b>SOURCE OF ELECTRIC POWER</b>
	Admission Register	1			PHCN
	Attendance Register	2			Generator
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			Solar
	Visitors Book	5			None
					1 Other
					2
					3
					4
					5
					6

TABLE 67 Contd

**ONDO WEST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	Name of Institution	A Nature of building Materials	B No of Functional classrooms	C No of roofs in bad condition	D No of walls in bad condition	E No of windows in bad condition	F No of floors in bad condition	G No of doors in bad condition	H Total access to Seat	I Total access to Desk	J Availability of library (Y/N)	K Library well stocked? (Y/N)	L Availability of Computer (Y/N)	M Health / Water Supply / Sanitation Facilities available	N Recreational facilities available	O School Records available	P Source of Electric power	R		S	
																		M	F	M	F
																		51	Ogo-Olorun C/S Pry Sch, Oke Sarowo Ondo	2	3
52	Olasunmi Motalatu Pry Sch, Akinjagunla- Ondo	2	8	4	-	-	-	8	332	332	N	N	N	1,6	1	2,3,4,5,8,9		128	132	-	13
53	Orimolade Comm Pry Sch, Ayetoro- Igbokuta, Ondo	1	2	3	24	26	4	6	92	104	N	N	Y	1	4	1,2,4,5,8,9,10	5	152	198	5	0
54	Orimolade Cpm Pry Sch, Litaye	1	4	2	20	8	2	4	252	252	N	-	-	3,5	1	1,2,4,5,8,9,10	3	92	75	4	7
55	Our Savior's Anglican Primary School, Ondo	3	18	15	60	72	15	30	588	588	Y	Y	Y	1,4,5	1,5	1,2,3,4,5,6,8,9	1	388	385	1	21
56	Saint Catherine's R.C.M Primary School, Ondo	2	12	9	40	40	6	20	600	600	N	N	N	-	1	1,2,3,4,5,8,9	5	313	319	1	17
57	Salvation Army Pry Schl Orisunmibare- Ondo	3	7	5	20	20	5	10	226	202	N	N	N	1,3	1	1,2,3,4,5,8,9,10	5	108	132	-	18
58	Siraju-Deen Primary School, Gbagia- Ondo	1		7	28	28	7	14	240	240	N	N	Y	1,5	1	2,3,4,5,8,9	5	110	100	4	-
59	St Agnes R.C.M Pry Schl, Oke-Igbala, Ondo	3	10	-	45	60	15	30	180	199	N	N	N	1,6	1	1,2,3,4,5,8,9	5	300	310	-	16
60	St Helen, Dem Pry Schl, Ademulegun-Ondo	2	35	35	108	100	35	34	865	865	Y	Y	Y	1,4,5	1,4	2,3,4,5,6,7,8,9	3	740	780	9	95

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6 (Q)	<b>SOURCE OF ELECTRIC POWER</b>		
(P)	<b>SCHOOL RECORDS</b>				PHCN	1 Other	6
	Admission Register	1			Generator	2	
	Attendance Register	2			PHCN/Generator/	3	
	Syllabus/Plan of Work	3			Solar	4	
	Supervision Book	4			None	5	
	Visitors Book	5					

TABLE 67 Contd

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		61	St Michael Orimolade Com Pry Schl, Ondo	2	-
62	St Peter's Rcm Pry Schl, Abusoro, Ondo	1	-	-	19	24	5	12	58	62	N	N	N	1	1	1-5, 8, 9, 10	5	223	220	5	2
63	St. Luke's A/C Pry Sch, Orisunmibare	2	6	-	28	28	-	10	240	240	N	N	Y	3	1	1,2,3,4,5, 8,9,10	2	63	83	6	2
64	ST. Albert's RCM Pry Sch. Lemoso	1	4	4	12	12	4	4	160	160	N	N	N	1	1	1-5,8,9	5	83	78	4	1
65	St. Andrew's (Ang) Primary School Ondo	3	23	4	40	50	4	20	440	440	Y	N	N	3,5		1,2,3,4,5, 8,9	1	398	359	1	27
66	St. Andrew's R.C.M Pry, Sch, Ayesanmi	2	6	-	-	-	-	-	48	48	N	-	-	1,6	1	1,2,3,4,5, 6,7,8,9	5	63	51	3	4
67	St. Anne's Rcm Pry Schl Oke-Agunla Ondo	3	4	20	80	80	20	40	130	130	N	N	N	6	0	1,2,3,4,5, ,8,9	5	265	295	4	14
68	St. Augustine's RCM Pry Schl Mojolu Ondo	1	2	-	7	7	0	7	420	420	N	N	N	1,6	1	1,2,3,4,5, 8,9,10	5	136	144	5	8
69	St. Batholmew's Primary School, Bagbe, Ondo	1	3	4	4	16	3	7	200	200	N	N	N	1	1	1,2,3,4,5, 8,9	5	1	6	9	2
70	St. Francis R.C.M Primary School Lekere, Ondo	2	4	-	12	4	4	4	150	150	N	N	N	1,5	1	2,3,4,5,8, 9	5	115	138	3	5

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
(P)	SCHOOL RECORDS				PHCN	1 Other	6
	Admission Register	1			Generator	2	
	Attendance Register	2			PHCN/Generator/	3	
	Syllabus/Plan of Work	3			Solar	4	
	Supervision Book	4			None	5	
	Visitors Book	5					

TABLE 67 Contd

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	A Nature of building Materials	B No of Functional classrooms	C No of roofs in bad condition	D No of walls in bad condition	E No of windows in bad condition	F No of floors in bad condition	G No of doors in bad condition	H Total access to Seat	I Total access to Desk	J Availability of library (Y/N)	K Library well stocked? (Y/N)	L Availability of Computer (Y/N)	M Health / Water Supply / Sanitation Facilities available	N Recreational facilities available	O School Records available	P Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		71	St. John Bosco R.C.M Primary School Ondo	2	9
72	St. John's Orimolade Primary School, Ondo	3	5	5	20	20	5	10	120	120	N	N	N	1	1,2,3	2,3,4,5,6,7,8,9	5	103	99	5	20
73	St. Joseph's C.A.C Pry School, Oke-Isegun, Ondo	3	-	-	80	80	18	44	310	331	N	N	Y	1,4,6	1,5	2,3,4,5,8,9	3	539	556	1	30
74	St. Kevin R.C.M Pry School Igunsin-Ondo	3	6	4	14	10	6	8	181	181	N	N	Y	5	1	1,2,3,4,5,8,9	3	106	111	3	7
75	St. Leo's R.C.M Primary School Ayeyemi-Ondo	3	16	11	52	52	11	24	325	325	N	N	N	1,4,6	1	1,2,3,4,5,8,9	5	250	340	5	34
76	St. Luke's Anglican Pry School, Oka-Ondo	2	-	-	54	-	-	6	595	584	N	N	Y	1,4,5	1,2,4	2,3,4,5,8,9	1	359	356	3	23
77	St. Mark's Ang Primary School Ayetima Ondo	1	4	12	48	48	12	24	240	240	N	N	N	1	1	1,2,3,4,5,8,9	5	187	225	4	1
78	St. Mark's Anglican Pry Sch, Igbindo- Ondo	1	8	4	40	40	6	20	700	690	N	N	Y	-	1	1,2,3,4,5,8,9,10		260	355	4	1
79	St. Mark's Anglican Pry Sch, Bagbe Ondo	2	11	11	18	60	11	15	220	224	N	N	N	6	1	1,2,3,4,5,8,9	5	237	218	1	14
80	St. Mary Gbose Memorial Pry Sch, Ondo	3	6	5	40	40	5	20	512	512	Y	N	Y	5	-	1,2,3,4,5,6,8,9,10	1	499	523	3	29

KEY

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6 (Q)	SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5

TABLE 67 Contd

**ONDO WEST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
81	St. Mary's A/C Primary School Ilutitun, Ondo	2	6	6	36	24	6	12	240	240	N	N	Y	1,6	1,4	1-5,8,9	2	80	80	2	3
82	St. Mary's R.C.M Pry Sc, Oke-Gbala, Ondo	2	18	10	40	40	10	30	660	650	N	N	N	1,6	1	1,2,3,4,5,8,9,10	5	424	496	2	24
83	St Matthew's Pry Schl Oke-Paadi, Ondo	3	5	2	15	15	1	7	660	660	N	N	Y	1,4	1	1-5,8,9,10	1	694	671	4	35
84	St Matthew's A/C Pry Sch, Eloyowo	1	-	8	7	8	8	8	120	120	N	-	N	1	1	1-5,8,9,10	5	75	87	3	1
85	St. Micheal's A/C Pry Sch, Olgbe va, Ondo	1	6	4	4	4	4	4	91	77	N	-	-	1	1	1-5,8,9	5	78	102	4	1
86	St. Monica's R.C.M Pry Schl, Laje Ondo	3	6	17	17	17	17	17	189	164	Y	N	N	1,5	1,2,4	1-5,8,9	5	200	20-5	5	2
87	St. Paatrick's R.C.M Pry Schl, Yaba Ondo	3	6	1	10	20	1	10	1108	1108	N	N	Y	4,5	1,4	1-5,8,9,10	3	869	851	4	60
88	St. Paul's A/C Primary School, Olosan-Ondo	1	4	-	-	-	-	-	60	60	N	N	N	1	1	1-5,8,9,10	5	144	147	4	3
89	St. Paul's Anglican Pry Schl, Odowo-Ondo	2	-	14	56	56	14	28	268	268	N	N	N	1	1,4	1-5,8,9	5	111	102	4	5
90	St. Paul's Anglican Pry Schl, Ogho-Ondo	3	4	6	6	6	6	6	240	240	N	N	N	1	1	1-5,8,9,10	5	163	180	3	3

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 67 Contd

**ONDO WEST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS**

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		91	St. Paul's R.C.M Primary School, Yaba, Ondo	3	20
92	St. Peter's C.A.C Pry Sch Oke-Igbala, Ondo	3	7	10	19	38	16	8	91	183	N	N	N	1,5	4	1,2,3,4,5,8,9,10	5	328	402	-	35
93	St. Peter's F.A.C Pry School, Odosida, Ondo	2	14	6	30	36	7	16	445	445	N	N	N	1,4,6	1	1,2,3,4,5,8,9	1	321	342	-	22
94	St. Philip's A/C Primary School Ikonja Ondo	1	6	6	24	24	6	12	32	32	N	N	N	1	1,6	2,3,4,5,8,9	5	134	144	5	3
95	St. Spephen's (Ang) Pry Schl, Odosida Ondo	2	18	2	42	36	12	20	240	240	Y	N	N	1,3,5	3	1,2,3,4,8,9,10	5	370	380	1	22
96	St. Stephen's A/C Pri Sch, Oke ipa	1	4	2	15	4	-	8	64	64	N	N	N	1	1	1,2,3,4,5,8,9	5	53	48	2	-
97	The Apostolic Pry School Lotogbe, Ondo	2	-	-	12	12	2	6	68	68	N	N	N	5	-	1,2,3,4,5,8,9	5	56	50	1	8
98	United Primary School, Ajegunle- Ondo	1	6	3	18	22	14	14	281	360	Y	N	N	-	1,4	1,2,3,4,5,8,9	5	101	102	4	1

**KEY**

(B)	<b>NATURE OF BUILDING:</b>	(N)	<b>HEALTH/WATER/SANITATION FACILITIES:</b>	(O)	<b>RECREATIONAL FACILITIES</b>		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	<b>SCHOOL RECORDS</b>		Water Closet	6 (Q)	<b>SOURCE OF ELECTRIC POWER</b>		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 68

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	All Saints Grammer School, Oka, Ondo	2	12	6	8	48	6	24	52	60	Y	N	4,5	Y	4,5	1,2	1,2,3,4,5,8,9	1	239	267	11	26
2	A.U.D Comm. Junior High Sch. Ondo	2	-	12	48	48	12	12	400	400	N	N	4	N	-	1	2-5,7-9	1	294	353	14	18
3	Bagbe/ Ilunla High School, Bagbe-Ondo	3	6	-	4	6	4	12	90	196	Y	N	4	Y	1,5	1,2,4	1,2,3,4,5,6,8,9	1	210	258	9	9
4	C.A.C Grammar School, Oka Ondo	1	17	-	51	17	17	34	696	680	N	N	-	Y	1,5	1,4	1,2,3,4,5,8,9	1	374	485	9	25
5	C.A.C Oke Isegun High School, Ondo	3	9	9	29	29	9	9	100	100	N	N	1,2,3	Y	-	1,4	1,2,3,4,5,8,9	3	243	280	8	21
6	Celestial Junior Secondary School,	2	12	-	40	40	-	20	1100	550	Y	N	4	Y	1,4,5,6	1,2,4	1-10	3	267	227	8	14
7	Comm. Junr. Gram. School, Ondo	2	4	3	30	10	5	10	40	40	N	N	4	Y	1	1,2	2-6, 8-10	5	86	92	4	3
8	Community Comp. High School, Aiebambo Ondo	2	3	-	4	4	4	2	115	126	N	N	1,2,3	N	1,4	1	1,2,3,4,5,8,9	5	140	138	7	4
9	Community Grammer School, Oluwabasiri Ondo	1	2	2	8	8	2	4	39	100	Y	-	-	Y	5	1,2,3	1,2,3,4,5,6,7,8,9	5	67	64	5	-
10	Community junior Grammar School, Laie	2	3	3	-	24	6	12	185	185	Y	-	-	N	-	1,2,4	1,2,3,4,5,8,9	5	103	79	8	1

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 68 Contd

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Gbagiyetimbo Comm. Jnr. Sch. Ave	2	6	4	12	13	3	10	20	30	N	N	4	Y	-	1,2	2-5,8,9	5	88	86	4	2
12	Holy Flock Of Christ Gram Schl, Ayeyemi Street, Ondo	2	11	9	37	44	11	22	240	240	N	-	-	Y	5	1	1,2,3,4,5,8,9	1	268	279	9	15
12	Ifedapo Comm. Gram. Sch. Ondo	2	4	3	10	15	3	8	40	40	N	N	4	Y	-	1,2	2-5,8,8	5	126	128	6	2
14	Igbado Comm. Grammer School, Igbado, Ondo	3	4	3	8	8	2	4	150	150	Y	N	4	Y	1,5	1	1-10	1	102	97	8	7
15	Igbindo Community High School, Igbindo- Ondo	3	5	-	20	20	5	10	160	180	N	-	-	Y	1,3	1,2,3,4	1,2,3,4,5,6,8,9	5	178	125	8	1
16	Igunsin Comm. Gram. Sch. Ondo	1	2	4	22	20	4	10	30	30	N	N	4	Y	1	1,2	2-6,8,9	5	96	83	6	8
17	Independence Grammer School, Ore Road, Ondo	2	13	8	16	16	8	4	280	280	N	N	1,2,3,5	Y	1	1,2	1,2,3,4,5,8,9	1	219	213	13	18
18	Jubilee Comm. Gram. Sch., Ondo	3	16	11	24	24	8	27	840	840	N	N	4,5	Y	1,4,5	4	2-6,8,9	1	315	506	8	20
19	Lujomu Comprehensive High School Oka, Ondo	2	3	3	12	12	3	6	40	40	N	N	-	N	1,5	1,2	1,2,3,4,5,8,9	1	139	121	3	13
20	Methodist Grammar School, Oke-Agunla Ondo	2	6	6	20	14	6	6	130	120	N	N	4	Y	-	1	1,5,7,8,9	5	129	136	9	12

KEY

(B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

(M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

(O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

(P) RECREATIONAL FACILITIES:

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

(Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

(R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		



TABLE 68 Contd

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
21	Ogo Olorun C&S Jnr. High Sch. Ondo	2	3	2	-	4	3	4	214	214	N	N	5	N	5	1,2	2-5,7-10	5	89	134	4	8
22	Ondo Anglican Grammar School, Ondo	2	12	6	20	20	4	11	150	150	N	N	-	Y	3	1,2,4	1,2,3,4,5,7,8,9	3	448	-	9	27
23	Ondo Boy's High School, Idimoge Street, Ondo	3	24	-	-	96	24	48	800	800	Y	N	4,5	Y	1	1,2,3	1-10	1	1180	-	13	44
24	Orimolade C.C High School, Sabo, Ondo	2	4	4	14	14	-	4	104	104	Y	N	4,5	Y	1,3,5	1,2	1-9	1	83	62	4	16
25	St. Ambrose's Jnr. Sec. Sch. Ondo	3	10	-	15	53	-	28	585	602	N	N	6	Y	-	1,2,4	1-5,8,8	3	296	395	6	23
26	St. Andrew's Anglican Gram Sch, Canon Adeyemi Road Ondo	2	8	1	44	52	14	26	400	400	N	-	4	Y	3	1,2	1-5,7-9	3	229	455	10	23
27	St. Helen's Unity Jnr. Sec. Sch. Ondo	3	13	-	-	-	10	26	29	29	Y	N	5	Y	1,3,5	1-4	2-9	1	-	562	5	19
28	St. Jame's Cath. Jnr. Sec. Sch. Ondo	3	11	-	-	44	8	22	243	350	Y	Y	4,5	Y	1,4,5	1,2,3	1-10	1	319	461	8	28
29	St. Joseph's College Ife Road, Ondo	2	18	14	72	72	-	36	615	630	N	-	-	Y	5	1	1-9	1	801	-	15	33
30	St. Louis Junior Sec Sch, Ondo	3	15	-	-	-	-	-	590	590	Y	N	4,5	Y	1,3,4,6	1,2	1,2,3,4,8,9,10	3	-	545	9	23

KEY

(B) NATURE OF BUILDING:

- Mud 1
- Cement/Burnt Brick2 2
- Both 3
- Others 4

(M) LABORATORY:

- Physics 1
- Chemistry 2
- Biology 3
- Intro. Tech. 4
- Home Econs. 5
- Others 6

(O) HEALTH/WATER/SANITATION FACILITIES:

- Wash Hand Basin 1
- Pipe Borne Water 2
- Bore Hole 3
- Protected Well 4
- VIP/Traditional Pit Latrine 5
- Water Closet 6

(P) RECREATIONAL FACILITIES

- Play Ground 1
- School Hall 2
- Table Tennis Court 3
- Food Vendor/Canteen 4
- Swimming Pool 5

(Q) SCHOOL RECORDS

- Admission Register 1
- Attendance Register 2
- Syllabus/Plan of Work 3
- Supervision Book 4
- Visitors Book 5
- Visitors Book 5

(R) SOURCE OF ELECTRIC POWER

- PHCN 1
- Generator 2
- PHCN/Generator/ 3
- Solar 4
- None 5
- None 5
- Other 6

TABLE 68 Contd

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
31	St. Monica's Grammer School, Ife Road, Ondo	3	18	15	32	68	18	30	450	800	N	-	4	Y	1,3,4,5	1,2,4	1,2,3,4,5,6,7,8,9,10	1,3	-	965	7	31
32	St. Stephen's (Ang) Grammer School, Odosida Street, Ondo	2	19	16	49	76	5	38	258	258	Y	N	4,5	Y	3,5	1,2,4	1,2,3,4,5,6,7,8,9,10	1	386	540	9	27

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 68 Contd

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	All Saints Grammer School, Oka, Ondo	2	10	-	20	40	-	10	350	350	Y	N	-	Y	5	1,2,4	1,2,3,4,5,6,7,8,9	1	238	277	12	24
2	A.U.D Comm. Senior High Sch. Ondo	2	13	3	30	10	7	5	103	103	Y	Y	-	Y	3	2,3	1-10	1	230	318	17	14
3	Ajebambo Comm. Comp. Senior High School	2	3	3	5	4	-	3	100	100	N	N	-	Y	1,3	1,2	1,2,3,4,5,6,8,9	5	148	122	11	-
4	Bagbe/ Ilunla High School, Bagbe-Ondo	2	7	2	28	28	7	14	250	250	Y	N	-	Y	6	1,2,4	1,2,3,4,5,6,8,9	1	217	142	12	7
5	C.A.C Community Grammar School, Oka Ondo	2	15	15	15	15	15	30	400	400	Y	N	1,2	Y	1,4	2	1,2,3,4,5,8,9	1	187	311	12	18
6	C.A.C Oke Isegun High School, Ondo	3	9	9	36	36	9	18	280	280	Y	N	1,2,3,5	Y	1,4	1	1,2,3,4,5,8,9	3	205	290	6	13
7	Celestial Senior Gram. Secondary School	2	10	10	30	30	10	20	600	600	Y	N	1,3,5	N	1,4,5,6	1,2	1-4,7-9	1	210	224	13	16
8	Comm. Senior Gram. School, Ondo	2	4	3	30	10	7	5	30	30	Y	N	2,3	Y	1,6	1,2	109	5	96	94	10	1
9	Communioty Grammer School, Oluwabasiri Ondo	1	4	4	24	-	3	12	58	58	Y	N	3	Y	5	1,2,4	1,2,3,4,5,6,8,9	5	129	112	7	-
10	Community Grammar School, Iaje Ondo	3	4	-	-	16	-	8	140	140	Y	N	1,2	Y	5	1,2	1,2,3,4,5,6,7,8,9	2	136	142	7	2

KEY

(B) NATURE OF BUILDING:

- Mud 1
- Cement/Burnt Brick2 2
- Both 3
- Others 4

(M) LABORATORY:

- Physics 1
- Chemistry 2
- Biology 3
- Intro. Tech. 4
- Home Econs. 5
- Others 6

(O) HEALTH/WATER/SANITATION FACILITIES:

- Wash Hand Basin 1
- Pipe Borne Water 2
- Bore Hole 3
- Protected Well 4
- VIP/Traditional Pit Latrine 5
- Water Closet 6

(P) RECREATIONAL FACILITIES

- Play Ground 1
- School Hall 2
- Table Tennis Court 3
- Food Vendor/Canteen 4
- Swimming Pool 5

(Q) SCHOOL RECORDS

- Admission Register 1
- Attendance Register 2
- Syllabus/Plan of Work 3
- Supervision Book 4
- Visitors Book 5
- Visitors Book 5

(R) SOURCE OF ELECTRIC POWER

- PHCN 1
- Generator 2
- PHCN/Generator/ 3
- Solar 4
- None 5
- None 5
- Other 6

TABLE 68 Contd

**ONDO WEST**  
**INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS**

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Gbagiyetimbo Comm. Gram. Sch. Ave	3	3	6	13	14	7	7	40	40	N	N	1,2	Y	1	1,2,5	2-3, 7-10	5	170	125	8	6
12	Holy Flock Of Christ Grammar School, Ayeyemi Street, Ondo	2	6	5	15	15	5	8	98	98	Y	N	1,2,3	N	1,6	1,2,4	1,2,3,4,5,6,7,8,9	1	173	162	13	10
13	Ifedapo Comm. Gram. Sch. Ondo	2	2	3	10	8	3	4	20	20	Y	N	-	Y	1,4	1-4	1-8	1	18	18	5	-
14	Igbado Comm Gram Sch, Igbado, Ondo	2	5	5	5	5	2	2	70	70	Y	N	2,5	N	-	1,4	1,2,3,4,5,6,8,9	1	81	45	11	5
15	Igbindo Community High School, Igbindo, Ondo	2	6	3	12	12	6	12	136	136	Y	N	1,2,3	Y	1,4	1,2	1,2,3,4,5,6,7,8,9	5	113	95	2	5
16	Igunsin Comm. Gram. Sch. Ondo	3	4	5	10	10	3	2	40	40	Y	N	2,5	N	-	1,4	1-10	1	112	142	11	2
17	Independence Grammer School, Ore Road, Ondo	2	11	22	88	88	22	44	200	200	Y	N	1,2,3,5	N	1,3	1,2,4	1,2,3,4,5,6,8,9,10	1,2	140	144	23	26
18	Jubilee Comm. Gram. Sch., Ondo	2	16	13	64	64	13	26	400	400	N	N	1,2,3,5	Y	1,5	1,2,4	2-10	1	260	398	22	21
19	Lujomu Comprehensive High School Oka, Ondo	2	3	3	12	12	3	6	93	93	Y	N	1,2,3	N	1,5	1	1,2,3,4,8,9	1	116	115	10	7
20	Methodist Grammar School, Ondo	2	6	-	6	6	6	6	200	200	Y	N	-	N	-	2	1,2,3,4,5,6,8,9	1	146	103	13	10

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		

TABLE 68 Contd

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
21	Ogo Olorun C&S Snr. High Sch. Ondo	2	3	3	12	12	3	6	40	40	N	N	3	Y	3,5	1,2	1-10	-	120	92	14	4
22	Ondo Anglican Grammar School, Ondo	2	12	-	-	-	-	6	120	120	Y	N	1,2,3	Y	3,5	1,2	1,2,3,4,5,6,7,8,9,10	3	336	-	16	17
23	Ondo Boy's High School, Idimoge Street, Ondo	2	24	10	24	40	16	16	250	250	Y	N	1,2,3,4	N	1,3,5	1,2,3	1,2,3,4,5,6,7,8,9	1	770	-	24	18
24	Orimolade C.C High School, Sabo, Ondo	2	5	6	20	4	2	12	45	45	Y	N	-	N	4,5	1,2	1,2,3,4,5,6,8,9	1	106	105	11	10
25	Saint Andrew's Anglican Grammar School, Canon Adeyemi Road, Ondo	2	12	8	14	16	3	24	420	420	Y	N	4	Y	5	1,4	1,2,3,4,5,6,7,8,9	1	155	289	17	24
26	St. Ambrose's Jnr. Sec. Sch. Ondo	2	12	-	-	40	-	24	300	300	Y	Y	1,2,3,5	Y	1,4,5	1,4	1-6-8,9	1	126	313	13	20
27	St. Helen's Unity Snr. Sec. Sch. Ondo	2	14	14	56	56	14	28	32	32	Y	Y	1,2,3,5	Y	1-4	1,2,4,5	1-9	-	85	32	17	17
28	St. Jame's Cath. Snr. Sec. Sch. Ondo	2	12	12	48	48	12	24	150	150	Y	N	2	Y	1,4,5	1,2,4	1-10	1	349	415	13	17
29	St. Joseph's College Ife Road, Ondo	2	16	3	40	64	-	32	800	800	Y	Y	1,2,3,4,5	Y	1,5,6	1,2	1,2,3,4,5,6,7,8,9	3	703	-	19	27
30	St. Louis Secondary School, Ondo	2	14	-	42	-	-	28	560	560	Y	Y	1,2,3,4,5	Y	1,3,4,5,6	1,2	1,2,3,4,5,6,7,8,9	3	-	551	10	25

KEY

(B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

(M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

(O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

(P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

(Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

(R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 68 Contd

ONDO WEST  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
31	St. Monica's Grammer School, Ife Road, Ondo	2	17	5	16	5	8	-	400	400	Y	N	1,2,3,5	Y	1,4,5,6	1,2,3,4	1,2,3,4,5,6,7,8,9	1	-	568	15	28
32	St. Stephen's (Ang) Grammer School, Odoosida Street, Ondo	2	13	8	50	52	13	26	180	180	Y	N	2,5	Y	1,4	1	1,2,3,4,5,6,8,9	3	240	414	24	22

KEY

(B) NATURE OF BUILDING:

- Mud 1
- Cement/Burnt Brick2 2
- Both 3
- Others 4

(M) LABORATORY:

- Physics 1
- Chemistry 2
- Biology 3
- Intro. Tech. 4
- Home Econs. 5
- Others 6

(O) HEALTH/WATER/SANITATION FACILITIES:

- Wash Hand Basin 1
- Pipe Borne Water 2
- Bore Hole 3
- Protected Well 4
- VIP/Traditional Pit Latrine 5
- Water Closet 6

(P) RECREATIONAL FACILITIES

- Play Ground 1
- School Hall 2
- Table Tennis Court 3
- Food Vendor/Canteen 4
- Swimming Pool 5

(Q) SCHOOL RECORDS

- Admission Register 1
- Attendance Register 2
- Syllabus/Plan of Work 3
- Supervision Book 4
- Visitors Book 5
- Visitors Book 5

(R) SOURCE OF ELECTRIC POWER

- PHCN 1
- Generator 2
- PHCN/Generator/ 3
- Solar 4
- None 5
- None 5
- Other 6

TABLE 69

OSE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		1	A.U.D. Pry. school, Ifon	2	6
2	A.U.D. Pry. school, Idoani	2	5	-	-	-	5	-	78	90	N	N	Y	1	1	6,7,8,9,10	5	47	65	3	12
3	AC/CAC United Pry. Sch, Idoani	2	9	2	8	20	3	10	120	120	N	N	N	-	1	1-5, 8,9	5	178	203	1	8
4	Ansar-Ud-Deen Primary School, Idogun	2	6	3	36	12	6	10	140	140	N	N	Y	1	1	1-6,8,9	1	210	2253	5	
5	Ausar-Ud Deen Primary School Ute	2	4	2	2	6	2	4	106	114	N	N	N	1	1,4	1-5,8,9	5	117	128	2	4
6	Baptist Primary School Ifon	2	6	-	-	56	-	18	240	240	N	N	N	3	1	1-6,8-10	5	56	35	4	10
7	C.A.C Primary School, Okikanmi, Idoani	1	2	2	8	8	2	4	60	60	N	N	Y	1,3	1	1-5, 8,9	5	102	109	11	-
8	C.A.C. pry. Sch, Okeluse	3	6	-	-	-	6	-	60	60	N	N	N	1	1	2-5,8-10	5	181	161	2	10
9	Catholic/Methodist Primary School, Idoani	2	9	-	-	-	4	12	80	80	N	N	Y	1,6	1	1,2,3,5,8,9,10	5	128	126	4	6
10	Community Primary School, Owajalaye, Ute	1	6	6	24	24	6	12	78	78	N	N	Y	1,5	1	2-5,8-10	5	158	160	6	2

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 69 Contd

OSE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		11	Community Primary School, Uka, Imeri	3	12
12	Community Pry. Sch. Elerinla	2	4	2	8	16	2	4	148	148	N	N	N	5	1	1-5, 8,9	5	288	321	4	2
13	Community Pry. Sch. Omi Alafa	2	6	-	-	-	-	12	240	240	N	N	Y	6	1	1-9	5	194	200	5	3
14	Community Pry. Sch. Omiobi Imoru	1	5	-	-	20	-	-	174	174	N	N	Y	-	1	1-5, 8,9	5	123	141	3	1
15	Community Pry. School abusoro	2	2	-	6	6	6	8	30	22	N	N	N	-	1	1-5,8,9	5	41	38	12	-
16	Community Pry. School Iwoye Afo	2	6	6	-	8	-	4	260	260	N	N	Y	-	1	1-5, 8,9	5	75	53	5	1
17	Holy Trinity A/C Pry. Sch. Ido Ani	2	7	6	24	16	4	6	600	600	N	N	Y	2,6	1	1,2,3,4,5, 8,9,10	5	269	236	5	7
18	Holy Trinity A/C Pry. Sch. Owani	2	12	2	8	8	2	4	220	224	N	N	Y	1,5	1	1-5,8-10	5	101	95	6	5
19	L. A Primary School Ijagba	2	6	-	-	10	-	6	240	240	N	N	N	1,6	1	1-5,8-10	1	67	60	3	2
20	L. A. Comm. Pry. Schl., Arimogija	2	4	2	2	34	16	34	200	90	N	N	N	5	-	1-5,8-10	5	194	322	9	2

KEY

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
			Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
(P)	SCHOOL RECORDS				PHCN	1 Other	6
	Admission Register	1			Generator	2	
	Attendance Register	2			PHCN/Generator/	3	
	Syllabus/Plan of Work	3			Solar	4	
	Supervision Book	4			None	5	
	Visitors Book	5					



TABLE 69 Contd

OSE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers		
21	L. A. Primary School, Afo	2	6	-	-	8	-	-	64	70	N	N	Y	4	1	1-5, 8-10	5	126	1283	5	
22	L.A/A.U.D Sch., Idoani	1	8	-	-	-	-	-	120	120	Y	N	Y	1	1	1-6,8-10	5	149	153	6	19
23	Local Authority Primary School I fon	2	9	2	4	15	15	10	180	180	N	N	Y	3,5	1,4	1-5,8,9	5	199	171	4	18
24	Model Primary Scschool, Imeri	2	8	6	-	12	-	-	240	240	N	N	Y	1,5,6	1,5	1,2,3,4,5,6,8,9	5	269	236	14	9
25	New Church Primary School Arimogija	3	14	-	-	8	-	6	360	360	N	N	N	1,5	1	1-5,8-9	5	359	331	8	7
26	New Church Pry. School, Omolege	3	6	6	4	6	8	-	240	240	N	N	N	-	1	1-5,8,9	5	12	13	6	1
27	Social Primary School, Isewa Qtrs. Idoani	2	10	2	6	14	-	-	60	60	N	N	Y	1	1	1,2,3,4,5,8,9	5	102	109	11	-
28	St David's Ang. Pry. Sch., Afo	2	12	2	16	10	2	4	67	80	N	N	Y	4,6	1	1-5,8-10	5	107	113	4	8
29	St Jacob's C&S Primary School I fon	2	6	8	8	8	8	8	160	120	N	N	N	3,6	1,4	1-5,8,9	5	95	102	9	9
30	St Joseph C.A.C Primary School I fon	2	6	10	6	8	4	6	298	300	N	N	N	1,5	1,4	1-6,8,9	-	195	200	7	10

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
			Water Closet	6	
(P)	SCHOOL RECORDS			(Q)	SOURCE OF ELECTRIC POWER
	Admission Register	1		PHCN	1 Other
	Attendance Register	2		Generator	2
	Syllabus/Plan of Work	3		PHCN/Generator/	3
	Supervision Book	4		Solar	4
	Visitors Book	5		None	5

TABLE 69 Contd

OSE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers		
31	St. Andrew's Primary School Elegbeka	2	6	-	-	6	4	4	440	440	Y	N	-	1,5	1,4	1-5,8-10	-	388	311	6	12
32	St. Augustine Rcm Primary School Ifon	2	6	-	6	-	6	-	300	300	N	N	N	1	1	1-5,8-10	5	76	93	4	8
33	St. Barnabar's Ang Primary School Ifon	3	6	15	15	15	18	18	240	240	N	N	N	5	1	1-5,8,9	-	241	218	10	10
34	St. DAVid's/James's Pry. Sch., Afo	3	10	-	-	16	8	10	72	72	N	N	Y	-	1	1,2,3,5,8,9	5	83	114	4	7
35	St. DAVid's/James's Pry. Sch., Afo	3	10	-	-	16	8	10	72	72	N	N	Y	-	1	1,2,3,5,8,9	5	83	114	3	12
36	St. Finians Rcm Primary School Ute	2	7	2	2	4	4	4	400	400	N	N	N	1,5	1,4	2-5,8-10	5	166	165	5	5
37	St. James Ang . Pry. Sch. Idogun	2	11	8	16	8	8	16	200	120	Y	Y	Y	1,3,6	1	1-3, 5, 8, 9	2	129	133	3	7
38	St. James Ang Primary School Ijagba	2	12	2	-	-	2	2	168	180	N	N	-	1,4	1	1-5,8,9	5	103	51	4	1
39	St. James Pry. School Ogbese Falodun	3	4	-	-	16	-	3	240	240	N	N	N	-	1	1-5,8,9	5	158	182	4	1
40	St. Luke's Ang Primary Ute	1	3	6	6	12	6	6	440	440	N	N	-	-	1	1-5,8,9	5	313	307	5	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
			Water Closet	6		
(P)	SCHOOL RECORDS		6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1		PHCN	1 Other	6
	Attendance Register	2		Generator	2	
	Syllabus/Plan of Work	3		PHCN/Generator/	3	
	Supervision Book	4		Solar	4	
	Visitors Book	5		None	5	

TABLE 69 Contd

OSE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils	No of Teachers		
41	St. Mary's Primary School Imoru	2	6	6	6	6	6	6	98	98	N	N	N	5	1	1-5,8,9	5	79	83	4	2
42	St. Michael Primary School Ifon	2	5	5	5	5	5	5	302	300	Y	N	N	3	1,4	1-5,8,9	5	198	114	2	12
43	St. Monica's Rcm Primary School Ikaro	3	8	8	8	8	8	12	192	200	Y	N	N	-	1	1-5,8,9	5	125	120	5	7
44	St. Patricks R.C.M Pry. Sch. Oke-Afo	3	6	12	48	72	2	24	85	85	N	N	Y	1	1	1-5,8,9	5	84	89	3	7
45	St. Paul's Ang Primary School Imoru	2	7	-	6	-	-	4	102	102	N	N	-	-	1	1-5,8-10	5	98	113	5	3
46	St. Paul's Ang Primary School Imoru Ijagba	3	6	4	4	6	6	6	166	174	Y	N	N	5	1	1-5,8,9	5	186	218	8	2
47	St. Paul's Primary School Okeluse	1	8	-	-	-	-	3	280	280	N	N	Y	-	1, 4	2-10	5	260	248	7	19
48	St. Paul's Primary School, Ifon	2	2	14	14	20	20	20	202	212	Y	N	N	5	1	1-5,8,9	5	243	238	10	12
49	St. Paul's Pry. School, Ikaro	2	8	4	-	-	2	4	110	104	N	N	N	1,5	1	1-5,8-10	5	72	58	2	5
50	St. Paul's Primary School, Idogun	2	9	2	2	8	4	14	120	100	N	N	Y	1,5	1	1-5, 8-10	3	137	124	8	10

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE 69 Contd

OSE  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		51	St. Peter's Primary School Okeluse	2	8
52	St. Peter's Primary School Ori-ohin, Ifon	3	6	-	6	24	-	12	240	240	N	N	N	1	1	1-5,8-10	5	155	180	6	3
53	St. Stephen Ang. Primary School, Ute	2	8	-	4	-	-	4	262	262	N	N	N	1	1,4	1-5,8-10	5	104	130	4	4
54	The Apostolic Pry. Sch. Idoani	2	6	-	8	8	-	12	300	300	N	N	Y	6	1	1-5,8-10	5	127	128	3	9
55	The Apostolic Pry. Sch. Idogun	2	12	-	-	-	-	-	120	120	N	N	Y	1,6	1	1-5,8,9	5	173	168	4	12

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	



TABLE 70

OSE

## INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Ekamarun Ang Grammar School, Ifon	2	6	6	24	24	6	18	150	150	N	N	Y	Y	-	1,4	1-6,8,10	1	218	163	9	7
2	Idoani Grammar School, Idoani	2	2	3	12	12	3	6	50	50	Y	N	-	Y	1,2	1,3	1-6,8-10	1	96	86	4	7
3	Idogun High School, Idogun	3	12	6	-	24	12	6	250	250	Y	N	1	Y	6	1,4	1-6,8,9	3	201	187	21	5
4	Ifon Comprehensive High Schl, Ifon	2	12	-	36	36	3	18	900	900	Y	N	Y	Y	1,6	1,4	2-6,8,9	1,2	470	435	9	11
5	Ijagba/Imoru Grammar School, Ijagba/Imoru	2	5	-	15	15	5	10	120	191	N	N	-	Y	-	1,2,4	1-5,8,9	3	284	243	7	2
6	Ikaro high School Ikaro	2	2	2	16	16	4	8	138	138	Y	N	N	N	5	1	1-9	5	81	66	7	8
7	Imeri Comp. College Imeri	2	6	-	-	12	-	12	150	150	N	N	N	N	3	1	1-3,5,8,9	3	110	111	8	2
8	Irekari Comp. High School, Ido-Ani.	2	6	7	92	92	10	30	200	250	N	N	Y	Y	1	1,4	1-5,9,10.	2	200	182	9	12
9	More High School, Afo	3	4	4	16	16	4	8	120	120	N	N	-	Y	-	1	1-5,7-9	1	123	92	5	3
10	Okeluse Ang Grammar School, Okeluse	2	-	6	-	48	-	24	120	170	Y	N	Y	Y	5	1,2	1-5,8-10	1	178	154	9	4

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 70 Contd

OSE

## INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Ute High School, Ute	2	4	6	24	24	6	12	220	220	N	N	N	N	1,5	1,4	2-5,7-9	1	396	327	14	2
12	Word of Faith College, Arimogija	3	6	-	-	24	-	6	120	120	N	N	N	Y	6	1	1-5,8,9	1	174	161	7	2

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		





TABLE 70 Contd

OSE

## INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	Ekamarun Ang Grammar School, Ifon	2	6	6	24	24	6	12	150	150	N	N	1,2	Y	1	1,4	1-6,8-10	1	217	216	9	4
2	Idoani Grammar School, Idoani	2	4	3	12	12	3	6	50	50	Y	N	1,2,3	Y	1,3	1,3	1-6,8-10	1	64	82	5	1
3	Idogun High School, Idogun	2	6	-	1	-	-	12	200	200	Y	N	2,3	Y	6	1,2,4	1-6,8,9	1,2	134	129	5	3
4	Ifon Comprehensive High Schl, Ifon	2	10	-	24	24	3	12	590	590	Y	N	Y	Y	-	1,4	1-6,8,9	3	352	341	14	7
5	Ijagba/Imoru Gils Sec. Schl, Ijagba /Imoru.	2	16	8	48	72	18	36	325	334	Y	N	1	N	1,5	1,2,4	1-9	5	341	315	12	3
6	Ikaro high School Ikaro	2	6	3	24	24	6	12	240	210	Y	N	1,2,3	Y	1,5	1,2,4	1-5,8-9	4	107	78	2	3
7	Imeri Comp. College Imeri	3	6	6	-	24	-	12	100	100	Y	Y	1,2	Y	3,6	1,2	1-3,5,8,9	3	140	93	8	3
8	Irekari Comp. High School, Ido-Ani.	2	6	6	68	68	6	12	294	294	Y	Y	1,2,3	Y	1,5	1,2,4	2-5,8,9	1	166	128	23	15
9	More High School, Afo	2	3	3	-	24	6	12	100	100	Y	Y	2	N	-	1	2-9	1	109	87	4	2
10	Okeluse Ang. Snr. Gram. Sch., Okeluse	3	10	-	24	8	2	20	150	120	Y	N	2,3	Y	5	1,2,4	1-9	1,2	150	165	10	3

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 70 Contd

OSE  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (y/N)	Library well stocked? (y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	Ute High School Ute.	2	6	4	40	40	10	20	40	40	Y	N	N	N	5	1	1-5,8,9	5	30	-	3	7
12	Word of faith College Arimogija	3	5	2	8	8	2	4	120	120	N	N	Y	Y	1	1	2-5,8,9	1	159	132	159	291

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick2	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		



TABLE71

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		M	F	M	F
																		No of Pupils		No of Teachers	
1	St. John's School, Unity compound, Owo	3	16	10	-	10	10	10	165	320	N	N	-	1,6	1,4	1,2,4,5	1	129	146	3	33
2	St. James NG. School, Asolo Camp Owo	3	4	-	4	4	-	4	88	77	N	N	N	-	1	1-5	6	45	35	4	1
3	A.U.D Pry Iyere	2	14	-	8	20	2	5	350	350	N	N	N	1,5	-	1-5	1	195	144	2	15
4	A.U.D III Ogbomo	2	12	12	48	48	12	24	220	220	N	N	N	1	1,2,3	2,3,4,5	5	69	64	1	10
5	A.U.D Ehin-Ogbe, Owo	2	6	2	8	24	3	8	160	160	N	N	N	1	1	1-5,8,9	5	57	58	4	5
6	A.U.D Pry. Schl, Ago-Miller Ipele	2	6	-	24	24	6	-	240	240	N	N	N	1	1	2,3,5	5	164	129	4	4
7	A.U.D. School, Uwese	2	9	9	36	36	9	18	240	240	N	N	N	1,5	1	1,3,9	94	139	94	9	6
8	Adeolu Pry School, Owo	2	18	11	6	32	6	12	164	164	N	N	N	5	1	1-5	6	505	509	3	20
9	Ang. Agunbiade	2	3	-	-	-	1	2	40	32	N	N	N	-	1	1-5	5	24	19	5	-
10	Aud Pry School SANUSI CAMP, Owo	2	4	4	8	8	2	8	240	240	N	N	N	1	1	1,2,5,8,9	-	74	68	3	-

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE71 Contd

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
11	AUD I School, Owatowose, Owo	2	6	6	24	24	6	12	250	250	N	N	N	1,2,5	1,2	1-5	5	205	176	6	12
12	AUDII School, Owo	2	18	10	10	18	14	18	296	296	N	N	Y	1,5	1	1,2,4,5	3	334	328	4	10
13	Aud Pry School, Ipele	3	10	-	40	40	10	20	229	241	N	N	N	1,4	1,5	1,2,4,5	6	147	142	7	7
14	Audi Pry School, Owo	2	10	1	-	20	2	6	438	438	N	N	Y	1,5	-	1,2,4,5	2	251	206	9	8
15	Baptist Pry. School, Owo	2	9	-	-	-	-	-	158	158	N	N	N	1,5	1	1-5	5	87	96	-	10
16	C.A.C Ago Oloko	1	3	-	12	12	3	6	48	48	N	N	N	1	2	1-5	6	35	32	7	1
17	C.A.C. School, Uso	3	8	3	12	12	3	6	206	206	N	N	N	5	1	1-5,8,9	5	144	137	2	6
18	Community Pry Idasen	2	6	-	-	16	3	22	296	308	Y	N	N	1,5	1	1-5	5	146	125	6	14
19	Community Pry School, Eporo	2	3	4	16	16	4	8	160	175	N	N	N	1,6	1	2,3,4,5	5	78	85	3	6
20	Community Sch. Utelu	3	12	-	10	10	10	10	248	244	N	N	N	1,4	1	1-5	6	221	207	6	11

**KEY**

(B) NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
Mud	1	Wash Hand Basin	1	Play Ground
Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
Both	3	Bore Hole	3	Table Tennis Court
Others	4	Protected Well	4	Food Vendor/Canteen
		VIP/Traditional Pit Latrine	5	Swimming Pool
(P) SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER
Admission Register	1			PHCN
Attendance Register	2			Generator
Syllabus/Plan of Work	3			PHCN/Generator/
Supervision Book	4			Solar
Visitors Book	5			None
				1 Other
				2
				3
				4
				5
				6

TABLE71 Contd

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
21	Community Schl. Egbodo Emure-Ile, Owo	3	4	4	-	-	3	8	200	200	N	N	N	1	1	1-5,8,9	5	35	27	7	-
22	Community Schl. Owasoyo	2	4	4	16	16	-	8	80	80	N	N	N	1	1	1,2,4,5,8,9	5	74	64	2	7
23	Community School.	2	8	-	-	32	-	4	300	300	N	N	N	1,5	1	1-5	5	150	118	6	7
24	Emm. School, Aralepo	2	6	-	12	12	4	12	20	20	N	N	N	1,6	1	1-5	5	104	93	6	4
25	Government ii school, owo	2	6	6	24	24	4	8	96	96	N	N	N	1,6	1	2,3,4,5	1	79	104	3	10
26	Government School, Owo	3	17	11	4	26	11	14	326	326	N	N	Y	5	2	1-5	2	258	244	8	16
27	L.a pry school, Alete-Eporo, Owo	2	3	3	12	12	3	20	12	12	N	N	N	1	1	1-5	6	130	136	-	-
28	L.a pry school, isuada	3	12	3	12	28	5	6	200	200	N	N	N	1	1	1,2,4,5	5	218	176	3	9
29	L.A Pry. Schl. Igbanasa	2	10	-	8	8	1	2	372	358	Y	Y	N	5	1	1,2,4,5	1	219	169	5	15
30	L.A. Pry. School Igbe	3	12	8	20	32	8	14	220	220	N	N	N	-	1	1-5,9	5	115	113	4	8

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE71 Contd

OWO

## INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		31	L.A. Schl. Ogbese	3	8
32	L.A. School, Ojama	2	6	2	8	24	4	12	128	114	N	N	N	5	1,4	1-5	6	73	49	6	3
33	Meth. Ii School, Owo	2	12	-	1	29	7	16	240	240	N	N	N	-	1	1-5	6	174	178	2	14
34	Meth. School, Odofin	2	4	3	8	4	-	6	96	94	N	N	N	1	1	1-5,8,9	5	102	89	2	3
35	Meth. School, Owo	2	8	2	8	8	2	4	208	208	N	N	N	1,5	1	1-5,8,9	1	45	40	2	5
36	Meth. School, Ugbeta	2	4	-	16	16	-	8	40	40	N	N	N	-	1	2,5,8,9	5	76	102	5	1
37	New Church Agbowa	2	2	2	-	16	16	8	19	326	N	N	N	1	1	1-5	6	95	77	5	-
38	New Church Aruwajoye	2	4	-	-	16	16	8	200	300	N	N	N	1	1	1-5	6	67	76	4	4
39	New Church Pry. Ipele	2	4	4	24	16	4	6	134	134	N	N	N	1	-	1-5	5	69	54	-	9
40	New Church School, Owo	2	6	-	-	8	2	4	440	290	N	N	N	1,6		1-5,8,9	1	122	118	-	9

## KEY

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE71 Contd

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
41	Olagbegi C&S Owo	1	3	3	24	24	-	12	136	134	N	N	N	-	1	1,2,3,9	5	130	143	1	9
42	Our saviour's emure-ile	2	11	18	64	64	18	36	228	428	Y	N	N	6	1	1,2,4,5,6,8,9	5	255	289	1	17
43	St. Andrew's Rcm, Owo	2	8	3	3	15	1	11	252	504	N	N	Y	1,5	-	1,2,4,5	6	75	117	2	14
44	St. Andrew's school IMOLA STRT, uso	2	16	22	40	80	2	34	317	300	Y	N	N	1,5	1,4	1-5	5	233	249	3	22
45	ST. ANDREWS ANG. PRY USO	2	19	-	-	52	13	26	320	380	N	N	Y	1,5	1	1-5	3	373	375	4	20
46	St. Augustus Agoyeye	2	2	-	-	-	-	-	80	80	N	N	Y	1	-	1-5	6	196	151	2	7
47	St. Augustus Amehint	3	5	5	12	-	-	10	142	142	N	N	N	1	1	1-5,8,9	6	115	90	6	2
48	St. Francis Rcm, Owo	1	15	15	12	24	15	11	34	190	N	N	N	-	1	1,2,5	6	383	265	3	13
49	St. George's School, Owo	2	9	9	28	12	7	14	140	140	N	N	N	6	1,5	1,2,5,8,9	6	175	181	1	16
50	St. James IPEMEN	3	6	-	30	22	8	10	328	328	N	N	N	1,3	1	1-5	5	225	216	5	6

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES
	Mud	1	Wash Hand Basin	1	Play Ground
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall
	Both	3	Bore Hole	3	Table Tennis Court
	Others	4	Protected Well	4	Food Vendor/Canteen
			VIP/Traditional Pit Latrine	5	Swimming Pool
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER
	Admission Register	1			PHCN
	Attendance Register	2			Generator
	Syllabus/Plan of Work	3			PHCN/Generator/
	Supervision Book	4			Solar
	Visitors Book	5			None
					1 Other
					2
					3
					4
					5
					6



TABLE71 Contd

OWO

## INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		51	St. James Pry Uso	2	7
52	St. James school, ISAIPEN	3	17	17	36	69	17	34	339	407	N	N	N	1	1	1-5	5	247	235	4	40
53	St. John school, amurin	2	8	-	-	-	-	2	326	652	N	N	N	1,3,6	2	1-5	6	165	144	5	8
54	St. John's Ang New Street, Ipele	2	11	-	-	20	7	-	284	284	N	N	N	5,6	-	1-5	1	142	139	5	11
55	St. John's School, Iyere	2	13	3	11	12	7	14	140	386	N	N	-	1,5	1	1-5	-	207	186	2	14
56	St. John's school, Omolege, Ipele	2	3	-	-	16	-	-	82	2	N	-	N	1	1	1-5	-	81	54	5	4
57	St. Luke Isijogun	3	4	4	16	16	6	6	66	66	N	N	N	1	1	1,2,4,5,6,7,8	87	69	87	4	5
58	St. Martins Rcm, Owo	3	11	8	12	12	16	15	117	240	N	N	N	1	1	1-5	6	194	203	1	15
59	St. Mary Pry. Shool Owo	3	10	8	6	20	12	14	164	164	N	N	N	1,5	1	1,2,4,5	6	118	112	2	9
60	St. Mathew's Pry. Otapete	2	3	-	-	12	-	-	120	118	N	N	N	1	-	1-5	6	108	104	2	11

## KEY

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE71 Contd

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		61	St. Michael'S C&s Owo	2	6
62	St. Michael's a/c owo	3	2	11	44	-	-	22	200	340	N	N	N	1	1	1-5	5	35	33	-	8
63	St. Micheal Aghoro	2	3	2	16	16	2	8	22	22	N	N	N	3	1	1,2,3,5	6	37	33	5	1
64	St. Moses C&S Owo	2	8	-	32	-	-	16	88	88	N	N	N	5	1	1-5	6	128	141	1	16
65	St. Patricks Ang. Pry School, Owo	3	10	4	10	10	10	10	90	180	N	N	N	1	4	1,2,4,5	6	237	251	5	15
66	St. Paul's Ijebu Owo	2	8	8	-	32	-	16	290	290	N	N	N	-	-	1-5	6	263	239	2	16
67	St. Paul's Ipele	2	4	3	8	2	2	1	80	100	N	N	N	1	1	1-5	5	162	158	-	5
68	St. Peter C& S School, Uso	2	6	-	-	-	-	-	180	180	Y	N	N	6	-	1-5,8,9	5	117	117	9	18
69	St. Peter,S Cac, Owo	3	14	11	12	12	12	12	386	386	N	N	N	6	1	1-5	6	143	136	5	33
70	St. Peter's Sasere	2	4	-	12	12	4	8	20	-	N	N	N	1	1	1,2,4,5	6	78	69	7	-

**KEY**

(B) NATURE OF BUILDING:	(N) HEALTH/WATER/SANITATION FACILITIES:	(O) RECREATIONAL FACILITIES
Mud 1	Wash Hand Basin 1	Play Ground 1
Cement/Burnt Brick 2	Pipe Borne Water 2	School Hall 2
Both 3	Bore Hole 3	Table Tennis Court 3
Others 4	Protected Well 4	Food Vendor/Canteen 4
	VIP/Traditional Pit Latrine 5	Swimming Pool 5
(P) SCHOOL RECORDS	Water Closet 6 (Q)	SOURCE OF ELECTRIC POWER
Admission Register 1		PHCN 1 Other 6
Attendance Register 2		Generator 2
Syllabus/Plan of Work 3		PHCN/Generator/ 3
Supervision Book 4		Solar 4
Visitors Book 5		None 5

TABLE71 Contd

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R		S	
																		No of Pupils		No of Teachers	
																		M	F	M	F
71	St. Pius Rcm School, Owo	3	6	8	32	32	8	16	280	280	N	N	N	5	1	1-5	6	121	134	1	10
72	St. Saviour's C&S, Owo	3	8	3	5	-	3	2	285	461	N	N	N	1	1	1-5	6	220	201	1	19
73	St. Stephen's Ose	2	10	-	-	-	-	8	40	44	N	N	N	-	1	1-5,8,9	5	161	134	2	6
74	St. Stephen's Rcm Owo	1	7	6	-	24	6	4			N	N	N	1	1	1-5,8,9	5	320	303	6	10
75	St. Stephen's rcm, ipele	2	12	18	72	-	-	-	262	241	N	N	N	-	1	1,2,4,5	5	122	150	2	13
76	St. Thomas's Pry School, Owo	2	6	-	-	24	1	12	120	120	N	N	N	1	1	1,2,4,5	6	221	277	2	10
77	St. Michael Ilalekeji	1	6	2	16	16	1	7	60	60	N	N	N	1	1	1-5,8,9	5	29	24	6	8
78	The Apostolic Emure	3	12	12	36	33	16	31	200	200	N	N	N	1	1	1-5,9	5	77	122	2	10
79	The Apostolic Pry School, Owo	3	12	6	6	12	6	6	360	360	N	N	N	6	-	1-5	1	127	107	1	14
80	The Salvation Army, Owo	3	6	6	24	24	6	12	56	56	N	N	N	1,5	1	1-5	6	165	238	1	17

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES		
	Mud	1	Wash Hand Basin	1	Play Ground	1	
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2	
	Both	3	Bore Hole	3	Table Tennis Court	3	
	Others	4	Protected Well	4	Food Vendor/Canteen	4	
			VIP/Traditional Pit Latrine	5	Swimming Pool	5	
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER		
	Admission Register	1			PHCN	1 Other	6
	Attendance Register	2			Generator	2	
	Syllabus/Plan of Work	3			PHCN/Generator/	3	
	Supervision Book	4			Solar	4	
	Visitors Book	5			None	5	

TABLE71 Contd

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC PRIMARY SCHOOLS

S/N	A Name of Institution	B Nature of building Materials	C No of Functional classrooms	D No of roofs in bad condition	E No of walls in bad condition	F No of windows in bad condition	G No of floors in bad condition	H No of doors in bad condition	I Total access to Seat	J Total access to Desk	K Availability of library (Y/N)	L Library well stocked? (Y/N)	M Availability of Computer (Y/N)	N Health / Water Supply / Sanitation Facilities available	O Recreational facilities available	P School Records available	Q Source of Electric power	R No of Pupils		S No of Teachers	
																		M	F	M	F
																		81	United School Ago Panu	1	10

**KEY**

(B)	NATURE OF BUILDING:	(N)	HEALTH/WATER/SANITATION FACILITIES:	(O)	RECREATIONAL FACILITIES	
	Mud	1	Wash Hand Basin	1	Play Ground	1
	Cement/Burnt Brick	2	Pipe Borne Water	2	School Hall	2
	Both	3	Bore Hole	3	Table Tennis Court	3
	Others	4	Protected Well	4	Food Vendor/Canteen	4
			VIP/Traditional Pit Latrine	5	Swimming Pool	5
(P)	SCHOOL RECORDS		Water Closet	6 (Q)	SOURCE OF ELECTRIC POWER	
	Admission Register	1			PHCN	1 Other 6
	Attendance Register	2			Generator	2
	Syllabus/Plan of Work	3			PHCN/Generator/	3
	Supervision Book	4			Solar	4
	Visitors Book	5			None	5

TABLE 72

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	A.u.D. Comp. H.S. Owo	2	9	-	-	36	9	18	270	270	Y	N	-	Y	1,4	1,2,4	1-10	1	235	189	7	12
2	Ahmadiya G. S. Owo	3	12	5	13	13	13	13	350	400	Y	N	4,6	Y	1,5	1,4	1-9	3	375	265	22	23
3	Amuye C.A.C.H.S.Owo	3	12	8	32	32	8	16	450	500	Y	N	4,5	Y	1,6	1,2,4	1-6,8,9	3	310	208	9	13
4	Ijebu Comm. G.S.ijebu Owo	2	12	6	24	48	6	24	100	100	N	N	-	Y	1,5	1,4	1-5,8,9	5	170	149	12	4
5	Imade College ,Owo	2	17	-	9	36	68	8	460	360	Y	N	4,5	Y	4,5	1,2,3,5	1-9	3	998	-	16	25
6	Isuada CGS, Isuada.	2	3	3	12	12	3	6	240	240	N	N	-	Y	1,4	1,2,4	1-10	5	45	15	5	4
7	Methodist .H.s Owo	2	16	12	64	64	10	28	289	336	Y	N	4,5	Y	4,5	1,4	2-5,8,9	1	318	81	7	19
8	New Church G.S Owo	3	15	-	-	48	12	48	250	250	Y	N	-	Y	1,4,5	1,2	1-5,7-9	1	401	212	12	14
9	Owo high Sch. Owo	2	20	15	60	80	7	40	710	710	Y	N	-	N	5	1,2	1-6,8-10	5	593	427	10	26
10	ST, Catherine,s Ang Grm. Sch. Owo	3	15	-	20	40	5	20	435	435	N	N	4-6	Y	1,3,5,6	1,4	1-9	1	-	533	19	8

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 72 Contd

OWO

INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	JUNIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	St. John /Mary unity sec. schl .Owo	3	6	-	-	16	4	8	190	190	Y	N	1-5	N	2,4,5	1,2	1-9	1	117	73	12	6
12	St. Louis G.S Owo	2	17	-	-	68	-	34	800	800	Y	N	4	N	1,4,6	1,2,4	1-6,8,9	1,2	-	826	8	26
13	Uso G.S. USO.	2	8	8	24	24	8	16	240	240	Y	N	4,5	Y	1,4,5	1,2,4	1-4,6-9	1	302	323	10	23
14	C&S Grammar School, Owo	2	3	-	-	-	-	6	240	240	N	Y	-	Y	1,5	1	1-5,8,9	5	39	23	3	1
15	Ipele Comm. H/S, Ipele	2	5	5	-	20	-	20	287	287	Y	N	2	Y	1,5	1	2,9	5	168	119	11	2
16	Ipenmen Comm. H/S, Owo	3	6	6	24	24	6	12	194	194	Y	Y	2,3,3	Y	1,5	1	1-5,8,9	5	140	68	7	5
17	Adeyemi / Iyere Comp. H/S	2	10	2	5	10	4	4	450	450	Y	Y	1,2,3	Y	1,4,6	1,2,4	1-9	1	216	161	12	8
18	Comm. Gramm. Sch, Emure Ile	3	9	3	-	36	9	18	40	120	Y	Y	1-3,5,6	Y	1,5	1,2	1-10	1	116	134	10	9

KEY

(B) NATURE OF BUILDING:

- Mud 1
- Cement/Burnt Brick 2
- Both 3
- Others 4

(M) LABORATORY:

- Physics 1
- Chemistry 2
- Biology 3
- Intro. Tech. 4
- Home Econs. 5
- Others 6

(O) HEALTH/WATER/SANITATION FACILITIES:

- Wash Hand Basin 1
- Pipe Borne Water 2
- Bore Hole 3
- Protected Well 4
- VIP/Traditional Pit Latrine 5
- Water Closet 6

(P) RECREATIONAL FACILITIES

- Play Ground 1
- School Hall 2
- Table Tennis Court 3
- Food Vendor/Canteen 4
- Swimming Pool 5

(Q) SCHOOL RECORDS

- Admission Register 1
- Attendance Register 2
- Syllabus/Plan of Work 3
- Supervision Book 4
- Visitors Book 5
- Visitors Book 5

(R) SOURCE OF ELECTRIC POWER

- PHCN 1
- Generator 2
- PHCN/Generator/ 3
- Solar 4
- None 5
- None 5

2405

TABLE 72 Contd

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
1	A.U.D. Comp. H.S. Owo	2	12	2	24	48	12	24	120	120	Y	N	2,3	Y	4	1,2,4	1-6,8-10	1	231	139	18	6
2	Ahmadiya G. S. Owo	3	6	-	-	24	-	12	98	216	Y	N	4	Y	-	1,4	1-5,8-10	3	294	179	24	9
3	Amuye C.A.C H.S.Owo	3	10	3	28	40	8	20	50	50	Y	N	-	Y	3,6	1,2,4	2,8,9	1	274	148	20	6
4	Ijebu Comm. G.S.ijebu Owo	2	9	13	44	52	4	26	164	160	Y	N	1,2,3	N	-	1,4	2-10	5	220	147	13	5
5	Imade College ,Owo	2	13	3	-	16	-	-	406	431	Y	N	1-6	Y	1,4,5	1,2,3,4	1-9	3	742	-	26	16
6	Isuada CGS, Isuada.	2	2	2	8	8	2	4	140	160	N	N	-	Y	1,4,5	1,2	1-10	5	70	61	10	1
7	Methodist .H.s Owo	2	19	4	16	96	16	48	335	135	Y	Y	1-5	Y	3	1,2,4	1-3,5,6,8,9	1	261	143	23	9
8	New Church G.S Owo	2	15	13	24	40	-	15	560	500	Y	N	1-5	N	4,5,6	1,2,4	1-6,8,9	3	295	285	19	14
9	Owo high Sch. Owo	3	15	4	-	60	5	15	618	618	Y	N	2,3	N	1,4	1,2,4	1-6,8,9	1	335	315	-	15
10	St, Catherine's Ang Grm. Sch. Owo	3	11	-	1	63	10	23	150	150	Y	N	1,2,3,5	Y	4,5	1,2,4	1-5,8-10	3	-	356	10	13

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		

TABLE 72 Contd

OWO  
INFRASTRUCTURAL FACILITIES IN PUBLIC SECONDARY SCHOOLS

S/N	SENIOR																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S		T	
	Name of Institution	Nature of building Materials	No of Functional classrooms	No of roofs in bad condition	No of walls in bad condition	No of windows in bad condition	No of floors in bad condition	No of doors in bad condition	Total access to Seat	Total access to Desk	Availability of library (Y/N)	Library well stocked? (Y/N)	Laboratories Available	Availability of Computer (Y/N)	Health / Water Supply / Sanitation Facilities available	Recreational facilities available	School Records available	Source of Electric power	M	F	M	F
11	St. John /Mary unity sec. schl .Owo	3	8	5	2	20	13	41	350	280	Y	N	1-5	N	1,5	1,2,4	2-10	1	107	60	30	16
12	St. Louis G.S Owo	2	12	-	-	-	-	14	201	257	Y	N	1,2	N	4	1,2	1-9	1	-	887	12	16
13	Uso G.S. USO.	2	12	-	-	64	8	32	120	135	Y	N	2,3,4,5	Y	1,4,5	1,2	1-9	1	186	173	41	20
14	C&S Grammar School, Owo	2	1	-	-	-	1	2	120	120	N	N	-	Y	1,5	1	2-5,8,9	5	17	3	2	1
15	Ipele Comm. H/S, Ipele	2	5	5	-	20	-	10	287	287	Y	N	2	Y	1,5	1	2-9,	5	168	119	11	2
16	Ipenmen Comm H/S, Owo	3	6	6	24	24	6	12	194	194	Y	Y	2,3,4	Y	1,5	1	1-5,8,9	5	140	68	7	5
17	Adeyeri/Iyere Comp. H/S	2	10	2	5	10	4	4	450	450	Y	Y	1,2,3	Y	1,4,6	1,2,4	1-9,	1	216	161	12	8
18	Comm. Gramm Sch, Emure-ile	3	9	3	-	36	9	18	40	120	Y	Y	1-3,5,6	Y	1,5	1,2	1-10,	1	116	134	10	9

## KEY

## (B) NATURE OF BUILDING:

Mud	1
Cement/Burnt Brick	2
Both	3
Others	4

## (M) LABORATORY:

Physics	1
Chemistry	2
Biology	3
Intro. Tech.	4
Home Econs.	5
Others	6

## (O) HEALTH/WATER/SANITATION FACILITIES:

Wash Hand Basin	1
Pipe Borne Water	2
Bore Hole	3
Protected Well	4
VIP/Traditional Pit Latrine	5
Water Closet	6

## (P) RECREATIONAL FACILITIES

Play Ground	1
School Hall	2
Table Tennis Court	3
Food Vendor/Canteen	4
Swimming Pool	5

## (Q) SCHOOL RECORDS

Admission Register	1
Attendance Register	2
Syllabus/Plan of Work	3
Supervision Book	4
Visitors Book	5
Visitors Book	5

## (R) SOURCE OF ELECTRIC POWER

PHCN	1	Other	6
Generator	2		
PHCN/Generator/	3		
Solar	4		
None	5		
None	5		



